

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30941

Vehicle Insured : SHD 6939 L
Accident Date : 19-Dec-2019

Date : 24-Dec-2019

Our Ref : 190776 (FIRST CAP) / SANDRA

PAGE : 1

BIBI & BABA PTE LTD
Singapore

Not Authorised
Recovery B4 gain *5 days*

ESTIMATED COST OF REPAIR FOR NISSAN NV200 DX 1.6A (2019) GBJ2074Y
=====

1 pc front bumper		CM	536.10	n	✓
10 pcs front bumper clips	@ S\$ 4.40	CM	44.00	n	✓
1 pc n/s front bumper side retainer		CM	23.90	n	✓
1 pc n/s headlamp			446.40	n	?
1 pc n/s headlamp lower garnish			329.30	n	?
1 pc n/s front fender		B	504.70	n	✓
1 pc n/s front fender inner shield		CM	138.90	n	✓
8 pcs n/s front fender inner shield clips	@ S\$ 4.40	CM	35.20	n	✓
1 pc n/s front door		B	1,219.70	n	✓
2 pcs n/s front door hinges (top/lower)	@ S\$ 56.10		112.20	n	?
1 pc n/s front door checker		L	49.50	n	X
1 pc n/s front wheel rim cap cover		mir	136.80	n	✓
1 pc n/s front lower arm		B	200.50	n	✓
1 pc n/s front tie rod end			93.00	n	?
2 pcs front stabilizer bar bush	@ S\$ 11.20		22.40	n	?
			3,892.60		
	Less 10% :		-389.26		
			3,503.34		

1 pc n/s front door ROC sticker		CM	25.00	sn	✓
1 pc n/s front tyre			280.00	sn	?
1 pc n/s front wheel rim	LP	nd	219.20	sn	301n
1 pc n/s front knuckle arm		B	375.20	sn	✓
1 pc n/s front knuckle arm bearing		CM	296.90	sn	✓
1 pc n/s front shock absorber			252.80	sn	?
1 pc n/s front shock absorber stopper			57.10	sn	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display the original vehicle condition
- Parts prices without prejudice
- Third party liability on "Without Prejudice" basis
- No illegal, fraudulent or dishonest
- Supplier of parts and materials surveyed and is subject to the insurance Company

Continue Page 2 ...

Acknowledged:
Signature:
Date:

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHD 6939 L
Our Ref : 190776

Page : 2
No. : 30941

1 pc n/s front shock absorber bearing	126.10	sn 7
1 pc n/s front stabilizer bar linkage	49.50	sn 7
1 pc n/s front drive shaft	861.70	sn 7
1 pc steering rack & pinion	1,570.80	sn 7
1 pc front stabilizer bar	435.50	sn 7
To tow accident vehicle to workshop by normal towing	60.00	501
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	850.00	501
To focus headlamps. To check front wiring and lighting operation.	50.00	201
To apply undersealing	120.00	601
To remove door's fittings	80.00	601
To dismantle and check front under-carriages. To replace affected portions.	240.00	2001
To conduct front wheel alignment test.	100.00	601
To putty and respray on affected portions.	1,100.00	6001
Total :	S\$10,653.14	

Singapore Dollars Ten Thousand Six Hundred and Fifty Three and Cents Fourteen Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.