

NOT MOTOCAR
 2/5 2850/ Page No. 1
 Zubeidat. After 14-


VEHICLE NO. SJT 8490S TOYOTA ALTIS

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear bumper 525.10	20/pe	1298.00	✓
2	Rear bumper side retainers @ 98.00 65.10	0/5 set	196.00	1/6
2	Rear bumper reflectors @72.50	11	145.00	X
1	Rear bootlid	11	1452.00	X
2	Rear bootlid hinges @49.00	11	98.00	X
1	Rear boot edge weatherstrip	11	264.00	X
1	Rear bootlid inner lock	11	238.00	X
1	Rear bootlid lock catch	11	46.20	X
1	Rear bootlid Toyota badge	11	48.00	X
1	Rear bootlid ALTIS emblem	11	78.00	X
1	Rear bootlid COROLLA emblem	11	98.00	X
1	Rear bootlid 1.6 emblem	11	24.00	X
1	Rear bootlid inner trim	11	278.00	X
4	Rear bootlid rubber stopper @18.00	11	72.00	X
1	Rear bootlid centre chrome moulding	11	328.00	X
2	Rear bootlid reflectors @498.20	11	996.40	X
2	RHS & LHS Taillamps @752.40 365.30	0/5 set	1504.80	1/6
1	RHS Rear fender	REPAIR/LABOUR 11	0.00	X
1	Rear reinforcement frame 'bracket 0/5	97.50 11	780.00	✓
1	Rear bumper foam	11	68.00	✓
1	Rear spare tyre panel top board	11	172.00	X
1	Rear end panel 645.20	11	782.00	✓
2	Rear end panel outer bracket	11	142.00	X
1	Rear end panel top garnish	11	242.00	✓
			9350.40	
50% less 25%			2337.60	25%
			7012.80	
<u>SPECIAL NETT ITEMS</u>				
1	Reverse sensor set	should	280.00	200
1	Reverse camera	11	480.00	X
1	Rear end panel sealant	11	100.00	50
2	Rear bumper RH & LH side chrome moulding	11	250.00	X
1	Rear bootlid ELEGANCE emblem plate	11	98.00	X
1set	Rear bootlid inner trim clips	11	60.00	X
1set	Rear bumper clips	11	60.00	40
1set	Rear end panel top garnish clips	11	60.00	X
TOTAL PARTS			8400.80	

VEHICLE NO. SJT 8490S TOYOTA ALTIS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components.	1400.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1000.00	800
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	150.00	20
4	To remove rear fittings, garnish, trimmings etc so as to facilitate repairs at rear	200.00	80
5	To remove and replace reverse sensors and check for proper function	100.00	50
6	To remove and replace reverse camera and check for proper function	120.00	X
7	To provide anti-rust treatment on affected areas	210.00	30
	Labour Total :	3180.00	
	TOTAL (PARTS & LABOUR):	11580.80	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts



9-2008.20
 1004.1
 502
 9-1004.10
 S.V-290.00
 L-1580.00
 2874.11