

DELGRO ENGINEERING PTE LTD

ESTIMATE*

FILE NO : SH 7805G

DA

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Typ
	Rear Bumper <i>de</i> ✓	
	Rear Bumper Clip 10 pcs <i>nee</i> ✓	
	Rear Bumper Bracket <i>x n n</i> ✓	
	Rear Bumper Under Cover <i>x f</i> ✓	
SUB TOTAL		
LESS 20%		
DISCOUNTED TOTAL		

Rear Bumper Reverse Sensor *hw* ✓
 Rear Bumper Advertisement Logo *nd* ✓
 Rear Bumper Rubber Mat *mac* ✓
 Rear Fender Advertisement Logo (LH/RH) *nee* ✓

Labour Charge

Panel Beating
 Spray Painting Charge
 Wiring Charge
 Remove/Refix Reverse Sensor

TOTAL LABOUR

ESTIMATE TOTAL

Taufik 97495749
WP 27/12/12 @ 320pm
humpun
Resurvey after repair
02 days
taufik @ Mountview

4528/300

0 • C

553 • +

22 • =

575 • *

575 • x

80 • %

460 • *

20

0 • C

135 • 7 +

50 • +

50 • +

200 • +

=

435 • 7 *

0 • C

~~2,800 • +~~

~~0 • C~~

280 • +

200 • +

30 • +

30 • =

540 • *

0 • C

460 • +

435 • 7 +

540 • =

1,435 • 7 *

103 • 5 +

228 • =

331 • 5 *

331 • 5 x

80 • %

265 • 2 *

0 • C

1,435 • 7 +

265 • 2 =

1,700 • 9 *

1,700 • 9 x

80 • %

1,360 • 72 *

t

.00

.00

.20

3.00

4.20

4.84

9.36

35.70

50.00

50.00

200.00

435.70

350.00

250.00

50.00

80.00

730.00

1,865.06

ce notify

g:

ainting

ing resurvey

imation

out Prejudice" basis

wed

resurveyed and

Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.