

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24337

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1525/2019/NS
Date : 27-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : SDY 123 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Heo Jaehyeok
Address : 37 Amber Road
#10-20
Singapore 439946
Telephone : (HP)+65 82255157
Type of Claim : Third Party Claims
Policy No. : 1900141829
Vehicle No : **SMN 2767 E**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : Jul-19
Engine No : CVK 079367
Chassis No : WAUZZZF48KN011309
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Dec-19
Place of Accident : Nanson Road Outside Of the Quayside Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMN 2767 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed. <i>500 x 1.5</i>	\$ 1,400.00 <i>750</i>	
3	To respray front bumper and bonnet. <i>550</i>	\$ 2,000.00 <i>500</i>	
4	To carry out diagnostic checks.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 4,072.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 2767 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER X R	\$	1,999.00
2	FRONT BUMPER FIXING PARTS X	\$	531.00
3	FRONT BUMPER SECURING STRIP ?	\$	32.00
4	FRONT BUMPER GRILLE - CENTRE X	\$	178.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	\$	191.00
6	FRONT BUMPER AIR GUIDE - RH X	\$	56.00
7	RADIATOR GRILLE / CRA	\$	1,227.00
8	FRONT BUMPER AIR GUIDE GRILLE - RH X	\$	123.00
9	FRONT BUMPER FOAM FILLER PIECE X	\$	113.00
10	FRONT BUMPER CARRIER X	\$	733.00
11	FRONT BUMPER COVER X	\$	116.00
12	FRONT BUMPER GUIDE SECTION - RH X	\$	34.00
13	CAUTION SIGN STICKER X	NEC \$	13.00
14	AIRCON STICKER X	NEC \$	7.00
15	LOCK CARRIER BRACKET X	\$	125.00
16	FRONT BUMPER SUPPORT - LH / RH X	2 \$	52.00
17	HORN - RH LOW TONE X	\$	262.00
18	SPRING SHACKLE - RH X	\$	26.00
19	FRONT PARKING AID SENSOR - INNER / OUTER X	2 \$	462.00
20	FRONT PARKING AID SEAL RING / MK	4 \$	12.00
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,292.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 2767 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	LED HEADLIGHT - RH ✓ (phish replace)	\$ 7,087.00	
22	LIFT CYLINDER - RH X	\$ 192.00	
23	RADIATOR OUTER DUCT - RH X	\$ 25.00	
24	RADIATOR INNER DUCT - RH X	\$ 11.00	
25	RADIATOR AIR GUIDE - UPPER X	\$ 15.00	
26	RADIATOR AIR GUIDE - LOWER X	\$ 19.00	
27	FRONT NO PLATE ✓ (N)	S/N \$ 40.00	
28	SUNDRIES ?	\$ 300.00	

TOTAL SPARE PARTS CHARGES	:	\$ 13,981.00
TOTAL LABOUR CHARGES	:	\$ 4,072.00
GRAND TOTAL	:	\$ 18,053.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Star (LKK)
Surveyed Date :
Authorised Date : WKL ML
Excess Cost : 13/1/10, 11.990k
Liability :
Remarks : PIP
My BoL sy
3 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: