

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8949 E

1 pc	Front o/s head lamp <i>cut</i>	\$	1,028.00
1 pc	Bonnet grille <i>crq</i>	\$	385.00
1 pc	Front bumper <i>crq</i>	\$	531.00
1 pc	Front bumper emblem <i>hec</i>	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00 <i>xnn</i>	\$	32.00
1 pc	Front bumper o/s upper bracket <i>xnn</i>	\$	16.00
1 pc	Front bumper o/s support bracket <i>xnn</i>	\$	16.00
1 pc	Front bumper o/s protector <i>scr</i>	\$	51.00
1 pc	Front bumper o/s fog lamp cover <i>xnn</i>	\$	66.00
1 pc	Front bumper centre grille <i>?</i>	\$	174.00
1 pc	Front bumper lower stiffer <i>xnn</i>	\$	134.00
1 pc	Front bumper lip <i>xnn</i>	\$	52.00
1 pc	Front bumper reinforcement <i>?</i>	\$	328.00
1 pc	Front bumper inner sponge <i>?</i>	\$	110.00
1 pc	Front o/s wheel cover <i>scr</i>	\$	116.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

Acknowledged by Repairer
Signature:
Date:

\$ 3,083.00
\$ 308.30
\$ 2,774.70

S/NETT

1 pc	Front bumper clips <i>hec</i>	\$	48.00
1 pc	Front o/s fender sticker <i>hec</i> <i>xnn</i>	\$	60.00
1 set	Front o/s fender inner shield clips <i>xnn</i>	\$	20.00
1 pc	Front no. plate <i>Bt</i>	\$	50.00

To adjust/focus front o/s head lamp

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel, etc.

To putty and spray painting on front bumper, front o/s fender, Bonnet grille

To apply rustproofing on the repaired and replaced panels.

\$ 30.00
\$ 600.00 *\$360*
\$ 600.00 *\$360*
\$ 60.00 *\$50*
\$ 4,242.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Rqm (LKK)
26/12/19 1645hrs
Parasuram@lkkauto.com
8862778hp
3 refitting days
LIS
Aft
Refit
photo