

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

26-Dec-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8949 E

|       |                                                           |    |          |
|-------|-----------------------------------------------------------|----|----------|
| 1 pc  | Front o/s head lamp <i>cut</i>                            | \$ | 1,028.00 |
| 1 pc  | Bonnet grille <i>org</i>                                  | \$ | 385.00   |
| 1 pc  | Front bumper <i>org</i>                                   | \$ | 531.00   |
| 1 pc  | Front bumper emblem <i>new</i>                            | \$ | 44.00    |
| 2 pcs | Front bumper n/s & o/s side retainer @ \$16.00 <i>xnn</i> | \$ | 32.00    |
| 1 pc  | Front bumper o/s upper bracket <i>xnn</i>                 | \$ | 16.00    |
| 1 pc  | Front bumper o/s support bracket <i>xnn</i>               | \$ | 16.00    |
| 1 pc  | Front bumper o/s protector <i>scr</i>                     | \$ | 51.00    |
| 1 pc  | Front bumper o/s fog lamp cover <i>xnn</i>                | \$ | 66.00    |
| 1 pc  | Front bumper centre grille <i>cut</i>                     | \$ | 174.00   |
| 1 pc  | Front bumper lower stiffer <i>xnn</i>                     | \$ | 134.00   |
| 1 pc  | Front bumper lip <i>xnn</i>                               | \$ | 52.00    |
| 1 pc  | Front bumper reinforcement <i>1200</i>                    | \$ | 328.00   |
| 1 pc  | Front bumper inner sponge <i>88r</i>                      | \$ | 110.00   |
| 1 pc  | Front o/s wheel cover <i>scr</i>                          | \$ | 116.00   |
|       |                                                           | \$ | 3,083.00 |
|       |                                                           | \$ | 308.30   |
|       |                                                           | \$ | 2,774.70 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*TO: a.sur*  
*L/S: \$2650/-*  
*3 repair days*

### S/NETT

|       |                                                |    |       |
|-------|------------------------------------------------|----|-------|
| 1 pc  | Front bumper clips <i>new</i>                  | \$ | 48.00 |
| 1 pc  | Front o/s fender sticker <i>xnn</i>            | \$ | 60.00 |
| 1 set | Front o/s fender inner shield clips <i>xnn</i> | \$ | 20.00 |
| 1 pc  | Front no. plate <i>bt</i>                      | \$ | 50.00 |

To adjust/focus front o/s head lamp

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel, etc.

To putty and spray painting on front bumper, front o/s fender, Bonnet grille

To apply rustproofing on the repaired and replaced panels.

|    |          |
|----|----------|
| \$ | 30.00    |
| \$ | 600.00   |
| \$ | 600.00   |
| \$ | 60.00    |
| \$ | 4,242.70 |

*RQM (LKK)*  
*26/12/19 1645hrs*  
*88622778ph*  
*3 repair days*  
*L/S*  
*AFI*  
*REPAIR*  
*photo*

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.