

ASS. REC. BY:

REF:

CS12219022254/Ed302

Special Instructions:

Service: Steve

Munich

ASSIGNMENT (Office)

From (Person): Meenachi

of

III

Date/Time: 22/12/19 @ 9:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 7232C

Insured:

at Workshop in/s

Performance LODGE

Tel:

9116 5200 6383 7362

of

303 Alexandra Road BRADDELL

Policy No:

018MPC0001876-01

Claim No:

Sum Insured:

Excess:

75A 600

Make of Veh:

(Client's Record)

D.O.A. 23/12/19

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Mr. Chua

Vehicle IN/OUT

Date/Time

Action/Instruction

Taking /

SKM 7232C: NAUT19022254/CS 2012/12/19

30/12/19 @ 9:38am VEH sent to Meena via Meenachi.

30/12/19 The vehicle tow out from pml to LODGE BraddeLL for repair.

31/12/19 @ 10:28am Calligraphy informed C/A at US \$13K & Ex: \$600 by email.

31/12/19 @ 10:49am informed Andrew C/A not more than \$13K & Ex: \$600.

ASSIGNMENT

From:

Date:

27/12/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKM 7232C

at Workshop m/s

Performance

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

Mr. Chua

car in

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKM 7232C

Yr Regn:

31/3/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 316

c.c.

1598

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

91184

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAJA 160 90N SK195

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/12/19

D.O.I.

27/12/19

Survey held at

Performance Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV- 67,000

PV- 53,656

NV- 13,344

RECEIVED 06 FEB 2020

06/02/20 @ 10.50am conferred with Andrew final fig @ 12180.44, 8 days.
(Lrd @ 9092.91, 43%)
no lump sum.

Date/Time, File Pass to?



Prel. Report

06/2/2020



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Report Format:

MER-00


Lump Sum / LBJ: \$

12180.44

450

11

461



Nivitha (LKK Auto)

From: C Meenachi - III <Meenachi@iii.com.sg>
Sent: Friday, 27 December 2019 9:17 AM
To: Admin-D (LKK Auto) (admin-d@lkkauto.com)
Cc: 'SUR'; Lalitha Krishnan - III; Motor Claim - III; Stanley Lai; Gabriel Wee
Subject: SKM7232C - Own claim recovery
Attachments: SKM_558e19122409230.pdf

VERY URGENT

Dear Sirs,

Kindly arrange for an OD survey urgently today.

Please revert urgently.

Meena
Motor & Work Injury Claim Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6073 Fax: 6224 4174

-----Original Message-----

From: Chua Kee Sin [mailto:chua.kee.sin@simedarby.com.sg]
Sent: Tuesday, 24 December, 2019 10:34 AM
To: C Meenachi - III <Meenachi@iii.com.sg>; Lalitha Krishnan - III <lalitha@iii.com.sg>
Cc: Cresendo Llorca Lagman <cresendo.lagman@simedarby.com.sg>
Subject: SKM7232C - Own claim recovery

Dear India Insurance officer,

Kindly refer to the attachment accident report for your arrange surveyor for the own claim recovery.

Car plate no SKM7232C - Vehicle tow in

Thank you

Regards,
Chua Kee Sin
Senior Customer Service Advisor | Body and Paint Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 9116 5200 | Fax (+65) 6479 4601 chua.kee.sin@simedarby.com.sg

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the

Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Shiau Chan (LKKAuto)

From: Andrew Cornelius Goh Cheng Chuan <AndrewCorneliusGoh@sparkcarcare.com>
Sent: Thursday, 6 February 2020 10:56 AM
To: Shiau Chan (LKKAuto)
Cc: Ngo Toh Wee; William Wang Kiat Seng; Denis Teo Chin Chye; Patrick Chung Chan Kim
Subject: Re: SKM7232C BMW 316i

Dear Shiau Chan

Amount confirm.

Best Regards

Andrew C. Goh
External Business | ComfortDelGro Engineering Pte Ltd
T (65) 6383 7362 | F (65) 6281 5767
www.SPARKcarcare.com



Think Before Printing

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 5 February 2020 5:38 PM
To: Andrew Cornelius Goh Cheng Chuan <AndrewCorneliusGoh@sparkcarcare.com>
Cc: Ngo Toh Wee <Ngotw@sparkcarcare.com>; William Wang Kiat Seng <WilliamWangKS@sparkcarcare.com>; Denis Teo Chin Chye <denisteo@sparkcarcare.com>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>
Subject: RE: SKM7232C BMW 316i

Dear Andrew,

WITHOUT PREJUDICE

Offer final fig \$12,180.44 before excess \$600.00 & GST and 8 repair days.

Kindly check and confirm.

„Wishing you a Happy and Prosperous Lunar New Year“

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 23 January 2020 11:14 AM
To: Andrew Cornelius Goh Cheng Chuan <AndrewCorneliusGoh@sparkcarcare.com>

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 31 December 2019 10:49 AM
To: CDGE Braddell Private Cars Crash Repair Operation
Cc: Denis Teo Chin Chye; Patrick Chung Chan Kim
Subject: RE: SKM 7232C BMW 316i

Dear Andrew,

As instructed by our client, please proceed to repair the insured vehicle **SKM 7232C** at repair cost not more than Lump Sum **\$13,000.00 (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Wishes for Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Sent: Tuesday, 31 December 2019 9:40 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Denis Teo Chin Chye <denisteo@sparkcarcare.com>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>; CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Subject: Re: SKM 7232C BMW 316i

Dear Shiau Chan

Estimate forward for your reference.

Please advice on the authorization to repair.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	27 Dec 2019 12:52	Cim Dtl Modified	Insured Name: -> -.	[A] Nivitha Govindasamy
2	27 Dec 2019 12:52	Cim Veh Model Changed	(205082) BMW 316I 1.6 AT D/AB 4DR ABS HID (A).	[A] Nivitha Govindasamy
3	27 Dec 2019 12:52	Cim Created	Reg No: SKM7232C, Policy No: D18MPC0001876, Acct Date: 2019/12/23, Claim Type: OD, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Performance Motors Limited (Alexandra)	[A] Nivitha Govindasamy
4	27 Dec 2019 12:52	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
5	27 Dec 2019 12:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/01/08	[A] Nivitha Govindasamy
6	27 Dec 2019 12:52	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
7	27 Dec 2019 12:53	Adj Adjuster Assigned	[None] -> CHEN TSUE YEE	[A] Nivitha Govindasamy
8	27 Dec 2019 13:16	Cim Dtl Modified	Insured Name: - -> CHIU LOO TONG, Insured ID: -> S1121470C.	[A] DENISE TAY KWEE CHENG
9	27 Dec 2019 13:32	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
10	27 Dec 2019 13:32	Cim Dtl Modified	Claim Conclusion: -> 3.	[A] DENISE TAY KWEE CHENG
11	27 Dec 2019 13:32	Cim Dtl Modified	JPJ Reg. Date: -> 2014/03/31.	[A] DENISE TAY KWEE CHENG
12	27 Dec 2019 13:32	Cim Details Notified		[A] DENISE TAY KWEE CHENG
13	30 Dec 2019 09:31	Claim Offer Type Changed	Offer Type: Cost of Repairs->Total Loss, Total Loss Type: N/A->BER	[A] SHIAU CHAN
14	30 Dec 2019 09:38	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/01/08	[A] SHIAU CHAN
15	30 Dec 2019 09:38	Adj Mandate Request	Cur.Reg:0.00:DAMAGES CONSISTENT, REPAIR COST NOT ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	31 Dec 2019 09:53	Cim Registration Modified	Excess: -> 600.00.	[I] Lalitha Krishnan
17	31 Dec 2019 09:54	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/01/08, Mandate Remarks: Please note that the vehicle is now at CDGE and CDGE have agreed to repair vehicle based on ERV as given by you. You may authorise repairs	[I] Lalitha Krishnan
18	31 Dec 2019 09:54	Adj Mandate Set	Approved:13000.00:Please note that the vehicle is now at CDGE and CDGE have agreed to repair vehicle based on ERV as given by you. You may authorise repairs	[I] Lalitha Krishnan

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2388915	27 Dec 2019 13:32:49	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKM7232C		11.77

Shiau Chan (LKKAuto)

From: Lalitha Krishnan - III <lalitha@iii.com.sg>
Sent: Tuesday, 31 December 2019 10:28 AM
To: Denis Teo Chin Chye
Cc: Mekavathanan Sarangapani; Admin-D (LKKAuto)
Subject: SKM7232C Excess \$600 for insured and Named drivers

Dear Denis

We refer to the above vehicle.

We have approve repairs at sum of \$13,000 lump sum. Kindly note that there is a policy excess of \$600.

Best Regards

LalithaKrishnan

Motor and Work Injury Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6139 Fax: 6224 4174



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Shiau Chan (LKKAUTO)

From: Chua Kee Sin <chua.kee.sin@simedarby.com.sg>
Sent: Monday, 30 December 2019 9:21 AM
To: Denise Tay (LKKAUTO)
Cc: SUR; Teng Wai Khan; Cresendo Llorca Lagman
Subject: RE: SKM 7232C / OD / III

Dear Denise,

Please do keep you informed we cannot accept the offer cost.

Thank you

Regards,

Chua Kee Sin

Senior Customer Service Advisor | Body and Paint
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Hp (+65) 9116 5200 | Fax (+65) 6479 4601
chua.kee.sin@simedarby.com.sg



ACCELERATE YOUR JOY THIS CHRISTMAS

Follow us on Facebook for more updates.

Find out more

<http://www.pml.com.sg/catatestdrive/>



Please consider the environment before printing this e-mail.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, December 27, 2019 2:42 PM
To: Chua Kee Sin <chua.kee.sin@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SKM 7232C / OD / III

[External Mail] This email originated from outside of the organisation; be careful with requests, attachments and links.

Dear Chua,

The economical repair limit is at \$13,000/-(subjected to insurance's approval), Please check if able to repair within the amount.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 27 Dec 2019

Preliminary Advice

Vehicle No	: SKM7232C	Accident Date	: 23/12/2019
Make	: BMW 316I	Policy No.	: D18MPC0001876
Assignment Date	: 27/12/2019	Excess	: S\$0.00
Date of Inspection	: 27/12/2019	Est. Duration of Repair	: 6.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front LH portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,720.35
Revised Amount	:S\$	15,027.05
Check Items (Estimated)	:S\$	12,849.35
Total	:S\$	27,876.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	53,656.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,344.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 27 Dec 2019

Preliminary Advice

Vehicle No	: SKM7232C	Accident Date	: 23/12/2019
Make	: BMW 316I	Policy No.	: D18MPC0001876
Assignment Date	: 27/12/2019	Excess	: S\$0.00
Date of Inspection	: 27/12/2019	Est. Duration of Repair	: 6.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front LH portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,720.35
Revised Amount	:S\$	15,027.05
Check Items (Estimated)	:S\$	12,849.35
Total	:S\$	27,876.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	53,656.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,344.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note the margin for repair is at \$13,344/-

Celine 27/12/19.

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 27 Dec 2019

Preliminary Advice

Vehicle No	: SKM7232C	Accident Date	: 23/12/2019
Make	: BMW 316I	Policy No.	: D18MPC0001876
Assignment Date	: 27/12/2019	Excess	: S\$0.00
Date of Inspection	: 27/12/2019	Est. Duration of Repair	: 6.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front LH portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,720.35
Revised Amount	:S\$	15,027.05
Check Items (Estimated)	:S\$	10,457.60
Total	:S\$	25,484.65
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	53,656.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,344.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note the the margin for repair is at \$13,344/-

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 470C

Vehicle Details

Vehicle No.: 90M7222C

Vehicle code:
Exempted: NoIntended
Deregistration Date: 28 Dec 2019

Vehicle Make: BMW

Vehicle Model: 316i 1.8 AT D/48
4DR ABS 16D

Primary Colour: Black

Manufacturing Year: 2013

Engine No.: B30A1J576N13B16A

Chassis No.: WBA3A10090N526105

Maximum Power
Output: 100.0 kW (134 hp)

Open Market Value: \$36,219.00

Original Registration
Date: 31 Mar 2014First Registration
Date: 31 Mar 2014

Transfer Count: 1

Actual ARF Paid: \$32,757.00

Intended PARF Rebate Details

PARF Eligible: Yes

PARF Eligibility
Expiry Date: 30 Mar 2024PARF Rebate
Amount: \$22,894.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2024

COE Category: A - Car (1600cc &
below)

COE Period (Years): 10

OP Paid: \$72,290.00

COE Rebate Amount: \$30,762.00

Total Rebate
Amount: \$53,654.00The information contained herein is correct as at 27
Dec 2019

OK

Please do not use your browser's Back or Forward
buttons as this may result in information loss.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 470C

Vehicle Details

Vehicle No.: SKM7232C
Vehicle to be Exported: No
Intended Deregistration Date: 27 Dec 2019
Vehicle Make: B.M.W.
Vehicle Model: 316I 1.6 AT D/AB 4DR ABS HID
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: B304J576N13B16A
Chassis No.: WBA3A16090NS36105
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$36,219.00
Original Registration Date: 31 Mar 2014
First Registration Date: 31 Mar 2014
Transfer Count: 1
Actual ARF Paid: \$32,707.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Mar 2024
PARF Rebate Amount: \$22,894.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2024
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$72,290.00
COE Rebate Amount: \$30,781.00
Total Rebate Amount: \$53,675.00

The information contained herein is correct as at 27 Dec 2019

OK



PROFESSOR, EMERITUS

Stand out with a hidden car plate number



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2019 09:58
Date Of Accident	23/12/2019 18:05
Exact Location Of Accident	JUNCTION OF HIGH STREET AND NORTH BRIDGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM7232C
Insured/Policyholder	
Name Of Registered Owner	CHIU LOO TONG
NRIC No	SXXXX470C
Email Address	LOOTONGCHIU@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96674367
Alternative Phone No	OTHERS-96300345

Vehicle Particulars

Manufacturer	BMW
Model	316i
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MPC0001876-01
Cover Note Number	

Driver

Name of Driver	CHIU LOO TONG
NRIC No	SXXXX470C
Date Of Birth	19/05/1955
Occupation	INDOOR
Date Of Driving Pass	30/11/1972
Driving Experience	47 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96674367
Fax Number	
Contact Number	OTHERS-96300345
Email Address	LOOTONGCHIU@GMAIL.COM

Address	5 TAMAN WARNA #04-16
Postcode	276342
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TJIOE MIOUW HOEN GENDER: : FEMALE
Passenger 2	NAME: : CHIU ROUJIA TRICIA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4629999 - FAX NO: 64628933
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MISS NORIZAN
Phone Number	97406112
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV9530T
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS 1.6

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	KOH CHIEW LIAN
NRIC/Passport Number	
Contact Number	96311066
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: Dec 24, 2019
9:20 am

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO POLICE REPORT ATTACHED
ADDITIONAL COMMENTS:

The driver of vehicle STV 93307 irresponsibly & blatantly drove through a red light & crashed into my vehicle.

As the junction is monitored by many street cameras (outside of the Supreme Court), the footage will clearly indicate that STV 93307 was in gross violation of traffic rules & regulations!

The independent witness ~~is~~^{is} a pedestrian who was about to cross the ~~road~~^{road} when the green man came on but stepped back when she ~~and~~^{and} other pedestrians saw a speeding car ~~coming~~^{coming} at them as it shot past the red light.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: DEC 24, 2019
 9:20 am

Driver's Signature

(If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature

Name:
 NRIC/FIN No.:

24/12/2019
 93307



**SINGAPORE
POLICE FORCE**



T/20191223/2164

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

1 of 4

Report No. T/20191223/2164

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/12/2019 21:17		Vide Report No.: A/20191223/0111		Station Diary No.: 69	
Informant's Particulars					
Name of Informant: CHIU LOO TONG			Address: 5 TAMAN WARNA #04-16 SINGAPORE 276342		
ID Type / ID No.: NRIC NO / S1121470C			Contact No.: Home/Office: Mobile: 96674367		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 19/05/1955	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SELF-EMPLOYED			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/12/2019 18:05	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 HIGH STREET NORTH BRIDGE ROAD Junction of High Street and North Bridge Road				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJV9530T	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Seriously Damaged	0
SKM7232C	Car	BMW	316I 1.6 AT D/AB 4DR ABS HID	Black	Seriously Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20191223/2164

2 of 4

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20191223/2164

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKM7232C	INDIA INTERNATIONAL INSURANCE PTE LTD	D18MPC0001876_01	01/10/2019	30/09/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	KOH CHIEW LIAN		ID No.	-
Related Vehicle	SJV9530T (Car)		Contact No.	96311066
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	CHIU LOO TONG		ID No.	S1121470C
Related Vehicle	SKM7232C (Car)		Contact No.	96674367
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On the 23/12/2019 at 1805hrs, I was travelling along High Street when I got into a traffic accident at the junction of North Bridge Road.

I was travelling on the extreme right of the 3 lane road of High Street. My vehicle (SKM7232C) came to a stop when the traffic light at the junction of North Bridge Road turned red. As the light change to green, I proceeded forward across the junction. Suddenly, a vehicle (SVJ9530T) came from my left and to avoid him, I swerved right. The vehicle (SVJ9530T) hit my vehicle (SKM7232C) and crashed into a bollard near the traffic light.

The front of the other vehicle (SVJ9530T) crashed into the front left side of my vehicle. It looks like the damages to my vehicle is a huge dent at the front left tire area, collapsed car suspension and broken hydraulic pipes.

The other driver was smoking when the incident happened and I am not sure if he was drink driving. He



**SINGAPORE
POLICE FORCE**



T/20191223/2164

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

3 of 4

Report No. T/20191223/2164

CONTINUATION OF REPORT

immediately apologized to us when he got off the car.

I was travelling with my daughter and my wife. We will be visiting the doctor as soon as we feel any pain.

I am lodging this report for insurance claims and for record purposes.



**SINGAPORE
POLICE FORCE**



T/20191223/2164

4 of 4

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20191223/2164

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 KIANG KOK SUAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

23/12/2019 21:17

Officer In Charge Of Case:

TP / GIT /

Sgt 2 PHUA TIAK YEE

Contact No.: 65472077

Classification Of Case:

SN 170

Authentication Stamp

NP168



SIGNATURE

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1980 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

CERTIFICATE NO.: D18MPC0001876_01		COVER: COMPREHENSIVE
1. Index Mark and Registration Number of Vehicle	: SKM7232C	
Chassis No	: WBA3A16090NS36105	
2. Name of Policyholder	: CHIU LOO TONG	
3. Effective date of Insurance	: 01 Oct 2019	
4. Expiry date of Insurance	: 30 Sep 2020	
5. Persons or Classes of Persons entitled to drive*		
<p>(a) The Policyholder The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.</p> <p>(b) Any other person who is driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle</p>		
6. Limitations as to use*		
Use only for social, domestic and pleasure purposes and for the Policyholder's business.		
The Policy does not cover		
<p>a) Use for hire or reward.</p> <p>b) Use for racing, pace-making, reliability trial, speed-testing.</p> <p>c) Use for the carriage of goods other than samples in connection with any trade or business.</p> <p>d) Use for any purpose in connection with the Motor Trade.</p>		
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		
Insured & Named Drivers Excess Sect I : SGD600.00		
Unnamed Drivers Excess Sect I : SGD1,100.00		
Windscreen Excess : SGD100.00		
Hire Purchase Company : United Overseas Bank Limited		
FOR DRIVERS BELOW 21 YEARS OR ABOVE 65 YEARS OF AGE &/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, ADDITIONAL EXCESS OF \$2500/- ON SECTION I WILL BE APPLICABLE.		
I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).		
Agent/Broker : B000018/COMFORTDELGRO INSURANCE BROKERS PTE LTD		For India International Insurance Pte Ltd
Date of Issue : 16/09/2019 15:07:48		
MX1-Private Car (Insured Driving)		
		 Authorised Signatory

Performance Motors Limited

A Siam Darby Motors Company
 Co. Reg. No. 1974015394 GST Reg. No. M2-0020081-X
 Toll-Free Number (1800-2255394)

307, Alexandra Road
 Siam Darby Performance Centre
 Singapore 159941
 Fax: 64747772

280, Kampong Kiang Road
 East Coast Centre
 Singapore 438188
 Fax: 63449772

113, Alexandra Road
 Siam Darby Business Centre
 Singapore 159941
 Fax: 64746611 (AfterSales)
 64746612 (Business)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53891
 Date Estimated : 24/12/2019
 Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Chiu Loo Tong
 7 Brookvale Dr
 #03-04

Singapore 599971

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
 64 Cecil Street
 #04-05 IOB Building
 Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

DESCRIPTION

VALUE

Replace front support front left side fender, bonnet, front bumper include remove attachment etc and repair on accident damage area	150X3	2550	5,950.00
Spray painting front bumper, bonnet and both front side fender		2898.90	4,106.00
To tow accident vehicle to PML workshop.			195.00
To carry out body cavity preservation (2 panel).		200	236.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)		451	531.00
To remove and install front suspension for inspection and replace damaged parts.		1128	2,655.00
To replace tyre and wheel rim including balancing (1x) left front		80	94.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system according to BMW specification	451	?	531.00
To remove and install radiator assembly, fan housing with fan including to conduct pressure test, bleed cooling system and check for leak. (For all models except 7 series).	572	?	673.00
To remove and install air con condenser and piping including vacuum system, top up freon gas and checks for leak. (For all models except for 7 series).	691	?	814.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150	177.00
To replace left headlight.		408	481.00

Performance Motors Limited

A Siam Daily Vehicle Company
 201, Keng Kong Road
 Singapore 119441
 Tel: 64784111 Fax: 64784112

201, Keng Kong Road
 Siam Daily Performance Centre
 Singapore 119441
 Tel: 64784111 Fax: 64784112

180, Keng Kong Road
 Siam Daily Performance Centre
 Singapore 119441
 Tel: 64784111 Fax: 64784112

111, Keng Kong Road
 Siam Daily Performance Centre
 Singapore 119441
 Tel: 64784111 Fax: 64784112



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53891
 Date Estimated : 24/12/2019
 Prepared By : Chua Kee Sin

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	3161A/4	0

DESCRIPTION

Sundries.

Pirelli 225/50 17 094W CP7* r.f (1 PC) (70%)
 left front

VALUE

150.00

373.75

Total Labour 1:

16,966.75

DESCRIPTION

RADIATOR MODULE MOUNT LH / mis
 CHARGE AIR COOLER
 HEX SCREW WITH COLLAR M12X1.5X85 ?
 LH WISHBONE
 COLLAR NUT M12X1.5X45
 SPHERICAL COLLAR SCREW M12X1.25X45 ?
 WHEEL HUB WITH BEARING FRT ?
 FRT LH CARRIER
 FRT SWING SUPPORT ?
 STABILIZER FRT WITH RUBBER MOUNTING ?
 FRT SPRING STRUT
 FRONT COIL SPRING ?
 ADDITIONAL SHOCK ABSORBER FRT ?
 LH TIE ROD / BT
 RH TIE ROD X
 REPAIR KIT BELLOWS (TKP) ?
 EXCH STEERING BOX ELECTR. (TKP) ?
 COMBINATION NUT M14X1.5
 HEX NUT WITH FLANGE
 ALLOY RIM 7.5JX17 STAR SPK 393 / CRT
 HUB CAP WITH CHROME EDGE (BMW) X
 BONNET / DD
 FRT LH SIDE PANEL / DD
 FRT RH TOP SUPPORT SIDE PANEL ?
 FRONT SHOCK ABSORBER ?
 FRT BUMPER TOP MOUNT
 INSERT AIR INTAKE CENTER ?
 FRT LH DEFORMATION ELEMENT ?
 FRT LH LOWER DEFORMATION ELEMENT ?
 LH SUPPORT FOGLAMP
 FINISHER ROD CENTER (SPORT) ?
 FRT RH BOTTOM MOUNTING SIDE PANEL ?
 FRT BUMPER PANEL TRIM (LINES SRA) / BR
 SUPPORT CENTRAL
 MOUNT FOR SUPPORT
 CLOSED GRID LH (LINES SPORT) ?
 CLOSED GRID LH (LINES SPORT) ?
 FRT LH GRILLE (SPORT) / BR

QTY PRICE

1 78.00

1 662.90

1 8.05

1 271.15

8 7.65

4 8.05

1 484.55

1 463.45

2 99.60

1 390.10

1 496.65

1 230.30

1 41.65

1 296.65

1 296.65

2 165.20

1 3,648.60

1 5.80

1 2.50

1 840.00

1 28.95

1 1,281.20

1 702.65

1 20.10

1 54.55

1 380.00

1 125.70

1 102.30

1 86.85

1 42.05

1 42.90

1 20.10

1 1,037.05

1 11.40

1 7.05

1 90.50

1 90.50

1 128.60

VALUE

78.00

662.90

8.05

271.15

61.20

32.20

484.55

463.45

199.20

390.10

496.65

230.30

41.65

296.65

296.65

330.40

3,648.60

5.80

2.50

840.00

28.95

1,281.20

702.65

20.10

54.55

380.00

125.70

102.30

86.85

42.05

42.90

20.10

1,037.05

11.40

7.05

90.50

90.50

128.60

Performance Motors Limited

A Siam City Motors Company
 Ch. Reg. No. 947611494 QTC Reg. No. 947611494
 Toll-Free Number: 1200-225529

109, Alexandra Road
 Siam City Performance Centre
 Singapore 119941
 Fax: 64767770

245, Kanyang Road
 East Coast Centre
 Singapore 416281
 Fax: 64447771

109, Alexandra Road
 Siam City Performance Centre
 Singapore 119941
 Fax: 64767770 (Afterhours)
 64764224 (Emergency)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53891
 Date Estimated : 24/12/2019
 Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
LICENCE PLATE BASE (ECE) X	1	69.60	69.60
INSCRIPTION SIDE (SPORT LINE) ?	1	46.55	46.55
GROMMET / MC	2	0.80	1.60
GAS STRUT HOOD X	2	118.70	237.40
STOP BUFFER - bonnet X	2	14.55	29.10
FRONT PANEL V-STRUT X	1	112.75	112.75
LH SUPPORT	1	132.15	132.15
LH HEADLIGHT BRACKET / M1	1	10.40	10.40
FRONT CROSSLINK	1	169.10	169.10
LH COVER BOTTOM	1	117.15	117.15
AIR DUCT RADIATOR	1	105.35	105.35
AIR DUCT BOTTOM	1	105.35	105.35
ADJUSTER	1	6.35	6.35
LH ENGINE HOOD SEALING	1	39.05	39.05
RH ENGINE HOOD SEALING X	1	39.05	39.05
PLAQUE 82MM / MC	1	71.60	71.60
LH HEADLIGHT (XENON) / DR	1	2,130.35	2,130.35
LH FOG LIGHT	1	300.25	300.25
CONDENSER AIR CONDITIONING	1	1,033.60	1,033.60
ULTRASONIC SENSOR BLACK / M1	1	238.05	238.05
ULTRASONIC SENSOR BLACK X	4	238.05	952.20

Total Parts : 19,753.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 27/12/19, 12:15 pm Excess \$5
 Surveyor's Name STEVE (LKK) Sign _____
 Surveyor's Tel _____ Authorised Yes / No _____
 Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

LKK Auto Consultancy notice
 the Repairer of the following:
 • To resurvey before starting painting
 • To display damaged parts during resurvey
 • To provide evidence to code of ethics
 • This party is not a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary items must be resurveyed and
 is subject to final approval from Insurance Company.

Acknowledged by Repairer

Labour 1	:	16,966.75
Parts	:	19,753.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,570.42
Grand Total	:	39,290.77

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53891
Date Estimated : 24/12/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Chiu Loo Tong
7 Brookvale Dr
#03-04

Singapore 599971

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

DESCRIPTION

VALUE

Replace front support front left side fender, bonnet, front
bumper include remove attachment etc and repair on accident
damage area

2550 5,950.00

Spray painting front bumper, bonnet and both front side
fender

2898.90 4,106.00

To tow accident vehicle to PML workshop.

195.00

To carry out body cavity preservation.
(2 panel).

200 236.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1X)

451 531.00

To remove and install front suspension for inspection and
replace damaged parts.

1128 2,655.00

To replace tyre and wheel rim including balancing. (1x).
left front

80 94.00

To conduct chassis alignment measuring check using
Car-O-Liner measuring system according to BMW specification

451 531.00

To remove and install radiator assembly, fan housing with fan
including to conduct pressure test, bleed cooling system and
check for leak. (For all models except 7 series).

7 673.00

To remove and install air con condenser and piping including
vacuum system, top up freon gas and checks for leak.
(For all models except for 7 series).

691 814.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

To replace left headlight.

498 481.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Sempang Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



revised purpose

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53891
Date Estimated : 24/12/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

DESCRIPTION

VALUE

Sundries

150.00

Pirelli 225/50 17 094W CP7* r-f (1 PC) (70%)
left front

373.75

Total Labour 1: 16,966.75

DESCRIPTION

QTY

PRIC

VALUE

RADIATOR MODULE MOUNT LH / mis	1	78.00	78.00
CHARGE AIR COOLER	1	662.90	662.90
HEX SCREW WITH COLLAR M12X1.5X85	1	8.05	8.05
LH WISHBONE	1	271.15	271.15
COLLAR NUT M12X1.5X45	8	7.65	61.20
SPHERICAL COLLAR SCREW M12X1.25X45	4	8.05	32.20
WHEEL HUB WITH BEARING FRT	1	484.55	484.55
FRT LH CARRIER	1	463.45	463.45
FRT SWING SUPPORT	2	99.60	199.20
STABILIZER FRT WITH RUBBER MOUNTING	1	390.10	390.10
FRT SPRING STRUT	1	496.65	496.65
FRONT COIL SPRING	1	230.30	230.30
ADDITIONAL SHOCK ABSORBER FRT	1	41.65	41.65
LH TIE ROD / BT	1	296.65	296.65
RH TIE ROD X	1	296.65	296.65
REPAIR KIT BELLOWS (TKP)	2	165.20	330.40
EXCH STEERING BOX ELECTR. (TKP)	1	3,648.60	3,648.60
COMBINATION NUT M14X1.5	1	5.80	5.80
HEX NUT WITH FLANGE	1	2.50	2.50
ALLOY RIM 7.5JX17 STAR SPK 393 / CRT	1	840.00	840.00
HUB CAP WITH CHROME EDGE (BMW) X	1	28.95	28.95
BONNET / DD	1	1,281.20	1,281.20
FRT LH SIDE PANEL / DD	1	702.65	702.65
FRT RH TOP SUPPORT SIDE PANEL	1	20.10	20.10
FRONT SHOCK ABSORBER	1	54.55	54.55
FRT BUMPER TOP MOUNT	1	380.00	380.00
INSERT AIR INTAKE CENTER	1	125.70	125.70
FRT LH DEFORMATION ELEMENT	1	102.30	102.30
FRT LH LOWER DEFORMATION ELEMENT	1	86.85	86.85
LH SUPPORT FOGLAMP	1	42.05	42.05
FINISHER ROD CENTER (SPORT)	1	42.90	42.90
FRT RH BOTTOM MOUNTING SIDE PANEL	1	20.10	20.10
FRT BUMPER PANEL TRIM (LINES SRA) / BR	1	1,037.05	1,037.05
SUPPORT CENTRAL	1	11.40	11.40
MOUNT FOR SUPPORT	1	7.05	7.05
CLOSED GRID LH (LINES SPORT)	1	90.50	90.50
CLOSED GRID LH (LINES SPORT)	1	90.50	90.50
FRT LH GRILLE (SPORT) / BR	1	128.60	128.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

307, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64794601
64794624

(After Sales)
(Motorist)

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company



GST REG. NO : M2 - 0020081 - X

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Estimate No. : b1 53891
Date Estimated : 24/12/2019
Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
LICENCE PLATE BASE (ECE) X	1	69.60	69.60
INSCRIPTION SIDE (SPORT LINE) ?	1	46.55	46.55
GROMMET / MC	2	0.80	1.60
GAS STRUT HOOD X	2	118.70	237.40
STOP BUFFER - bonnet X	2	14.55	29.10
FRONT PANEL V-STRUT X	1	112.75	112.75
LH SUPPORT	1	132.15	132.15
LH HEADLIGHT BRACKET / MID	1	10.40	10.40
FRONT CROSSLINK	1	169.10	169.10
LH COVER BOTTOM	1	117.15	117.15
AIR DUCT RADIATOR	1	105.35	105.35
AIR DUCT BOTTOM	1	105.35	105.35
ADJUSTER	1	6.35	6.35
LH ENGINE HOOD SEALING ?	1	39.05	39.05
RH ENGINE HOOD SEALING X	1	39.05	39.05
PLAQUE 82MM / MC	1	71.60	71.60
LH HEADLIGHT (XENON) / DR	1	2,130.35	2,130.35
LH FOG LIGHT	1	300.25	300.25
CONDENSER AIR CONDITIONING ?	1	1,033.60	1,033.60
ULTRASONIC SENSOR BLACK / MIS	1	238.05	238.05
ULTRASONIC SENSOR BLACK X	4	238.05	952.20

Total Parts : 19,753.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 27/12/19, 12:15 pm Excess S\$ _____
Surveyor's Name STEVE (LKK) Sign _____
Surveyor's Tel _____ Authorised Yes / No _____
Authorised Date _____ Time _____

OD - Not Authorised (Rev 1)
Excess - ?
6 days
By Ref - SM

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend _____

Labour 1	:	16,966.75
Parts	:	19,753.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,570.42
Grand Total	:	39,290.77

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53891**
Date Estimated : **24/12/2019**
Prepared By : **Chua Kee Sin**

Page No. : **4 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : **b1 53891**
 Date Estimated : **24/12/2019**
 Prepared By : **Chua Kee Sin**

Page No. : **5 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 53891**
Date Estimated : **24/12/2019**
Prepared By : **Chua Kee Sin**

Page No. : **6 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM7232C	WBA3A16090NS36105	31/03/2014	316iA/4	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pmi.com.sg

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)205 Braddell Road
Singapore 579701

Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

INSURER: India International Insurance Pte Ltd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	D18MPC0001876-01	Date of Loss:	23/12/2019
Vehicle Reg. No.:	SKM7232C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHIU LOO TONG		
Make/Model:	BMW 316i, 1.6 (A)	Vehicle Reg. Date:	31/03/2014
Vehicle Colour:	Metallic Black		
Engine No:	B304J576N13B16A	Chassis No:	WBA3A16090NS3610
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

COST OF CLAIMS	Amount
Parts	18,765.92
Miscellaneous Items	11.00
Labour	6,280.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	25,056.92
+ GST 7.00% (S\$)	1,753.98
Nett Amount (S\$)	26,810.90

This claim is handled by: ANDREW CORNELIUS GOH CHENG CHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

* record purpose.

* CGE copy PML estimate

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Dec 2019)
 Parts: 143 BMW 316i 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SKM7232C/31/12/2019 09:37
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR MODULE MOUNT LH / MIS	5.00	0.00	*78.00 FL
2	1		*CHARGE AIR COOLER ?	5.00	0.00	*662.90 FL
3	1		*HEX SCREW WITH COLLAR M12X1.5X85 ?	5.00	0.00	*8.05 FL
4	1	*	*LH WISHBONE ? / BT	5.00	0.00	*271.15 FL
5	1		*COLLAR NUT M12X1.5X45 ?	5.00	0.00	*61.20 FL
6	1		*SPHERICAL COLLAR SCREW M12X1.25X45 ?	5.00	0.00	*32.20 FL
7	1	*	*WHEEL HUB WITH BEARING FRT ? / MC	5.00	0.00	*484.55 FL
8	1	*	*FRONT LH CARRIER ? / BT	5.00	0.00	*463.45 FL
9	1	*	*FRONT SWIBNG SUPPORT ? / BT	5.00	0.00	*199.20 FL
10	1		*STABILIZER FRONT WITH RUBBER MOUNTING ?	5.00	0.00	*390.10 FL
11	1	*	*FRONT SPRING STRUT ? / BT	5.00	0.00	*496.65 FL
12	1		*FRONT COIL SPRING ?	5.00	0.00	*230.30 FL
13	1		*ADDITIONAL SHOCK ABSORBER FRONT ?	5.00	0.00	*41.65 FL
14	1	*	*LH TIE ROD / BT	5.00	0.00	*296.65 FL
15	1		*RH TIE ROD X	5.00	0.00	*296.65 FL
16	1		*REPAIR KIT BELLOWS (TKP) ?	5.00	0.00	*330.40 FL
17	1		*EXCH STEERING BOX ELECTR (TKP) ?	5.00	0.00	*3,648.60 FL
18	1		*COMBINATION NUT M14X1.5 ?	5.00	0.00	*5.80 FL
19	1		*HEX NUT WITH FLANGE ?	5.00	0.00	*2.50 FL
20	1		*ALLOY RIM 7.5JX17 STAR SPK 393 / CVT	5.00	0.00	*840.00 FL
21	1		*HUP CAP WITH CHROME EDGE (BMW) X	5.00	0.00	*28.95 FL
22	1		*BONNET / 00	5.00	0.00	*1,281.20 FL
23	1		*FRONT LH SIDE PANEL / 00	5.00	0.00	*702.65 FL
24	1		*FRONT RH TOP SUPPORT SIDE PANEL ?	5.00	0.00	*20.10 FL
25	1		*FRONT SHOCJ ABSORBER ?	5.00	0.00	*54.55 FL
26	1		*FRONT BUMPER TOP MOUNT ?	5.00	0.00	*380.00 FL
27	1		*INSERT AIR INTAKE CENTER ?	5.00	0.00	*125.70 FL
28	1		*FRONT LH DEFORMATION ELEMENT ?	5.00	0.00	*102.30 FL
29	1		*FRONT LH LOWER DEFORMATION ELEMENT ?	5.00	0.00	*86.85 FL
30	1		*LH SUPPORT FOGLAMP ?	5.00	0.00	*42.05 FL
31	1		*FINISHER ROD CENTER 9SPORT ?	5.00	0.00	*42.90 FL
32	1		*FRONT RH BOTTOM MOUNTING SIDE PANEL ?	5.00	0.00	*20.10 FL
33	1		*FRONT BUMPER PANEL TRIM (LINES SRA) / BR	5.00	0.00	*1,037.05 FL
34	1		*SUPPORT CENTRAL ?	5.00	0.00	*11.40 FL
35	1		*MOUNT FOR SUPPORT ?	5.00	0.00	*7.05 FL
36	1		*CLOSED GRID LH (LINES SPORT) ?	5.00	0.00	*90.50 FL
37	1		*CLOSED GRID LH (LINES SPORT) ?	5.00	0.00	*90.50 FL
38	1		*FRONT LH GRILLE (SPORT) / BR	5.00	0.00	*128.60 FL
39	1		*LICENSE PLATE BASE (ECE) X	5.00	0.00	*69.60 FL
40	1		*INSCRIPTION SIDE (SPORT LINE) ?	5.00	0.00	*46.55 FL
41	1		*GROMMET / MC	5.00	0.00	*1.60 FL
42	1		*GAS STRUT HOOD X	5.00	0.00	*237.40 FL
43	1		*STOP BUFFER - BONNET X	5.00	0.00	*29.10 FL
44	1		*FRONT PANEL V STRUT X	5.00	0.00	*112.75 FL
45	1		*LH SUPPORT X	5.00	0.00	*132.15 FL
46	1		*LH HEADLIGHT BRACKET / MIS	5.00	0.00	*10.40 FL
47	1		*FRONT CROSSLINK ?	5.00	0.00	*169.10 FL

48	1	*LH COVER BOTTOM	?	5.00	0.00	*117.15 FL
49	1	*AIR DUCT RADIATOR	?	5.00	0.00	*105.35 FL
50	1	*AIR DUCT BOTTOM	?	5.00	0.00	*105.35 FL
51	1	*ADJUSTER	?	5.00	0.00	*6.35 FL
52	1	*LH ENGINE HOOD SEALING	?	5.00	0.00	*39.05 FL
53	1	*RH ENGINE HOOD SEALING	X	5.00	0.00	*39.05 FL
54	1	*PLAQUE 82MM	✓ APC	5.00	0.00	*71.60 FL
55	1	*LH HEADLIGHT (XENON)	✓ OR	5.00	0.00	*2,130.35 FL
56	1	*LH FOG LIGHT	?	5.00	0.00	*300.25 FL
57	1	*CONDENSER AIR CONDITIONING	?	5.00	0.00	*1,033.60 FL
58	1	*ULTRASONIC SENSOR BLACK	✓ MIS (1pc) 238.05	5.00	0.00	*952.20 FL
59	1	*ULTRASONIC SENSOR BLACK	X	5.00	0.00	*952.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	19,753.60
- List Item Discount on L Items (S\$)	987.68
Total Parts (S\$)	18,765.92

ComfortDelGro Engineering Pte Ltd/SKM7232C/31/12/2019 09:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISMANTLE AND REPLACE LH FRONT SUSPENSION AND UNDERCARRIAGE TO FACILITATE REPAIRS AND BLEED BRAKE SYSTEM	New	250.00
2	TO REMOVE AND REPLACE AIR CON PARTS, VACUUM AND RECHARGE AIR CON GAS	New	120.00
3	TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH TO RE-ALIGN CHASSIS MEMBERS AND BODY STRUCTURE	New	250.00
4	LABOR CHARGES TO REPAIR, PANEL BEAT AND REPAIR ON FRONT AND LH FRONT DAMAGES PARTS AND AFFECTED AREAS <i>280 per day</i>	New	2,800.00
5	TO CHECK WIRING FUNCTIONS AND LIGHTING	New	120.00
6	TO INSTALL FRONT ULTRASONIC SENSORS	New	120.00
7	TO PUTTY AND SPRAY PAINT ON BONNET, LH FRONT FENDER, FRONT BUMPER, RH FRONT FENDER, LH FRONT DOOR, FRONT SUPPORT PANEL AND AFFECTED AREAS <i>200 per pt</i>	New	2,000.00
8	TO CHECK AND RESET STEERING GEOMETRY AND FOUR WHEEL ALIGNMENT	New	120.00
9	TO DIAGNOSE AND REPROGRAM ELECTRONIC SYSTEM	New	500.00
Gross Labour Cost (S\$)			6,280.00

ComfortDelGro Engineering Pte Ltd/SKM7232C/31/12/2019 09:37. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve CLKK) 31/12/19, 10.39am

8322 8813

00 - Not Authn.

Excess - ?

6 days

Ry DeL SJ

13k limit repair

[Signature]
31/12/19

Shiau Chan (LKKAUTO)

From: CDGE Braddell Private Cars Crash Repair Operation
<braddell_operation@sparkcarcare.com>
Sent: Tuesday, 31 December 2019 11:05 AM
To: Shiau Chan (LKKAUTO); Steve Chen (LKK Auto)
Cc: Denis Teo Chin Chye; Patrick Chung Chan Kim
Subject: Re: SKM 7232C BMW 316i

Dear Steve

Kindly note that our spray paint per panel is at \$250/panel.

Andrew
Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)
Fax: 6281 5767
www.SPARKcarcare.com

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 31 December 2019 10:56 AM
To: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Cc: Denis Teo Chin Chye <denisteo@sparkcarcare.com>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>
Subject: RE: SKM 7232C BMW 316i

Dear Andrew,

Please find the attached of our surveyor's marking estimate.

Best Wishes for Happy New Year 2020

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 31 December 2019 10:49 AM
To: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Cc: Denis Teo Chin Chye <denisteo@sparkcarcare.com>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>
Subject: RE: SKM 7232C BMW 316i

Dear Andrew,

As instructed by our client, please proceed to repair the insured vehicle **SKM 7232C** at repair cost not more than Lump Sum **\$13,000.00 (Excess \$600/-)**.



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : ODVehicle No. : SKM7232CMake & Model : BMW 316IYear of Manufacture : 2013Chassis No. : WBA3A16090NS36105Ins Company : III

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 23/12/2019

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair EstimateCase Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ 14,316.98Plus/Less 5% \$ 715.85Total of Cost / List \$ 13,601.13(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 13,601.13Labour (Appendix B) \$ 6,280.00Total Repair Cost \$ 19,881.13

Contact No

Frt Counter Operation

Patrick Tia 6383 7466

Brenda Ng 6383 7730

Rohani 6383 7890

Workshop Operation

Ngo Toh Wee 6383 7656

William Wang 6383 8115

Andrew Goh 6383 7362

Andrewcorneliusgoh@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor	: <u>Star (LKK)</u>	OD - Not M (R)
Company	: <u>P/R - Rg BL sy</u>	
Survey conducted on	: <u>27/12/19</u>	at _____
Remarks By Surveyor		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	: <u>8</u>	day(s)
(c) Resurvey	Required / Not Required	
(d) Excess	: <u>\$</u>	
(e) Signature of surveyor	: <u>[Signature]</u>	Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SKM7232C Case Owner : Andrew

Make & Model : BMW 316I Year Manufacture : 2013

Chassis No : WBA3A16090NS36105 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper / <u>BR</u>	1		\$ 1,037.05			
2	Front bumper fog lamp LH ?	1		\$ 300.25			
3	Front bumper fog lamp bracket LH /	1	<u>BR</u>	\$ 45.05			
4	Front bumper side lower bracket LH /	1	<u>BR</u>	\$ 45.10			
5	Front bumper reinforcement / <u>DD</u>	1		\$ 380.00			
6	LH front fender / <u>DD</u>	1		\$ 762.65			
7	LH front fender inner shield front / <u>CEV</u>	1		\$ 117.15			
8	LH front fender inner shield rear / <u>CEV</u>	1		\$ 117.15			
9	LH front fender inner shield cover / <u>MVS</u>	1		\$ 21.00	<u>35-95</u>		
10	Bonnet / <u>DD</u>	1		\$ 1,281.20			
11	Headlamp LH / <u>BR</u>	1		\$ 2,130.35			
12	Headlamp gas discharge lamp LH / <u>BR</u>	1		\$ 383.40			
13	Headlamp LED module set / <u>SHW</u>	1		\$ 256.05			
14	Headlamp washer pump LH / <u>BR</u>	1		\$ 160.85			
15	Headlamp washer cover LH / <u>BR</u>	1		\$ 43.50			
16	Front bumper grille LH / <u>BR</u>	1		\$ 128.60			
17	Front bumper grille RH / <u>BR</u>	1		\$ 128.60			
18	LH front wheel hub / <u>PRC</u>	1		\$ 484.85			
19	LH front knuckle arm / <u>LT</u>	1		\$ 403.45			
20	LH front shock absorber / <u>LT</u>	1		\$ 561.20			
21	LH front shock absorber dust boot X <u>NAI</u>	1		\$ 20.75			
22	LH front swing support	1		\$ 99.60			
23	LH height adjuster lever	1		\$ 25.15			
24	LH front track cont arm / <u>LT</u>	1		\$ 271.15			
25	LH front tension rod / <u>LT</u>	1		\$ 271.15			
26	LH front tension rod rubber	1		\$ 105.53			
27	Steering rack X <u>NAI</u>	1		\$ 3,648.60			
28	Front stabilizer	1		\$ 390.10			
29	Front headlamp adjuster sensor X <u>NAI</u>	1		\$ 154.05			
30	Front tie rod LH / <u>LT</u>	1		\$ 296.85			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

13/01/2020

11:02 AM

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SKM7232C Case Owner : Andrew

Make & Model : BMW 316I Year Manufacture : 2013

Chassis No : WBA3A16090NS36105 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Front tie rod end LH / RT	1		\$ 178.10			
32	LH front signal lamp holder assy ? / MU	1		\$ 25.00			
33	Headlamp washer cover RH ? X	1		\$ 43.50			
34	0	0					
35	0	0					
36	0	0					
37	0	0					
38	0	0					
39	0	0					
40	0	0					
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

13/01/2020

11:02 AM

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (S79701)

Labour

Vehicle No.	:	<u>SKM7232C</u>	Case Owner	:	<u>Andrew</u>
Make & Model	:	<u>BMW 316I</u>	Year of Manufacture	:	<u>2013</u>

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ComfortDelgro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Bill To : _____ Vehicle Number : SKM7232C
Attn to : _____ Type Of Claim : OD

<i>Parts</i>	<u>\$ 9,942.05</u>	<i>Total Parts</i>	<u>\$ 10,707.45</u>
<i>Supplementary</i>	<u>\$ -</u>	<i>Total Labour</i>	<u>\$ 2,520.00</u>
<i>Nett Price</i>	<u>\$ -</u>	<i>Total Repair</i>	<u>\$ 13,227.45</u>
<i>S/Nett</i>	<u>\$ -</u>	<i>P/P Total</i>	<u>13,227.45</u>
<i>Supplementary Nett</i>	<u>\$ 631.25</u>	Lump Sum Less <u>0%</u>	<u>\$ -</u>
<i>Supplementary S/Nett</i>	<u>\$ -</u>		
		Lump Sum Rounding	<u>\$ 13,227.45</u>
		Total Finalized	<u>\$ 13,227.45</u>

Total Spare Parts Price	\$ 9,942.05
Cost plus / List Down <u>5%</u>	497.10
Total	9,444.95

Total Nett Price	\$ 631.25
Nett Price Less _____	\$ -
Total	631.25

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In _____	Total Repair Day _____
Date Survey _____	LOU/ Day _____
Date Out _____	Total LOU _____
Sat/Sun/Pl. _____	Rental/Day _____
Authorized Repair Day _____	Total Rental _____
Submitted By / Date : _____	Confirmed By / Date : _____
Andrew / _____	
Office: 6383 7362	

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jan 2020)

Parts: 143 BMW 316i 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SKM7232C/14/01/2020 11:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	5.00	0.00	*1,037.05 FL <i>64</i>
2	1		*Front bumper fog lamp LH	5.00	0.00	*300.25 FL <i>?</i>
3	1		*Front bumper fog lamp bracket LH	5.00	0.00	*45.05 FL <i>64</i>
4	1		*Front bumper side lower bracket LH	5.00	0.00	*45.10 FL <i>64</i>
5	1		*Front bumper reinforcement	5.00	0.00	*380.00 FL <i>64</i>
6	1		*LH front fender	5.00	0.00	*762.65 FL <i>64</i>
7	1		*LH front fender inner shield front	5.00	0.00	*117.15 FL <i>64</i>
8	1		*LH front fender inner shield rear	5.00	0.00	*117.15 FL <i>64</i>
9	1		*LH front fender shield cover HID covering cap	5.00	0.00	*35.95 FL <i>64</i>
10	1		*Bonnat	5.00	0.00	*1,281.20 FL <i>64</i>
11	1		*Headlamp LH	5.00	0.00	*2,130.35 FL <i>64</i>
12	1		*Headlamp gas discharge lamp LH	5.00	0.00	*383.40 FL <i>64</i>
13	1		*Headlamp LED module set	5.00	0.00	*258.05 FL <i>64</i>
14	1		*Headlamp washer pump LH	5.00	0.00	*160.85 FL <i>64</i>
15	1		*Headlamp washer cover LH	5.00	0.00	*43.50 FL <i>64</i>
16	1		*Front bumper grille LH	5.00	0.00	*128.60 FL <i>64</i>
17	1		*Front bumper grille RH	5.00	0.00	*128.60 FL <i>64</i>
18	1		*LH front wheel hub	5.00	0.00	*484.85 FL <i>64</i>
19	1		*LH front knuckle arm	5.00	0.00	*403.45 FL <i>64</i>
20	1		*LH front shock absorber	5.00	0.00	*581.20 FL <i>64</i>
21	1		*LH front shock absorber dust boot	5.00	0.00	*20.75 FL <i>64</i>
22	1		*LH front swing support	5.00	0.00	*99.60 FL <i>?</i>
23	1		*LH height adjuster lever	5.00	0.00	*25.15 FL <i>?</i>
24	1		*LH front track control arm	5.00	0.00	*271.15 FL <i>64</i>
25	1		*LH front tension rod	5.00	0.00	*271.15 FL <i>64</i>
26	1		*LH front tension rod rubber	5.00	0.00	*105.53 FL <i>?</i>
27	1		*Steering rack	5.00	0.00	*3,648.60 FL <i>64</i>
28	1		*Front stabilizer	5.00	0.00	*390.10 FL <i>?</i>
29	1		*Front headlamp adjuster sensor	5.00	0.00	*154.05 FL <i>64</i>
30	1		*Front tie rod LH	5.00	0.00	*296.85 FL <i>64</i>
31	1		*Front tie rod end LH	5.00	0.00	*178.10 FL <i>64</i>
32	1		*LH front signal lamp holder assy	5.00	0.00	*25.00 FL <i>64</i>
33	1		*Headlamp washer cover RH	5.00	0.00	*43.50 FL <i>X</i>
34	1		*Front bumper clips <i>MC</i>	5.00	0.00	<i>30/</i> *50.00 FL
35	1		*Front bumper rivets <i>MC</i>	5.00	0.00	<i>30/</i> *50.00 FL
36	1		*Front bumper sensors outer LH <i>64</i>	5.00	0.00	*238.05 FL <i>/</i>
37	1		*Front bumper sensors inner LH <i>X MC</i>	5.00	0.00	*238.05 FL

P: Franchise part, L: List Item Disc.

Sub Total (S\$) 14,908.03

- List Item Discount on L Items (S\$) 745.40

Total Parts (S\$) 14,162.63

ComfortDelGro Engineering Pte Ltd/SKM7232C/14/01/2020 11:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			11.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISMANTLE AND REPLACE LH FRONT SUSPENSION AND UNDERCARRIAGE TO FACILITATE REPAIRS AND BLEED BRAKE SYSTEM	New	2.65 250.00
2	TO REMOVE AND REPLACE AIR CON PARTS, VACUUM AND RECHARGE AIR CON GAS	New	120.00 ?
3	TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH TO RE-ALIGN CHASSIS MEMBERS AND BODY STRUTURE	New	250.00 X
4	LABOR CHARGES TO REPAIR, PANEL BEAT AND REPAIR ON FRONT AND LH FRONT DAMAGES PARTS AND AFFECTED AREAS	New	135 2,800.00
5	TO CHECK WIRING FUNCTIONS AND LIGHTING	New	80 120.00
6	TO INSTALL FRONT ULTRASONIC SENSORS	New	50 120.00
7	TO PUTTY AND SPRAY PAINT ON BONNET, LH FRONT FENDER, FRONT BUMPER, RH FRONT FENDER, LH FRONT DOOR, FRONT SUPPORT PANEL AND AFFECTED AREAS	New	750 2,000.00
8	TO CHECK AND RESET STEERING GEOMETRY AND FOUR WHEEL ALIGNMENT	New	60 120.00
9	TO DIAGNOSE AND REPROGRAM ELECTRONIC SYSTEM	New	500.00 ?
Gross Labour Cost (S\$)			6,280.00

ComfortDelGro Engineering Pte Ltd/SKM7232C/14/01/2020 11:13, Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

UKK Auto Consultants hereby notify the Repairer of the following:-

- To ensure betterment being painted
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal notification is allowed
- Supplementary items must be insured and subject to final approval from Insurance Company

Authorised by Insurer:

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jan 2020)
 Parts: 143 BMW 318i 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SKM7232C/15/01/2020 13:47
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Oil filter housing / OR	5.00	0.00	*437.25 FL (17)
2	1		*Engine oil / MC (50%)	0.00	0.00	50, *100.00 F (2)
F=Franchise part, L=List Item Disc.						
Sub Total (S\$)						537.25
- List Item Discount on L Items (S\$)						21.86
Total Parts (S\$)						515.39

ComfortDelGro Engineering Pte Ltd/SKM7232C/15/01/2020 13:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jan 2020)
 Parts: 143 BMW 318i 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SKM7232C/22/01/2020 15:25
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper fog lamp cover LH / MIS	5.00	0.00	*90.50 FL
2	1		*Front bumper fog lamp cover chrome moulding LH / MIS	5.00	0.00	*23.50 FL
3	1		*Camshaft intake sensor X BR (WAV & TW)	5.00	0.00	*144.25 FL
4	1		*Rocker cover gasket X N/A	5.00	0.00	*62.10 FL

F=Franchise part, L=List Item Disc.

Sub Total (\$)	320.35
- List Item Discount on L Items (\$)	16.02
Total Parts (\$)	304.33

ComfortDelGro Engineering Pte Ltd/SKM7232C/22/01/2020 15:25. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MPC0001876-01	Date of Loss:	23/12/2019
Vehicle Reg. No.:	SKM7232C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHIU LOO TONG		
Make/Model:	BMW 316I, 1.6 (A)	Vehicle Reg. Date:	31/03/2014
Vehicle Colour:	METALLIC BLACK	Chassis No:	WBA3A16090NS36105
Engine No:	B304J576N13B16A		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

COST OF CLAIMS	Amount
Parts	14,162.63
Miscellaneous Items	11.00
Labour	6,280.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	20,453.63
+ GST 7.00% (S\$)	1,431.75
Nett Amount (S\$)	21,885.38

This claim is handled by: ANDREW CORNELIUS GOH CHENG CHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

& surveyed on 23/12/19 @ PHL
 & received estimate on 14/01/20
 & CDGE re-created estimate by their own work. (latest estimate)
 as their unable to understand PHL estimate, parts & labour.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jan 2020)
 Parts: 143 BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SKM7232C/14/01/2020 11:13
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	5.00	0.00	*1,037.05 FL <i>BR</i>
2	1		*Front bumper fog lamp LH	5.00	0.00 X <i>NN</i>	*300.25 FL ?
3	1		*Front bumper fog lamp bracket LH	5.00	0.00	*45.05 FL <i>BR</i>
4	1		*Front bumper side lower bracket LH	5.00	0.00	*45.10 FL <i>BR</i>
5	1		*Front bumper reinforcement	5.00	0.00	*380.00 FL <i>BR</i>
6	1		*LH front fender	5.00	0.00	*762.65 FL <i>BR</i>
7	1		*LH front fender inner shield front	5.00	0.00	*117.15 FL <i>BR</i>
8	1		*LH front fender inner shield rear	5.00	0.00	*117.15 FL <i>BR</i>
9	1		*LH front fender shield cover HID covering ca	5.00	0.00	*35.95 FL <i>BR</i>
10	1		*Bonnet	5.00	0.00	*1,281.20 FL <i>BR</i>
11	1		*Headlamp LH	5.00	0.00	*2,130.35 FL <i>BR</i>
12	1		*Headlamp gas discharge lamp LH	5.00	0.00	*383.40 FL <i>BR</i>
13	1		*Headlamp LED module set	5.00	0.00 <i>Good</i>	*256.05 FL <i>BR</i>
14	1		*Headlamp washer pump LH	5.00	0.00	*160.85 FL <i>BR</i>
15	1		*Headlamp washer cover LH	5.00	0.00	*43.50 FL <i>BR</i>
16	1		*Front bumper grille LH	5.00	0.00	*128.60 FL <i>BR</i>
17	1		*Front bumper grille RH	5.00	0.00	*128.60 FL <i>BR</i>
18	1		*LH front wheel hub	5.00	0.00	*484.85 FL <i>BR</i>
19	1		*LH front knuckle arm	5.00	0.00	*403.45 FL <i>BR</i>
20	1		*LH front shock absorber	5.00	0.00	*561.20 FL <i>BR</i>
21	1		*LH front shock absorber dust boot	5.00	0.00	*20.75 FL <i>BR</i>
22	1		*LH front swing support	5.00	0.00 <i>QT</i>	*99.60 FL ?
23	1		*LH height adjuster lever	5.00	0.00 X <i>NN</i>	*25.15 FL ?
24	1		*LH front track control arm	5.00	0.00	*271.15 FL <i>BR</i>
25	1		*LH front tension rod	5.00	0.00	*271.15 FL <i>BR</i>
26	1		*LH front tension rod rubber	5.00	0.00 X <i>NN</i>	*105.53 FL ?
27	1		*Steering rack	5.00	0.00	*3,648.60 FL <i>BR</i>
28	1		*Front stabilizer	5.00	0.00 X <i>NN</i>	*390.10 FL ?
29	1		*Front headlamp adjuster sensor	5.00	0.00	*154.05 FL <i>BR</i>
30	1		*Front tie rod LH	5.00	0.00	*296.85 FL <i>BR</i>
31	1		*Front tie rod end LH	5.00	0.00 X <i>NN</i>	*178.10 FL <i>BR</i>
32	1		*LH front signal lamp holder assy	5.00	0.00	*25.00 FL <i>BR</i>
33	1		*Headlamp washer cover RH	5.00	0.00 X <i>NN</i>	*43.50 FL X
34	1		*Front bumper clips <i>BR</i>	5.00	0.00 <i>30</i>	*50.00 FL
35	1		*Front bumper rivets <i>BR</i>	5.00	0.00 <i>30</i>	*50.00 FL
36	1		*Front bumper sensors outer LH <i>BR</i>	5.00	0.00	*238.05 FL <i>BR</i>
37	1		*Front bumper sensors inner LH X <i>NN</i>	5.00	0.00	*238.05 FL

F=Franchise part, L=List Item Disc.

Sub Total (\$\$)	14,908.03
- List Item Discount on L Items (\$\$)	745.40
Total Parts (\$\$)	14,162.63

ComfortDelGro Engineering Pte Ltd/SKM7232C/14/01/2020 11:13. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISMANTLE AND REPLACE LH FRONT SUSPENSION AND UNDERCARRIAGE TO FACILITATE REPAIRS AND BLEED BRAKE SYSTEM	New	200 / 250.00
2	TO REMOVE AND REPLACE AIR CON PARTS, VACUUM AND RECHARGE AIR CON GAS	New	X 120.00 ?
3	TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH TO RE-ALIGN CHASSIS MEMBERS AND BODY STRUTURE	New	250.00 X
4	LABOR CHARGES TO REPAIR, PANEL BEAT AND REPAIR ON FRONT AND LH FRONT DAMAGES PARTS AND AFFECTED AREAS	New	980 / 2,800.00
5	TO CHECK WIRING FUNCTIONS AND LIGHTING	New	80 / 120.00
6	TO INSTALL FRONT ULTRASONIC SENSORS	New	50 / 120.00
7	TO PUTTY AND SPRAY PAINT ON BONNET, LH FRONT FENDER, FRONT BUMPER, RH FRONT FENDER, LH FRONT DOOR, FRONT SUPPORT PANEL AND AFFECTED AREAS	New	750 / 2,000.00
8	TO CHECK AND RESET STEERING GEOMETRY AND FOUR WHEEL ALIGNMENT	New	60 / 120.00
9	TO DIAGNOSE AND REPROGRAM ELECTRONIC SYSTEM	New	200 / 500.00 ?
Gross Labour Cost (S\$)			6,280.00

ComfortDelGro Engineering Pte Ltd/SKM7232C/14/01/2020 11:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal proceedings is allowed
- Supplementary items must be resurveyed and is subject to fees charged from Insurance Company

Authorised By Repairer

Signature:

Date:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

(SUPPLEMENTARY)

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MPC0001876-01	Date of Loss:	23/12/2019
Vehicle Reg. No.:	SKM7232C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHIU LOO TONG		
Make/Model:	BMW 316I, 1.6 (A)	Vehicle Reg. Date:	31/03/2014
Vehicle Colour:	METALLIC BLACK		
Engine No:	B304J576N13B16A	Chassis No:	WBA3A16090NS36105
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

COST OF CLAIMS	Amount
Parts	515.39
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	515.39
+ GST 7.00% (S\$)	36.08
Nett Amount (S\$)	551.47
+ Previous Estimates (S\$)	21,885.38
Claim Total (S\$)	22,436.85

Generated using Merimen e-Claims Internet Estimation & Adjusting System

2273.35

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jan 2020)

Parts: 143 BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SKM7232C/15/01/2020 13:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Oil filter housing / OR	5.00	0.00	*437.25 FL (17)
2	1		*Engine oil / ALL (50%)	0.00	0.00	So, *100.00 F (17)
Sub Total (S\$)						537.25
- List Item Discount on L Items (S\$)						21.86
Total Parts (S\$)						515.39

F=Franchise part, L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SKM7232C/15/01/2020 13:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SKM7232C/15/01/2020 13:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

(SUPPLEMENTARY)

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MPC0001876-01	Date of Loss:	23/12/2019
Vehicle Reg. No.:	SKM7232C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHIU LOO TONG		
Make/Model:	BMW 316I, 1.6 (A)	Vehicle Reg. Date:	31/03/2014
Vehicle Colour:	METALLIC BLACK		
Engine No:	B304J576N13B16A	Chassis No:	WBA3A16090NS36105
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

COST OF CLAIMS	Amount
Parts	304.33
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	304.33
+ GST 7.00% (S\$)	21.30
Nett Amount (S\$)	325.63
+ Previous Estimates (S\$)	22,436.85
Claim Total (S\$)	22,762.48

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jan 2020)

Parts: 143 BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SKM7232C/22/01/2020 15:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper fog lamp cover LH / MIS	5.00	0.00	*90.50 FL
2	1		*Front bumper fog lamp cover chrome moulding LH / MIS	5.00	0.00	*23.50 FL
3	1		*Camshaft intake sensor X NH BR (New & Test)	5.00	0.00	*144.25 FL
4	1		*Rocker cover gasket X NAI	5.00	0.00	*62.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	320.35
- List Item Discount on L Items (S\$)	16.02
Total Parts (S\$)	304.33

ComfortDelGro Engineering Pte Ltd/SKM7232C/22/01/2020 15:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SKM7232C/22/01/2020 15:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Dec 2019 09:14 Sendback Est	14 Jan 2020 11:13 \$520,453.63	02 Jan 2020 08:34 Edit Adj Rpt	\$512,180.44 Edit Estimates	\$512,180.44 View Rpt		Pending for Survey Report Cancel Case
Supp #1	14 Jan 2020 11:13	15 Jan 2020 13:47 \$5515.39	15 Jan 2020 13:47			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	22 Jan 2020 15:24	22 Jan 2020 15:25 \$5304.33	22 Jan 2020 15:25			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **CHIU LOO TONG**, ID: S1121470C

Vehicle Reg. No.: SKM7232C	Date of Loss: 23/12/2019 00:00 - :59 [68 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type: OD	Policy/Cover Note No.: D18MPC0001876-01 (Comprehensive)
Excess:	

Repairer: **ComfortDelGro Engineering Pte Ltd (Braddell)** 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118

Handling Insurer: **India International Insurance Pte Ltd (HQ)** - Tel: 63476100 ... [Handled by **Lalitha Krishnan** - 6347 6139]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **CHEN TSUE YEE**] ... **[Final Rpt due 13/01/2020]**

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)





































- III_SG (02/01/2020): Alert - Adj Mandate Approved (\$513000.00) - SKM7232C - Claim Handler: Lalitha Kr...



















































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)



















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents

SKM7232C
OD
Dec 23 2019 12:00AM
[CHIU LOO TONG]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	14/01/20 11:13	Repairer Estimates	 Load HTM	<input type="checkbox"/>
2	15/01/20 13:47	Repairer Estimates Suppl. #1	 Load HTM	<input type="checkbox"/>
3	22/01/20 15:25	Repairer Estimates Suppl. #2	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
2	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/01/20 19:18	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
5	14/01/20 19:18	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
6	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
34	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/01/20 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
84	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	14/01/20 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	14/01/20 19:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
134	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	14/01/20 19:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	14/01/20 19:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	14/01/20 19:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
184	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	30/01/20 09:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/01/20 08:19	Singapore Accident Statement - ID SAS - SKM7232 C	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/20 13:49	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III19022754/EQD3E2

Date: 07/02/2020

REFERENCE

Insured/Claimant:	CHIU LOO TONG	Policy No:	D18MPC0001876-01	Claim No:	N/A
Date of Loss:	23/12/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM7232C	Engine No:	B304J576N13B16A
Make & Model:	BMW 316I, 1.6 (A)	Chassis No:	WBA3A16090NS36105
Reg. Date:	31/03/2014 (Man. Year: 2013)	Odometer:	91184 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,982.35	9,849.44	5,132.91	34.26
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	6,280.00	2,320.00	3,960.00	63.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,273.35	12,180.44	9,092.91	42.74
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	21,273.35	11,580.44	9,692.91	45.56
+ GST 7.00/7.00% (S\$)	1,489.13	810.63	678.50	45.56
Nett Amount (S\$)	22,762.48	12,391.07	10,371.41	45.56

INSPECTION

Date of Assignment:	02/01/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	27/12/2019 Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2020)
Parts: 143	BMW 316i 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKM7232C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Broken	1,037.05 FL	*1,037.05 FL
2	1		*Front bumper fog lamp LH	Not Necessary	300.25 FL	*- FL
3	1		*Front bumper fog lamp bracket LH	Broken	45.05 FL	*45.05 FL
4	1		*Front bumper side lower bracket LH	Broken	45.10 FL	*45.10 FL
5	1		*Front bumper reinforcement	Dented	380.00 FL	*380.00 FL
6	1		*LH front fender	Dented	762.65 FL	*762.65 FL
7	1		*LH front fender inner shield front	Crushed	117.15 FL	*117.15 FL
8	1		*LH front fender inner shield rear	Crushed	117.15 FL	*117.15 FL
9	1		*LH front fender shield cover HID covering cap	Missing	35.95 FL	*35.95 FL
10	1		*Bonnet	Dented	1,281.20 FL	*1,281.20 FL
11	1		*Headlamp LH	Broken	2,130.35 FL	*2,130.35 FL
12	1		*Headlamp gas discharge lamp LH	Broken	383.40 FL	*383.40 FL
13	1		*Headlamp LED module set	Shorted	256.05 FL	*256.05 FL
14	1		*Headlamp washer pump LH	Broken	160.85 FL	*160.85 FL
15	1		*Headlamp washer cover LH	Broken	43.50 FL	*43.50 FL
16	1		*Front bumper grille LH	Broken	128.60 FL	*128.60 FL
17	1		*Front bumper grille RH	Broken	128.60 FL	*128.60 FL
18	1		*LH front wheel hub	Necessary	484.85 FL	*484.85 FL
19	1		*LH front knuckle arm	Bent	403.45 FL	*403.45 FL
20	1		*LH front shock absorber	Bent	561.20 FL	*561.20 FL
21	1		*LH front shock absorber dust boot	Not Necessary	20.75 FL	*- FL
22	1		*LH front swing support	Bent	99.60 FL	*99.60 FL
23	1		*LH height adjuster lever	Not Necessary	25.15 FL	*- FL
24	1		*LH front track cont arm	Bent	271.15 FL	*271.15 FL
25	1		*LH front tension rod	Bent	271.15 FL	*271.15 FL
26	1		*LH front tension rod rubber	Not Necessary	105.53 FL	*- FL
27	1		*Steering rack	Not Necessary	3,648.60 FL	*- FL
28	1		*Front stabilizer	Not Necessary	390.10 FL	*- FL
29	1		*Front headlamp adjuster sensor	Not Necessary	154.05 FL	*- FL
30	1		*Front tied rod LH	Bent	296.85 FL	*296.85 FL
31	1		*Front tied rod end LH	Not Necessary	178.10 FL	*- FL
32	1		*LH front signal lamp holder assy	Missing	25.00 FL	*25.00 FL
33	1		*Headlamp washer cover RH	Not Necessary	43.50 FL	*- FL
34	1		*Front bumper clips	Necessary	50.00 FL	*30.00 FL
35	1		*Front bumper rivets	Necessary	50.00 FL	*30.00 FL
36	1		*Front bumper sensors outer LH	Shorted	238.05 FL	*238.05 FL
37	1		*Front bumper sensors inner LH	Not Necessary	238.05 FL	*- FL
Supplementary #1						
38	1		*Oil filter housing	Broken	437.25 FL	*437.25 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*Engine oil (50%)	Necessary	100.00 F	*50.00 FS
Supplementary #2						
40	1		*Front bumper fog lamp cover LH	Missing	90.50 FL	*90.50 FL
41	1		*Front bumper fog lamp cover chrome moulding LH	Missing	23.50 FL	*23.50 FL
42	1		*Camshaft intake sensor	Not Necessary	144.25 FL	*- FL
43	1		*Rocker cover gasket	Not Necessary	62.10 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,765.63	10,365.20
- List Item Discount on L Items 5.00/5.00% (S\$)					783.28	515.76
Total Parts (S\$)					14,982.35	9,849.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REPLACE LH FRONT SUSPENSION AND UNDERCARRIAGE TO FACILITATE REPAIRS AND BLEED BRAKE SYSTEM	New	250.00	200.00
2	TO REMOVE AND REPLACE AIR CON PARTS, VACUUM AND RECHARGE AIR CON GAS	New	120.00	0.00
3	TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH TI RE-ALIGN CHASSIS MEMBERS AND BODY STRUTURE	New	250.00	0.00
4	LABOR CHARGES TO REPAIR, PANEL BEAT AND REPAIR ON FRONT AND LH FRONT DAMAGES PARTS AND AFFECTED AREAS	New	2,800.00	980.00
5	TO CHECK WIRING FUNCTIONS AND LIGHTING	New	120.00	80.00
6	TO INSTALL FRONT ULTRASONIC SENSORS	New	120.00	50.00
7	TO PUTTY AND SPRAY PAINT ON BONNET, LH FRONT FENDER, FRONT BUMPER, RH FRONT FENDER, LH FRONT DOOR, FRONT SUPPORT PANEL AND AFFECTED AREAS	New	2,000.00	750.00
8	TO CHECK AND RESET STEERING GEOMETRY AND FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	TO DIAGNOSE AND REPROGRAM ELECTRONIC SYSTEM	New	500.00	200.00
Gross Labour Cost (\$\$)			6,280.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >