

ASS. REC. BY:

REF:

CS/LPC 19022763/Gld3

Special Instructions:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Gekild poh

of

LPC

Date/Time: 27/12/19 @ 9.08am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIT 90R

Insured:

SMA 1661B

at Workshop m/s

cheng Mohr

Tel:

at 1 kaki Bukit Ave G # 01-83 Ardoray

Policy No:

Claim No:

19/19/20/MP05/022821

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/12/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:22am @ 27/12/19

Person Contacted:

Alan

Vehicle IN/OUT

Date/Time

Action/Instruction

Tel: 011-222763

27/12/19

Receiver agreed after survey to surveyor cease Admin on leave.

SMA 1661B CS/LPC 19022763/Gld3

23/12/19

SIT 90R : X

30/12-5:34pm - verified via preli advise via email.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Cheng Motor
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$84K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIT90R (r Regn: 23 Jul 2019)
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Shuttle c.c. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 13330 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 6P72001919
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front R/Bal. 8 mm Rear R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. _____ D.O.I. 27-12-19

Survey held at w/s 4:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/3 COE: 47231
limited \$25190.04 with Allen.
(Red: 17461.91, 40%)

RECEIVED

Date/Time, File Pass to?

11/12/3 Typist

Date/Time, File Return to?

3

Date/Time, File Return to?

Long Sum / R.R. is 25190.04

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Mech. Insp (\$)

Survey Fee:

Transportation:

8 + RS \$

Flies

Obst

FILE

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 27 December 2019 9:08 AM
To: 'assignments@lkkauto.com'
Cc: MT_Claim_SG; 'tan lay keng'
Subject: FW: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE [External Confidential]
Attachments: 27122019090617.pdf

Lonpac External - Confidential


Dear Nivitha,

Please see attached and proceed as requested.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: tan lay keng [mailto:tanlaykengandco@gmail.com]
Sent: Thursday, 26 December 2019 5:38 pm
To: GERALD POH WEE BIN
Subject: Re: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE [External General]

Dear Mr Gerald Poh

Our client has decided on no. 10 (Adrian Ling - LKK).

Best Regards

Raymond Ng

On Thu, Dec 26, 2019 at 10:31 AM GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Lonpac External - General

WITHOUT PREJUDICE

Our Ref : 19/19/20/VP05/022821

Dear Sirs,

Please see our list of Motor surveyors and revert.

1	Nicholas Tey-Appraisal
2	Jackson Quek - Appraisal
3	Faizal Gulam Mohd _ Appraisal[
4	Steve Chen- LKK
5	Kalvin Ang - LKK
6	Mohd Taufik - LKK
7	Kenneth Kong- LKK
8	Marcus Chua) LKK
9	Mohd Rasul -LKK
10	Adrian Ling - LKK


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: tan lay keng [mailto:tanlaykengandco@gmail.com]

Sent: Tuesday, 24 December 2019 11:42 am

To: MT_Claim_SG

Subject: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE

Motor Claims Department

Lonpac Insurance Bhd

Singapore

Dear Sirs

Attached is our letter dated 24 Dec 2019.

Rgds

Raymond Ng

Tan Lay Keng & Co

RN.bh.0048.15.V6

Denise Tay (LKKAUTO)


From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 12 March 2020 4:51 PM
To: Denise Tay (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE [External Confidential]

Lonpac External - Confidential

HI Denise,

Our reference is 19/19/20/VP05/022821

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 12 March 2020 4:45 pm
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; GERALD POH WEE BIN <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE [External Confidential]

Dear All,

Please provide your ref no.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Monday, 30 December 2019 5:34 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE [External Confidential]

Tan Lay Keng & Co.

Advocates & Solicitors * Commissioners for Oaths * Notaries Public * Trade Mark Agents

Tan Lay Keng LL.B. (Hong), (Singapore)

Raymond Y.E. Ng LL.B. (Hong), LL.M. (Singapore)

Your Ref:

Our Ref: RN.bh.0048.15.V6

24 December 2019



111 North Bridge Road
#14-03 Peninsula Plaza
Singapore 179098
Tel: 6338 2388, 6338 3330
Fax: 6338 3730
UEN No. 53131292E

Motor Claims Department
Lonpac Insurance Bhd
300 Beach Road #17-04
The Concourse
Singapore 199555

By Email
mt_claim@lonpac.com

Dear Sirs

Accident on 23.12.2019 involving SJT 90R, SMA 1661B and
SFB 95U along PIE towards CTE

We are instructed by the owner of motor vehicle No. SJT 90R.

You are the insurers of motor vehicle No. SMA 1661B.

We are instructed to give you 48 Hours' Notice for the pre-repair inspection under NIMA protocol of the damage to our client's motor vehicle before any repairs are carried out.

Our client's car may be inspected at Cheng Motor Work Company at 1 Kaki Bukit Avenue 6 #01-83, Singapore 417883. Contact person : Mr Alan Tan Tel: 6555 1185 / 9671 3335.

Yours faithfully

cc client

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 30 December 2019 5:34 PM
To: Admin-D (LKKAuto); 'GERALD POH WEE BIN'; assignments
Cc: 'MT_Claim_SG'; SUR
Subject: RE: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE [External Confidential]
Attachments: PRELI ADVISED OF SJT 90R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJT 90R**
Number of days (estimated) : 12 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 27 December 2019 11:45 AM
To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: Accident on 23.12.2019 involving SJT 90R, SMA 1661B and SFB 95U along PIE [External Confidential]

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that due to the unavailability of the the appointed surveyor Mr.Adrian,

Repairer agreed another surveyor of ours to survey this vehicle.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: TBA

Date: 30/12/2019

Our Ref: CS/LPC19022763/Gtd3

The Motor Claims Department
LONPAC INSURANCE BHD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SJT 90R.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 27/12/2019 at the premises of M/s Cheng Motor Work Co. and have the following to report: -

Workshop Estimate Amount	: S\$ 39,503.15
Revised Estimate Amount	: S\$ 16,639.95
"Check" Items Amount	: S\$ 15,882.30
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Repair days: 12

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Guo Qiang

Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renege policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for retaining and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as needed.

ACCIDENT STATEMENT

Date Of Report 24/12/2019 09:37
Date Of Accident 23/12/2019 17:35
Exact Location Of Accident ALONG PIE TWRDS CTE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJT90R
Insured/Policyholder
Name Of Registered Owner TAY TZEE NGANN BENJAMIN(ZHENG ZHIYAN BENJAMIN)
NRIC No SXXXX067G
Email Address BEN@YESIR.COM.SG
Mobile Phone No (LOCAL) +65-97865500
Alternative Phone No OTHERS-97865500

Vehicle Particulars

Manufacturer HONDA
Model SHUTTLE HYBRID 1.5 AUTO

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5111266584
Cover Note Number

Driver

Name of Driver TAY TZEE NGANN BENJAMIN(ZHENG ZHIYAN BENJAMIN)
NRIC No SXXXX067G
Date Of Birth 31/07/1980
Occupation INDOOR
Date Of Driving Pass 02/12/2000
Driving Experience 19 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97865500
Fax Number
Contact Number OTHERS-97865500
Email Address BEN@YESIR.COM.SG

Address	679 CHANGI ROAD
Postcode	419959
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	
Insurance Company of Driver's Own Vehicle	

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA1661B
Vehicle Make/Model/Colour	HYUNDAI / I30 PDE 1.4 T-GDI DCT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFB95U
-----------------------------	--------

Vehicle Make/Model/Colour

VOLVO / S60 T5 A/T ABS D/AIRBAG 2WD

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the incident to your insurer's claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as correct and accurate as possible. Any willful misrepresentation or withholding of material facts may prove grounds for companies to repudiate policy liability.
4. The issue and signing of this Form by the relevant companies is not an admission of policy liability on the part of the insurers or companies.
5. Any later reduction may be referred to the Police for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report or the company's endorsement to the signing of this report at the centre and to copies of this report being made available thereafter:
8. Consent under the Personal Data Protection Act (PDPA):
 - (a) I, the Policyholder, agree and consent that:
 - (i) the insurers and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, process and/or process my personal data (which information will put in this Form) and any other personal information (which information is provided by me, such as, but not limited to the "Personal Information") and disclose and transfer such personal data (which information) to their third party service providers involved in this accident (all insurers) who have insured vehicles involved in this accident and be collected, referred to as the "Insurers", the insurers' lawyers/law firms, the General Insurance Association of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - (i) in settling, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) to prevent fraud, the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internal cover of correspondence; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) Insurers who have insured vehicles involved in the accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my personal information for one or more of the above Purposes; and
 - (c) My Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be stored outside of Singapore, for one or more of the above Purposes.
 - (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, underwriting and management in present and future claims.
 - (e) The information collected under this Form may be shared with:
 - (i) all insurers and/or any other third parties that assist in evaluating, investigating, settling or managing fraud, reduction of loss and/or other and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Accident's Signature
Date & Time

Owner's Signature
(If different from the Policyholder)
Date & Time

IPAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 414033
Tel: 67418697 Fax: 67492306
Email: ipac.kbk@vacor.com.sg
Reporting Centre Personnel's Signature
Name:
VAC/IN No: 7-10-2013

Accident Sketch Plan

SWITCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

Now we can begin highlighting particulars, like this, in every respect:

© 2000 Blackwell Science Ltd

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 674 66997 Fax: 67492305

Email: info@updown.com.sg

Regarded (Printed Name) _____ Signature _____

4

ARTICLE 10

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	067G
Vehicle No:	SJT90R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2018
Engine No:	LEB7102666
Chassis No:	GP72001919
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,955.00
Original Registration Date:	23 Jul 2019
First Registration Date:	23 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$12,737.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2029
PARF Rebate Amount:	\$9,552.00
COE Expiry Date:	22 Jul 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period (years):	10
QP Paid:	\$39,406.00
COE Rebate Amount:	\$37,679.00
Total Rebate Amount:	\$47,231.00

The information contained herein is correct as at 29 Dec 2019

OK

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

Lonpac Insurance Bhd.
300 Beach Road #17-04
The Concourse
Singapore 199555

Estimate Cost of Repair Vehicle No: SJT 90 R

Rear Bumper	✓ RL	1385.70	1150.6
2pcs Rear Bumper side retainer \$51.50x2	✓ RL	103.00	53
2pcs Rear Bumper side clip	✓ RL	10.40	—
12pcs Rear Bumper lower garnish Clip	✓ RL	52.40	20
2pcs rear bumper reflector \$55.20x2	✓ RL	110.40	45
2pcs rear bumper reflector grille \$151.80x2	✓ RL	303.60	45
Rear bumper tow cover	✓ RL	88.55	—
2pcs rear bumper sponge \$102.60x2	✓ RL	205.20	84
Rear End Panel	✓ RL	599.40	—
Rear End Panel top garnish	✓ RL	282.40	155.5
4pcs End Panel Clip	✓ RL	20.80	10
Rear windscreen moulding	✓ RL	267.40	100
Tailgate	✓ RL	1368.70	1193.7
Tailgate moulding chrome	✓ RL	383.10	—
Tailgate weatherstrip	✓ RL	168.50	—
Tail gate top lock	✓ RL	198.90	157.5
Tail gate lower lock	✓ RL	89.90	X
Tail gate emblem 'LOGO'	✓ RL	50.30	38.5
Tail gate emblem 'SHUTTLE'	✓ RL	54.70	—
Tailgate emblem HYBRID	✓ RL	80.10	48
Tailgate inner trim holder	✓ RL	54.80	X
Rear wiper motor	✓ RL	390.00	X
Rear wiper blade	✓ RL	66.50	X
Rear wiper arm	✓ RL	95.50	X
2pcs tail gate reflector lamp \$340.80x2	✓ RL	681.60	—
Tail gate inner garnish	✓ RL	320.00	—
Rear muffler (exhaust pipe)	✓ RL	693.70	X
2pcs tail lamp \$569.20x2	✓ RL	1138.40	—
2pcs Rear end panel extension \$385x2	✓ RL	770.00	—
Keyless sensor	✓ RL	157.80	—
Keyless replay	✓ RL	145.90	X

LOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- 26/12/2019
- Part(s) subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7423.25

42651.95

Spare tyre wheel house Panel	✓ PHS	956.00	/
Spare tyre top wooden pad	X		
Rear mudguard inner shield R/h	✓ NN	147.50	/
10 pcs inner shield clip	X	35.00	X
2pc Tailgate number lamp \$38.50x2	X	77.00	X
2pc tail lamp panel \$210.20x2	X	420.40	X
2pcs rear mudguard inner trim \$489.60x2	✓ PRR	979.20	/
Sponge tool lid	✓ Cut	350.00	165
Cargo box	✓ Cut	295.00	/
Box cargo floor	✓ Cut	350.00	/
Front Radiator support panel	✓ BT	785.00	605
2pcs Support panel side garnish \$38x2	✓ CRA	76.00	/
Radiator assy	✓ BT	1540.00	/
Radiator fan motor	✓ NW	329.80	/
Radiator fan motor blade	✓ Cut	78.00	/
Radiator fan crowing	✓	115.00	/
Air con condenser	✓ BT	985.00	/
Air con condenser motor	✓ NW	330.00	/
Air con condenser motor crowing	✓ Cut	121.90	/
Front bonnet	✓ BT	980.80	920.8
Front bonnet insulator	X NN	140.00	X
10pc insulator clip	✓ NW	35.00	/
Bonnet rubber	X NN	27.40	X
Bonnet beam stay		45.00	X
Front grille	✓ CRA	395.00	/
Front grille chrome top	✓ CRA	362.50	302.8
Front grille chrome bottom	✓	220.70	/
6pcs front grille clip	✓ NW	21.00	/
2pcs Front Headlamp \$2250x2	✓ CRA	4500.00	/
2pcs front headlamp top garnish \$55.10x2	X NW	110.20	X
2pcs front headlamp bracket garnish \$38x2	✓ CRA	76.00	/
2pcs Front fender \$435x2	✓ BUC	870.00	/
2pcs fender inner shield \$110.50x2	X NW	221.00	X
Front bumper	✓	1050.00	/
2pc front bumper side retainer \$15.40x2	✓	30.80	/
2pc front bumper front retainer \$38x2	✓	76.00	X
Front bumper tow cover	✓	25.00	/
Front bumper reinforcement	✓ BT	420.90	/
2pcs Front fog lamp cover \$95x2	✓ Cut	190.00	50
2pcs front bumper grille \$95x2	✓ Cut	190.00	90
Wiper washer tank	X	75.00	X
Wiper washer tank motor	X	59.60	X
2pcs Front wheel house \$319x2	X Repair	638.00	X
2pc front wheel house extension panel outer	X	300.00	X

16081.4

2pc front wheel house extension panel inner X 300.00
 2pcs wheel house panel \$234.90x2 X 469.80
 Front engine mounting R/h X 280.00
 Front sensing sensor X
 Front sensing relay X

25187.55

20%: 20150.04

S/nett items

Rear windscreen sealant / MC
 2pc number plate / SR
 Reverse Camera X NN
 Reverse SENSOR / DM
 Radiator coolant / MC

60.00 40
 80.00 40
 700.00 X
 400.00 200
 60.00 30

310

To remove, cut out front and rear portion, jack out, straighten,
 Repair both rear chassis members, wheel houses, welding, align
 And renew replaced parts

To spray Paint front and rear portion.

To undersealing damaged front and rear portion

To apply rust-proofing on repaired, replaced panel

To dismantle & refit rear windscreen for repaired

To dismantle/transfer tailgate component

To dismantle & renew exhaust muffler

To dismantle/refit new Reverser Sensor

To dismantle /refit new reverse camera

To remove, refit rear seat, carpet and trims.

To check wiring (front and rear)

To dismantle/renew aircon condenser and refill gas

To remove, refix fuel tank

To remove, renew radiator, fan motor

To clean up the interior and shampoo

3500.00 2000 - 2400
 2800.00 1800
 300.00 60
 200.00 60
 150.00 100
 150.00 60
 150.00 60
 150.00 60
 100.00 40
 150.00 40
 380.00 80
 150.00 30
 150.00 60
 150.00 60
 150.00 40
 200.00 X - NN

4490

25190.04

~~3000.00~~

12 Days.

part by mt.

refue paint photos.

Gmo Qiang - 82 88 0282

27/12/19.

30/12/19

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83
SINGAPORE 417883
Tel:65551185/6 Fax:65551184
H/P: 96713335
E-mail:chengmotor27@yahoo.com

Lonpac Insurance Bhd
300 Beach Road #17-04
The Concourse
Singapore 199555

30/12/2019

Supplementary estimate cost of repair vehicle no: SJT 90 R

2pc front bonnet hinge \$45x2	BT	90.00	/
2pc front fender bracket \$49x2	X NA	98.00	X
1pc spare tyre Stiffener	X Repair	105.00	X
1pc Spare tyre wheel house Plug air core big	1	30.00	/
1pcs Spare tyre wheel house plug air core small	2	25.00	/
2pcs Spare tyre panel rubber cover \$15x2	3	30.00	/
4pcs Spare tyre panel Pug 25mm \$10x4	4	40.00	/

245

~~200~~
10

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83
SINGAPORE 417883
Tel:65551185/6 Fax:65551184
H/P: 96713335
E-mail:chengmotor27@yahoo.com

Lonpac Insurance Bhd
300 Beach Road #17-04
The Concourse
Singapore 199555

30/12/2019

Supplementary estimate cost of repair vehicle no: SJT 90 R

Front bumper lower grille ✓ <i>Cut</i>	140.00	✓
Support panel top panel ✓ <i>RT</i>	180.00	✓
Radiator grille top cover ✓ <i>Cut CPA</i>	58.20	48.3
Air duct ✓ <i>Cut</i>	80.60	✓
Radiator grille center bracket ✓ <i>RT</i>	65.00	✓
Radiator Grille logo logo <i>mis</i>	320.00	23.4
Radiator Grille logo base ✓ <i>Cut</i>	27.50	✓
Bonnet lock ✓ <i>RT</i>	135.00	✓
Temperature sensor ✓ <i>DM</i>	48.50	✓
Spare tank ✓ <i>ee</i>	71.40	✓
2pcs front fender HYBRID EMBLEM \$58x2 ✓ <i>ABC</i>	116.00	✓
Guawiper garnish ✓ <i>Cut</i>	241.10	✓
Guawiper side garnish r/h ✓ <i>ee</i>	15.00	✓
2pc front windscreen side moulding \$155.80x2 ✓ <i>ABC</i>	311.60	190.3
Box cargo side cover ✓ <i>ee</i>	85.80	✓
Labor for remove/refit Hybird Battery for knocking		
Spare tyre wheel house ✓	480.00	✓
To re-program hybrid battery ✓	380.00	✓
To re-program Radar sensor distant ✓	380.00	✓

1467.9

240

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

Lonpac Insurance Bhd.
300 Beach Road #17-04
The Concourse
Singapore 199555

Estimate Cost of Repair Vehicle No: SJT 90 R

Rear Bumper	✓ RL	RH ✓	1385.70
2pcs Rear Bumper side retainer \$51.50x2			103.00
2pcs Rear Bumper side clip	✓ RL		10.40
12pcs Rear Bumper lower garnish Clip	✓ RL		52.40
2pcs rear bumper reflector \$55.20x2		✓ RH	110.40
2pcs rear bumper reflector grille \$151.80x2		✓ RH	303.60
Rear bumper tow cover	✓ RL		38.55
2pcs rear bumper sponge \$102.60x2	✓ RL		205.20
Rear End Panel	✓ RL		599.40
Rear End Panel top garnish	✓ RL		282.40
4pcs End Panel Clip	✓ RL		20.80
Rear windscreen moulding	✓ RL		267.40
Tailgate	✓ RL		1368.70
Tailgate moulding chrome			383.10
Tailgate weatherstrip	✓ RL		168.50
Tail gate top lock	✓ RL		198.90
Tail gate lower lock	X		89.90
Tail gate emblem 'LOGO'	✓ RL		50.30
Tail gate emblem 'SHUTTLE'	✓ RL		54.70
Tailgate emblem HYBRID	✓ RL		80.10
Tailgate inner trim holder	7		54.80
Rear wiper motor	X		390.00
Rear wiper blade	X		66.50
Rear wiper arm	X		95.50
2pcs tail gate reflector lamp \$340.80x2	✓ RL		681.60
Tail gate inner garnish	✓ RL		320.00
Rear muffler (exhaust pipe)	X repair		693.70
2pcs tail lamp \$569.20x2	✓ RL		1138.40
2pcs Rear end panel extension \$385x2	✓ RL		770.00
Keyless sensor	✓ RL		157.80
Keyless replay	X		145.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part(s) are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Spare tyre wheel house Panel	✓ P's	956.00
Spare tyre top wooden pad	X	
Rear mudguard inner shield R/h	✓ TN	147.50
10 pcs inner shield clip	X	35.00
2pc Tailgate number lamp S38.50x2	X	77.00
2pc tail lamp panel S210.20x2	X	420.40
2pcs rear mudguard inner trim S489.60x2	✓ BR	979.20
Sponge tool lid	✓ Cut	350.00
Cargo box	Color cut	295.00
Box cargo floor	R cut	350.00
Front Radiator support panel	✓ BT	785.00
2pcs Support panel side garnish S38x2	✓ CAA	76.00
Radiator assy	✓ BT	1540.00
Radiator fan motor	✓ NW	329.80
Radiator fan motor blade	✓ Cut	78.00
Radiator fan crowing	✓ BT	115.00
Air con condenser	✓ NW	985.00
Air con condenser motor	✓ Cut	330.00
Air con condenser motor crowing	✓ Cut	121.90
Front bonnet	✓ BT	980.80
Front bonnet insulator	X	140.00
10pc insulator clip	✓ MC	35.00
Bonnet rubber	X	27.40
Bonnet beam stay	X	45.00
Front grille	✓ CAA	395.00
Front grille chrome top	✓ CAA	362.50
Front grille chrome bottom	✓ MC	220.70
6pcs front grille clip	✓ MC	21.00
2pcs Front Headlamp S2250x2	✓ CAA	4500.00
2pcs front headlamp top garnish S55.10x2	X	110.20
2pcs front headlamp bracket garnish S38x2	✓ CAA	76.00
2pcs Front fender S435x2	✓ Buc	870.00
2pcs fender inner shield S110.50x2	X	221.00
Front bumper	✓ RL	1050.00
2pc front bumper side retainer S15.40x2	✓ RL	30.80
2pc front bumper front retainer S38x2	✓ X	76.00
Front bumper tow cover	✓ RL	25.00
Front bumper reinforcement	✓ BT	420.90
2pcs Front fog lamp cover S95x2	✓ Cut	190.00
2pcs front bumper grille S95x2	✓ Cut	190.00
Wiper washer tank	X	75.00
Wiper washer tank motor	X	59.60
2pcs Front wheel house S319x2	X Repair	638.00
2pc front wheel house extension panel outer	X	200.00

2pc front wheel house extension panel inner	X	300.00
2pcs wheel house panel \$234.90x2	X	469.80
Front engine mounting R/h	X	280.00
Front sensing sensor	X	
Front sensing relay		

S/nett items

Rear windscreen sealant	/	REC	60.00
2pc number plate	/		80.00
Reverse Camera	X		700.00
Reverse SENSOR	/		400.00
Radiator coolant	/		60.00

To remove, cut out front and rear portion, jack out, straighten,
Repair both rear chassis members, wheel houses, welding, align
And renew replaced parts

To spray Paint front and rear portion.

To undersealing damaged front and rear portion.

To apply rust-proofing on repaired, replaced panel

To dismantle & refit rear windscreen for repaired

To dismantle/transfer tailgate component

To dismantle & renew exhaust muffler

To dismantle/refit new Reverser Sensor

To dismantle /refit new reverse camera

To remove, refit rear seat, carpet and trims.

To check wiring (front and rear)

To dismantle/renew aircon condenser and refill gas

To remove, refix fuel tank

To remove, renew radiator, fan motor

To clean up the interior and shampoo

3500.00	2000 - 2400
2800.00	1800
300.00	60
200.00	60
150.00	100
150.00	60
150.00	60
100.00	40
150.00	40
380.00	80
150.00	30
150.00	60 60
150.00	60
150.00	40
200.00	X

12 Days -

part by part -

refue part photos -

Gmo Qiang - 82 88 0282

27/12/19 -