22/03/2002 -	\$ 1 X 1	*		
ASS. REC. BY		section:		
Surveyor:	CENTRAL ASSIGNMENT (Office)			
From (Person	a): 8 ubrumonian Divya shini of MG Date/Ti	ine: 27/12/190 917cm		
Estimate Co.				
OD FTD W	STTP RES / OD RES / EVA / INV / MV / CS			
	ehicle No: SKS 10466 Insured:	SKV7930Z		
at Workshop		833008 .		
of				
Policy No:		3555175 9003		
Sum Insured;				
Make of Veh: (Client's Record	E DOA	22/12/19		
CA / REV	/ REP. / REV 24 HRS	D 17 1		
Date/Time: 11:63am@ 27 12/19 Person Contacted: Mr. Chory Vehicle IN OUT				
	Vehicle	тинопт		
Date/Time	Action/Instruction Tohonoly			
SKV 79302 506/A1G17620243/Uhq3g2 DOA 30/10/2017				
	SKS TOAGG X			
03/01/201	@ 11.48 on Mr Chang will check the extinute we	rather veeling.		
		0		
· 7/2	61 Pmg & 26501 eneil			
	1 5 0000 CHEIL			

.

ASS. REC. BY: REF: AG	
- //	
Kenneth	ASSIGNMENT
From: Date:	
Estimated Cost:	Veh No: SKS 10466 Yr Regn: 03 15
OD / P WS / TP RES / OD RES / EVA / INV / MV	
To Inspect Vehicle No:	Truck / Traller or
at Workshop m/s	Make: NIS April CC 14Pf
of they go her	Colour M. Come AC: Insured / Std / NI / NA
Insured:	Sp.Reading 875.61 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No;
Claims No.	CNO: MNTBBAN1770500076
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inordet PJammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: NII / S/RIm / STD/A/Rim or
(Policy Condition)	Tyre Size: F: 185/65R13
Remark: The yeh had command to	R: 400/10
repair at the time of inspection.	O/S BS / DUN / EXNOVA / GY / FS / LIZA V MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	TOYOTYOKO or Winrun
IDAC Accident Rport: Consistent? : Yes or No	Fron! Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal, 9 mm R/Bal. S
Est. Repairs: 5 days Res.: Yes or No	L/Bal. 9 mm L/Bal. 9 mm
Lum Sum: % 3 Val.: Yes or No	D.O.A. 22/12/19 D.O.I. 27/12/19
CONTRACTOR OF THE PROPERTY OF	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt Rear O/S N/S U/C Rooftop or
Date:Person Contacted: Vehicle: IN / O	140- 1/5
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
File pass To	
27/12 Est not ready	
Submit LS \$2650, 5 days	
(Red \$5481, 67%)	
Oate/Time, File Pass to?	
22/07 Typiot Prell. Report	Days Of Repair: 5
1) 23/07 Typist : Final Report	Resuprov No47
Add Fee	9: Site Insp (\$) S.RS CI
Parad F	I Intendeur /\$
Report Format: MER-TP	Tech love (\$
Lump Sum / L.D.I. (5 2650	Weekend (\$
6 October 1987 (1987)	
	- 107AL

PRE-REPAIR INSPECTION REQUEST - SKS1046G vs SKV7930Z (OI) on D.O.A.: 22/12/2019

From: Subramaniam, Divyashni

Ta: assignments@lkkauto.com, Admin A

Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Hor, Yinrul, boo@kurupn Ce:

12/27/2019 9:17:15 AM Sent:

Attachments: 3445.EMAIL.24.12.19.pdf 3445.EMAIL.24.12.19.pdf

Hi,

Please refer to the enclosed request from Kurup & Boo.

Claim no Case Owner

: 0644355517SG003 : Chee Heng Loh

If you have any queries/concerns, please let us know.

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thank you.

Best Regards.

Divyashni Subramaniam

AIG

Claim Adjuster II. Singapore FNOL, Claims Operations - Auto

Divyashni.Subramaniam@aig.com | www.aig.sg

From: boo@kurupnboo.com.sg <boo@kurupnboo.com.sg>

Sent: Thursday, December 26, 2019 4:18 PM

To: Subramaniam, Divyashni < Divyashni, Subramaniam@aig.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina

<Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur

<ashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; boo@kurupnboo.com.sg

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV7930Z AND SKS1046G ON 22/12/2019

Our Ref : BMC.3445.19.wh

26 December 2019

AIG Asia Pacific Insurance Pte Ltd.

Dear Sirs

We refer to your email dated 26 December 2019.

We are instructed to appoint Mr Kenneth Kong of LKK Auto Consultants Pte Ltd for the pre repair inspection.

Regards

Boo Moh Cheh

Kurup & Boo

111 North Bridge Road

#15-03 Peninsula Plaza

Singapore 179098

Tel: 6223 3343 Fax: 62257248

From: Subramaniam, Divyashni

Sent: Thu, 26 Dec 2019 04:50:50 +0000 To: Boo Moh Cheh

Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni,

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV7930Z AND SKS1046G ON 22/12/2019

Without Prejudice

Your Reference : BMC.3445.19.wh Our Reference: 0644355517SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Divyashni Subramaniam

AIG

Claim Adjuster II, Singapore FNOL. Claims Operations - Auto

Divyashni,Subramaniam@aig.com | www.aig.sg

From: Boo Moh Cheh <boo@kurupnboo.com.sg>

Sent: Tuesday, December 24, 2019 9:39 AM

To: AIG SGP, Claims-Survey < AIGSGP Claims Survey@aig.com>

Subject: [EXTERNAL] Our Ref: BMC.3445.19.wh

This message is from an external sender; be cautious with links and attachments.

Our Ref : BMC.3445,19,wh

Your Ref: Insured vehicle no. SKV 7930Z

24 December 2019

AIG Asia Pacific Insurance Pte Ltd

Dear Sirs

REQUEST FOR PRE REPAIR INSPECTION ACCIDENT INVOLVING VEHICLE NO. SKS 1046G AND SKV 7930Z AT JUNCTION OF TAMPINES AVENUE 9 AND AVENUE 7 ON **22 DECEMBER 2019**

We attach a copy of our letter today for your attention.

Regards

Boo Moh Cheh Kurup & Boo 111 North Bridge Road #15-03 Peninsula Plaza Singapore 179098 Tel: 6223 3343 Fax: 6225 7248

From: Divyashni.Subramaniam@aig.com

To: boo@kurupnboo.com.sg

Without Prejudice

Your Reference : BMC.3445.19.wh Our Reference : 0644355517SG003

Dear Sir/Madam.

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Divyashni Subramaniam

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Boo Moh Cheh < boo@kurupnboo.com.sg>

Sent: Tuesday, December 24, 2019 9:39 AM

To: AIG SGP, Claims-Survey < AIGSGP_ClaimsSurvey@aig.com>

Subject: [EXTERNAL] Our Ref : BMC.3445.19.wh

This message is from an external sender; be cautious with links and attachments.

Our Ref ; BMC.3445.19.wh

Your Ref : Insured vehicle no, SKV 7930Z

24 December 2019

AIG Asia Pacific Insurance Pte Ltd

Dear Sirs

REQUEST FOR PRE REPAIR INSPECTION
ACCIDENT INVOLVING VEHICLE NO. SKS 1046G AND SKV 7930Z
AT JUNCTION OF TAMPINES AVENUE 9 AND AVENUE 7 ON
22 DECEMBER 2019

We attach a copy of our letter today for your attention.

Regards

Boo Moh Cheh Kurup & Boo 111 North Bridge Road #15-03 Peninsula Plaza Singapore 179098 Tel: 6223 3343 Fax: 6225 7248

KURUP & BOO

UEN 53130914B ADVOCATE & SOLICITOR COMMISSIONER FOR OATHS NOTARY PUBLIC #15-03 Peninsula Plaza Singapore 179098 Tel. No. 6223 3343 6221 8623 Fax. No. 6225 7248

Writer's e-mail : boo@kurupnboo.com.sg

Our Ref : BMC.3445.19.wh

Your Ref: Insured vehicle no.SKV 7930Z

24 December 2019

URGENT

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Via Email aigsgp_claimssurvey@aig.com and BY HAND

Dear Sirs

ACCIDENT INVOLVING VEHICLE NO. SKS 1046G AND SKV 7930Z AT JUNCTION OF TAMPINES AVENUE 9 AND AVENUE 7 ON 22 DECEMBER 2019

We act for Apoh Trading Pte Ltd, the owner of the vehicle no. SKG 1046G which was involved in the above accident.

For your immediate attention, we attach a copy of the Singapore Accident Statement lodged by or on behalf of our client.

By way of notice, we inform you that our client damaged vehicle is now in the workshop named below:

Heng Yap Seng Auto Services

Block 160, Sin Ming Drive #08-13 Sin Ming AutoCity Singapore 575722

Contact: Mr Chong Han Meng

HP No.: 9183 3008 Fax: 6873 2017

We hereby give you **two days**' notice for your representative to go the above workshop to inspect our client's damaged vehicle. Kindly contact Mr Chong Han Meng prior to going to the workshop for the survey.

Yours faithfully

воо мон снен

enc

cc Heng Yap Seng Auto Service

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722 Tel: 6266 9511 Fax: 6266 9512 NOT Whairs Many 8 2650h Runny After Paint 5day SKS1046G Vehicle No Vehicle Model NISSAN ALMERA Estimate Repair Cost Parts List Items No. Qty \$ 4 645.10 1 1 Rear bumper M 72.00 X 2 2 Rear bumper brackets MICHA 2 100.80 4 3 Rear bumper retainers NIPS 588.00 X 1 Rear bumper lower garnish 4 Rear bumper reverse sensor LH 224.00 5 1 40.00 6 1 set Rear bumper clips cms 535.90 Taillamp LH 7 1 By 102.40 8 1 Taillamp panel LH 2,5 1,104.00 Rear fender LH 9 1 72.40 1 Rear fender inner shield LH 10 Ju 254.40 X 11 1 Rear fender inner trim LH 1 454.30 K 12 1 Rear end panel 160 189.00 X 1 Rear end panel top garnish 13 \$ 788.70 ⊀ 14 1 Rear spare tyre compartment 5 m 270.00 4 15 Rear spare tyre top board 108 Total 5,441.00 Parts Special Nett Items 60.00 1 16 Rear number plate 60.00 \$ **Total Parts** 5,501.00 Labour 1,200.00 Fool Labour charge to remove, cut out damage portion, jack out, 1 straighten, panel beating, welding, align and renew replaced parts. 900.00 6001 \$ 2 To putty and respray painting on affected areas. 300.00 1001 To remove, replace rear fender fittings to facilitate repair. 3 To remove, replace rear reverse sensor, hence notify 150.00 301 \$ 4 the Repairer of the following: 80.00 201 To check wiring and lightings vey before the spray painting \$ 5 To display damaged part(s) during resurvey · Parts prices are subject to confirmation \$ 2,630.00 Total Labour Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed 8.131.00 \$ Supplementary item(s) must be Total Parts and Labour. is subject to final approval from Insurance Company Acknowledged by Repairer

> Signature: Date:

Enquire Vehicle Transfer Fee

Vehicle Details

-5	
	Vehicle No. SKS1046G
	Make / Model NISSAN / ALMERA 1.5 4AT ABS AIRBAG 2WD 4DR
	Vehicle Type : Z10 - Private Hire (Chauffeur) Motor Car
	Vehicle Attachment 1:
	No Attachment No Attachment
	Vehicle Scheme :
	Normal
	Chassis No.:
	MNTBBAN17Z0500076
	Propellant:
	Petrol
	Engine No.:
	HR15972877C
	Motor No.:
	Engine Capacity:
	1498 cc
	Power Rating :
	• Cover Nating .
	Maximum Power Output:
	73.0 kW (97 bhp)
	Maximum Laden Weight:
	1440 kg
	Unladen Weight: 1040 kg
	2010 1/8
	Year Of Manufacture :
	DD4.4

Original Registration Date :
26 Mar 2015
Lifespan Expiry Date :
COE Category:
A - Car up to 1600cc & 97kW (130bhp)
Quota Premium: \$64,700.00
COE Expiry Date :
25 Mar 2025
Road Tax Expiry Date :
25 Mar 2020
PARF Eligibility Expiry Date :
25 Mar 2025
Inspection Due Date :
25 Mar 2020
Intended Transfer Date :
07 Feb 2020
CO2 Emission :
159.00 (g/km)
CEV/VES Rebate Utilised Amount :
\$5,000.00
CO Emission :
HC Emission :
F)
NOx Emission :
PM Emission :

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (26 Mar 2020 to 25 Sep 2020)	
Road Tax Renewal - 12 months (26 Mar 2020 to 25 Mar 2021)	\$342.00
12 Months (20 Mai 2020 to 25 Mai 2021)	\$684.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.