

CLASS. REC. BY:

REP: CS/CT119022767/Brd352

Special Instruction:

Surveyor: Mr. Kim

ASSIGNMENT (Office)

Maximen

From (Person): Irene Tay

of CTI

Date/Time: 28/12/19 @ 6.19pm

Estimated Cost: Bill to:

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 9748L

Insured: GBH 5082P

at Workshop n/s Team AutoPRO

Tel: 6288 1955

of 160 Sin Ming Drive # 01-14

Policy No: DMCVSNA000018a1900

Claim No: SNM19D206114C02 / 7HP

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.17am @ 27/12/19

Person Contacted: peach

Vehicle  IN /  OUT

Date/Time	Action/Instruction
	Estimate ✓
	GBH 5082P X
	SJG 9748L X
9/1/2020	@ 1040am Peach said her estimator will contact surveyor
27/1/20	@ 226pm Peach said they submit \$ 5783

AGS. REC. BY: Mr Lim

REF: CT1

VENOM

### ASSIGNMENT

From: \_\_\_\_\_ Date: 27/12/2019

Veh No: SJG 9748 L Yr Regn: 22/7/2008

Estimated Cost: \_\_\_\_\_

Type:  Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  Truck /  Trailer or \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Make: Honda Fit 1.3G A c.c. 1339

To Inspect Vehicle No: SJG 9748 L

Colour: Black A/C: Insured / Std / NI / NA

at Workshop m/s Dean Auto Pro

Sp. Reading: 135551 T/Radio: Insured / Std / NI / NA

of 160 Sun King Drive # 01-14

Eng/No: L13A4101333

Insured: \_\_\_\_\_

C/No: GE61094730

Policy No. \_\_\_\_\_

Gen. Cond: Good / Fair /  Burnt

Claims No. \_\_\_\_\_

Steering: Inorder / Jammed / Leaked / Burnt or ?

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or ?

(Client's Record)

Make of Veh: Check on consistency of damages

Modi: Nil /  Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 195/55R15

R: 195/55R15

Bal. or Market Value: 19,000/2

BS /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /  TOYO /  YOKO or \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

Front R/Bal. 5 mm Rear R/Bal. 5 mm

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

L/Bal. 5 mm L/Bal. 5 mm

Est. Repairs: 19 days Res.: Yes or No

D.O.A. 23/12/19 D.O.I. 27/12/19

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at Dean Auto Pro

CA / REV / REP. / 24 HRS

Des. of Damages  Fr /  Rear  O/S /  N/S /  UIC /  Rooftop or \_\_\_\_\_

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Vehicle: IN / OUT

Date / Time	Action / Instruction
	Range <u>17,000/- - 18,000/2</u> w/s accepted car @ 5783/2 with 19 days. On 23/1/2020 @ 4:11pm <u>Terim Lim</u> 29/1/2020
	Lump sum <u>17,650/2</u>
	Recommendation - Beyond economical repair <u>Terim Lim</u> 6/1/2020
	MV <u>19,000/2</u>
	PV <u>13,217/2</u>
	NV <u>5,783/2</u>

RECEIVED 20 FEB 2020

*Handwritten signature and date: 8/1/2020*

*Handwritten signature and date: Terim Lim 30/1/19*

Date/Time, File Pass to?  : Preli. Report  : Final Report

Days Of Repair: 19 Resurvey No. of Trip: 4

Date/Time, File Return to? 2) 28/1 - typist

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)

Survey Fee:	
Transportation:	
S - RS - SI	
Photos	
Others	
TOTAL	

Rep. Format: menmen Lump Sum / U.C. / (F) RS \$ 5783

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	23 Dec 2019		26 Dec 2019 18:19 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	Q'SON KITCHEN EQUIPMENT PTE LTD, Co. Reg. No.: 199607070H								
Main Claimant:	SIA WEN HAN DANIEL, ID: S9120895D								
Vehicle Reg. No.:	SJG9748L	Date of Loss:	23/12/2019 19:00 - :59						
Claim Type:	TP / SNM19D206114C02/THP	Policy/Cover Note No.:	DMCVSNA00001891900 (Comprehensive) Coverage: 14/12/2019 - 13/12/2020						
Vehicle Reg. No. (Insured):	GBH5082P	Policy No. (Claimant):	18-MT105750-R00						
		Excess:	S\$500.00						
Repairer:	Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity, 575722 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/01/2020]								
Adj. Asg. Remarks:	Please survey third party and check on consistency of damages								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Thursday, 26 December 2019 5:52 PM  
**To:** teamautopl@gmail.com; 'assignments'; 'SUR'  
**Cc:** Irene Tay; Chee So Chow; Angie Foo; Lim Shu Min; Alfred Toh  
**Subject:** RE: OUR REF: SNM19D206114/GBH5082P/IRENE & YOUR REF: SJG9748L -PRS -2  
Days Notice: SJG 9748 L Dated 23rd December 2019  
**Attachments:** REPORT OF SJG9748L.pdf

*Without Prejudice*

Your Ref: SJG9748L  
Our Ref: SNM19D206114C02/2(thp)

Dear Sirs

We confirm LKK to be appointed to survey your client's vehicle.

Aside to M/s LKK Auto Consultants Pte Ltd., please assist to arrange for the survey.

Aside to Irene, please assist to follow up on the matter.

**Best Regards**

Alfred Toh  
Senior Executive  
Claims Department  
China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Thursday, 26 December, 2019 5:19 PM  
**To:** Alfred Toh <alfred.toh@sg.cntaiping.com>; teamautopl@gmail.com; Irene Tay <irene.tay@sg.cntaiping.com>  
**Subject:** OUR REF: SNM19D206114/GBH5082P/IRENE & YOUR REF: SJG9748L -PRS -2 Days Notice: SJG 9748 L Dated 23rd December 2019

Dear Alfred,

Please conduct PRS –SJG9748L soonest possible on behalf of Irene Tay.

Officer In Charge-Irene Tay –DID 6389 6192.

Dear Peach,

**\*\*\* kindly quote our reference number when replying\*\*\***

Regards

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website:[www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** TeamAutoPro North [<mailto:teamautopl@gmail.com>]

**Sent:** Thursday, 26 December, 2019 2:36 PM

**To:** Claims Dept of CTI

**Subject:** Re: 2 Days Notice: SJG 9748 L (Our Ref) and GBH 5082 P (Your Ref) Dated 23rd December 2019

Dear sir,

With regards to our 2 days notice sent on 24/12/2019, we have yet to receive your list of surveyors or confirmation if LKK Auto has been appointed.

Do note that the delay to this process will result in a higher demand of LOU/ LOR from our client.

Thank you.

--

\*The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.\*

Wish you Merry Christmas and Happy New Year

Cheers,

Peach

**Team AutoPro Pte Ltd**

Tel: 6258 1955

Fax: 6258 1956

**(Newly Shifted) Main Office:** 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

**Workshop/Survey Venue:** 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

On Tue, Dec 24, 2019 at 10:09 AM TeamAutoPro North <[teamautopl@gmail.com](mailto:teamautopl@gmail.com)> wrote:

Dear Sir/Madam,

**Road Traffic Accident Involving SJG 9748 L (Our Ref) and GBH 5082 P (Your Ref)**

**Dated 23<sup>rd</sup> December 2019, Time around 19:05HRS**

**@ BKE TOWARDS WOODLANDS AFTER MANDAI EXIT**

We represent our client; SIA WEN HAN DANIEL, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SJG 9748 L and your insured's vehicle registration number: GBH 5082 P.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel:-**

Contact Person	Eric Lee	8269 9999
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

--

\*The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.\*

Wish you Merry Christmas and Happy New Year

Cheers,  
Peach  
Team AutoPro Pte Ltd  
Tel: 6258 1955  
Fax: 6258 1956

**(Newly Shifted) Main Office:** 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722  
**Workshop/Survey Venue:** 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

Email: sm@idac.com.sg  
Tel no: 6555 6888 Fax no: 6454 3279

**Personal Particulars of Owner & Driver (Vehicle A)**

Date of Accident: 23/12/2019 (dd/mm/yy) Time of Accident: 19:05 (24-HR-FORMAT)  
Vehicle No.: SJG 9748 L Vehicle Make & Model: HONDA FIT 1.3G A  
Exact location of Accident: BKE TOWARDS WOODLANDS AFTER MANDAI EXIT  
Policyholder's Name / IC No.: SIA WEN HAN, DANIEL S9120895D  
Driver's Name / IC No.: SIA WEN HAN, DANIEL S9120895D (As Above)   
Driver's Contact No.: 9661 4979 Company Contact No.: \_\_\_\_\_  
Driver's Address: 204D PUNGGOL FIELD #11-348 S824204  
Insurance Company: TOKIO MARINE Email address (if any): \_\_\_\_\_

**Relationship between Owner & Driver:** OWNER or Others specify: \_\_\_\_\_

**What do you wish to claim? (Please TICK one only)**

Own Insurance /  Other Vehicle (The one you want to claim against) /  Reporting (For Record Purpose)

**Exact purpose for which the vehicle was being used at time of accident?**

Private use /  Work purpose

**Occupation (nature of job)**  Indoor /  Outdoor

**No. of Passengers (Including Driver):** 01

**Passenger Name :** \_\_\_\_\_  
**Passenger Name :** \_\_\_\_\_

**Gender :** \_\_\_\_\_  
**Gender :** \_\_\_\_\_

**Weather condition & Road conditions? (On the day of accident)**

Clear & Dry /  Raining & Wet /  After-Rain & Wet /  Drizzling & Wet / Others: \_\_\_\_\_

**Was there any video captured by your Car Camera?**  Yes /  No

**Any Injuries:**  Yes /  No (If YES) Injured Person' Name: \_\_\_\_\_

Injuries Sustain: \_\_\_\_\_ Injured Person in Which Vehicle: \_\_\_\_\_

**Police Report filed:**  Yes /  No (If YES) Which Police Station: \_\_\_\_\_

**The Other Party(s) Details:**

1. Driver's Name / IC No: \_\_\_\_\_ Vehicle No: GBH 5082 P (B)

Driver's Contact No: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

2. Driver's Name / IC No: \_\_\_\_\_ Vehicle No: SFT 473 S (C)

Driver's Contact No: \_\_\_\_\_ Insurance Company (If any): SJK5532C (D)

\*Independent Witness (If Any): \_\_\_\_\_ Contact No: \_\_\_\_\_

Preferred Workshop Name: \_\_\_\_\_ Contact No: \_\_\_\_\_

\*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	895D
Vehicle Details	
Vehicle No.:	SJG9748L
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L13A4101333
Chassis No.:	GE61094730
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,436.00
Original Registration Date:	22 Jul 2008
First Registration Date:	22 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$12,436.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$18,583.00
COE Rebate Amount:	\$13,217.00
Total Rebate Amount:	\$13,217.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Dec 2019

OK

3-7

Dep 5,210/yr  
434/mth

MV 19,000/2

PV 13,217/2

NV 5,783/2



Posted: 26-Nov-2019 Tags: 2008 Honda Fit, 2008 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda



**Honda Fit 1.3A G (COE till 08/2023)** - N.A 12-Aug-2008 1,339 cc - Hatchback **SOLD**

Great Condition, With No Repairs Needed. Seats Are Refurbished, New Sets Of Suspension Too! Comes With 4 New Tyres, And New Sports Rims Too. One Of The Best Unit In The Market. Great Fuel Efficiency Of 13Km/L Or More! Accident Free Unit And Also High Paper...

Tan Wei Auto Pte Ltd

Posted: 24-Dec-2019 Tags: 2008 Honda Fit, 2008 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda



**Honda Fit 1.3A G (COE till 08/2023)** - N.A 07-Aug-2008 1,339 cc - Hatchback **SOLD**

Bank Loan At 3.25% Only. 100% Loan At ONLY \$599 Per Month For 44 Months. 100% Loan Available, In House Or Bank Loan Available. Highest Trade In Available. Free Colour Choice And Free Leather Seat Upholstery, Grab Now! Price Negotiable, Please Call In For Appoin...

Posted: 10-Dec-2019 Tags: 2008 Honda Fit, 2008 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda



**Honda Fit 1.3A G (COE till 07/2023)** \$18,700 \$5,210 /yr 04-Aug-2008 1,339 cc 185,000 km Hatchback **Available**

Don't Miss Good Deal

Posted: 24-Dec-2019 Tags: 2008 Honda Fit, 2008 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

Back ( 1 ... 7 8 9 10 11 ... 12 ) Next >

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find used Honda, Honda Singapore, used Honda Singapore, used Honda, used vehicles Singapore or even buy used Honda Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

SJE : \_\_\_\_\_  
 Date of Survey : \_\_\_\_\_  
 Date of ReSurvey: \_\_\_\_\_ **After-Paint:** \_\_\_\_\_  
 Contacts : \_\_\_\_\_

Vehicle Nos : **SJG 9748 L**  
 Model : Honda Fit  
 Year : \_\_\_\_\_  
 Chassis No : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 985.00	\$ <del>985.00</del> 849.60	DD✓
2	Tailgate logo	1	\$ 86.20	\$ <del>86.20</del> 68.00	NECV
3	Tailgate inner lock	1	\$ 310.50	\$ <del>310.50</del> 289.00	JAMV
4	Tailgate striker	1	\$ 48.90	\$ <del>48.90</del> ✓ 48.90	BTV
5	Tailgate weatherstrip	1	\$ 186.20	\$ <del>186.20</del> ✓ 186.20	TNV
6	Tailgate inner trim board	1	\$ 358.40	\$ <del>358.40</del> 254.50	?BR
7	Tailgate inner handle	1	\$ 56.20	\$ <del>56.20</del> ✓ 56.20	P
8	Tailgate outer garnish	1	\$ 263.20	\$ <del>263.20</del> ✓ 263.20	BRV
9	Tailgate no plate lamp	2	\$ 88.50	\$ <del>177.00</del> ✓ 177.00	BTV
10	Tailgate solenoid switch	1	\$ 235.00	\$ <del>235.00</del> ✓ 235.00	SCV
11	Tailgate windscreen	1	\$ 980.00	\$ <del>980.00</del> ✓ 980.00	BRV
12	Tailgate windscreen moulding	1	\$ 132.60	\$ <del>132.60</del> ✓ 132.60	NECV
13	Tailgate windscreen wiper arm	1	\$ 143.50	\$ <del>143.50</del> ✓ 143.50	BTV
14	Tailgate windscreen wiper motor	1	\$ 289.30	\$ <del>289.30</del> ✓ 289.30	BRV
15	Tailgate windscreen wiper garnish	1	\$ 68.30	\$ <del>68.30</del> ✓ 68.30	DLV
16	Tailgate third brake lamp	1	\$ 268.70	\$ <del>268.70</del> 185.00	?BR✓
17	Rear bumper	1	\$ 976.40	\$ <del>976.40</del> 879.00	BRV
18	Rear bumper side retainer	2	\$ 87.50	\$ <del>175.00</del> ✓ 175.00	NECV
19	Rear bumper bracket	2	\$ 75.60	\$ <del>151.20</del> ✓ 151.20	BTV
20	Rear end panel	1	\$ 865.70	\$ <del>865.70</del> 492.90	DDV
21	Rear end panel top garnish	1	\$ 186.50	\$ <del>186.50</del> ✓ 186.50	DLV
22	Spare tyre panel	1	\$ 881.70	\$ <del>881.70</del> 737.00	DDV
23	Spare tyre panel top board	1	\$ 250.00	\$ <del>250.00</del> ✓ 250.00	?DISV
24	Spare tyre panel insulator	1	\$ 188.60	\$ <del>188.60</del> ✓ 188.60	?NSPX
25	Taillamp Rh	1	\$ 386.00	\$ <del>386.00</del> 305.00	BRV
26	Taillamp lower bracket Rh	1	\$ 85.00	\$ <del>85.00</del> ✓ 85.00	BRV
27	Taillamp base panel Rh	1	\$ 138.00	\$ <del>138.00</del> ✓ 138.00	DDV
28	Taillamp Lh	1	\$ 386.00	\$ <del>386.00</del> ✓ 386.00	BRV
29	Taillamp lower bracket Lh	1	\$ 85.00	\$ <del>85.00</del> ✓ 85.00	BRV
30	Taillamp panel Lh	1	\$ 138.00	\$ <del>138.00</del> ✓ 138.00	DDV
31	Rear fender Rh	1	\$ 648.40	\$ <del>648.40</del> ✓ 648.40	DDV
32	Rear fender inner trim Rh	1	\$ 350.00	\$ <del>350.00</del> ✓ 350.00	?BRV
33	Rear fender inner cowling	1	\$ 115.90	\$ <del>115.90</del> ✓ 115.90	?NDX
34	Rear fender quarter glass moulding	2	\$ 103.50	\$ <del>207.00</del> ✓ 207.00	NECV
35	Rear fender Lh	1	\$ 648.40	\$ <del>648.40</del> ✓ 648.40	DDV
36	Rear fender inner trim Lh	1	\$ 350.00	\$ <del>350.00</del> ✓ 350.00	?BRV
37	Exhaust pipe	1	\$ 1,036.00	\$ <del>1,036.00</del> 580.70	DDV
38	Exhaust pipe mounting	2	\$ 48.60	\$ <del>97.20</del> ✓ 97.20	BTV
39	Exhaust pipe heat shield	1	\$ 156.00	\$ <del>156.00</del> ✓ 156.00	BTV
40	Rear door lock assy Rh	1	\$ 286.30	\$ <del>286.30</del> ✓ 286.30	?RX
41	Rear spoiler	1	\$ 862.40	\$ <del>862.40</del> ✓ 862.40	NDX
42	Rear air vents	2	\$ 202.60	\$ <del>405.20</del> ✓ 405.20	BRV
43	Front bumper	1	\$ 1,532.00	\$ <del>1,532.00</del> 684.00	BRV

44	Front bumper reinforcement	1	\$ 365.20	\$ 365.20	✓	365.20	?BT ✓
45	Front bumper side retainier	2	\$ 86.40	\$ 104.00		172.80	NECV ✓
46	Front bumper lower grille	1	\$ 201.50	\$ 201.50	✓	201.50	BRV ✓
47	Front bumper emblem 'MUGEN'	1	\$ 120.40	\$ 120.40	✓	120.40	NECV ✓
48	Headlamp	2	\$ 1,253.10	\$ 1,570.00		2,506.20	BRV ✓
49	Headlamp lower bracket	2	\$ 268.70	\$ 172.00		537.40	BRV ✓
50	Front fender	2	\$ 571.00	\$ 958.30		1,916.60	BT ✓
51	Front bonnet	1	\$ 1,095.40	\$ 800.00		1,095.40	BRV ✓
52	Front bonnet lock	1	\$ 365.40	\$ 130.00		365.40	?HAM
53	Front support panel	1	\$ 685.30	\$ 589.00		685.30	?BT
54	Front support panel top garnish	1	\$ 298.30	\$ 298.30		298.30	?NSPX
55	Radiator	1	\$ 853.40	\$ 853.40	✓	853.40	?BT ✓
56	A/c condenser	1	\$ 836.20	\$ 792.00		836.20	?BT ✓
				Parts Sub Total :	\$ 18462.70	26,131.00	6841.50
				20% Discount	\$ 3692.54	5,226.20	
				<b>PARTS TOTAL :</b>	<b>\$ 14,770.16</b>	<b>20,904.80</b>	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$			
1	Sundries	1	\$ 60.00	\$ 60.00	NNX		
2	Rear bumper clips	1	\$ 50.00	\$ 30.00	} NEC ✓		
3	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00			
4	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00			
5	Tailgate outer garnish clips	1	\$ 50.00	\$ 30.00			
6	Tailgate windscreen clips	1	\$ 50.00	\$ 30.00			
7	Tailgate primer and cleaner	1	\$ 80.00	\$ 80.00		NNX	
8	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00	} NEC ✓		
9	Rear no plate	1	\$ 80.00	\$ 50.00			
10	Rear bumper reverse sensor	2	\$ 200.00	\$ 200.00	MIS ✓		
11	Rear end panel sealant	1	\$ 100.00	\$ 40.00	} NEC ✓		
12	Taillamp inner seal	2	\$ 80.00	\$ 80.00			
13	Taillamp clips Rh	1	\$ 50.00	\$ 30.00			
14	Taillamp clips Lh	1	\$ 50.00	\$ 30.00			
15	Rear fender inner trim clips Rh	1	\$ 50.00	\$ 30.00			
16	Rear fender inner trim clips Lh	1	\$ 50.00	\$ 30.00			
17	Rear fender inner cowling clips Rh	1	\$ 50.00	\$ 50.00	NNX		
18	Rear fender sealant	2	\$ 100.00	\$ 80.00	NECV ✓		
19	Spare tyre panel sealant	1	\$ 100.00	\$ 40.00	} NEC ✓		
20	Rear fender quarter glass clips	2	\$ 50.00	\$ 50.00			
21	Rear spoiler seal	1	\$ 50.00	\$ 30.00	} NEC ✓		
22	Radiator coolant	1	\$ 60.00	\$ 40.00			
23	A/c fluid	1	\$ 60.00	\$ 60.00	NECV ✓		
24	Front support panel sealant	1	\$ 80.00	\$ 30.00	NECV ✓		
25	Front bumper clips	1	\$ 50.00	\$ 30.00	} NEC ✓		
26	Front fender sealant	2	\$ 80.00	\$ 80.00			
27	Front bumper lower grille clips	1	\$ 50.00	\$ 30.00			
28	Front no plate	1	\$ 80.00	\$ 50.00			
				<b>SPECIAL NETT TOTAL :</b>	<b>\$ 1140.00</b>	<b>2,470.00</b>	

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 80.00	100.00
2	R&R rear windscreen	\$ 120.00	250.00
3	R&R upholstery	\$ 80.00	180.00
4	R&R exhaust pipe assy	\$ 120.00	250.00
5	R&R fuel tank	\$ 80.00	100.00
6	R&R rear fender quarter glass Lh and RH	\$ 160.00	150.00
7	R&R reverse sensor	\$ 60.00	80.00
8	Mount bench work	\$ 350.00	350.00
9	Rear Chasis alignment	\$ 300.00	300.00
10	Disconnect wire harness to facilitate repair, reconnect and check function	\$ 60.00	80.00
11	Rear Panel beat	\$ 1400.00	1,800.00
12	Rust proofing	\$ 60.00	150.00
13	Rear Spray painting	\$ 1400.00	1,800.00
14	R&R radiator	\$ 80.00	150.00
15	R&R a/c condenser	\$ 80.00	150.00
16	Front panel beat	\$ 800.00	1,200.00
17	Front spray painting	\$ 1000.00	1,200.00
<b>LABOUR TOTAL :</b>		<b>\$ 6,170.00</b>	<b>8,290.00</b>

Resurvey 30/12/19

1600hrs

TCLim Min

Lump sum repair

Repair days 17

PARTS TOTAL : \$ 14,770.16 20,904.80

SPECIAL NETT TOTAL : \$ 1,140.00 2,470.00

LABOUR TOTAL : \$ 6,170.00 8,290.00

**GRAND TOTAL : \$ 31,664.80**

22,080.00

@ 20 %

4,416.03

17664.13

L/S 17,650/2

TCLim Min  
6/1/2020

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2019		26 Dec 2019 18:19 <a href="#">Edit Adj Rpt</a>	<b>S\$5,783.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,783.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>Q'SON KITCHEN EQUIPMENT PTE LTD</b> , Co. Reg. No.: 199607070H								
Main Claimant:	<b>SIA WEN HAN DANIEL</b> , ID: S9120895D								
Vehicle Reg. No.:	<b>SJG9748L</b>	Date of Loss:	23/12/2019 19:00 - :59 <b>[137 Months and 1 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / SNM19D206114C02/THP</b>	Policy/Cover Note No.:	DMCVSNA00001891900 (Comprehensive) Coverage: 14/12/2019 - 13/12/2020						
Vehicle Reg. No. (Insured):	<b>GBH5082P</b>	Policy No. (Claimant):	18-MT105750-R00						
		Excess:	S\$500.00						
Repairer:	<b>Team Auto Pro Pte Ltd - Sin Ming (HQ)</b> 160 Sin Ming Drive #01-14 Sin Ming Autocity, 575722 Sin Ming - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Claimant's Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 07/01/2020]</b>								
Adj Asg. Remarks:	Please survey third party and check on consistency of damages								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJG9748L (SNM19D206114C02/THP)**  
**[GBH5082P]**  
**TP**  
**SIA WEN HAN DANIEL**  
**Dec 23 2019 7:00PM**  
**[Q'SON KITCHEN EQUIPMENT PTE LTD]**  
**Team Auto Pro Pte Ltd - Sin Ming**

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser ▾		
<b>Photos/Images</b>								3 per page ▾		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	28/02/20 09:35	<b>General View</b>					 Load PDF			
2	28/02/20 09:35	<b>Reinspection Photo (1)</b>					 Load PDF			
3	28/02/20 09:35	<b>Reinspection Photo (2)</b>					 Load PDF			
4	28/02/20 09:35	<b>Reinspection Photo (3)</b>					 Load PDF			
5	28/02/20 09:36	<b>Reinspection Photo (4)</b>					 Load PDF			
<b>Documentation</b>								1 per page ▾		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print		
1	26/12/19 18:16	<b>REPORT OF SJG9748L</b>					 Load PDF			
2	26/12/19 18:16	<b>Singapore Accident Statement</b>					 Load PDF			
3	26/12/19 18:17	<b>SFT473S</b>					 Load PDF			
4	26/12/19 18:17	<b>REPORT OF SKC5532C</b>					 Load PDF			

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI19022767/BVD3S2  
**Date:** 02/03/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00001891900  
**Claimant Vehicle No :** SJG9748L **Insured Vehicle No :** GBH5082P  
 Date of Loss: 23/12/2019 Nature of Claim: TP Claim No: SNM19D206114C02/THP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG9748L**  
 Make & Model: HONDA FIT, 1.3 G (A) Engine No: L13A4101333  
 Reg. Date: 22/07/2008 (Man. Year: 2008) Chassis No: GE61094730  
 Colour: Black Odometer: 135551 km  
 Engine Capacity: 1339 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Poor Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15  
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,374.80	16,517.68	6,857.12	29.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,290.00	6,170.00	2,120.00	25.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>31,664.80</b>	<b>22,687.68</b>	<b>8,977.12</b>	<b>28.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,783.00</b>		
<b>Nett Amount (S\$)</b>	<b>31,664.80</b>	<b>5,783.00</b>	<b>25,881.80</b>	<b>81.74</b>

### INSPECTION

Date of Assignment: 26/12/2019  
 Date Inspected: 27/12/2019 Inspected At: Team Auto Pro Pte Ltd  
 160 Sin Ming Drive #01-14 Sin Ming Autocity  
 Singapore 575722  
 Estimated Period of Repair: 19.0 days

**Adjuster:** Lim Teow Guan

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2020)
<b>Parts:</b> 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJG9748L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	985.00 FL	*849.60 FL
2	1		*TAILGATE LOGO	Necessary	86.20 FL	*68.00 FL
3	1		*TAILGATE INNER LOCK	Jammed	310.50 FL	*289.00 FL
4	1		*TAILGATE STRIKER	Bent	48.90 FL	*48.90 FL
5	1		*TAILGATE WEATHERSTRIP	Torn	186.20 FL	*186.20 FL
6	1		*TAILGATE INNER TRIM BOARD }	Broken	358.40 FL	*254.50 FL
7	1		*TAILGATE INNER HANDLE }		56.20 FL	*- FL
8	2		*TAILGATE NO PLATE LAMP	Bent	177.00 FL	*177.00 FL
9	1		*TAILGATE SOLENOID SWITCH	Short Circuit	235.00 FL	*235.00 FL
10	1		*TAILGATE WINDSCREEN	Broken	980.00 FL	*980.00 FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	132.60 FL	*132.60 FL
12	1		*TAILGATE WINDSCREEN WIPER ARM	Bent	143.50 FL	*143.50 FL
13	1		*TAILGATE WINDSCREEN WIPER MOTOR	Broken	289.30 FL	*289.30 FL
14	1		*TAILGATE WINDSCREEN WIPER GARNISH	Dislodged	68.30 FL	*68.30 FL
15	1		*TAILGATE THIRD BRAKE LAMP	Broken	268.70 FL	*185.00 FL
16	1		*REAR BUMPER	Broken	976.40 FL	*879.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	175.00 FL	*175.00 FL
18	2		*REAR BUMPER BRACKET	Bent	151.20 FL	*151.20 FL
19	1		*REAR END PANEL	Dented	865.70 FL	*492.90 FL
20	1		*REAR END PANEL TOP GARNISH	Dislodged	186.50 FL	*186.50 FL
21	1		*SPARE TYRE PANEL	Dented	881.70 FL	*737.00 FL
22	1		*SPARE TYRE PANEL TOP BOARD	Distorted	250.00 FL	*250.00 FL
23	1		*SPARE TYRE PANEL INSULATOR	No such part	188.60 FL	*- FL
24	1		*TAILLAMP RH	Broken	386.00 FL	*305.00 FL
25	1		*TAILLAMP LOWER BRACKET RH	Broken	85.00 FL	*85.00 FL
26	1		*TAILLAMP BASE PANEL RH	Dented	138.00 FL	*138.00 FL
27	1		*TAILLAMP LH	Broken	386.00 FL	*386.00 FL
28	1		*TAILLAMP LOWER BRACKET LH	Broken	85.00 FL	*85.00 FL
29	1		*TAILLAMP PANEL LH	Dented	138.00 FL	*138.00 FL
30	1		*REAR FENDER RH	Dented	648.40 FL	*648.40 FL
31	1		*REAR FENDER INNER TRIM RH	Broken	350.00 FL	*350.00 FL
32	1		*REAR FENDER INNER COWLING	Not Damaged	115.90 FL	*- FL
33	2		*REAR FENDER QUARTER GLASS MOULDING	Necessary	207.00 FL	*207.00 FL
34	1		*REAR FENDER LH	Dented	648.40 FL	*648.40 FL
35	1		*REAR FENDER INNER TRIM LH	Broken	350.00 FL	*350.00 FL
36	1		*EXHAUST PIPE	Dented	1,036.00 FL	*580.70 FL
37	2		*EXHAUST PIPE MOUNTING	Bent	97.20 FL	*97.20 FL
38	1		*EXHAUST PIPE HEAT SHIELD	Bent	156.00 FL	*156.00 FL
39	1		*REAR DOOR LOCK ASSY RH	Repair	286.30 FL	*- FL
40	1		*REAR SPOILER	Not Damaged	862.40 FL	*- FL
41	2		*REAR AIR VENTS	Broken	405.20 FL	*405.20 FL
42	1		*FRONT BUMPER	Broken	1,532.00 FL	*684.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT BUMPER REINFORCEMENT	Bent	365.20 FL	*365.20 FL
44	2		*FRONT BUMPER SIDE RETAINER	Necessary	172.80 FL	*104.00 FL
45	1		*FRONT BUMPER LOWER GRILLE	Broken	201.50 FL	*201.50 FL
46	1		*FRONT BUMPER EMBLEM MUGEN	Necessary	120.40 FL	*120.40 FL
47	2		*HEADLAMP	Broken	2,506.20 FL	*1,570.00 FL
48	2		*HEADLAMP LOWER BRACKET	Broken	537.40 FL	*173.00 FL
49	2		*FRONT FENDER	Bent	1,916.60 FL	*1,143.00 FL
50	1		*FRONT BONNET	Broken	1,095.40 FL	*800.00 FL
51	1		*FRONT BONNET LOCK	Jammed	365.40 FL	*130.00 FL
52	1		*FRONT SUPPORT PANEL	Bent	685.30 FL	*589.00 FL
53	1		*FRONT SUPPORT PANEL TOP GARNISH	No such part	298.30 FL	*- FL
54	1		*RADIATOR	Bent	853.40 FL	*853.40 FL
55	1		*A/C CONDENSER	Bent	836.20 FL	*792.00 FL
56	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
57	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
59	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
60	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
61	1		*TAILGATE WINDSCREEN GLASS	Necessary	50.00 FS	*30.00 FS
62	1		*TAILGATE PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
63	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
64	1		*REAR NO PLATE	Necessary	80.00 FS	*50.00 FS
65	2		*REAR BUMPER REVERSE SENSOR	Missing	400.00 FS	*200.00 FS
66	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
67	2		*TAILLAMP INNER SEAL	Necessary	160.00 FS	*80.00 FS
68	1		*TAILLAMP CLIPS RH	Necessary	50.00 FS	*30.00 FS
69	1		*TAILLAMP CLIPS LH	Necessary	50.00 FS	*30.00 FS
70	1		*REAR FENDER INNER TRIM CLIPS RH	Necessary	50.00 FS	*30.00 FS
71	1		*REAR FENDER INNER TRIM CLIPS LH	Necessary	50.00 FS	*30.00 FS
72	1		*REAR FENDER INNER COWLING CLIPS RH	Not Necessary	50.00 FS	*- FS
73	2		*REAR FENDER SEALANT	Necessary	200.00 FS	*80.00 FS
74	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
75	2		*REAR FENDER QUARTER GLASS CLIPS	Necessary	100.00 FS	*50.00 FS
76	1		*REAR SPOILER SEAL	Necessary	50.00 FS	*30.00 FS
77	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
78	1		*A/C FLUID	Necessary	60.00 FS	*60.00 FS
79	1		*FRONT SUPPORT PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
80	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
81	2		*FRONT FENDER SEALANT	Necessary	160.00 FS	*80.00 FS
82	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
83	1		*FRONT NO PLATE	Necessary	80.00 FS	*50.00 FS
84	1		*TAILGATE OUTER GARNISH	Broken	263.20 FL	*263.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>28,601.00</b>	<b>20,347.10</b>
- List Item Discount on L Items 20.00/20.00% (\$)	5,226.20	3,829.42
<b>Total Parts (\$)</b>	<b>23,374.80</b>	<b>16,517.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R TAILGATE COMPONENT.	New	100.00	80.00
2	R&R REAR WINDSCREEN.	New	250.00	120.00
3	R&R UPHOLSTERY.	New	180.00	80.00
4	R&R EXHAUST PIPE ASSY.	New	250.00	120.00
5	R&R FUEL TANK.	New	100.00	80.00
6	R&R REAR FENDER QUARTER GLASS LH AND RH.	New	150.00	100.00
7	R&R REVERSE SENSOR.	New	80.00	60.00
8	MOUNT BENCH WORK.	New	350.00	350.00
9	REAR CHASSIS ALIGNMENT.	New	300.00	300.00
10	DISCONNECT WIRE HARNESS TO FACILITATE REPAIR, RECONNECT AND CHECK FUNCTION.	New	80.00	60.00
11	REAR PANEL BEAT.	New	1,800.00	1,400.00
12	RUST PROOFING.	New	150.00	60.00
13	REAR SPRAY PAINTING.	New	1,800.00	1,400.00
14	R&R RADIATOR.	New	150.00	80.00
15	R&R A/C CONDENSER.	New	150.00	80.00
16	FRONT PANEL BEAT.	New	1,200.00	800.00
17	FRONT SPRAY PAINTING.	New	1,200.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,290.00</b>	<b>6,170.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >