

1/20/2019

ASS. REC. BY:

REF: es/cr119022769/Kyd3

Special Instruction:

EXCESS \$350K

Envelope: Kenneth

ASSIGNMENT (Office)

From (Person): chong Boon Sen

of CFS

Date/Time: 27/12/19 @ 2.19pm

Estimated Cost: Bill to:

COMP / TWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 6034C

Insured:

at Workshop m/s Loi Huet Mang Kee

Tel: 64538110

of 160 Sin Ming Drive # 04-01

Policy No: DMCVSN3057061901

Claim No: SNM190206124/GBG6034C/CBS

Sum insured:

Excess: \$35000

Make of Veh:

D.O.A. 22/12/2019

(Client's Record)

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2.21pm @ 27/12/19

Person Contacted: Jenny

Vehicle: IN/LOUT

Horizon OK

Date/Time	Action/Instruction
	Estimated (✓)
	GBG 6034C - CC31E@180022904/Klub3j2 Date: 10/2/2018

ASS. REC. BY:

REF: CTZ / 08/CTE19022769 May 03

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Lidmck

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 3501

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 850k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBG 60342 Yr Regn: 09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Dyno c.c. 2982

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 132405 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA T35460K 208987

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: B.S 195/75R15

R: 195/55R15 155R12x8(0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 9 9 mm

L/Bal. 7 mm L/Bal. 9 9 mm

D.O.A. 22/12/19 D.O.I. 27/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
1/12	File pass to
30/12	Revert Via Mermer
31/12	Approval Mandate by Irene Tay
3/12	Sent email to Lai Huan Meng Kee Authorise.

FINALIZE AT \$8,957.80, 8DAYS
RED: 1380.2;13%

Date/Time, File Pass to? : Prel. Report
 : Final Report

Date/Time, File Return to? _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 8

Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S + RS, SI	_____
Fees	_____
Others	_____
TOTAL	_____

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Tuesday, December 31, 2019 11:13 AM
To: jenny.lim@laihuat.com.sg
Subject: VEHICLE NO: GBG6034C DOA: 22/12/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBG6034C (excess \$350/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 30 Dec 2019

Preliminary Advice

Vehicle No	: GBG6034C	Accident Date	: 22/12/2019
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSN3057061901
Assignment Date	: 27/12/2019	Excess	: S\$350.00
Date of Inspection	:	Est. Duration of Repair	:
Inspection At	:		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,252.29
Revised Amount	:S\$	4,800.00
Check Items (Estimated)	:S\$	2,070.00
Total	:S\$	6,870.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	24,761.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,239.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

GBG6034C (SNM19D206154/GBG6034C/CBS)

OD

Dec 21 2019 2:00PM

[HONG SOON FISHERY PTE LTD]
Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **31/12/2019 10:24 AM**.
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$6870.00) - GBG6034C - Claim Handler: Chong Boon Sen**

Approved:6870.00.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2019 Sendback Est	26 Dec 2019 17:56 S\$8,647.00	27 Dec 2019 14:19 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HONG SOON FISHERY PTE LTD , Co. Reg. No.: 201207463M		
Vehicle Reg. No.:	GBG6034C	Date of Loss:	22/12/2019 14:00 - :59 [27 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D206124/GBG6034C/CBS	Policy/Cover Note No.:	DMCVSN3057061901 (Comprehensive)
		Excess:	S\$350.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/01/2020]		
Driver/Custodian:	TEO CHONG BENG (61 / Male), NRIC: S1329472], Tel: +6591207807 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2019 16:34
Date Of Accident	22/12/2019 14:30
Exact Location Of Accident	PIE TOWARDS CLEMENTI AVENUE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG6034C
Insured/Policyholder	
Name Of Registered Owner	HONG SOON FISHERY PTE LTD
Co Reg No	2XXXXX463M
Email Address	HBSARAH05@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97593168
Alternative Phone No	OFFICE-97961141

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3057061901
Cover Note Number	

Driver

Name of Driver	TEO CHONG BENG
NRIC No	SXXXX472J
Date Of Birth	31/10/1958
Occupation	OUTDOOR
Date Of Driving Pass	27/11/2013
Driving Experience	6 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91207807
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address: BLK 113 JALAN BUKIT MERAH #02-1714
 Postcode: 160113
 Was driver an employee of the Insured's Company: YES
 If No, Relationship of the Driver with the Insured:
 Vehicle Registration Number of Driver's Own Vehicle: -
 Insurance Company of Driver's Own Vehicle: -

General Information of the Accident

Type Of Accident: COLLISION - HEAD TO REAR
 Weather Conditions: RAINING
 Road Surface: WET

Other Information

Was any foreign vehicle involved in this accident?: NO
 Number of vehicles (including own vehicle) involved in the accident: 2
 Was any body injured in the Accident?: NO
 Was any injured conveyed to hospital by ambulance?: NO
 Was any other material or property damaged?: YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance: NO
 Number of Passengers (Including Driver): 1

Details of Police Action

Was the accident reported to the police?: NO
 If Yes, Please state which Police Station:
 Was notice of intended Prosecution given?: NO
 If Yes, against whom?:

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?: NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
 Was there any video captured by Car Camera?: NO
 Was there any audio recorded?: NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number: XB687M
 Vehicle Make/Model/Colour:
 Details Of Properties:
 Vehicle Category: COMMERCIAL VEHICLE
 Name of Driver:
 NRIC/Passport Number:
 Contact Number:
 Address:
 Postcode:
 Insurance Company Name:
 Nature Of Damage:
 No. Of Passenger (Including Driver):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators; law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

23 DEC 2019




Driver's Signature
(If driver is not the policyholder)
Date & Time:

23 DEC 2019

Reporting Centre Person's Name:
Jenny Lim

Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident happened on 22/12/2019 at around 2.30pm.

I was driving my lorry GBG 6034C along PIE towards Clementi Avenue 6. I did not noticed there was a truck XB 687 M stopped at the road side for some roadworks.

I quickly stepped on the brakes but my lorry still move forward and hit onto the rear of the truck. No one was injured. It was raining very heavily.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



23 DEC 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time

23 DEC 2019

Reporting Centre Personnel's Signature

Name:

Jenny Lim

NRIC/FIN No.:

MOTOR COMMERCIAL VEHICLE R

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1987
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1989 (Malaysia)

ORIGINAL

CERTIFICATE No.	DMCVSN3057061901	Engine No :IKD2745494 Chamo:JTFAT35Y60K208987
1. Index Mark and Registration Number of Vehicle	GBG6034C	
2. Name of Policy Holder	HONG SOON FISHERY PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Occurrence or Fractured	15 September 2019	Excess Sect I S\$350.00 EX ON WINDSCREEN S\$100.00
4. Date of Expiry of Insurance	14 September 2020	

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor vehicle.

6. Limitations as to use:

- (1) Use in connection with the Policyholder's business.
 - (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 - (3) Use for social, domestic or pleasure purposes.
- The Policy does not cover,
- (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.
 - (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

By CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: HO LI HWA IRENE
Authorized Officer


Authorized Signatory

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
 Owner ID: 463M

Vehicle Details

Vehicle No.: GBG6034C
 Vehicle to be Exported: Yes
 Intended Deregistration Date: 23 Dec 2019
 Vehicle Make: TOYOTA
 Vehicle Model: DYNA 150 5MT
 Primary Colour: Silver
 Manufacturing Year: 2017
 Engine No.: 1KD2745494
 Chassis No.: JTFAT35Y60K208987
 Maximum Power Output: -
 Open Market Value: \$27,084.00
 Original Registration Date: 15 Sep 2017
 First Registration Date: 15 Sep 2017
 Transfer Count: 0
 Actual ARF Paid: \$1,355.00

Intended PARF Rebate Details

PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2027
 COE Category: C - Goods Vehicle & Bus
 COE Period(Years): 10
 PQP Paid: \$32,090.00
 COE Rebate Amount: \$24,796.00
Total Rebate Amount: \$24,796.00

The information contained herein is correct as at 23 Dec 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	463M
Vehicle Details	
Vehicle No.:	GBG6034C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2745494
Chassis No.:	JTFAT35Y60K208987
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	15 Sep 2017
First Registration Date:	15 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,090.00
COE Rebate Amount:	\$24,761.00
Total Rebate Amount:	\$24,761.00

The information contained herein is correct as at 27 Dec 2019

OK

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMCVSN3057061901
 Repairer Reference: 71152
 Date calculated: 26/12/2019 4:53 PM

Full Report
 Registration: GBG 6034C
 Printed: 26/12/2019 4:56 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMCVSN3057061901	Date of Incident:	22/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		<i>Not Authorized</i> <i>Resurvey B4 paint</i> <i>Ex 8350h</i> <i>Bolcar</i>
Model:	DYNA		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 1C 01		
Registration:	GBG 6034C		
VIN number:			
Odometer:	132405		
Model Specs			
FROM 09/2017	AIR CONDITIONING	CENTRAL LOCKING	FOG LAMP ROUND 70W
TWIN AIRBAGS	STANDARD CAB	VERS GEN COUNTRIES	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW ENGINE COVER		60.0	252.00
NO NUMBER	R + R BADGE "DYNA"		2.0	8.40
520011	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		10.0	42.00
751011	R + R RADIATOR GRILLE		3.0	12.60
810051)	R + R L/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
810051)	R + R R/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
810151A	ADJUST HEADLAMPS		3.0	12.60
554011)	R + R WINDSCREEN INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS		30.0	126.00
670051)	R + R LEFT FRONT DOOR		3.0	12.60
670301	R + R LEFT FRONT DOOR TRIM		3.0	12.60

Code	Description	WU	Price SGD
671011)	R + R LEFT FRONT DOOR WINDOW	2.0	8.40
670051)	R + R RIGHT FRONT DOOR	3.0	12.60
743201)	DETACH + REFIT HEADLINING	4.0	16.80
743511)	R + R FRONT CARPET INCLUDES: R + R FRONT SEATS.	6.0	25.20
883621)	R + R HEATING CPL	14.0	58.80
870151)	R + R HEATER BLOWER	4.0	16.80
883611)	R + R EVAPORATOR	17.0	71.40
NO NUMBER	R + R AIRBAG CONTROL UNIT	3.0	12.60
550451)	R + R INSTRUMENT PANEL	9.0	37.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)	2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	7.0	29.40
NO NUMBER	DRAIN + REFILL COOLANT	3.0	12.60
441101	R + R STEERING WHEEL	4.0	16.80
002889	DRAIN AND REFILL AIR CONDITIONING	7.0	29.40
0933	L/A-PILLAR REINF REPAIR	25	40.0* 2 168.00
0934	R/A-PILLAR REINF REPAIR	25	40.0* 2 168.00
1482	RIGHT FRONT DOOR REPAIR	6.0	25.20
2296	FRONT FLOOR PANEL REPAIR	30	40.0* ? 168.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		32.70	327.0
Total of Labour			1,373.40

Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
LE 0413	ENGINE FIREWALL NEW PART PAINT ST 1	30.0	126.00
LI 1482	RIGHT FRONT DOOR REPAIR PAINT ST III	17.0	71.40
L 0933	L/A-PILLAR REINF INNER- PAINT STG II	4.0	16.80
L 0934	R/A-PILLAR REINF INNER- PAINT STG II	4.0	16.80
L 2296	FRONT FLOOR PANEL INNER- PAINT STG II	7.0	29.40
NO NUMBER	PREPARE FOR PAINTING	21.0	88.20
Total Paint		Hrs	WU
		8.30	83.0
			348.60

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER	52101 37A50		BT/KM ✓ 220.00
0293	L/F BUMPER BRACKET	52012 37080		Dij ✓ 85.00
0410	GRILLE	53111 37891		Mij ✓ 195.00
0413	ENGINE FIREWALL	55700 37420		BT ✓ 400.00
0431	BADGE	75315 37080		M ✓ 30.00
0433	BADGE MODEL	75311 37290		M ✓ 25.00
0571	LEFT HEADLAMP ASSY	81170 37690		Mij ✓ 300.00
0572	RIGHT HEADLAMP ASSY	81130 37690		" ✓ 300.00
0887	L/END MOULDING	53814 37100A0		✓ ? 85.00
				nec ✓

Code	Description	Part Number	Supplier	Price SGD
0888	R/END MOULDING	53813 37100A0	serviceable	85.00
0889	L/MOULding SEAL	55785 37050	serviceable	85.00
0890	R/MOULding SEAL	55785 37050	nec	85.00
1410	WINDSCREEN SEAL	56121 25040		95.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131		0.00
1519	L/F DOOR WINDOW	68102 37140		195.00
4325	PASSENGER AIRBAG	73970 37040		1,250.00
4415	HEATER BLOWER CPL	87210 37110		800.00
4661	L/F SEAT BELT	73210 37411B0		320.00
4662	R/F SEAT BELT	73210 37411B0		320.00
7440	AIRBAG CONTROL UNIT	89170 37122	dd 550	750.00
7445	DRIVER AIRBAG	45130 37170C0		850.00
1000	L/F PANEL AIR DUCT	RENEW		140.00
1001	STEERING SPRING COIL	RENEW		180.00
Savings				0.00
Subtotal				6,795.00
Total				6,795.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1002	W/S SEALANT SN	40.00*
1003	AIR CON GAS SN	50.00*
1004	IU BRACKET SN	15.00*
1005	FRONT NUMBER PLATE SN	25.00*
Total Extras		130.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Final Calculation

	SGD	SGD
Parts	6,795.00	
Total Parts		6,795.00
Labour Time Base 10 WU/h		
Total 327.0 WU X 42.00 SGD/h	1285.2	
Total of Labour	1,373.40	1,373.40
Total Of Extras	75	130.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 42.00 SGD/h	348.60	
Total Paint Including Material		348.60
Repair Cost Excludes GST		8,647.00
GST (+7.0%)		605.29
Repair Cost Included GST		9,252.29
Deductions (Excludes GST)		
Deduction For Excess	-350.00	
Total Of Deductions (Excludes GST)		-350.00
Grand Total Excludes GST		8,297.00
GST (+7.0%)		580.79
Grand Total Included GST		8,877.79

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: DMCVSN3057061901
Repairer Reference: 71152
Date calculated: 30/12/2019 5:44 PM

Full Report
Registration: GBG 6034C
Printed: 30/12/2019 5:45 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMCVSN3057061901	Date of Incident:	22/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	DYNA
Sub Model:	BASE MODEL
Model Sheet Number:	70 1C 01
Registration:	GBG 6034C
VIN number:	
Odometer:	132405

Model Specs

FROM 09/2017	AIR CONDITIONING	CENTRAL LOCKING	FOG LAMP ROUND 70W
TWIN AIRBAGS	STANDARD CAB	VERS GEN COUNTRIES	TWO COAT METALLIC
PREPARE OFF VEHICLE			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All
Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW ENGINE COVER		60.0	252.00
NO NUMBER	R + R BADGE "DYNA"		2.0	8.40
520011	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		10.0	42.00
751011	R + R RADIATOR GRILLE		3.0	12.60
810051)	R + R L/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
810051)	R + R R/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.20
810151A	ADJUST HEADLAMPS		3.0	12.60
554011)	R + R WINDSCREEN INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS		30.0	126.00
670051)	R + R LEFT FRONT DOOR		3.0	12.60
670301	R + R LEFT FRONT DOOR TRIM		3.0	12.60
671011)	R + R LEFT FRONT DOOR WINDOW		2.0	8.40
670051)	R + R RIGHT FRONT DOOR		3.0	12.60
743201)	DETACH + REFIT HEADLINING		4.0	16.80
743511)	R + R FRONT CARPET INCLUDES: R + R FRONT SEATS.		6.0	25.20
883621)	R + R HEATING CPL		14.0	58.80
883611)	R + R EVAPORATOR		17.0	71.40
550451)	R + R INSTRUMENT PANEL		9.0	37.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)		2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)		7.0	29.40
NO NUMBER	DRAIN + REFILL COOLANT		3.0	12.60
441101	R + R STEERING WHEEL		4.0	16.80
002889	DRAIN AND REFILL AIR CONDITIONING		7.0	29.40
0933	L/A-PILLAR REINF REPAIR		25.0*	105.00
0934	R/A-PILLAR REINF REPAIR		25.0*	105.00
1482	RIGHT FRONT DOOR REPAIR		6.0*	25.20
0887	L/END MOULDING CHECK			
0888	R/END MOULDING CHECK			
0889	L/MOULDING SEAL CHECK			
0890	R/MOULDING SEAL CHECK			
2296	FRONT FLOOR PANEL CHECK			
4415	HEATER BLOWER CPL CHECK			
7440	AIRBAG CONTROL UNIT CHECK			
1001	STEERING SPRING COIL CHECK			180.00*
	Labour Cost		Hrs	WU
	Panel / Mechanical Labour		25.00	250.0
	Fixed Rate			1,050.00
				180.00
	Total of Labour			1,230.00

Paint

Paint Work		Time Basis 10 WU/h		
Code	Description - TWO COAT METALLIC	WU	Price SGD	
LE 0413	ENGINE FIREWALL NEW PART PAINT ST 1	30.0	126.00	
LI 1482	RIGHT FRONT DOOR REPAIR PAINT ST III	17.0	71.40	
L 0933	L/A-PILLAR REINF INNER- PAINT STG II	4.0	16.80	
L 0934	R/A-PILLAR REINF INNER- PAINT STG II	4.0	16.80	
NO NUMBER	PREPARE FOR PAINTING	21.0	88.20	
Total Paint		Hrs 7.60	WU 76.0	Price SGD 319.20

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER	52101 37A50		220.00
0293	L/F BUMPER BRACKET	52012 37080		85.00
0410	GRILLE	53111 37891		195.00
0413	ENGINE FIREWALL	55700 37420		400.00
0431	BADGE	75315 37080		30.00
0433	BADGE MODEL	75311 37290		25.00
0571	LEFT HEADLAMP ASSY	81170 37690		300.00
0572	RIGHT HEADLAMP ASSY	81130 37690		300.00
1410	WINDSCREEN SEAL	56121 25040		95.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131		0.00
1519	L/F DOOR WINDOW	68102 37140		195.00
4325	PASSENGER AIRBAG	73970 37040		1,250.00
4661	L/F SEAT BELT	73210 37411B0		320.00
4662	R/F SEAT BELT	73210 37411B0		320.00
7445	DRIVER AIRBAG	45130 37170C0		850.00
1000	L/F PANEL AIR DUCT	RENEW		140.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,725.00
u: Used parts	Total			4,725.00

Extras

Code	Description	Price SGD
1003	AIR CON GAS SN	50.00*
1005	FRONT NUMBER PLATE SN	25.00*
Total Extras		75.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	4,725.00	4,725.00
Labour Time Base 10 WU/h		
Total 250.0 WU X 42.00 SGD/h	1,050.00	
Fixed Rate	180.00	
Total of Labour		1,230.00
Total Of Extras		75.00
Paint Work Time Base 10 WU/h		
Labour Cost 76.0 WU X 42.00 SGD/h	319.20	
Total Paint Including Material		319.20
Repair Cost Excludes GST		6,349.20
GST (+7.0%)		444.44
Repair Cost Included GST		6,793.64
Deductions (Excludes GST)		
Deduction For Excess	-350.00	
Total Of Deductions (Excludes GST)		-350.00
Grand Total Excludes GST		5,999.20
GST (+7.0%)		419.94
Grand Total Included GST		6,419.14

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.