

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	71152
Policy No:	DMCVSN3057061901	Date of Loss:	21/12/2019
Vehicle Reg. No.:	GBG6034C	Driveable?	
Driver Age/Info:	61 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HONG SOON FISHERY PTE LTD		
Driver:	TEO CHONG BENG		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	15/09/2017
Vehicle Colour:	Silver		
Engine No:	1KD2745494	Chassis No:	JTFAT35Y60K208987
Odometer:	132405 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	867.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	867.00
+ GST 7.00% (S\$)	60.69
Nett Amount (S\$)	927.69
+ Previous Estimates (S\$)	8,877.79
Claim Total (S\$)	9,805.48

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Jan 2020)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/GBG6034C/09/01/2020 10:49

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WASHER RESERVOIR dd	0.00	0.00	*55.00 F
2	1		*LWR INSTR PANEL TRIM dd	0.00	0.00	*120.00 F
3	1		*R/LWR INSTR PNL CVR dd	0.00	0.00	*140.00 F
4	1		*FRONT CHASSIS CROSS MEMBER bt	0.00	0.00	*95.00 F
5	1		*R/F BUMPER BRACKET bt	0.00	0.00	*85.00 F
6	1		*FAN dis	0.00	0.00	*65.00 F
7	1		*BOOSTER PUMP BRACKET nn	0.00	0.00	*280.00 F
8	7		*RADIATOR GRILLE CLIPS nec	0.00	0.00	*17.50 F
9	1		*WIPER PANEL CLIPS nec	0.00	0.00	*3.50 F
10	2		*FRONT CORNER PANEL CLIPS nec	0.00	0.00	*6.00 F

F=Franchise part.

Total Parts (\$\$)

867.00

Lai Huat (Meng Kee) Motor Pte Ltd/GBG6034C/09/01/2020 10:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/GBG6034C/09/01/2020 10:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >