

ASS. REC. REV.

REF: CS/CT119022770/Uvd3/1

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

26/12/11 @ 5.57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SML 985AM

Insured:

SJG 1401P

at Workshop w/s

Rico GO

Tel:

91878064

of

8 Kelki Bukit Ave 4 #02-24 premier

Policy No:

Claim No:

SNMIAD206108

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/11/2011

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:14am @ 27/12/11

Person Contacted:

Shanelle

Vehicle IN / OUT

Date/Time

Action/Instruction

1-shanille /

SJG 1401P CS/12216014770/07341302 N/A CS/1053016


SML 985AM X

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SML 9859M**
 at Workshop m/s **Rico 60**
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: **88k.**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 G/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **4** days Res.: Yes or No
 Lum Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 50979
 Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SML 9859M** Yr Regn: **7 / 16**Type: **Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or **CA**Make: **Mer Benz GLA180** c.c. **1595**Colour: **Grey** A/C: Insured / Std / NI / NASp. Reading: **61368** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WDC1569 422J265452**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **Good** / Jammed / Leaked / Burnt orBrake: **Good** / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / STD A/Rim orTyre Size: F: **235/50 R18**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **6** mm

Rear

R/Bal. **6** mmL/Bal. **6** mmL/Bal. **6** mmD.O.A. **21/12/19**D.O.I. **27/12/19**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/1/20 2/5 @ 6700 Confirmed with John (Ref 65,08435, 9190)

RECEIVED 16 JAN 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) **16h - typist**

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) \$ + RS. \$ _____

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

)

Report Format: **Meimen**Lump Sum / I.B.I.: (\$ **6700**)

TOTAL

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 26 December 2019 5:57 PM
To: Rico 60
Cc: 'assignments'
Subject: RE: RE: OUR REF: SNM19D206108/SJG1401P/CBS & YOUR REF: SML9859M -PRI Arrangement for SML 9859 M

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Rico 60 [mailto:claims@rico60.com]
Sent: Thursday, December 26, 2019 4:50 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: RE: OUR REF: SNM19D206108/SJG1401P/CBS & YOUR REF: SML9859M -PRI Arrangement for SML 9859 M

Dear all,

Please have Marcus Chua to survey the said vehicle.

Thank you.

Best Regards,

Elfphaine Tan



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

From: Chong Boon Sen

Sent: Thursday, 26 December 2019 2:13 PM

To: claims@rico60.com

Subject: RE: OUR REF: SNM19D206108/SJG1401P/CBS & YOUR REF: SML9859M -PRI Arrangement for SML 9859 M

Without prejudice

Dear Sir,

LKK

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, December 26, 2019 2:07 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; claims@rico60.com

Subject: OUR REF: SNM19D206108/SJG1401P/CBS & YOUR REF: SML9859M -PRI Arrangement for SML 9859 M

Dear Boon Sen,

Please conduct PRS –SML9859M soonest possible.

File to officer in charge- Chong Boon Sen- DID: 6389 6171.

Dear Shanelle,

**** kindly quote our reference number when replying ******

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Enquiry [<mailto:claims@rico60.com>]

Sent: Tuesday, 24 December, 2019 12:19 PM

To: Claims Dept of CTI

Subject: PRI Arrangement for SML 9859 M

Dear all,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SML 9859 M

Your Insured – SJG 1401 P

DOA – 21/12/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

> Back to OneMotoring

Singapore

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	773H
Vehicle Details	
Vehicle No.:	SML9859M
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Dec 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA180 (R18 BI)
Primary Colour:	Purple
Manufacturing Year:	2016
Engine No.:	27091030989837
Chassis No.:	WDC1569422J265452
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,438.00
Original Registration Date:	18 Jul 2016
First Registration Date:	18 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$26,814.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2026
PARF Rebate Amount:	\$20,110.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$30,869.00
Total Rebate Amount:	\$50,979.00

The information contained herein is correct as at 23 Dec 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 3 Years Renewal C&C Toyota 2016 1.6L



2016 1.6L, 52,000km, 10,000km
Full-time 2016 1.6L, 2 years
Warranty, Engine, Gearbox
CV Credit, 100000



Sort by Date Posted

20 results/page

5 vehicles

MERCEDES-BENZ GLA180

Basic Search



Price Any price Depre Any depre Reg Date 2016 to 2016 Eng Cap Any Veh Type All types
Fuel Any fuel Mileage Any OMV Any Gear Any Gear Past Owners Any
Category All categories Scheme All schemes Dealer Any Dealer Location Any Status Available

Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
 Mercedes-Benz GLA-Class GLA180 AMG	\$88,000	\$12,110 /yr	28-Jan-2016	1,595 cc	42,456 km	SUV	Available
Prestige Condition, 1 Owner Beautiful Red Hot Chili GLA 180 For Sale, 100% Free, Flexible Loan, High Trade For You Used Car, 100% Loan Available, In House Loan No Problem, Call For More Information Today.							
Auto Inn							
Posted: 23-Dec-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz							
 Mercedes-Benz GLA-Class GLA180	\$103,666	\$13,080 /yr	22-Nov-2016	1,595 cc	59,000 km	SUV	Available
1.98% Available! C&C Unit, 1 Owner, Low Mileage, Fully Agent Service, Interior/Exterior Condition Looks New, Well Maintained, Good Condition, High Loan Amount Offering Bank And In House Loan Available, Trade In Are Welcome, Accident Free Buy With A Peace Of Mi...							
Privilege Motors Pte Ltd							
Posted: 22-Dec-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz							
 Mercedes-Benz GLA-Class GLA180	\$110,000	\$13,830 /yr	08-Dec-2016	1,595 cc	36,000 km	SUV	Available
Offer Loan Interest At 2.28%, Extremely Well Maintained, It's 100% Accident-Free. View To Believe! Up To 70% Financing Of The Car Price Possible! Trade-In Welcome Call/SMS To Arrange A Viewing Today! Viewing Strictly By Appointment Only.							
Posted: 19-Dec-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz							
 Mercedes-Benz GLA-Class GLA180	\$95,800	\$13,620 /yr	25-Jan-2016	1,595 cc	13,500 km	SUV	Available
Extremely Low Mileage, 1 Owner Unit, Fully Serviced And Maintained By C&C. Owner Just Recently Spent 1k+ On Servicing & Wear And Tear! Workshop/STA Evaluation Welcome, 90% Loan Of The Car Price Available With Lowest Interest Rates From 2.28%, Trade In Welc...							
Posted: 16-Dec-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz							
 BCC Automotive Pte Ltd (Deutsch) - Specialty Workshops							
BCC Automotive Pte Ltd specialise in French Automobile servicing and repairs. They are also representatives for multiple motor insurance.							
More info about this shop							
 Mercedes-Benz GLA-Class GLA180	\$93,800	\$13,350 /yr	29-Jan-2016	1,595 cc	79,000 km	SUV	Available
Chrome Sports Grille, Front And Back Dashboard Cameras/Recorder, Full C&C Servicing, Mint Condition, No Modifications, All Factory Original Part, Well Maintained By Owner, 100% Accident-Free, Due To Overwhelming Text Messages, Serious Buyers Please Call After 1...							
Posted: 24-Oct-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz							
Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2019 16:59
Date Of Accident	21/12/2019 23:30
Exact Location Of Accident	CAVENGH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML9859M
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	WOO KUAN HOONG PATRICK(HU JUNHONG PATRICK)
NRIC No	SXXXX773H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98625309
Alternative Phone No	OFFICE-98625309

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLA180 (R18 BI)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI19V04971/VPE/R00
Cover Note Number	

Driver

Name of Driver	WOO KUAN HOONG PATRICK(HU JUNHONG PATRICK)
NRIC No	SXXXX773H
Date Of Birth	15/02/1975
Occupation	INDOOR
Date Of Driving Pass	30/11/2006
Driving Experience	13 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98625309
Fax Number	
Contact Number	OFFICE-98625309
EMail Address	NOEMAIL

Address	BLK 515D TAMPINES CENTRAL 7 #09-34
Postcode	524515
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG1401P
Vehicle Make/Model/Colour	MITSUBISHI / LANCER 1.6 A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH SI MA(DU SIMIN)
NRIC/Passport Number	SXXXX524C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAJI BUKIT (YAG)
23 Kaji Bukit Ave 4 #02-02
Singapore 415933
Tel: 674 16887 Fax: 674 892505
Email: yag@idac.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Accident Sketch Plan

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on the middle lane when I heard a bang from my right door. I alighted the vehicle, retrieved my video footage & realised vehicle B had collided into my right portion of my vehicle while switching lanes to avoid construction up ahead.

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (YAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415833
Tel: 67416687 Fax: 67482305
E-mail: info@idac.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SML 9859 M
MERCEDES GLA180

Not Allowed
1/53
Hdy
27/12/19

DESCRIPTION - PARTS		QTY	PRICE
1	FRONT DOOR (RH) <i>12X</i>	1	
2	FRONT DOOR SIDE MIRROR ASSY (RH) <i>11X</i>	1	
3	FRONT DOOR SIDE MIRROR COVER (RH) <i>11X</i>	1	
4	FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH) <i>11X</i>	1	
5	FRONT DOOR HANDLE (RH) <i>11X</i>	1	
6	FRONT DOOR HANDLE END CAP (RH) <i>11X</i>	1	
7	FRONT DOOR LOCK CYLINDER (RH) <i>11X</i>	1	
8	FRONT DOOR WINDOW MOULDING (RH) <i>11X</i>	1	
9	FRONT DOOR WINDOW INNER MOULDING (RH) <i>11X</i>	1	
10	FRONT DOOR WINDOW CHROME STRIP (RH) <i>11X</i>	1	
11	FRONT DOOR LOCK (RH) <i>11X</i>	1	
12	FRONT DOOR LOCK CATCH (RH) <i>11X</i>	1	
13	FRONT DOOR INNER BOARD (RH) <i>11X</i>	1	
14	FRONT DOOR INNER BOARD SWITCH (RH) <i>11X</i>	1	
15	FRONT DOOR INNER HANDLE (RH) <i>11X</i>	1	
16	FRONT DOOR CHECKER (RH) <i>11X</i>	1	
17	FRONT DOOR HINGE UPPER AND LOWER (RH) <i>11X</i>	1	
18	FRONT DOOR WINDOW REGULATOR (RH) <i>11X</i>	1	
19	FRONT DOOR POWER WINDOW MOTOR (RH) <i>11X</i>	1	
20	FRONT DOOR WEATHERSTRIP (RH) <i>11X</i>	1	
21	FRONT DOOR INNER WEATHERSTRIP (RH) <i>11X</i>	1	
22	REAR DOOR (RH) <i>12/12/19 ✓</i>	1	
23	REAR DOOR HANDLE (RH) <i>11X</i>	1	
24	REAR DOOR HANDLE END CAP (RH) <i>11X</i>	1	
25	REAR DOOR LOCK CYLINDER (RH) <i>11X</i>	1	
26	REAR DOOR WINDOW MOULDING (RH) <i>11 ✓</i>	1	
27	REAR DOOR WINDOW INNER MOULDING (RH) <i>11 ✓</i>	1	
28	REAR DOOR WINDOW CHROME STRIP (RH) <i>11 ✓</i>	1	
29	REAR DOOR LOCK (RH) <i>11X</i>	1	
30	REAR DOOR LOCK CATCH (RH) <i>11X</i>	1	
31	REAR DOOR INNER BOARD (RH) <i>11X</i>	1	
32	REAR DOOR INNER BOARD SWITCH (RH) <i>11X</i>	1	
33	REAR DOOR INNER HANDLE (RH) <i>11X</i>	1	
34	REAR DOOR CHECKER (RH) <i>11X</i>	1	
35	REAR DOOR HINGE UPPER AND LOWER (RH) <i>11X</i>	2	
36	REAR DOOR WINDOW REGULATOR (RH) <i>11X</i>	1	
37	REAR DOOR POWER WINDOW MOTOR (RH) <i>11X</i>	1	
38	REAR DOOR WEATHERSTRIP (RH) <i>11 ✓</i>	1	
39	REAR DOOR INNER WEATHERSTRIP (RH) <i>11 ✓</i>	1	
40	ROCKER PANEL (RH) <i>12X</i>	1	

41	ROCKER PANEL GARNISH (RH)	garnish —	1	
42	REAR WINDSCREEN MOULDING	11 X	1	
43	REAR FENDER (RH)	R X	1	
44	REAR FENDER INNER TRIM (RH)	11 X	1	
45	REAR FENDER COWLING (RH)	11 X	1	
46	REAR WHEEL ARC PROTECTOR (RH)	garnish —	1	
47	TAIL LAMP (RH)	11 X	1	
48	TAIL LAMP PANEL (RH)	11 X	1	
49	REAR BUMPER	cut/weld —	1	
50	REAR BUMPER RETAINER (RH)	11 X	1	
51	REAR BUMPER REINFORCEMENT BAR	11 X	1	
52	REAR BUMPER BRACKET (RH)	11 X	1	
53	REAR BUMPER BEAM	11 X	1	
54	REAR BUMPER SPONGE	11 X	1	
55	REAR BUMPER REVERSE SENSOR SET	shiled fpc	1	
56	REAR BUMPER LOWER	grinder —	1	
57	REAR BUMPER LOWER DIFFUSOR	11 X	1	
58	REAR BUMPER LOWER DIFFUSOR TOW COVER	11 X	1	
59	REAR ABSORBER (RH)	11 X	1	
60	REAR LOWER ARM (RH)	11 X	1	
61	REAR CONTROL ARM (RH)	11 X	1	
62	REAR STRAIGHT ARM (RH)	11 X	1	
63	REAR KNUCKLE ARM (RH)	11 X	1	
64	REAR KNUCKLE BEARING (RH)	11 X	1	
65	REAR BEARING HUB (RH)	11 X	1	
66	REAR AXLE	11 X	1	
67	REAR RIM SET	cut lpc	2	
SUBTOTAL			\$	-
LESS 10%			\$	-
PARTS TOTAL			\$	-
SPECIAL NETT			QTY	PRICE
1	FRONT DOOR INNER BOARD CLIPS	11 X	10	\$ 100.00
2	REAR DOOR INNER BOARD CLIPS	rec 50	10	\$ 100.00
3	ROCKER PANEL SEALANT	11 X	1	\$ 120.00
4	ROCKER PANEL GARNISH CLIPS	rec 50	10	\$ 100.00
5	REAR WINDSCREEN SEALANT	11 X	1	\$ 120.00
6	REAR FENDER SEALANT	11 X	1	\$ 120.00
7	REAR FENDER INNER TRIM CLIPS	11 X	10	\$ 100.00
8	REAR FENDER COWLING CLIPS	11 X	10	\$ 100.00
9	REAR WHEEL ARC PROTECTOR CLIPS	11 X	10	\$ 100.00
10	TAIL LAMP CLIPS	11 X	2	\$ 80.00
11	REAR BUMPER CLIPS	rec 50	10	\$ 100.00
12	REAR TYRE SET	11 X	2	\$ 2,400.00
SPECIAL NETT TOTAL			\$	3,540.00
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	600	1	\$ 2,400.00

	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	800	1	\$	2,400.00
	TO RUST PROOF ACCIDENT AFFECTED AREA	30	1	\$	250.00
	TO RNR REAR WINDSCREEN	n7x	1	\$	400.00
	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS	60	1	\$	400.00
	TO RNR DOOR MECHANISM	60	1	\$	800.00
	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	1	\$	150.00
	TO RNR UNDERCARRIAGE SYSTEM	n7x	1	\$	250.00
	TO CHECK WHEEL ALIGNMENT	60	1	\$	250.00
	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	20	1	\$	150.00
	TO RNR TYRE AND WHEEL BALANCING	n7x	1	\$	250.00
	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	n7x	1	\$	6,000.00
	TO DO WATER LEAK TEST .	n7x	1	\$	120.00
	TOTAL			\$	13,820.00
	GRAND TOTAL COST			\$	17,360.00



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SML 9859 M
MERCEDES GLA180

Not Allocated
1/5 #6700
Hdy.
27/12/19

ATTN	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	FRONT DOOR (RH) <i>12x</i>	1	\$3982.50
	2	FRONT DOOR SIDE MIRROR ASSY (RH) <i>11x</i>	1	\$1680.20
	3	FRONT DOOR SIDE MIRROR COVER (RH) <i>11x</i>	1	\$560.00
	4	FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH) <i>11x</i>	1	\$291.00
	5	FRONT DOOR HANDLE (RH) <i>11x</i>	1	\$399.00
	6	FRONT DOOR HANDLE END CAP (RH) <i>11x</i>	1	\$140.80
	7	FRONT DOOR LOCK CYLINDER (RH) <i>11x</i>	1	\$271.00
	8	FRONT DOOR WINDOW MOULDING (RH) <i>11x</i>	1	\$159.20
	9	FRONT DOOR WINDOW INNER MOULDING (RH) <i>11x</i>	1	\$168.00
	10	FRONT DOOR WINDOW CHROME STRIP (RH) <i>11x</i>	1	\$362.90
	11	FRONT DOOR LOCK (RH) <i>11x</i>	1	\$397.10
	12	FRONT DOOR LOCK CATCH (RH) <i>11x</i>	1	\$122.00
	13	FRONT DOOR INNER BOARD (RH) <i>11x</i>	1	\$1998.90
	14	FRONT DOOR INNER BOARD SWITCH (RH) <i>11x</i>	1	\$2140.80
	15	FRONT DOOR INNER HANDLE (RH) <i>11x</i>	1	\$311.40
	16	FRONT DOOR CHECKER (RH) <i>11x</i>	1	\$120.00
	17	FRONT DOOR HINGE UPPER AND LOWER (RH) <i>11x</i>	2	\$310.60
	18	FRONT DOOR WINDOW REGULATOR (RH) <i>11x</i>	1	\$420.00
	19	FRONT DOOR POWER WINDOW MOTOR (RH) <i>11x</i>	1	\$629.60
	20	FRONT DOOR WEATHERSTRIP (RH) <i>11x</i>	1	\$287.10
	21	FRONT DOOR INNER WEATHERSTRIP (RH) <i>11x</i>	1	\$320.70
	22	REAR DOOR (RH) <i>10/12/19 2022.14</i>	1	\$3921.90
	23	REAR DOOR HANDLE (RH) <i>11x</i>	1	\$399.00
	24	REAR DOOR HANDLE END CAP (RH) <i>11x</i>	1	\$140.80
	25	REAR DOOR LOCK CYLINDER (RH) <i>11x</i>	1	\$Nil
	26	REAR DOOR WINDOW MOULDING (RH) <i>11x 158.20</i>	1	\$159.20
	27	REAR DOOR WINDOW INNER MOULDING (RH) <i>11x 115.32</i>	1	\$168.00
	28	REAR DOOR WINDOW CHROME STRIP (RH) <i>11x 315.33</i>	1	\$362.90
	29	REAR DOOR LOCK (RH) <i>11x</i>	1	\$397.10
	30	REAR DOOR LOCK CATCH (RH) <i>11x</i>	1	\$122.00
	31	REAR DOOR INNER BOARD (RH) <i>11x</i>	1	\$1998.90
	32	REAR DOOR INNER BOARD SWITCH (RH) <i>11x</i>	1	\$2140.80
	33	REAR DOOR INNER HANDLE (RH) <i>11x</i>	1	\$311.40
	34	REAR DOOR CHECKER (RH) <i>11x</i>	1	\$120.00
	35	REAR DOOR HINGE UPPER AND LOWER (RH) <i>11x</i>	2	\$310.60
	36	REAR DOOR WINDOW REGULATOR (RH) <i>11x</i>	1	\$420.00
	37	REAR DOOR POWER WINDOW MOTOR (RH) <i>11x</i>	1	\$629.60
	38	REAR DOOR WEATHERSTRIP (RH) <i>11x 148.50</i>	1	\$287.10
	39	REAR DOOR INNER WEATHERSTRIP (RH) <i>11x 305.62</i>	1	\$320.70
	40	ROCKER PANEL (RH) <i>12x</i>	1	\$1760.90

28,524.10

41	ROCKER PANEL GARNISH (RH)	gmd — 745.00	1	\$ 966.40	X
42	REAR WINDSCREEN MOULDING	17 X	1	\$ 249.50	X
43	REAR FENDER (RH)	12 X	1	\$ 2786.20	X
44	REAR FENDER INNER TRIM (RH)	17 X	1	\$ 896.50	X
45	REAR FENDER COWLING (RH)	17 X	1	\$ 236.40	X
46	REAR WHEEL ARC PROTECTOR (RH)	gmd — 366.50	1	\$ 439.50	X
47	TAIL LAMP (RH)	17 X	1	\$ 989.00	X
48	TAIL LAMP PANEL (RH)	17 X	1	\$ 420.50	X
49	REAR BUMPER	cut/pc — 1345	1	\$ 2897.10	X
50	REAR BUMPER RETAINER (RH)	17 X	1	\$ 404.00	X
51	REAR BUMPER REINFORCEMENT BAR	17 X	1	\$ 1071.00	X
52	REAR BUMPER BRACKET (RH)	17 X	1	\$ 458.00	X
53	REAR BUMPER BEAM	17 X	1	\$ NIL	X
54	REAR BUMPER SPONGE	17 X	1	\$ 864.00	X
55	REAR BUMPER REVERSE SENSOR SET	shld f/c 266 \$667.00	1	\$ 2648.00	17C
56	REAR BUMPER LOWER	gmd — 450	1	\$ 1482.80	X
57	REAR BUMPER LOWER DIFFUSOR	17 X	1	\$ 1066.10	X
58	REAR BUMPER LOWER DIFFUSOR TOW COVER	17 X	1	\$ 280.90	X
59	REAR ABSORBER (RH)	17 X	1	\$ 989.70	X
60	REAR LOWER ARM (RH)	17 X	1	\$ 870.00	X
61	REAR CONTROL ARM (RH)	17 X	1	\$ 891.00	X
62	REAR STRAIGHT ARM (RH)	17 X	1	\$ 799.80	X
63	REAR KNUCKLE ARM (RH)	17 X	1	\$ 659.00	X
64	REAR KNUCKLE BEARING (RH)	17 X	1	\$ 604.00	X
65	REAR BEARING HUB (RH)	17 X	1	\$ 426.00	X
66	REAR AXLE	17 X	1	\$ 2690.00	X
67	REAR RIM SET	cut 1pc \$2940.00	2	\$ 5880.00	1005.
31,947.40				\$ 60,471.50	
SUBTOTAL				\$ -	
LESS 10%				\$ -	
PARTS TOTAL				\$ 54,431.50	
SPECIAL NETT			QTY	PRICE	
1	FRONT DOOR INNER BOARD CLIPS	17 X	10	\$ 100.00	X
2	REAR DOOR INNER BOARD CLIPS	17 X	10	\$ 100.00	50
3	ROCKER PANEL SEALANT	17 X	1	\$ 120.00	X
4	ROCKER PANEL GARNISH CLIPS	17 X	10	\$ 100.00	50
5	REAR WINDSCREEN SEALANT	17 X	1	\$ 120.00	X
6	REAR FENDER SEALANT	17 X	1	\$ 120.00	X
7	REAR FENDER INNER TRIM CLIPS	17 X	10	\$ 100.00	X
8	REAR FENDER COWLING CLIPS	17 X	10	\$ 100.00	X
9	REAR WHEEL ARC PROTECTOR CLIPS	17 X	10	\$ 100.00	X
10	TAIL LAMP CLIPS	17 X	2	\$ 80.00	X
11	REAR BUMPER CLIPS	17 X	10	\$ 100.00	50
12	REAR TYRE SET	17 X	2	\$ 2,400.00	X
SPECIAL NETT TOTAL				\$ 3,540.00	
LABOUR			QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	600	1	\$ 2,400.00	

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Dec 2019		30 Dec 2019 08:43 Edit Adj Rpt	S\$6,700.00 Edit Estimates	S\$6,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ID: -								
Main Claimant:	WOO KUAN HOONG PATRICK(HU JUNHONG PATRICK), ID: S7504773H								
Vehicle Reg. No.:	SML9859M	Date of Loss:	21/12/2019 23:00 - :59 [41 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D206108C02	Policy/Cover Note No.:	DMPCSN30416119011						
Vehicle Reg. No. (Insured):	SJG1401P	Policy No. (Claimant):	SI19VD4971/VPE/ROD						
		Excess:	S\$0.00						
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SML9859M (SNM19D206108C02)
[SJG1401P]

TP

WOO KUAN HOONG PATRICK(HU JUNHONG PATRICK)

Dec 21 2019 11:00PM

[-]

RICO 60 AUTO SERVICES PTE LTD

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

Thumbnail

Print

No	Finalized On	VAC (Kaki Bukit)			
1	23/12/19 17:06	Accident Statement		Load HTML	

Photos/Images

3 per page

Thumbnail

Print

No	Finalized On	VAC (Kaki Bukit)			
1	23/12/19 17:04	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	23/12/19 17:04	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	23/12/19 17:04	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	23/12/19 17:04	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	23/12/19 17:04	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	23/12/19 17:04	Accident Photo [Linked Accident Report Documents]		Load JPG	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			
1	13/01/20 09:06	Chassis Number		Load JPG	
2	13/01/20 09:07	Odometer Reading		Load JPG	
3	13/01/20 09:09	General View		Load JPG	
4	13/01/20 09:09	General View		Load JPG	
5	13/01/20 09:09	General View		Load JPG	
6	13/01/20 09:09	General View		Load JPG	
7	13/01/20 09:09	General View		Load JPG	
8	13/01/20 09:09	General View		Load JPG	
9	13/01/20 09:09	General View		Load JPG	
10	13/01/20 09:09	General View		Load JPG	
11	13/01/20 09:09	General View		Load JPG	
12	13/01/20 09:09	General View		Load JPG	
13	13/01/20 09:09	General View		Load JPG	
14	13/01/20 09:09	General View		Load JPG	
15	13/01/20 09:09	General View		Load JPG	
16	13/01/20 09:09	General View		Load JPG	
17	13/01/20 09:09	General View		Load JPG	
18	13/01/20 09:09	General View		Load JPG	
19	13/01/20 09:09	General View		Load JPG	
20	13/01/20 09:09	General View		Load JPG	
21	13/01/20 09:09	General View		Load JPG	
22	13/01/20 09:09	General View		Load JPG	
23	13/01/20 09:09	General View		Load JPG	
24	13/01/20 09:09	General View		Load JPG	
25	13/01/20 09:09	General View		Load JPG	
26	13/01/20 09:09	General View		Load JPG	
27	13/01/20 09:10	General View		Load JPG	
28	13/01/20 09:10	General View		Load JPG	
29	13/01/20 09:10	General View		Load JPG	
30	13/01/20 09:10	General View		Load JPG	
31	13/01/20 09:10	General View		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
				☒
32	13/01/20 09:10	General View	 Load JPG	☒
33	13/01/20 09:10	General View	 Load JPG	☒
34	13/01/20 09:10	General View	 Load JPG	☒
35	13/01/20 09:10	General View	 Load JPG	☒
36	13/01/20 09:10	General View	 Load JPG	☒
37	13/01/20 09:10	General View	 Load JPG	☒
38	13/01/20 09:10	General View	 Load JPG	☒
39	13/01/20 09:10	General View	 Load JPG	☒
40	13/01/20 09:10	General View	 Load JPG	☒
41	13/01/20 09:10	General View	 Load JPG	☒
42	13/01/20 09:10	General View	 Load JPG	☒
43	13/01/20 09:10	After Repair Photo	 Load JPG	☒
44	13/01/20 09:10	After Repair Photo	 Load JPG	☒
45	13/01/20 09:10	After Repair Photo	 Load JPG	☒
46	13/01/20 09:10	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	23/12/19 17:06	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	23/12/19 17:06	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	23/12/19 17:06	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	23/12/19 17:04	Accident Photo	 Load JPG	☒
2	23/12/19 17:04	Accident Photo	 Load JPG	☒
3	23/12/19 17:04	Accident Photo	 Load JPG	☒
4	23/12/19 17:04	Accident Photo	 Load JPG	☒
5	23/12/19 17:04	Accident Photo	 Load JPG	☒
6	23/12/19 17:04	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	23/12/19 17:06	Accident Sketch Plan	 Load JPG	☒
2	23/12/19 17:06	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022770/UVD3Q2

Date: 23/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30416119011
Claimant Vehicle No :	SML9859M	Insured Vehicle No :	SJG1401P
Date of Loss:	21/12/2019	Nature of Claim: TP	Claim No: SNM19D206108C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML9859M	Engine No:	27091030989837
Make & Model:	BLUECAR BLUECAR, (A)	Chassis No:	WDC1569422J265452
Reg. Date:	18/07/2016 (Man. Year: 2016)	Odometer:	61368 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64,011.50	6,761.15	57,250.35	89.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,820.00	1,680.00	12,140.00	87.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	77,831.50	8,441.15	69,390.35	89.15
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	77,831.50	6,700.00	71,131.50	91.39
+ GST 7.00/7.00% (S\$)	5,448.21	469.00	4,979.21	91.39
Nett Amount (S\$)	83,279.71	7,169.00	76,110.71	91.39

INSPECTION

Date of Assignment:	30/12/2019	
Date Inspected:	27/12/2019 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2020)
Parts:	144	BLUECAR BLUECAR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML9859M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (RH)	Repair	3,982.40 F	*- FL
2	1		*FRONT DOOR SIDE MIRROR ASSY (RH)	Not Necessary	1,680.20 F	*- FL
3	1		*FRONT DOOR SIDE MIRROR COVER (RH)	Not Necessary	560.00 F	*- FL
4	1		*FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH)	Not Necessary	291.00 F	*- FL
5	1		*FRONT DOOR HANDLE (RH)	Not Necessary	399.00 F	*- FL
6	1		*FRONT DOOR HANDLE END CAP (RH)	Not Necessary	140.80 F	*- FL
7	1		*FRONT DOOR LOCK CYLINDER (RH)	Not Necessary	271.00 F	*- FL
8	1		*FRONT DOOR WINDOW MOULDING (RH)	Not Necessary	159.20 F	*- FL
9	1		*FRONT DOOR WINDOW INNER MOULDING (RH)	Not Necessary	168.00 F	*- FL
10	1		*FRONT DOOR WINDOW CHROME STRIP (RH)	Not Necessary	362.90 F	*- FL
11	1		*FRONT DOOR LOCK (RH)	Not Necessary	397.10 F	*- FL
12	1		*FRONT DOOR LOCK CATCH(RH)	Not Necessary	122.00 F	*- FL
13	1		*FRONT DOOR INNER BOARD (RH)	Not Necessary	1,998.90 F	*- FL
14	1		*FRONT DOOR INNER BOARD SWITCH(RH)	Not Necessary	2,140.80 F	*- FL
15	1		*FRONT DOOR INNER HANDLE (RH)	Not Necessary	311.40 F	*- FL
16	1		*FRONT DOOR CHECKER (RH)	Not Necessary	120.00 F	*- FL
17	2		*FRONT DOOR HINGE UPPER AND LOWER (RH)	Not Necessary	310.60 F	*- FL
18	1		*FRONT DOOR WINDOW REGULATOR (RH)	Not Necessary	420.00 F	*- FL
19	1		*FRONT DOOR POWER WINDOW MOTOR (RH)	Not Necessary	629.60 F	*- FL
20	1		*FRONT DOOR WEATHERSTRIP (RH)	Not Necessary	287.10 F	*- FL
21	1		*FRONT DOOR INNER WEATHERSTRIP (RH)	Not Necessary	320.70 F	*- FL
22	1		*REAR DOOR (RH)	Dented / Bent	3,421.90 F	*2,022.14 FL
23	1		*REAR DOOR HANDLE (RH)	Not Necessary	399.00 F	*- FL
24	1		*REAR DOOR HANDLE END CAP (RH)	Not Necessary	140.80 F	*- FL
25	1		*REAR DOOR LOCK CYLINDER (RH) (NPA)	Not Necessary	0.00 F	*- FL
26	1		*REAR DOOR WINDOW MOULDING (RH)	Necessary	159.20 F	*155.20 FL
27	1		*REAR DOOR WINDOW INNER MOULDING (RH)	Necessary	168.00 F	*115.32 FL
28	1		*REAR DOOR WINDOW CHROME STRIP (RH)	Necessary	362.90 F	*315.33 FL
29	1		*REAR DOOR LOCK (RH)	Not Necessary	397.10 F	*- FL
30	1		*REAR DOOR LOCK CATCH (RH)	Not Necessary	122.00 F	*- FL
31	1		*REAR DOOR INNER BOARD (RH)	Not Necessary	1,979.40 F	*- FL
32	1		*REAR DOOR INNER BOARD SWITCH(RH)	Not Necessary	2,140.80 F	*- FL
33	1		*REAR DOOR INNER HANDLE (RH)	Not Necessary	311.40 F	*- FL
34	1		*REAR DOOR CHECKER (RH)	Not Necessary	120.00 F	*- FL
35	2		*REAR DOOR HINGE UPPER AND LOWER (RH)	Not Necessary	310.60 F	*- FL
36	1		*REAR DOOR WINDOW REGULATOR (RH)	Not Necessary	420.00 F	*- FL
37	1		*REAR DOOR POWER WINDOW MOTOR (RH)	Not Necessary	629.60 F	*- FL
38	1		*REAR DOOR WEATHERSTRIP (RH)	Necessary	287.10 F	*148.50 FL
39	1		*REAR DOOR INNER WEATHERSTRIP (RH)	Necessary	320.70 F	*305.62 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*ROCKER PANEL (RH)	Repair	1,760.90 F	*- FL
41	1		*ROCKER PANEL GARNISH (RH)	Grazed	968.40 F	*745.00 FL
42	1		*REAR WINDSCREEN MOULDING	Not Necessary	249.50 F	*- FL
43	1		*REAR FENDER (RH)	Repair	2,786.20 F	*- FL
44	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	876.50 F	*- FL
45	1		*REAR FENDER COWLING (RH)	Not Necessary	236.40 F	*- FL
46	1		*REAR WHEEL ARC PROTECTOR (RH)	Grazed	429.50 F	*366.50 FL
47	1		*TAIL LAMP (RH)	Not Necessary	989.00 F	*- FL
48	1		*TAIL LAMP PANEL (RH)	Not Necessary	420.50 F	*- FL
49	1		*REAR BUMPER	Cracked / Deformed	2,897.10 F	*1,345.00 FL
50	1		*REAR BUMPER RETAINER (RH)	Not Necessary	404.00 F	*- FL
51	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	1,071.00 F	*- FL
52	1		*REAR BUMPER BRACKET (RH)	Not Necessary	458.00 F	*- FL
53	1		*REAR BUMPER BEAM (NPA)	Not Necessary	0.00 F	*- FL
54	1		*REAR BUMPER SPONGE	Not Necessary	864.00 F	*- FL
55	1		*SET REAR BUMPER REVERSE SENSOR	Shorted (1 PCS ONLY)	2,648.00 F	*266.00 FL
56	1		*REAR BUMPER LOWER	Grazed	1,492.80 F	*450.00 FL
57	1		*REAR BUMPER LOWER DIFFUSOR	Not Necessary	1,066.10 F	*- FL
58	1		*REAR BUMPER LOWER DIFFUSOR TOW COVER	Not Necessary	280.90 F	*- FL
59	1		*REAR ABSORBER (RH)	Not Necessary	989.70 F	*- FL
60	1		*REAR LOWER ARM (RH)	Not Necessary	870.00 F	*- FL
61	1		*REAR CONTROL ARM (RH)	Not Necessary	891.00 F	*- FL
62	1		*REAR STRAIGHT ARM (RH)	Not Necessary	799.80 F	*- FL
63	1		*REAR KNUCKLE ARM (RH)	Not Necessary	659.00 F	*- FL
64	1		*REAR KNUCKLE BEARING (RH)	Not Necessary	604.00 F	*- FL
65	1		*REAR BEARING HUB (RH)	Not Necessary	426.00 F	*- FL
66	1		*REAR AXLE	Not Necessary	2,690.00 F	*- FL
67	1		*SET REAR RIM	Cut (1 PCS ONLY)	5,880.00 FS	*1,000.00 FS
68	10		*FRONT DOOR INNER BOARD CLIPS	Not Necessary	100.00 FS	*- FS
69	10		*REAR DOOR INNER BOARD CLIPS	Not Necessary	100.00 FS	*50.00 FS
70	1		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
71	10		*ROCKER PANEL GARNISH CLIPS	Necessary	100.00 FS	*50.00 FS
72	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
73	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
74	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
75	10		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
76	10		*REAR WHEEL ARC PROTECTOR CLIPS	Not Necessary	100.00 FS	*- FS
77	2		*TAIL LAMP CLIPS	Not Necessary	80.00 FS	*- FS
78	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
79	2		*SET REAR TYRE	Not Necessary	2,400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **64,011.50** **7,384.61**
 - List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 623.46

Total Parts (\$\$) **64,011.50** **6,761.15**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS ,CUT/WELD ,KNOCK & REALIGN	New	2,400.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,400.00	800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	30.00
4	TO RNR REAR WINDSCREEN	New	400.00	0.00
5	TO RNR UPHOLSTERY ,GARNISH AND ATTACHMENT PARTS	New	400.00	60.00
6	TO RNR DOOR MECHANISM	New	800.00	60.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	150.00	50.00
8	TO RNR UNDERCARRIAGE SYSTEM	New	250.00	0.00
9	TO CHECK WHEEL ALIGNMENT	New	250.00	60.00
10	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	20.00
11	TO RNR TYRE AND WHEEL BALANCING	New	250.00	0.00
12	TO DO DIAGNOSIS AND RESET ,REPROGRAM OR CODING FAULT CODE	New	6,000.00	0.00
13	TO DO WATER LEAK TEST	New	120.00	0.00
Gross Labour Cost (S\$)			13,820.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >