

ASS. REC. BY:

REF: CS/CT219022773/09d3n2

Special Instruction:

Survey: Melrus

ASSIGNMENT (Office)

From (Person): Chong Soon Sen

of CTI

Date/Time: 27/12/09 11:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV556S

Insured: YP6796S

at Workshop in/s: Zoom Autowerks

Tel: 94507920

of 15 Kaki Bukit Road 4 # 01-53

Policy No: DMCVSN18191719011

Claim No: SNM19D20610902

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/12/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:03pm @ 27/12/19

Person Contacted: Gileen

Vehicle: IN/OUT

Date/Time	Action/Instruction
	<u>Vehicle in</u>
	<u>NO 6796S NO/27/12/09 22773/09d3n2</u>
	<u>SKV556S NO/27/12/09 22773/09d3n2</u>

(08/11/13) waf

ASS. REC. BY: Marcus

REF:

C711

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKU5565
 at Workshop m/s: Zoom
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKU5565 Yr Regn: 27/8/15
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Honda Odyssey c.c. 2358
 Colour: white A/C Insured / Std / NI / NA
 Sp. Reading: 88570 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMR C1890FC 202 433
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Worder / Jammed / Leaked / Burnt or
 Brake: Worder / Jammed / Leaked / Burnt or
 Modi: Nil S/Rip / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
NIS	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. or Market Value: 84
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 8895
 Date: _____ Person Contacted: next 17763 Vehicle: IN / OUT

Tyre Size: F: _____ R: 235/35R19
 BS / DUN / EXNOVA FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 24/1/19 D.O.I. 27/1/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or
Rear to R.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
14/1/20 2/5 @ 14.000 confirmed with Elin
(Red @ 16630.22, 54%)

RECEIVED 21 JAN 2020

Date/Time. File Pass to? : Prell. Report
 : Final Report
 Date/Time. File Return to?

Days Of Repair: 10
 Resurvey No. of Trip: 1

Report Format: MEB.70
 Lump Sum / I.B.A. (\$) 14000

Add Fee: : Site Insp (\$ _____)) \$ + RS. \$
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))

SURVEY FEE	
TRANSPORTATION	
TOTAL	220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 27 December 2019 11:17 AM
To: Zoom Autowerks
Cc: 'assignments'
Subject: RE: OUR REF: SNM19D206109/YP6796S/CBS & YOUR REF: SKV556S -Pre-Repair Inspection for SKV 556 S // Accident on 24/12/2019 @ 18:05HR at along Ubi Avenue 1, after Ubi Road 1 involving Vehicle Number SKV 556 S & YP 6796 S

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Friday, December 27, 2019 10:07 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D206109/YP6796S/CBS & YOUR REF: SKV556S -Pre-Repair Inspection for SKV 556 S // Accident on 24/12/2019 @ 18:05HR at along Ubi Avenue 1, after Ubi Road 1 involving Vehicle Number SKV 556 S & YP 6796 S

Dear All,

Kindly arrange Marcus Chua.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road
#08-1339 Singapore 470130
☎9450 7920
✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Thu, Dec 26, 2019 at 2:57 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice
Dear Sir,
LKK
LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, December 26, 2019 2:27 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; zoomautowerks@gmail.com

Subject: OUR REF: SNM19D206109/YP6796S/CBS & YOUR REF: SKV556S -Pre-Repair Inspection for SKV 556 S // Accident on 24/12/2019 @ 18:05HR at along Ubi Avenue 1, after Ubi Road 1 involving Vehicle Number SKV 556 S & YP 6796 S

Dear Boon Sen,

Please conduct PRS –SKV556S soonest possible.

File to officer in charge- Chong Boon Sen- DID: 6389 6171.

Dear Elin,

**** kindly quote our reference number when replying ******

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Wednesday, 25 December, 2019 7:38 PM

To: Claims Dept of CTI

Subject: Pre-Repair Inspection for SKV 556 S // Accident on 24/12/2019 @ 18:05HR at along Ubi Avenue 1, after Ubi Road 1 involving Vehicle Number SKV 556 S & YP 6796 S

Dear Sir/Madam,

We are instructed by Letz Interior LLP to notify you of a road traffic accident on 24

/12/2019

at about 18:05HR at along Ubi Avenue 1, after Ubi Road 1 involving our client's vehicle registration number SKV 556 S and vehicle registration number YP 6796 S driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178 08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

Range Rover Evoque

Volkswagen Sharan..

Nostalgic Photos from

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Suzuki Vitara 1GLX.6A @ \$68,300 Only .



1 Owner, Agent (Champion Motors) Unit, Zero Drive Away! 1.98% Interest Rate, Low Hamilton Autohub Pte StarAd

PRIME MOTOR
ICHENG YONG CREDIT ENTERPRISES PTE LTD
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

8 vehicles

Honda Odyssey

Sort by Date Posted

Advanced Search

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Honda	Odyssey	Any	Any	2015	Any	Any	Any



Honda Odyssey 2.4A EX-S

\$86,800

\$12,300 /yr

09-Dec-2015

2,356 cc

46,788 km

MPV

Comes With Agent Warranty Till Dec 2020 For Peace Of Mind! One Of The Best Handling, Popular And Reliable Japanese MPV Around! Equipped With A 2.4L I-VTEC Earth Dreams Engine Ensuring A Powerful And Fuel Efficient Drive! Spacious Cabin For Families To Travel...
Select By Performance Premium Selection

Posted: 01-Jan-2020 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



Honda Odyssey 2.4A EXV-S Sunroof

\$87,000

\$12,800 /yr

15-Jul-2015

2,356 cc

62,126 km

MPV

Free 6 Months Road Tax! 1 Owner In Smokey Topaz Metallic! A Slight Hue Of Purple! Low Mileage! 5 Years Agent Warranty! Full Agent Service Records! Highest Spec Unit With Rear Seats Entertainment System! Pricing At Lowest Depreciation And Lower Than Most Basic S...

Posted: 01-Jan-2020 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



Honda Odyssey 2.4A Absolute

\$95,000

\$14,590 /yr

21-May-2015

2,356 cc

105,400 km

MPV

Pre Loved, Well Maintained And All Major Servicing Done For Peace Of Mind. Accident Free. Call To Arrange To View Or Test Drive In West Area.

Posted: 30-Dec-2019 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



Honda Odyssey 2.4A EXV-S Sunroof

\$89,800

\$12,700 /yr

22-Oct-2015

2,356 cc

76,578 km

MPV

HURRY! 1.98% New Year Special Interest Rate, Warranty By Kah Motor Till Oct 2020. Free Ceramic Coating Worth \$888 Come With 5 Years Warranty. Agent Maintained, Can Arrange For STA Evaluation, High Trade In Up To \$2K More And Flexible High Loan Available, PL...
Accendore Autolution Pte Ltd

Posted: 29-Dec-2019 Tags: 2015 Honda Odyssey, 2015 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda



Enhance Interior Outlook With CF Steering

Honda Odyssey RC1 Carbon Fibre Steering Wheel.

More info about this product

1a Odyssey 2.4A EXV-S

\$82,800

\$11,290 /yr

08-Dec-2015

2,356 cc

142,904 km

MPV

3,000 Below Market (Only \$11,200 Depreciation) Yet Price Negotiable If Ok With Slight Higher Mileage! Agent Serviced With

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	859F
Vehicle Details	
Vehicle No.:	SKV556S
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	K24W71011141
Chassis No.:	JHMRC1890FC202433
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$26,576.00
Original Registration Date:	27 Aug 2015
First Registration Date:	27 Aug 2015
Transfer Count:	1
Actual ARF Paid:	\$29,207.00 <i>1x603</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2025
PARF Rebate Amount:	\$21,905.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,789.00
COE Rebate Amount:	\$34,332.00
Total Rebate Amount:	\$56,237.00

The information contained herein is correct as at 02 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2019 19:36
Date Of Accident	24/12/2019 18:05
Exact Location Of Accident	UBI AVE 1 AFTER UBI RD 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV556S
Insured/Policyholder	
Name Of Registered Owner	LETZ INTERIOR LIMITED LIABILITY PARTNERSHIP
Co Reg No	TXXXXX859F
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	HONDA
Model	ODYSSEY 2.4 EXV-S CVT SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3029201900
Cover Note Number	
Driver	
Name of Driver	LIM HAO SHENG
NRIC No	SXXXX222G
Date Of Birth	28/06/1985
Occupation	INDOOR
Date Of Driving Pass	27/09/2005
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92319960
Fax Number	
Contact Number	OFFICE-92319960
E-Mail Address	NOEMAIL

Address	BLK 615B EDGEFIELD PLAINS #02-347
Postcode	822615
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6796S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBA9931A
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may affect insurance companies to **repealate policy liability**.
4. The filing and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by concerned parties.
7. In the absence of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
- I, the undersigned, acknowledge, agree and consent that:
- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, process and/or process my personal data/personal information set out in this Form and any other personal information provided by me or provided by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Financial Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - investigating, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - investigating the accident and/or my claims;
 - complying with and/or dealing with my instructions or responding to any enquiries by me;
 - administering my claims (including the mailing of correspondence, statements, notices, reports or notices to me, which said notices disclose(s) of certain personal data about me to bring about delivery of the same as well as on the external email or messenger/instant packages), and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agencies (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, management and management in amount and all future claims.
 - any information or collected under (a) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated; or
 - for compliance with requirements under any regulations, laws or court orders.

LETZ
INTERIOR
LLP

This Form to be signed by
Policyholder


Driver's Signature
(Driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/IN No

Accident Sketch Plan

SKETCH PLAN

vehicle A: SKV556S
 vehicle B: YP6796S
 vehicle C: GBA9931A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date & time, I, vehicle A
 , SKV556S, was traveling straight along the stated
 venue. Front vehicle made an abrupt stop & I
 stopped as well. Suddenly, vehicle B, YP6796S,
 hit onto my stationary vehicle's rear portion, which
 propel my vehicle forward & hit onto the front
 vehicle

DECLARATION

LEIT
 INTERIOR
 LLP

LEIT
 INTERIOR

[Signature]

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

[Signature]

Reporting Officer's Signature
 Name
 Title (if any)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

*not Arthur
 LHK*

31 December 2019

*1/5# 14,000
 10 day.*

REG NO.: SKV 556 S
 MAKE/MODEL: HONDA ODYSSEY

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	LIST ITEMS	
1	Front bonnet	\$ 22 860.60 ✓
1	Front bonnet lock	\$ 7m 89.80 ✓
1	Front bonnet rubber	\$ 17 48.00 X
2	Front headlamps (HID) @ 1655 x 2 = 3310.	\$ CRU 3310.00 ✓
2	Front headlamp control units (HID)	\$ 17 617.20 X
1	Front bumper	\$ 22 779.20 ✓
1	Front bumper clip (1 set) 665.30	\$ 22 50.00 ✓
1	Front bumper fog lamps 38.00	\$ OFSCM 1,481.80 1PC
2	Front bumper fog lamp covers 450.30	\$ OFSTEIN 85.00 1PC
1	Front bumper lower grille 42.50	\$ TON 105.10 ✓
1	Front bumper lower spoiler	\$ 2 628.90 X
1	Front bumper reinforcement	\$ BEAT 230.20 ✓
2	Front bumper side retainers 26.50	\$ OFSDET 77.00 1PC
1	Front fender -R/H	\$ 2 529.50 X
1	Front support panel	\$ 2 748.50 X
1	Front brace panel	\$ 17 100.98 X
2	Horns	\$ 17 176.00 X
1	Air con condenser	\$ 17 882.70 X
1	Air intake duct	\$ 17 185.00 X
1	Rear windscreen glass 1011	\$ 320 1,103.50 ✓
2	Rear windscreen inner side garnishes	\$ 17 156.00 X
1	Rear windscreen inner top garnish -Centre	\$ 17 80.00 X
1	Rear windscreen moulding	\$ 22 109.80 ✓
1	Rear tailgate 1070.50	\$ BODY 1,952.50 ✓
2	Rear tailgate dampers	\$ 17 253.00 X
1	Rear tailgate inner trim board	\$ TON 299.60 ✓
2	Rear tailgate lamps 386.20 x 2 = 772.40	\$ CRU 1,078.20 ✓
1	Rear tailgate inner lock	\$ 22 205.70 ✓
1	Rear tailgate weatherstrip	\$ 2m 115.10 ✓
1	Rear tailgate reflector -Centre	\$ SCH 560.90 ✓
1	Rear wiper arm	\$ 17 68.50 X
1	Rear wiper blade	\$ 17 48.30 X
1	Rear wiper motor	\$ SM 426.50 ✓
2	Rear taillamps	\$ CRU 1,462.40 ✓
2	Rear taillamp lower garnishes 299.30	\$ NLS DE 665.00 1PC
1	Rear end panel 405.00	\$ OFDET 637.50 ✓
1	Rear end panel inner garnish	\$ 2m 246.40 ✓
		\$ 18,995.58

LIST ITEMS

1	Rear bumper	665.30	\$ DWS	1,557.20	✓
2	Rear bumper brackets		\$ Bery	111.20	✓
1	Rear bumper reinforcement		\$ NS	197.20	✓
2	Rear bumper lower mouldings		\$ 17	232.40	✓
1	Rear bumper tow hook cover		\$ 17	28.60	✓
2	Rear bumper side retainers		\$ 17	97.20	✓
2	Rear bumper reflectors		\$ 17	127.60	✓
4	Rear bumper PDC sensors		\$ slud	1,159.60	3005-✓
1	Rear bumper PDC sensor buzzer		\$ 22	158.90	✓
1	Rear floor board		\$ 17	210.00	✓
1	Rear floor panel		\$ 17	1,260.50	✓
2	Rear fenders		\$ 2	1,869.60	✓
2	Rear fender inner trim garnishes		\$ delton	911.20	✓
2	Rear fender quarter glass with mouldings		\$ 17	921.00	✓
			\$	27,837.78	
			Less 20%	\$ 5,567.56	
			\$	22,270.22	

SPECIAL NETT ITEMS

1	Front sport grille "MUGEN"		\$ CM	450.00	✓
1	Front bumper chrome moulding		\$ CM	380.00	✓
1	Front number plate with holder		\$ Bery	50.00	✓
1	Front camera		\$ slud	480.00	✓
1	Rear windscreen sealant		\$ 22	80.00	40
1	Rear tailgate chrome moulding		\$ CM	280.00	✓
1	Rear bumper clip (1 set)		\$ 22	50.00	35
1	Rear number plate with holder		\$ 22	50.00	✓
1	Rear reverse camera		\$ slud	480.00	380
2	Rear fender quarter glass sealants		\$ 17	160.00	✓
			\$	2,460.00	

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00		
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30	
3	To remove and refit inner garnishes.	\$	180.00	80	
4	To remove and refit rear reverse sensor and camera.	\$	180.00	50	
5	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00	60	
6	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	17	180.00	✓
7	To remove and refit rear windscreen glass.	\$	180.00	120	
8	To apply undercoating.	\$	300.00	100	
9	Panel beating.	\$	2,400.00	1400	
10	To re-spray painting on the affected areas.	\$	2,200.00	1800	
		\$	5,900.00		

GRAND TOTAL :

31797.26
\$ 30,630.22

• Repayment of excess must be received and approved by the Insurance Company

P-14491.7
2022
P-11592.88
S.N-2395.00
L-3640.00
17627.88
14102.30

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19022773/UQD3N2
Date: 29/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN18191719011
Claimant Vehicle No : SKV556S **Insured Vehicle No :** YP6796S
 Date of Loss: 24/12/2019 Nature of Claim: TP Claim No: SNM19D206109C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV556S**
 Make & Model: HONDA ODYSSEY, 2.4 EXV (RB1) (A) Engine No: K24W7101114
 Reg. Date: 27/08/2015 (Man. Year: 2015) Chassis No: JHMRC1890FC202433
 Colour: White Odometer: 88570 km
 Engine Capacity: 2356 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19 Rear Tyre Size: 235/35R19
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,897.26	13,987.88	11,909.38	45.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,900.00	3,640.00	2,260.00	38.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,797.26	17,627.88	14,169.38	44.56
Approved Total (Overridden) (S\$)		14,000.00		
Nett Amount (S\$)	31,797.26	14,000.00	17,797.26	55.97

INSPECTION

Date of Assignment: 30/12/2019
 Date Inspected: 27/12/2019 Inspected At: 15 Kaki Bukit Road 4# 01-53
 130 Bedok Reservoir Road, Eunos Spring, #08-1339
 Singapore 470130
 Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jan 2020)

Parts: M1-MPV HONDA ODYSSEY 2.4 EXV (RB1) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV556S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	860.60 FL	*860.60 FL
2	1		*FRONT BONNET LOCK	Twisted	89.80 FL	*89.80 FL
3	1		*FRONT BONNET RUBBER	Not Necessary	48.00 FL	*- FL
4	2		*FRONT HEADLAMPS (HID)	Cracked	3,310.00 FL	*3,310.00 FL
5	2		*FRONT HEADLAMPS CONTROL UNITS (HID)	Not Necessary	617.20 FL	*- FL
6	1		*FRONT BUMPER	Dented	779.20 FL	*665.30 FL
7	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FL	*38.00 FL
8	1		*FRONT BUMPER FOG LAMPS	O/s Cracked	1,481.80 FL	*450.50 FL
9	1		*FRONT BUMPER FOG LAMP COVERS	O/s Torn	85.00 FL	*42.50 FL
10	1		*FRONT BUMPER LOWER GRILLE	Torn	105.10 FL	*105.10 FL
11	1		*FRONT BUMPER LOWER SPOILER	Repair	628.90 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	230.20 FL	*230.20 FL
13	1		*FRONT BUMPER SIDE RETAINERS	O/s Bent	77.00 FL	*26.50 FL
14	1		*FRONT FENDER-R/H	Repair	529.50 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Repair	748.50 FL	*- FL
16	1		*FRONT BRACE PANEL	Not Necessary	100.98 FL	*- FL
17	2		*HORNS	Not Necessary	176.00 FL	*- FL
18	1		*AIR CON CONDENSER	Not Necessary	882.70 FL	*- FL
19	1		*AIR INTAKE DUCT	Not Necessary	185.00 FL	*- FL
20	1		*REAR WINDSCREEN GLASS	Broken	1,103.50 FL	*1,011.00 FL
21	2		*REAR WINDSCREEN INNER SIDE GARNISHES	Not Necessary	156.00 FL	*- FL
22	1		*REAR WINDSCREEN INNER TOP GARNISH-CENTRE	Not Necessary	80.00 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Necessary	109.80 FL	*109.80 FL
24	1		*REAR TAILGATE	Badly Dented	1,952.50 FL	*1,070.80 FL
25	2		*REAR TAILGATE DAMPERS	Not Necessary	253.00 FL	*- FL
26	1		*REAR TAILGATE INNER TRIM BOARD	Torn	299.60 FL	*299.60 FL
27	2		*REAR TAILGATE LAMPS	Cracked	1,078.20 FL	*772.40 FL
28	1		*REAR TAILGATE INNER LOCK	Dented	205.70 FL	*205.70 FL
29	1		*REAR TAILGATE WEATHERSTRIP	Twisted	115.10 FL	*115.10 FL
30	1		*REAR TAILGATE REFLECTOR-CENTRE	Scratched	560.90 FL	*560.90 FL
31	1		*REAR WIPER ARM	Not Necessary	68.50 FL	*- FL
32	1		*REAR WIPER BLADE	Not Necessary	48.30 FL	*- FL
33	1		*REAR WIPER MOTOR	Jammed	426.50 FL	*426.50 FL
34	2		*REAR TAILLAMPS	Cracked	1,462.40 FL	*1,462.40 FL
35	1		*REAR TAILLAMP LOWER GARNISHES	N/s Deformed	665.00 FL	*299.30 FL
36	1		*REAR END PANEL	Dented/Bent	637.50 FL	*405.00 FL
37	1		*REAR END PANEL INNER GARNISH	Twisted	246.40 FL	*246.40 FL
38	1		*REAR BUMPER	Distorted	1,557.20 FL	*665.30 FL
39	2		*REAR BUMPER BRACKETS	Bent	111.20 FL	*111.20 FL
40	1		*REAR BUMPER REINFORCEMENT	No such part	197.20 FL	*- FL
41	2		*REAR BUMPER LOWER MOULDINGS	Not Necessary	232.40 FL	*- FL
42	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.60 FL	*- FL
43	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	97.20 FL	*- FL
44	2		*REAR BUMPER REFLECTORS	Not Necessary	127.60 FL	*- FL
45	1		*REAR BUMPER PDC SENSOR BUZZER	Not Necessary	158.90 FL	*- FL
46	1		*REAR FLOOR BOARD	Not Necessary	210.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FLOOR PANEL	Not Necessary	1,260.50 FL	*- FL
48	2		*REAR FENDERS	Repair	1,869.60 FL	*- FL
49	2		*REAR FENDER INNER TRIM GARNISHES	Deformed/Torn	911.20 FL	*911.20 FL
50	2		*REAR FENDER QUARTER GLASS WITH MOULDINGS	Not Necessary	921.00 FL	*- FL
51	1		*REAR BUMPER PDC SENSORS	Shorted	927.68 FS	*300.00 FS
52	1		*FRONT SPORT GRILLE MUGEN	Cracked	450.00 FS	*450.00 FS
53	1		*FRONT BUMPER CHROME MOULDING	Cracked	380.00 FS	*380.00 FS
54	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*50.00 FS
55	1		*FRONT CAMERA	Shorted	480.00 FS	*480.00 FS
56	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
57	1		*REAR TAILGATE CHROME MOULDING	Cracked	280.00 FS	*280.00 FS
58	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*35.00 FS
59	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
60	1		*REAR REVERSE CAMERA	Shorted	480.00 FS	*380.00 FS
61	2		*REAR FENDER QUARTER GLASS SEALANTS	Not Necessary	160.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$)	31,524.66	16,886.10
- List Item Discount on L Items 20.00/20.00% (\$)	5,627.40	2,898.22
Total Parts (\$)	25,897.26	13,987.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING)	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	180.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	0.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
8	TO APPLY UNDERCOATING	New	300.00	100.00
9	PANEL BEATING	New	2,400.00	1,400.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,200.00	1,800.00
Gross Labour Cost (S\$)			5,900.00	3,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >