

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ben Tang

Date: 02 Jan 2020

Preliminary Advice

Vehicle No	: SKU4319P	Accident Date	: 23/12/2019
Make	: HONDA VEZEL	Policy No.	: DMPCSN3072301802
Assignment Date	: 27/12/2019	Excess	: S\$0.00
Date of Inspection	: 2/1/2020	Est. Duration of Repair	: 5
Inspection At	: JIN AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,167.32
Revised Amount	:S\$	1,758.72
Check Items (Estimated)	:S\$	3,305.00
Total	:S\$	5,063.72
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	37,087.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,913.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part, as there is no 2nd hand parts available.