

ASS. REC. BY:

REF: CS/CTI/9022776/Uvd3ek Special Instruction:

Survey: MORIS

ASSIGNMENT (Office)

From (Person):

Merimen

Ben Long

of

CTI

Date/Time:

27/12/19 @ 11:55am

Estimated Cost:

Bill to:

OD / HP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKU 4319 P

Insured:

at Workshop n/s:

Sin Auto

Tel:

6289 8126.

of

Blk 14 Defu Lane 10 # 01-410/412

Policy No:

DMPCSN307 2301802

Claim No:

SNM19D206120/sku 4319P/BEN

Sum Insured:

Excess:

78A 0

Make of Veh:

(Client's Record)

D.O.A.

23/12/19

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:44pm @ 27/12/19

Person Contacted:

Jouis

Vehicle-IN/OUT

Date/Time

Action/Instruction

Johny ✓

SKU 4319P-X

21/12/20

Revert via merimen, vehicle repair on part by part

31/12/20

Rece authorise repair from Alfred by merimen

31/12/20

Informed Jouis C/A ex 0 by email

CTI c8/c1119022776/Uvd3

ASSIGNMENT

From: Date: 2/1/2020
Estimated Cost:
To Inspect Vehicle No: SKU 4319 P
at Workshop no: Jin Auto
of Blk 14 Defu Lane 10 # 01-412
Insured:
Policy No:
Claims No:
Sum Insured: Excess: TBA
(Client's Record)
Make of Veh:

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: 47k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 5- days Res: Yes or No
Lum Sum: 151 % 3 Val: Yes or No
CA / (REV) REP. / 24 HRS 'up' 119x
Date: Person Contacted: Vehicle: IN / OUT

N/S	O/S

Veh No: SKU 4319 P Regn: 7 15
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CAI
Make: Honda yezel cc 1496
Colour: Black A/C: Insured / Std / NI / NA
Sp Reading: 5955 / T/Radio: Insured / Std / NI / NA
Eng No:
C/No: RU 111 0069 X
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215 / 60 R 16
R:
BS / DUNLOP / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 6 mm Rear: 6 mm
R/Bal: 6 mm L/Bal: 6 mm
D.O.A: 23/1/19 D.O.L: 2/1/20
Survey held at:
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

20/2/20
Date / Time Action / Instruction
LTA 37087 540.7km.
Wksp asking P/P because No second hand parts.
Bonaet call open insure still want to drive his car
Repairs didn't arrange before finally submit merimen already.
4117.80 Confirmed with Ins. (Red 1174.52, 22%) (No LS)
RECEIVED 25 FEB 2020

Days Of Repair: 5
Resurvey No. of Trip: 1
Add Fee: Site Insp (\$)
Interview (\$)
Tech Insp (\$)
Work used (\$)
Survey Fee: 220
Transportation: 3 + 10 = 13
Phone: 1000
Other: 1000
Total: 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	26 Dec 2019 Sendback Est	26 Dec 2019 11:16 S\$5,167.32	27 Dec 2019 11:55 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	WONG SIEN RUEY, ID: SXXXX119Z		
Vehicle Reg. No.:	SKU4319P	Date of Loss:	23/12/2019 11:00 - :59 [52 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D206120/SKU4319P/BEN	Policy/Cover Note No.:	DMPCSN3072301802 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/01/2020]		
Driver/Custodian:	MA YAFANG (/ Female) , NRIC: SXXXX533H Email:		
Adj Asg. Remarks:	Please arrange to survey of insured vehicle SKU4319P.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 3 January 2020 2:42 PM
To: jous; SUR
Subject: SKU 4319P-DOA: 23/12/2019 (CHINA TAIPING OD)

Dear Jouis,

As instructed by our client , please proceed to repair the **insured vehicle SKU 4319P (Excess S0)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKU4319P (SNM19D206120/SKU4319P/BEN)

OD

Dec 23 2019 11:00AM

[WONG SIEN RUEY]

Jin Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 03/01/2020 14:25 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5063.72) - SKU4319P - Claim Handler: Ben Tang

Approved:5063.72:Please proceed to authorize repairs at \$1,758.72 and UP TO \$5,063.72. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Ben Tang	Date:	02 Jan 2020

Preliminary Advice

Vehicle No	: SKU4319P	Accident Date	: 23/12/2019
Make	: HONDA VEZEL	Policy No.	: DMPCSN3072301802
Assignment Date	: 27/12/2019	Excess	: S\$0.00
Date of Inspection	: 2/1/2020	Est. Duration of Repair	: 5
Inspection At	: JIN AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,167.32
Revised Amount	:S\$	1,758.72
Check Items (Estimated)	:S\$	3,305.00
Total	:S\$	5,063.72
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	37,087.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,913.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part, as there is no 2nd hand parts available.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 119Z

Vehicle Details

Vehicle No.: SKU4319P
Vehicle to be Exported: No
Intended Deregistration Date: 02 Jan 2020
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: L15B4020696
Chassis No.: RU11100694
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$17,984.00
Original Registration Date: 27 Jul 2015
First Registration Date: 27 Jul 2015
Transfer Count: 0
Actual ARF Paid: \$7,984.00 392

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Jul 2025
PARF Rebate Amount: \$5,988.00

Intended COE Rebate Details

COE Expiry Date: 26 Jul 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,889.00
COE Rebate Amount: \$31,099.00
Total Rebate Amount: \$37,087.00

The information contained herein is correct as at 02 Jan 2020

OK

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Sell by Consignment

Consign your car to sell direct at the price you want without hassle.
No sale = no charges!

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW X1 SDrive 18d Sport (2.0M)

High Spec Premium Model! BMW
2.0M Turbo, Manly Manual
Transmission, Low Mileage!
Direct Owner StarAd

HIN LUNG AUTO

Ho Bee Group

30 years of car sale

One Stop Car Hub

Finance, Insurance, Workshop

New and Used Cars

Browse by Category

25 vehicles

Back (1 2) Next >

Sort by Date Posted

20 results/page

Search Selection

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Vezel

Any

Any

2015

Any

Any

Any

Available

Honda Vezel 1.5A X

\$56,800

\$8,950 /yr

05-Nov-2015

1,496 cc

52,000 km

SUV

Available

Sporty Look! 1 Owner Only, Very Low Mileage Clocked! Pristine Condition! Comes With Nice Car Plate Number! Low Interest Rate Just At...

Posted: 01-Jan-2020 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel 1.5A X

\$53,800

\$8,970 /yr

15-Jul-2015

1,496 cc

49,800 km

SUV

Available

SKL Automobile Pte Ltd

Posted: 11-Dec-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel 1.5A X Honda Sensing

\$54,800

\$8,910 /yr

27-Aug-2015

1,496 cc

51,000 km

SUV

Available

New Arrival! 1 Owner! AA Trust Certified Quality Vehicle! Cheapest High Spec Honda Sensing Unit Comes With Honda Sensing And Depa...

AA Trust Automotive

Posted: 30-Dec-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel 1.5A X

\$64,800

\$11,110 /yr

19-Jun-2015

1,496 cc

-

SUV

Available

This Baby Right Here, Is A Very Rare Green Coloured Masterpiece Which Was Well Kept By The Previous Owner. Help This Baby To Get...

Car House Pte Ltd

Posted: 28-Dec-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Style Vezel With Quality Leather Upholstery

Quality Half-Leather Upholstery For Honda Vezel Car Seat. Comes with an 15-month warranty & Life-Time Cleaning Service

More info about this product

Honda Vezel 1.5A X

\$57,800

\$9,060 /yr

17-Nov-2015

1,496 cc

18,895 km

SUV

Available

New Year Promo! Super Low Mileage 19KM Only! 1 (Non Grab) Owner! Bank And In House Full Loan At Low Interest Rate! Original Sto...

Posted: 28-Dec-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel 1.5A X

\$54,800

\$8,460 /yr

10-Dec-2015

1,496 cc

70,000 km

SUV

Available

Immediate Transfer Of Ownership For Peace Of Mind! No Delays! 1 Owner Only! Original Condition With Upgraded Sport Rims! This Unit...

GS Automobiles Pte Ltd

Posted: 28-Dec-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel 1.5A X

\$55,800

\$8,700 /yr

23-Nov-2015

1,496 cc

87,000 km

SUV

Available

Non PHV Car, Well Maintained And Serviced Regularly By Owner, New Paint Work, High And Full Loan Available. Please Text Or Contact...

Compare

https://www.sgcarmart.com/used_cars/listing.php?RGD=2015&MOD=Vezel&RPG=20&VEH=0&AVL... 02-Jan-20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2019 12:13
Date Of Accident	23/12/2019 11:30
Exact Location Of Accident	HOUGANG AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU4319P
Insured/Policyholder	
Name Of Registered Owner	WONG SIEN RUEY
NRIC No	SXXXX119Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83385288
Alternative Phone No	OFFICE-81816188

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3072301802
Cover Note Number	

Driver

Name of Driver	MA YAFANG
NRIC No	SXXXX533H
Date Of Birth	24/01/1973
Occupation	INDOOR
Date Of Driving Pass	14/04/2010
Driving Experience	9 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81816188
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	95 JOO CHIAT TERRACE
Postcode	427252
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE DRIVING ALONG HOUGANG AVE 3, I ACCIDENTALLY HIT VEHICLE B'S REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ2608S
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

24/11/19
11:40am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NUIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

DOA: 23/11/2019
A: SKU 439A
B: 2KZ26080.

Hougang Ave 3.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHILE DRIVING ALONG HOUGANG AVE 3, I ACCIDENTALLY HIT
VEHICLE B REAR PORTION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

 1 Arden Road #15-01 Springbank Tower Singapore 079106
 Tel: 6399 0111 Fax: 6325 1033
 Website: www.cti.com.sg
 Co. Reg. No. 200224294E

RENEWAL NOTICE

YOU CAN NOW PAY YOUR PREMIUM BY:-

1. ANY AXE STATIONS, OR
2. 0% INTEREST INSTALLMENT PLAN WITH OCBC CREDIT CARD SUBJECT TO A MINIMUM AMOUNT OF S\$500.00 CHARGED TO THE CARD.

Agency	AN2006A	Class of Policy	MOTOR PRIVATE CAR	Policy Number		DMPCSN1072301402
Account	AN2006A	Ren. Notice Date	22/05/2019	Expiry Date		26/07/2019
Client	6018979					

Renewal Period from 27/07/2019 to 26/07/2020 . both dates inclusive

 Insured's Name.... **WONG SIEM KHEE**

 Address.....
25 JOO CHIAI TERRACE
SINGAPORE 427252

 Business/Occupation... **MANAGER**

 Financial interest **WONG LEONG FINANCE LTD AS HP OWNER**

Premium	Base Annual Premium	S\$1,918.00		
	Less 15% Loyalty Discount	S\$167.70-		
	Less 20% Autosave Scheme	S\$126.06-		
	No Claim Discount	25.00%		
	Total Annual Premium	S\$913.97	Renew. Prem.	S\$913.97
			Premium GST	S\$63.91
			Total	S\$976.88

 * WEF 02.01.2019, THERE WILL BE NO REFUND FOR CANCELLATION IF THERE *
 * IS A WINDSCREEN CLAIM DURING THE POLICY PERIOD. *

Risk No. 001	MOTOR PRIVATE CAR			
	ORIGINAL REGISTRATION DATE:	27-07-2015		
1. Registration	SK04313P	Make/Model ..	HONDA VEZEL 1.5 I-VTEC (A)	
Type of Cover	Comprehensive	No. of seats	5	Body Type SUV
Engine No. ..	L15B4026696	Capacity cc's	1496	Yr of Manuf./Regn 2015/2015
Chassis No. ..	KU11106594			
				Certificate Ref. WK1F
Sum Insured..Market value at the time of loss				
Named Drivers Ex Sect. I		S\$500.00		
Additional & Other than Named Drivers:				
Ex Sect. I - Age <= 25		S\$3,000.00		
Ex Sect. I - Age >= 26		S\$500.00		
* Age as at date of accident				
EX ON WINDSCREEN		S\$100.00		
Named Drivers THE INSURED		MA YA FANG		

The following clauses and endorsements apply to this policy :

 Subject to Endts. 2, 25, 57, 72, 8 & W(undtd).
 AUTOSAVE SCHEME (W)

Continued on page 2

Alfa Credit Pte Ltd

1 Commercial Link

801 28 The Esplanade

Singapore 118544

Tel: 6644 6241 1275, 6244 4444 Fax: 6644 6232

Email: info@alfacredit.com.sg

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Insurer Reference: DMPCSN3072301802
Repairer Reference: SKU4319P
Date calculated: 26/12/2019 11:09 AM

Full Report
Registration: SKU4319P
Printed: 26/12/2019 11:11 AM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	DMPCSN3072301802	Date of Incident:	23/12/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	


Vehicle Details

Vehicle Manufacturer:	HONDA	<i>not allowed</i> <i>hbl</i> <i>Express?</i> <i>2/1/20</i> <i>Sing.</i>	
Model:	VEZEL RU1/5		
Sub Model:	LX		
Model Sheet Number:	35 VE 08		
Registration:	SKU4319P		
VIN number:			
Odometer:			
Model Specs			
AUTO AIR CON	LED HEADLAMP	1496CCM 97KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:
Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h Price = 42.00 SGD/h

Code	Description		WU	Price SGD
NO NUMBER	RENEW FRONT PANEL		32.0	134.40
8101A2	RENEW FRONT BUMPER		12.0	50.40
813110)	RENEW RADIATOR GRILLE		4.0	16.80
812100	RENEW BONNET		11.0	46.20
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE			
8121B6)	R + R L/BONNET SEAL		3.0	12.60
8121B7)	R + R R/BONNET HINGE		3.0	12.60
NO NUMBER	R + R BOTH FRONT WINGS (BUMPER REMOVED)		17.0	71.40
	INCLUDES: R + R FRONT HEADLAMPS, SILL COVER AND REQUIRED ATTACHED PARTS.			
NO NUMBER	R + R L/FRONT SCREEN FRAME AIR GRILLE		1.0	4.20
NO NUMBER	R + R R/FRONT SCREEN FRAME AIR GRILLE		1.0	4.20
616100)	R + R CONDENSER		2.0	8.40
620020	DRAIN + REFILL AIR CONDITIONING		7.0	29.40
0741	L/F WING REPAIR	0.5	20.0*	84.00
0742	R/F WING REPAIR	0.5	20.0*	84.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		13.30	133.0	558.60
Total of Labour				558.60

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT PANEL CPL SURFACE PAINT		6.0	
	FRONT BUMPER NEW PART PAINT K1G/P		21.0	
	BONNET REPAIR PAINTING >50%		32.0	
	L/F WING SURFACE PAINT		5.0	
	R/F WING SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD
1009	FRONT PANEL CPL SURFACE PAINT	11.21
0283	FRONT BUMPER NEW PART PAINT K1G/P	79.20
0471	BONNET REPAIR PAINTING >50%	50.17
0741	L/F WING SURFACE PAINT	7.72
0742	R/F WING SURFACE PAINT	7.72

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			69.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	10.20	102.0	428.40

Material Cost - Paint

Price SGD

New Part Painting - Plastic K1G/PUR
Repair Painting
Surface-/Blend Paint
Material-constant Metal Preparation
Material-constant Plastic
Total

79.20
50.17
26.65
28.60
12.70
197.32

Spare Parts

				prices as at 2015-06-01/01	Price SGD
Code	Description	Part Number	Supplier		
0257	FRONT NUMBER PLATE	KNPL3		Ref	35.00 ✓
0283	FRONT BUMPER	71101T7JH00ZZ ✓		Torn	185.00 ✓
0340	FRT BUMPER SUPPORT	71130T8NT00ZZ ✓		Ref 181	0.00 ✓
0343	L/BUMPER CORNER	71190T7A000 ✓		25 Ref	19.00 ✓
	BRKT			25 Ref	10.00 ✓
0344	R/BUMPER CORNER	71140T7A000 ✓			
	BRKT			11	0.00 ✓
0345	L/F AIR DUCT	71116T8NT50		17	20.00 ✓
0346	R/F AIR DUCT	71111T8NT50		cm	250.00 ✓
0410	GRILLE	71121T8NQ50 ✓		cm	20.00 ✓
0413	RAD GRILLE BRACKET	71150T7JH00 ✓		15 cm	20.00 ✓
0415	L/RAD-GRILLE BRACKET	71152T7A000 ✓		17	20.00 ✓
0416	R/RAD-GRILLE BRACKET	71151T7JH00 ✓		15 cm	250.00 ✓
0424	RAD GRILLE COVER	71122T8NT50 ✓		Ref	18.00 X
0431	GRILLE BADGE	75700TA0A00		20 500	28.00 ✓
0435	L/GRILLE TRIM	71128T8NT00 ✓		20 500	28.00 ✓
0436	R/GRILLE TRIM	71123T8NT00 ✓			460.00 X
0471	BONNET	60100T8NT00ZZ		Ref	35.00 ✓
0475	L/BONNET HINGE	60170T8NT01ZZ ✓		Ref	35.00 ✓
0476	R/BONNET HINGE	60120T8NT01ZZ ✓		Ref	65.00 ✓
0492	BONNET LOCK	74120T7WA01.		cm	850.00 ✓
0561	L/F HEADLAMP CPL	33150T7SE11 ✓		cm	850.00 ✓
0562	R/F HEADLAMP CPL	33100T7SE11 ✓			350.00 X
1009	FRONT PANEL CPL	60400T8NT00ZZ		Ref/2nd	320.00 ✓
4465	CONDENSER	80110T7A003 ✓		11	30.00 ✓
9646	LOW TONE HORN	38100T7AJ01			
f: OEM Parts					0.00
n: Non-OEM Parts					3,883.00
u: Used parts				Ref	100.00 ✓
Savings					
Subtotal					
Fixed Sundry Parts Price					
Total					3,983.00

Bonnet can't open anymore still using his website.

P-3075

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	3,883.00	
Total Parts	100.00	3,983.00
Labour Time Base 10 WU/h		
Total 133.0 WU X 42.00 SGD/h	310.80 558.60	
Total of Labour		558.60
Paint Work Time Base 10 WU/h		
Labour Cost 102.0 WU X 42.00 SGD/h	428.40	
Material Cost	197.32	
Total Paint Including Material		625.72
Repair Cost Excludes GST	5,167.32	5,167.32
GST (+7.00%)		361.71
Repair Cost Included GST		5,529.03

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: DMPCSN3072301802
Repairer Reference: SKU4319P
Date calculated: 02/01/2020 1:49 PM

Revert

Full Report
Registration: SKU4319P
Printed: 02/01/2020 1:49 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN3072301802	Date of Incident:	23/12/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	HONDA		
Model:	VEZEL RU1/5		
Sub Model:	LX		
Model Sheet Number:	35 VE 08		
Registration:	SKU4319P		
VIN number:			
Odometer:			
Model Specs			
AUTO AIR CON	LED HEADLAMP	1496CCM 97KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT PANEL		32.0	134.40
8101A2	RENEW FRONT BUMPER		12.0	50.40
813110)	RENEW RADIATOR GRILLE		4.0	16.80
812100	RENEW BONNET		11.0	46.20
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE			
NO NUMBER	R + R BOTH FRONT WINGS (BUMPER REMOVED) INCLUDES: R + R FRONT HEADLAMPS, SILL COVER AND REQUIRED ATTACHED PARTS.		17.0	71.40
616100)	R + R CONDENSER		2.0	8.40
620020	DRAIN + REFILL AIR CONDITIONING		7.0	29.40
0741	L/F WING REPAIR		20.0*	84.00
0742	R/F WING REPAIR		20.0*	84.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		12.50	125.0	525.00
Total of Labour				525.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT PANEL CPL SURFACE PAINT		6.0	
	FRONT BUMPER NEW PART PAINT K1G/P		21.0	
	BONNET REPAIR PAINTING >50%		32.0	
	L/F WING SURFACE PAINT		5.0	
	R/F WING SURFACE PAINT		5.0	

Paint Material Per Part

Code	Description	Price SGD
1009	FRONT PANEL CPL SURFACE PAINT	11.21
0283	FRONT BUMPER NEW PART PAINT K1G/P	79.20
0471	BONNET REPAIR PAINTING >50%	50.17
0741	L/F WING SURFACE PAINT	7.72
0742	R/F WING SURFACE PAINT	7.72

Labour Cost - Paint

	Factor	42.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			69.0	
	Preparation Main Work Metal		2.50	25.0	105.00
	Preparation Comp. Work Plastic		0.80	8.0	33.60
Total		10 WU/h	10.20	102.0	428.40

Material Cost - Paint

New Part Painting - Plastic K1G/PUR
Repair Painting
Surface-/Blend Paint
Material-constant Metal Preparation
Material-constant Plastic
Total

Price SGD
79.20
50.17
26.65
28.60
12.70
197.32

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		35.00
0283	FRONT BUMPER	71101T7JH00ZZ		185.00
0340	FRT BUMPER SUPPORT	71130T8NT00ZZ		0.00
0343	L/BUMPER CORNER	71190T7A000		10.00
	BRKT			
0344	R/BUMPER CORNER	71140T7A000		10.00
	BRKT			
0345	L/F AIR DUCT	71116T8NT50		0.00
0346	R/F AIR DUCT	71111T8NT50		20.00
0410	GRILLE	71121T8NQ50		250.00
0413	RAD GRILLE BRACKET	71150T7JH00		20.00
0415	L/RAD-GRILLE BRACKET	71152T7A000		20.00
0416	R/RAD-GRILLE BRACKET	71151T7JH00		20.00
0424	RAD GRILLE COVER	71122T8NT50		250.00
0431	GRILLE BADGE	75700TA0A00		18.00
0435	L/GRILLE TRIM	71128T8NT00		25.00
0436	R/GRILLE TRIM	71123T8NT00		25.00
0471	BONNET	60100T8NT00ZZ		460.00
0492	BONNET LOCK	74120T7WA01		65.00
0561	L/F HEADLAMP CPL	33150T7SE11		850.00
0562	R/F HEADLAMP CPL	33100T7SE11		850.00
1009	FRONT PANEL CPL	60400T8NT00ZZ		350.00
4465	CONDENSER	80110T7A003		320.00
9646	LOW TONE HORN	38100T7AJ01		30.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,813.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			3,913.00

Final Calculation

	SGD	SGD
Parts	3,813.00	
Fixed Sundry Parts Price	100.00	
Total Parts		3,913.00
Labour Time Base 10 WU/h		
Total 125.0 WU X 42.00 SGD/h	525.00	
Total of Labour		525.00
Paint Work Time Base 10 WU/h		
Labour Cost 102.0 WU X 42.00 SGD/h	428.40	
Material Cost	197.32	
Total Paint Including Material		625.72
Repair Cost Excludes GST		5,063.72
GST (+7.00%)		354.46
Repair Cost Included GST		5,418.18

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Insurer Reference: DMPCSN3072301802
Repairer Reference: SKU4319P
Date calculated: 23/01/2020 10:57 AM

Full Report
Registration: SKU4319P
Printed: 24/01/2020 9:46 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN3072301802	Date of Incident:	23/12/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL RU1/5
Sub Model:	LX
Model Sheet Number:	35 VE 08
Registration:	SKU4319P
VIN number:	
Odometer:	

Model Specs

AUTO AIR CON	LED HEADLAMP	1496CCM 97KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Code	Description	WU	Price SGD
8101A2	RENEW FRONT BUMPER	12.0	50.40
813110)	RENEW RADIATOR GRILLE	4.0	16.80
812100)	R + R BONNET	3.0	12.60
8121B6)	R + R L/BONNET SEAL	3.0	12.60
8121B7)	R + R R/BONNET HINGE	3.0	12.60
8101B1)	R + R FRONT BUMPER SUPPORT	2.0	8.40
8101C1)	R + R L/BUMPER CORNER SUPPORT	4.0	16.80
8101C2)	R + R R/BUMPER CORNER SUPPORT	4.0	16.80
NO NUMBER	R + R L/FRONT SCREEN FRAME AIR GRILLE	1.0	4.20
NO NUMBER	R + R R/FRONT SCREEN FRAME AIR GRILLE	1.0	4.20
7121B7)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS	8.0	33.60
616100)	R + R CONDENSER	2.0	8.40
620020	DRAIN + REFILL AIR CONDITIONING	7.0	29.40
0741	L/F WING REPAIR	28.0*0.5	84.00
0742	R/F WING REPAIR	28.0*0.5	84.00
1009	FRONT PANEL CPL REPAIR	10.0*	42.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		10.40	104.0
Total of Labour			436.80

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1G/P	21.0	
	BONNET REPAIR PAINTING >50%	32.0	
	L/F WING SURFACE PAINT	5.0	
	R/F WING SURFACE PAINT	5.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1G/P	79.20
0471	BONNET REPAIR PAINTING >50%	50.17
0741	L/F WING SURFACE PAINT	7.72
0742	R/F WING SURFACE PAINT	7.72
1009	FRONT PANEL CPL SURFACE PAINT	11.21

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			69.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	10.20	102.0	428.40

Material Cost - Paint

New Part Painting - Plastic K1G/PUR

Repair Painting

Surface-/Blend Paint

Material-constant Metal Preparation

Material-constant Plastic

Total**Price SGD****79.20****50.17****26.65****28.60****12.70****197.32****Spare Parts**

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
4465	CONDENSER	80110T7A003		320.00 ✓
0283	FRONT BUMPER	71101T7JH00ZZ		185.00 ✓
0257	FRONT NUMBER PLATE	KNPL3		35.00 ✓
0391	FRONT SPOILER	71110T7A000 (A)		125.00 ✓
0340	FRT BUMPER SUPPORT	71130T8NT00ZZ		185.00 ✓
0410	GRILLE	71121T8NQ50		250.00 ✓
0475	L/BONNET HINGE	60170T8NT01ZZ		35.00 ✓
0343	L/BUMPER CORNER	71190T7A000		25.00 ✓
	BRKT			
0561	L/F HEADLAMP CPL	33150T7SE11		850.00 ✓
0435	L/GRILLE TRIM	71128T8NT00		20.00 ✓
0415	L/RAD-GRILLE BRACKET	71152T7A000		15.00 ✓
0476	R/BONNET HINGE	60120T8NT01ZZ		35.00 ✓
0344	R/BUMPER CORNER	71140T7A000		25.00 ✓
	BRKT			
0562	R/F HEADLAMP CPL	33100T7SE11		850.00 ✓
0436	R/GRILLE TRIM	71123T8NT00		20.00 ✓
0413	RAD GRILLE BRACKET	71150T7JH00		20.00 ✓
0424	RAD GRILLE COVER	71122T8NT50		115.00 ✓
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 3,110.00
u: Used parts				Fixed Sundry Parts Price 100.00
Total				3,210.00

Final Calculation

	SGD	SGD
Parts	3,110.00	
Fixed Sundry Parts Price	100.00	
Total Parts		3,210.00
Labour Time Base 10 WU/h		
Total 104.0 WU X 42.00 SGD/h	436.80	
Total of Labour		436.80
Paint Work Time Base 10 WU/h		
Labour Cost 102.0 WU X 42.00 SGD/h	428.40	
Material Cost	197.32	
Total Paint Including Material		625.72
Repair Cost Excludes GST		4,272.52
GST (+7.00%)		299.08
Repair Cost Included GST		4,571.60

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Jin Auto Services Pte Ltd/SKU4319P/23/01/2020 10:59	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

Qo.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
	1		*FRONT LOWER BUMPER FACE	0e 0.00	0.00	*125.00 F
			Total Parts (S\$)			125.00

Jin Auto Services Pte Ltd/SKU4319P/23/01/2020 10:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



柏维汽车零件私人有限公司
PARTWARE AUTO PTE LTD

10 Kaki Bukit Road 1, #01-21 KB Industrial Building S416175
Company Registration No: 201540164H
Email: admin@partwareauto.com
Office: +(65) 6493 3228 Fax: +(65) 6493 3028

TAX INVOICE

GST Reg. No : 201540164H

Invoice No : AR202001-0437
Invoice Date : 10 Jan 2020
Page : Page 1 of 2
Salesman : KENNY
Term : 30 DAYS

AUTHORISED DEALER



HONDA

Box

Customer A/C No: JAS
JIN AUTO SERVICES PTE LTD
#01-412 BLK 14
DEFU LANE 10

SINGAPORE539195
TEL : 62898126 FAX : 62870590
ATTN : ACCOUNTS

Deliver to:
JIN AUTO SERVICES PTE LTD
SKU4319P=MING CHAI

ATTN :

S/N	Part No	Description	Quantity	Unit Price	Amount
1	60120-T7J-H00	RH, BONNET HINGE	1 PCS	35.00	35.00✓
2	60170-T7J-H00	LH, BONNET HINGE	1 PCS	35.00	35.00✓
3	33100-T7S-E11	RH, HEADLIGHT ASSY W LED	1 PCS	850.00	850.00✓
4	33150-T7S-E11	LH, HEADLIGHT ASSY W LED	1 PCS	850.00	850.00✓
5	71150-T7J-H00	FR UPPER CENTER, GRILLE GARNISH	1 PCS	20.00	20.00✓
6	71152-T7A-000	FR LH UPPER, HEADLAMP BRACKET	1 PCS	15.00	15.00✓
7	71101-T7J-H00ZZ	FR, BUMPER FACE	1 PCS	185.00	185.00✓
8	71130-T7A-000ZZ	FR, BUMPER BEAM COMP	1 PCS	185.00	185.00✓
9	71121-T7A-000	FR BASE, GRILLE	1 PCS	250.00	250.00✓
10	71122-T7A-000	FR UPPER, GRILLE MOLDING	1 PCS	115.00	115.00✓
11	71123-T8N-T00	FR RH, GRILLE MOLDING	1 PCS	20.00	20.00✓

Subtotal 2,560.00

GST 7%

Invoice Total SGD

Total Net Payments SGD

Amount Due SGD

- 1) GOODS SOLD ARE NOT REFUNDABLE.
2) OVERDUE AMOUNTS ARE SUBJECTED TO INTEREST AT UOB'S PREVAILING LENDING RATE.

GOODS RECEIVED IN GOOD ORDER & CONDITION.

PARTWARE AUTO PTE LTD

CUSTOMER'S SIGN & STAMP



柏维汽车零部件私人有限公司
PARTWARE AUTO PTE LTD

10 Kaki Bukit Road 1, #01-21 KB Industrial Building S416175
Company Registration No: 201540164H
Email: admin@partwareauto.com
Office: +(65) 6493 3228 Fax: +(65) 6493 3028

TAX INVOICE

GST Reg. No : 201540164H

Invoice No : AR202001-0437
Invoice Date : 10 Jan 2020
Page : Page 2 of 2
Salesman : KENNY
Term : 30 DAYS

AUTHORISED DEALER



Box

Customer A/C No: JAS
JIN AUTO SERVICES PTE LTD

#01-412 BLK 14
DEFU LANE 10

SINGAPORE539195
TEL : 62888126 FAX : 62870590
ATTN : ACCOUNTS

Deliver to:
JIN AUTO SERVICES PTE LTD
SKU4319P=MING CHAI

ATTN :

S/N	Part No	Description	Quantity	Unit Price	Amount
	BRING FORWARD				2,560.00
12	71128-T8N-T00	FR.LH, GRILLE MOLDING	1 PCS	20.00	20.00 ✓
13	91505-TM8-003	CLIP, BUMPER	10 PCS	1.50	15.00 ✓
14	71102-T7W-A00	FR LOWER, BUMPER FACE	1 PCS	125.00	125.00 ✓
15	71140-T7A-000	FR.RH UPPER, BUMPER BEAM	1 PCS	25.00	25.00 ✓
16	71190-T7A-000	FR.LH UPPER, BUMPER BEAM	1 PCS	25.00	25.00 ✓
17	80110-T7A-J01	CONDENSER COMP, AIRCON	1 PCS	320.00	320.00 ✓
					3,125

Subtotal 3,090.00

GST 7% 216.30

Invoice Total SGD 3,306.30

Total Net Payments SGD 0.00

Amount Due SGD 3,306.30

- 1) GOODS SOLD ARE NOT REFUNDABLE.
2) OVERDUE AMOUNTS ARE SUBJECTED TO INTEREST AT UOB'S PREVAILING LENDING RATE.

GOODS RECEIVED IN GOOD ORDER & CONDITION.

PARTWARE AUTO PTE LTD

CUSTOMER'S SIGN & STAMP

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: DMPCSN3072301802
Repairer Reference: SKU4319P
Date calculated: 24/01/2020 11:32 AM

Full Report
Registration: SKU4319P
Printed: 24/01/2020 11:32 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN3072301802	Date of Incident:	23/12/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL RU1/5
Sub Model:	LX
Model Sheet Number:	35 VE 08
Registration:	SKU4319P
VIN number:	
Odometer:	

Model Specs

AUTO AIR CON	LED HEADLAMP	1496CCM 97KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
8101A2	RENEW FRONT BUMPER		12.0	50.40
813110)	RENEW RADIATOR GRILLE		4.0	16.80
812100)	R + R BONNET		3.0	12.60
8121B6)	R + R L/BONNET SEAL		3.0	12.60
8121B7)	R + R R/BONNET HINGE		3.0	12.60
8101B1)	R + R FRONT BUMPER SUPPORT		2.0	8.40
8101C1)	R + R L/BUMPER CORNER SUPPORT		4.0	16.80
8101C2)	R + R R/BUMPER CORNER SUPPORT		4.0	16.80
NO NUMBER	R + R L/FRONT SCREEN FRAME AIR GRILLE		1.0	4.20
NO NUMBER	R + R R/FRONT SCREEN FRAME AIR GRILLE		1.0	4.20
7121B7)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		8.0	33.60
616100)	R + R CONDENSER		2.0	8.40
620020	DRAIN + REFILL AIR CONDITIONING		7.0	29.40
0741	L/F WING REPAIR		5.0*	21.00
0742	R/F WING REPAIR		5.0*	21.00
1009	FRONT PANEL CPL REPAIR		10.0*	42.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		7.40	74.0	310.80
Total of Labour				310.80

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1G/P		21.0	88.20
	BONNET REPAIR PAINTING >50%		32.0	134.40
	R/F WING SURFACE PAINT		5.0	21.00
	FRONT PANEL CPL SURFACE PAINT		6.0	25.20

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1G/P	79.20
0471	BONNET REPAIR PAINTING >50%	50.17
0742	R/F WING SURFACE PAINT	7.72
1009	FRONT PANEL CPL SURFACE PAINT	11.21

Labour Cost - Paint

	Factor	42.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			64.0	
	Preparation Main Work Metal		2.50	25.0	105.00
	Preparation Comp. Work Plastic		0.80	8.0	33.60
Total		10 WU/h	9.70	97.0	407.40

Material Cost - Paint

New Part Painting - Plastic K1G/PUR
 Repair Painting
 Surface-/Blend Paint
 Material-constant Metal Preparation
 Material-constant Plastic
Total

Price SGD
79.20
50.17
18.93
28.60
12.70
189.60

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
4465	CONDENSER	80110T7A003		320.00
0283	FRONT BUMPER	71101T7JH00ZZ		185.00
0257	FRONT NUMBER PLATE	KNPL3		35.00
0391	FRONT SPOILER	71110T7A000		125.00
0340	FRT BUMPER SUPPORT	71130T8NT00ZZ		185.00
0410	GRILLE	71121T8NQ50		250.00
0475	L/BONNET HINGE	60170T8NT01ZZ		35.00
0343	L/BUMPER CORNER BRKT	71190T7A000		25.00
0561	L/F HEADLAMP CPL	33150T7SE11		850.00
0435	L/GRILLE TRIM	71128T8NT00		20.00
0415	L/RAD-GRILLE BRACKET	71152T7A000		15.00
0476	R/BONNET HINGE	60120T8NT01ZZ		35.00
0344	R/BUMPER CORNER BRKT	71140T7A000		25.00
0562	R/F HEADLAMP CPL	33100T7SE11		850.00
0436	R/GRILLE TRIM	71123T8NT00		20.00
0413	RAD GRILLE BRACKET	71150T7JH00		20.00
0424	RAD GRILLE COVER	71122T8NT50		115.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,110.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			3,210.00

Extras

Code	Description	Price SGD
0741	[L]: L/F WING:	0.00*
0741	[I]: L/F WING:	0.00*

Final Calculation

	SGD	SGD
Parts	3,110.00	
Fixed Sundry Parts Price	100.00	
Total Parts		3,210.00
Labour Time Base 10 WU/h		
Total 74.0 WU X 42.00 SGD/h	310.80	
Total of Labour		310.80
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 97.0 WU X 42.00 SGD/h	407.40	
Material Cost	189.60	
Total Paint Including Material		597.00
Repair Cost Excludes GST		4,117.80
GST (+7.00%)		288.25
Repair Cost Included GST		4,406.05

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Shirley Hiew (LKK Auto)

From: jouis <jouis@jinauto.com.sg>
Sent: Thursday, 30 January 2020 10:03 am
To: SUR
Subject: FW: SKU 4319P-DOA: 23/12/2019 (CHINA TAIPING OD)

From: jouis [mailto:jouis@jinauto.com.sg]
Sent: Thursday, 30 January 2020 10:01 AM
To: 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>
Subject: RE: SKU 4319P-DOA: 23/12/2019 (CHINA TAIPING OD)

Dear Veron

Ok confirm .

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Friday, 24 January 2020 12:16 PM
To: jouis <jouis@jinauto.com.sg>; SUR <sur@lkkauto.com>; Marcus Chua (LKKAuto) <MarcusChua@lkkauto.com>
Subject: RE: SKU 4319P-DOA: 23/12/2019 (CHINA TAIPING OD)

Dear Jouis,

Attached finalise.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: DMPCSN3072301802
Repairer Reference: SKU4319P
Date calculated: 24/01/2020 11:32 AM

Full Report
Registration: SKU4319P
Printed: 24/01/2020 11:33 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	DMPCSN3072301802	Date of Incident:	23/12/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL RU1/5
Sub Model:	LX
Model Sheet Number:	35 VE 08
Registration:	SKU4319P
VIN number:	
Odometer:	

Model Specs

AUTO AIR CON	LED HEADLAMP	1496CCM 97KW	TWO COAT METALLIC
PREPARE OFF VEHICLE			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
8101A2	RENEW FRONT BUMPER		12.0	50.40
813110)	RENEW RADIATOR GRILLE		4.0	16.80
812100)	R + R BONNET		3.0	12.60
8121B6)	R + R L/BONNET SEAL		3.0	12.60
8121B7)	R + R R/BONNET HINGE		3.0	12.60
8101B1)	R + R FRONT BUMPER SUPPORT		2.0	8.40
8101C1)	R + R L/BUMPER CORNER SUPPORT		4.0	16.80
8101C2)	R + R R/BUMPER CORNER SUPPORT		4.0	16.80
NO NUMBER	R + R L/FRONT SCREEN FRAME AIR GRILLE		1.0	4.20
NO NUMBER	R + R R/FRONT SCREEN FRAME AIR GRILLE		1.0	4.20
7121B7)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		8.0	33.60
616100)	R + R CONDENSER		2.0	8.40
620020	DRAIN + REFILL AIR CONDITIONING		7.0	29.40
0741	L/F WING REPAIR		5.0*	21.00
0742	R/F WING REPAIR		5.0*	21.00
1009	FRONT PANEL CPL REPAIR		10.0*	42.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		7.40	74.0	310.80
Total of Labour				310.80

Paint

Code	Description - TWO COAT METALLIC	Time Basis 10 WU/h	WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1G/P		21.0	
	BONNET REPAIR PAINTING >50%		32.0	
	R/F WING SURFACE PAINT		5.0	
	FRONT PANEL CPL SURFACE PAINT		6.0	

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1G/P	79.20
0471	BONNET REPAIR PAINTING >50%	50.17
0742	R/F WING SURFACE PAINT	7.72
1009	FRONT PANEL CPL SURFACE PAINT	11.21

Labour Cost - Paint

	42.00 SGD/h	Hrs	WU	Price SGD
Factor				
Time Paint			64.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	9.70	97.0	407.40

Material Cost - Paint

New Part Painting - Plastic K1G/PUR

Repair Painting

Surface-/Blend Paint

Material-constant Metal Preparation

Material-constant Plastic

Total**Price SGD****79.20****50.17****18.93****28.60****12.70****189.60****Spare Parts**

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
4465	CONDENSER	80110T7A003		320.00
0283	FRONT BUMPER	71101T7JH00ZZ		185.00
0257	FRONT NUMBER PLATE	KNPL3		35.00
0391	FRONT SPOILER	71110T7A000		125.00
0340	FRT BUMPER SUPPORT	71130T8NT00ZZ		185.00
0410	GRILLE	71121T8NQ50		250.00
0475	L/BONNET HINGE	60170T8NT01ZZ		35.00
0343	L/BUMPER CORNER	71190T7A000		25.00
	BRKT			
0561	L/F HEADLAMP CPL	33150T7SE11		850.00
0435	L/GRILLE TRIM	71128T8NT00		20.00
0415	L/RAD-GRILLE BRACKET	71152T7A000		15.00
0476	R/BONNET HINGE	60120T8NT01ZZ		35.00
0344	R/BUMPER CORNER	71140T7A000		25.00
	BRKT			
0562	R/F HEADLAMP CPL	33100T7SE11		850.00
0436	R/GRILLE TRIM	71123T8NT00		20.00
0413	RAD GRILLE BRACKET	71150T7JH00		20.00
0424	RAD GRILLE COVER	71122T8NT50		115.00
f: OEM Parts				Savings
n: Non-OEM Parts				Subtotal
u: Used parts				Fixed Sundry Parts Price
Total				3,210.00

Extras

Code	Description	Price SGD
0741	[L]: L/F WING:	0.00*
0741	[I]: L/F WING:	0.00*

Final Calculation

	SGD	SGD
Parts	3,110.00	
Fixed Sundry Parts Price	100.00	
Total Parts		3,210.00
Labour Time Base 10 WU/h		
Total 74.0 WU X 42.00 SGD/h	310.80	
Total of Labour		310.80
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 97.0 WU X 42.00 SGD/h	407.40	
Material Cost	189.60	
Total Paint Including Material		597.00
Repair Cost Excludes GST		4,117.80
GST (+7.00%)		288.25
Repair Cost Included GST		4,406.05

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2019 Sendback Est	26 Dec 2019 11:16 \$5,167.32	27 Dec 2019 11:55 Edit Adj Rpt	\$4,117.80 Edit Estimates	\$4,117.80 View Rpt		Pending for Survey Report Cancel Case
Supp #1	23 Jan 2020 10:58	23 Jan 2020 10:59 \$125.00	23 Jan 2020 10:59			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: WONG SIEN RUEY , ID: SXXXX119Z									
Vehicle Reg. No.: SKU4319P		Date of Loss: 23/12/2019 11:00 - :59 [52 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM19D206120/SKU4319P/BEN		Policy/Cover Note No.: DMPCSN3072301802 (Comprehensive)							
		Excess: \$0.00							
Repairer: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/01/2020]									
Driver/Custodian: MA YAFANG (/ Female) , NRIC: SXXXX533H Email:									
Adj Asg. Remarks: Please arrange to survey of insured vehicle SKU4319P.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (03/01/2020): Alert - Adj Mandate Approved (\$5063.72) - SKU4319P - Claim Handler: Ben Tang									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKU4319P (SNM19D206120/SKU4319P/BEN)

OD

Dec 23 2019 11:00AM

[WONG SIEN RUEY]

Jin Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	26/12/19 11:16	Repairer Estimates	Load HTM	
2	23/01/20 10:59	Repairer Estimates Suppl. #1	Load HTM	
LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	02/01/20 14:01	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
2	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
3	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
4	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
5	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
6	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
7	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
8	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
9	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
10	26/12/19 11:16	Photographs of Damaged Items	Load JPG	☒
11	23/01/20 11:01	Photos - Before	Load JPG	☒
12	23/01/20 11:01	Photos - Before	Load JPG	☒
13	23/01/20 11:01	Photos - Before	Load JPG	☒
14	23/01/20 11:01	Photos - Before	Load JPG	☒
15	23/01/20 11:01	Photos - Before	Load JPG	☒
16	23/01/20 11:01	Photos - Before	Load JPG	☒
17	23/01/20 11:01	Photos - Before	Load JPG	☒
18	23/01/20 11:01	Photos - Before	Load JPG	☒
LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	02/01/20 14:26	Odometer Reading	Load JPG	☒
2	02/01/20 14:26	Chassis Number	Load JPG	☒
3	02/01/20 14:27	General View	Load JPG	☒
4	02/01/20 14:27	General View	Load JPG	☒
5	02/01/20 14:27	General View	Load JPG	☒
6	02/01/20 14:27	General View	Load JPG	☒
7	02/01/20 14:27	General View	Load JPG	☒
8	02/01/20 14:27	General View	Load JPG	☒
9	02/01/20 14:27	General View	Load JPG	☒
10	02/01/20 14:27	General View	Load JPG	☒
11	02/01/20 14:27	General View	Load JPG	☒
12	02/01/20 14:27	General View	Load JPG	☒
13	02/01/20 14:27	General View	Load JPG	☒
14	02/01/20 14:27	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
15	02/01/20 14:27	General View	 Load JPG	☒
16	02/01/20 14:27	General View	 Load JPG	☒
17	02/01/20 14:27	General View	 Load JPG	☒
18	02/01/20 14:27	General View	 Load JPG	☒
19	02/01/20 14:27	General View	 Load JPG	☒
20	02/01/20 14:27	General View	 Load JPG	☒
21	02/01/20 14:27	General View	 Load JPG	☒
22	02/01/20 14:27	General View	 Load JPG	☒
23	02/01/20 14:27	General View	 Load JPG	☒
24	02/01/20 14:27	General View	 Load JPG	☒
25	02/01/20 14:27	General View	 Load JPG	☒
26	02/01/20 14:27	General View	 Load JPG	☒
27	02/01/20 14:27	General View	 Load JPG	☒
28	02/01/20 14:27	General View	 Load JPG	☒
29	02/01/20 14:27	General View	 Load JPG	☒
30	02/01/20 14:27	General View	 Load JPG	☒
31	02/01/20 14:27	General View	 Load JPG	☒
32	02/01/20 14:27	General View	 Load JPG	☒
33	02/01/20 14:27	General View	 Load JPG	☒
34	02/01/20 14:27	General View	 Load JPG	☒
35	02/01/20 14:27	General View	 Load JPG	☒
36	02/01/20 14:27	General View	 Load JPG	☒
37	02/01/20 14:27	General View	 Load JPG	☒
38	02/01/20 14:27	General View	 Load JPG	☒
39	02/01/20 14:27	General View	 Load JPG	☒
40	02/01/20 14:27	General View	 Load JPG	☒
41	02/01/20 14:27	General View	 Load JPG	☒
42	02/01/20 14:27	General View	 Load JPG	☒
43	02/01/20 14:27	General View	 Load JPG	☒
44	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
45	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
46	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
47	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
48	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
49	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
50	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
51	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
52	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
53	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
54	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
55	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
56	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
57	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
58	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
59	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
60	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
61	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
62	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
63	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
64	07/01/20 16:27	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
65	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
66	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
67	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
68	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
69	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
70	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
71	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
72	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
73	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
74	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
75	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
76	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
77	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
78	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
79	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
80	07/01/20 16:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	26/12/19 10:51	E-filed GIA report	 Load PDF	
2	26/12/19 11:15	AUDATEX	 Load PDF	
3	17/01/20 13:47	Purchase Invoice	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/20 14:03	MARK ESTIMATE	 Load PDF	
2	02/01/20 14:03	AUDATEX	 Load PDF	
3	28/02/20 09:27	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119022776/UVD3E2

Date: 28/02/2020

REFERENCE

Insured/Claimant: WONG SIEN RUEY Policy No: DMPCSN3072301802

Date of Loss: 23/12/2019

Nature of Claim: OD

Claim No: SNM19D206120/SKU4319P/BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU4319P	Engine No:	L15B4020696
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11100694
Reg. Date:	27/07/2015 (Man. Year: 2015)	Odometer:	59591 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,108.00	3,210.00	898.00	21.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,184.32	907.80	276.52	23.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,292.32	4,117.80	1,174.52	22.19
+ GST 7.00/7.00% (S\$)	370.46	288.25	82.21	22.19
Nett Amount (S\$)	5,662.78	4,406.05	1,256.73	22.19

INSPECTION

Date of Assignment:	27/12/2019	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	02/01/2020	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU4319P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		3,983.00 F	*3,085.00 F
Supplementary #1						
2	1		*FRONT LOWER BUMPER FACE	Deformed	125.00 F	*125.00 F
F=Franchise part.						
Total Parts (S\$)					4,108.00	3,210.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	558.60	310.80
2	SPRAY PAINTING	New	625.72	597.00
Gross Labour Cost (S\$)			1,184.32	907.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >