

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 31 Dec 2019

Preliminary Advice

Vehicle No	: YQ385D	Accident Date	: 15/12/2019
Make	: HINO XZU700R	Policy No.	: Z19VC00103219
Assignment Date	: 27/12/2019	Excess	: S\$1,500.00
Date of Inspection	: 30/12/2019	Est. Duration of Repair	: 16 days
Inspection At	: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s, rear & rooftop portion and parts claimed are consistent to the accident. Undercarriage affected due to collision

Repairer's Estimate (Gross)	:S\$	34,100.25
Revised Amount	:S\$	26,802.00
Check Items (Estimated)	:S\$	3,611.25
Total	:S\$	30,413.25

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
Pre-Accident Value (inclusive refrigerator box)		83,000.00
COE / PARF Rebate	:S\$	11,102.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,898.00
Margin for Repair (inclusive refrigerator box)		71,898.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :