

ASS. REC. BY:

REF:

es/Ata/9022790/ Atd3

n2

Special Instruction:

Surety: Adrian

ASSIGNMENT (Office)

From (Person):

Subramaniam Dyrshini

ATG

Date/Time: 26/12/19 @ 2.38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 3170C

Insured:

SBX 8833K

at Workshop m/s

Yap Lee Motor

Tel:

6844 1555

of

1/cekki Bukit Ave 6 # 01-26 Autobay

Policy No:

Claim No:

2392372478541

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/12/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 10:05am @ 27/12/19

Person Contacted:

shirley

Vehicle IN/OUT

Date/Time	Action/Instruction
	GBD 3170C - NA/INC/8018601/13
	SBX 8833K - X.
	lump Sum \$1700/- (Red: 6597.51, 79%)

DATE REC'D BY

REF: A19

ASSIGNMENT

From:

Date:

31/01/2020

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBD 3170C

at Workshop m/s

Yap Lee Motor

of

1 Kaki Bukit Ave 6 # 01-26

Insured:

Autobay

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBD 3170C

Yr Regn:

2014 / Agent

Type: M.Car / M.Cycle / Bus / Van / Cont / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.C.

2982

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

-

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFA13SY60K203207

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

155 R15

R:

155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Cardor

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

31/01/20

Survey held at

Yap Lee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP A19

RECEIVED 17 MAR 2020

MV: 331C

PV: 179K

Nett: 15.1K

Date/Time, File Pass to?



Preli. Report

H/3 Typst



Final Report

Date/Time, File Return to?

3

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp \$



Interview \$



Tech. Insp \$



Wheel and \$

Survey Fee:

Transportation

3 + RS 31

Phone

Others

TOTAL

250

11

261

Report Format:

Lump Sum / R/B:

TP

17001-

PRE-REPAIR INSPECTION REQUEST – GBD3170C vs SBX8833K (OI) on D.O.A.: 05/12/2019

From: Subramaniam, Divyashni
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Sent: 12/26/2019 2:38:34 PM

Hi,

Please refer to the enclosed request from **M/s Hin Tat Augustine & Partners**.

Claim no : 2392372478SG003
Case Owner : Chan Kian Meng

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.*

Thank you.

Best Regards,

Divyashni Subramaniam
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Divyashni.Subramaniam@aig.com | www.aig.sg

From: Anil Kumar <anil@htapartners.com.sg>
Sent: Thursday, December 26, 2019 2:09 PM
To: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Cc: Ruby Ong <ruby@htapartners.com.sg>; Yap Lee Motor <yap_lee_motor@singnet.com.sg>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: [EXTERNAL] RE: - PRE-REPAIR INSPECTION -Yap Lee Motor <yap_lee_motor@singnet.com.sg> ACCIDENT INVOLVING OUR INSURED VEHICLE SBX8833K AND GBD3170C ON 05/12/2019
Importance: High

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sirs

We refer to your email dated 26TH December 2019.

Our client is agreeable to appoint **Mr Adrian Ling (LKK Auto Consultants Pte Ltd)** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **GBD3170C**.

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

Venue : **Yap Lee Motor**
1 Kaki Bukit Avenue 6
#01-26 Autobay@Kaki Bukit (417883)
Contact Person : **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212
Direct Fax: 63383536
Fax : 63383536

From: Ruby Ong <ruby@htapartners.com.sg>
Sent: Thursday, 26 December 2019 11:45 AM
To: Yap Lee Motor <yap_lee_motor@singnet.com.sg>
Cc: Anil Kumar <anil@htapartners.com.sg>
Subject: FW: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SBX8833K AND GBD3170C ON 05/12/2019

Without Prejudice

Your Reference : TCL.GCN.ro.50750.19.ylm
Our Reference : 2392372478SG003

Dear Sir/Madam,

We refer to your Notice of Accident dated 23/12/2019

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>

Sent: Thursday, 26 December 2019 10:42 AM

To: Ruby Ong <ruby@htapartners.com.sg>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SBX8833K AND GBD3170C ON 05/12/2019

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-01-01 20:42 CST to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

From: NoorMariesa.AbuKassim@aig.com
To: ruby@htapartners.com.sg
Cc: Andy-SY.Fong@aig.com, Winnie-LW.Fan@aig.com, Syazaidina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweerjeetkaur.Mithooosingh@aig.com, Divyashni.Subramaniam@aig.com, Yinrul.Hor@aig.com, Theerthan.Parthiban@aig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SBX8833K AND GBD3170C ON 05/12/2019
Date: Thu, 26 Dec 2019 02:42:11 +0000
Without Prejudice

Your Reference : TCL.GCN.ro.50750.19.ylm
Our Reference : 2392372478SG003

Dear Sir/Madam,

We refer to your Notice of Accident dated 23/12/2019

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Mariesa Abu Kassim (Mariesa)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

NoorMariesa.AbuKassim@aig.com | www.aig.com

From: Ruby Ong <ruby@htapartners.com.sg>
Sent: Thursday, December 26, 2019 10:19 AM
To: Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Cc: Yap Lee Motor <yap_lee_motor@singnet.com.sg>; Anil Kumar <anil@htapartners.com.sg>
Subject: [EXTERNAL] RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GBD 3170C [OUR REF. TCL.GCN.RO.50750.19.YLM]
Importance: High

This message is from an external sender; be cautious with links and attachments.

Your ref: SBX 8833K
Our ref: TCL.GCN.ro.50750.19.ylm
WITHOUT PREJUDICE

23 December 2019

Urgent Reminder

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shelton Way
#08-16 AIG Building
Singapore 079120

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: TAN SOON HUAH GAS SUPPLY PTE LTD

ACCIDENT INVOLVING GBD 3170C & SBX 8833K ALONG BUKIT TIMAH ROAD ON 5 DECEMBER 2019 @ 1450HRS

We are instructed by Tan Soon Huah Gas Supply Pte Ltd to notify you of a road traffic accident on 5 December 2019 at about 1450hrs along Bukit Timah Road involving our client's vehicle registration number GBD 3170C and vehicle registration number SBX 8833K driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

From: Ruby Ong

Sent: Monday, 23 December 2019 5:08 PM

To: Hor, Yirul <yirul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>

Cc: Yap Lee Motor <yap_lee_motor@singnet.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GBD 3170C [OUR REF: TCL.GCN.RO.50750.19.YLM]

Your ref: SBX 8833K

WITHOUT PREJUDICE

Our ref: TCL.GCN.ro.50750.19.ylm

23 December 2019

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: TAN SOON HUAH GAS SUPPLY PTE LTD

ACCIDENT INVOLVING GBD 3170C & SBX 8833K ALONG BUKIT TIMAH ROAD ON 5 DECEMBER 2019 @ 1450HRS

We are instructed by Tan Soon Huah Gas Supply Pte Ltd to notify you of a road traffic accident on 5 December 2019 at about 1450hrs along Bukit Timah Road involving our client's vehicle registration number GBD 3170C and vehicle registration number SBX 8833K driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

START
SEARCH
NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Agent Cayenne At Low Depreciation! Low Mileage!



Low Mileage, Brand New
Condition. Agent Unit under
Warranty
StarAd



AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

12 vehicles

Search

toyota dyna

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

toyota dyna

Any

Any

2014

Any

Any

Any

Available



Toyota Dyna 150 3.0M

\$32,068

\$7,510 /yr

12-May-2014

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Low Depreciation To Cut Your Operational Cost, Continue To Maintain Vehicle Well For Future COE. Easy Finance Package With High Trade Ins, Good Value Insurance And Quality Workshop Services All Under One Roof. Call Before Coming As Is Consignment Unit Which...

Posted: 15-Dec-2013 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$34,800

\$7,620 /yr

28-Aug-2014

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Doorstep Viewing Available. Full Canopy And Checkered Plate. Ready For Your Business Needs. Servicing And Aircon All Done Up. No Repairs Needed. Do Call Us For Non Obligated Discussion.

QIFel Auto Pte Ltd

Posted: 11-Jan-2014 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$42,800

\$9,370 /yr

28-Aug-2014

2,982 cc

154,135 km

Truck

Available

Fuel Type: Diesel

Bank Or In House Loan Available! Call For Viewing And Test Drive Now To Believe! Call Now For Appointment Before Vehicle Gone!

Convince Auto

Posted: 06-Jan-2014 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$34,800

\$7,580 /yr

05-Sep-2014

2,982 cc

-

Truck

Available

Fuel Type: Diesel

1 Owner Unit With Low Mileage, Well Known In Market For Its Reliability, Own It With Only \$734 Monthly. High Loan Up To 100% Available Or Full Cash Payment. Beautifully Done Up, Excellent Condition, Accident Free, Ready On The Road. Come With Free Retractable...

Car (S) Pte Ltd

Posted: 23-Feb-2014 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Rainbow Speakers For Toyota & Lexus Cars

Rainbow IL-C6.2 Toyota/Lexus Plug & Play Component Speakers with 20mm Silk Dome Tweeter.

More info about this product



Toyota Dyna 150 3.0M

\$34,888

\$7,520 /yr

24-Sep-2014

2,982 cc

92,500 km

Truck

Available

Fuel Type: Diesel

1 Owner As Tip Top Condition Low Mileage At 95000km, 100% Accidents Free, Call For Appointment Now. Vehicle Park At AMK Bk 4033. Free New Timing Belt, Free New Tyres, Free Full Tank Before CNY.

Posted: 05-Jan-2014 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$35,800

\$7,710 /yr

25-Sep-2014

2,982 cc

118,200 km

Truck

Available

Fuel Type: Diesel

2 Owners! Most Reliable Lorry In The Market. Call Today To Make Inquiries Or To Arrange For A Viewing Appointment!

Posted: 01-Feb-2014 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

SHORTLISTED HISTORY

Compare

Toyota Dyna 150 3.0M

\$33,800

\$7,250 /yr

02-Oct-2014

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Good Condition! October 2014 Toyota Dyna 150 10 Feet, One Owner, Low Monthly Installment \$570. Trade In / 100% Loan Available!

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Information	
Owner ID Type:	Company
Owner ID:	144H
Vehicle Details	
Vehicle No.:	GBD3170C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2414121
Chassis No.:	JTFAT35Y60K203207
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	28 Aug 2014
First Registration Date:	28 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$39,269.00
COE Rebate Amount:	\$17,924.00
Total Rebate Amount:	\$17,924.00

The information contained herein is correct as at 03 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2019 10:56
Date Of Accident	05/12/2019 14:50
Exact Location Of Accident	AT BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD3170C
Insured/Policyholder	
Name Of Registered Owner	TAN SOON HUAH GAS SUPPLY PTE LTD
Co Reg No	200207144H
Email Address	CHINGWEI@TSHGAS.COM.SG
Mobile Phone No	(LOCAL) +65-86569253
Alternative Phone No	OFFICE-86569253

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110106007
Cover Note Number	01/07/2019 - 30/06/2020

Driver

Name of Driver	SOH TONG YEONG
NRIC No	S1487319H
Date Of Birth	23/11/1961
Occupation	OUTDOOR
Date Of Driving Pass	08/01/1982
Driving Experience	37 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86569253
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	15 DEFU LANE 11
Postcode	S530311
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBX8833K
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded to the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and its copies of the report being made available elsewhere.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that


- (a) My insurer, my work group and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authorities (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to my claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of my delivery mail/packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers, lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile Claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Accident Centre Personnel's Signature
Name
GIA/C/114/10

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was exiting Bukit Timah Road
 then suddenly vehicle B collide onto the LH rear
 portion of my vehicle.

Reporting Party	NTUC
Policy No.	3-700
Date of Accident	05/10/2019
☐ Reasoning Only	
☐ Car Damage Claim	
☒ Third Party Claim	

Workshop Yap Lee Miter

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time

10/10

Driver's Signature
 I am not the policyholder

Date & Time

06/10/2019
 10:45am

Reporting Centre Personnel's Signature
 Name

NTUC / T.M. No.

YAP LEE MOTOR

No 1 Kaki Bukit Avenue 6 #01-26 AutoBay @ Kaki Bukit

Singapore 417883

Tel : 6844 1555 Fax : 6844 1311

3 February 2020

REG NO. : GBD 3170 C
MAKE/MODEL : TOYOTA DYNA

TPA16
Dense

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear tailgate <i>Reis</i>	\$ 1,265.60 x
1	Rear tailgate lock hinge	\$ 145.00 x
1	Rear tailgate lower member <i>3 New</i>	\$ 496.50 x
1	Rear tailgate lower stopper rubber <i>new</i>	\$ 72.60 x
1	Rear tailgate lower stopper bracket <i>Beit</i>	\$ 106.50 ✓
1	Rear taillamp -L/H <i>new</i>	\$ 329.65 x
1	Rear taillamp panel <i>new</i>	\$ 199.50 x
1	Side gate -L/H <i>Dented</i>	\$ 1,465.50 ✓
1	Side gate lower member <i>Reis</i>	\$ 682.50 x
		\$ 4,763.35
	Less 25%	\$ 1,190.84
		\$ 3,572.51

<u>SPECIAL NETT ITEMS</u>		
1	Rear tailgate "FLAMMABLE GAS" sticker <i>3 new</i>	\$ 40.00 x
1	Rear tailgate "70KM/H" sticker	\$ 25.00 x
1	Rear tailgate company sticker set <i>new</i>	\$ 350.00 x
1	Rear reverse sensor (1 set) <i>new</i>	\$ 350.00 x
1	Side gate company sticker set <i>new</i>	\$ 400.00 <i>280</i>
		\$ 1,165.00

<u>S/N</u>	<u>LABOUR CHARGES</u>	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>30</i>
2	To remove and refit rear reverse sensor.	\$ 180.00 <i>20</i>
3	To apply undercoating.	\$ 200.00 x
4	Panel beating.	\$ 1,600.00 <i>250</i>
5	To re-spray painting on the affected areas.	\$ 1,500.00 <i>400</i>
		\$ 3,560.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

GRAND TOTAL :

\$ 8,297.51

Total 2178.32
L/C 17K ✓

Admin Lj
L/S 31/01/20
03 Days

LKK Auto Consultants Pte Ltd (Co.,Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19022790/ATD3N2
Date: 20/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBD3170C **Insured Vehicle No :** SBX8833K
 Date of Loss: 05/12/2019 Nature of Claim: TP Claim No: 2392372478SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD3170C**
 Make & Model: TOYOTA DYNA 1.5T, 3.0 (M) Engine No: 1KD2414121
 Reg. Date: 28/08/2014 (Man. Year: 2014) Chassis No: JTFAT35Y60K203207
 Colour: Red Odometer: 0 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 155R12
 Front Left Side: Condor 6 mm Rear Left Side: Condor 6 mm
 Front Right Side: Condor 6 mm Rear Right Side: Condor 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,737.51	1,459.00	3,278.51	69.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	720.00	2,840.00	79.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,297.51	2,179.00	6,118.51	73.74
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	8,297.51	1,700.00	6,597.51	79.51

INSPECTION

Date of Assignment: 26/12/2019
 Date Inspected: 31/01/2020 Inspected At: Yap Lee Motor (HQ)
 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,265.60 FL	*- FL
2	1		*REAR TAILGATE LOCK HINGE	Not Necessary	145.00 FL	*- FL
3	1		*REAR TAILGATE LOWER MEMBER	Not Necessary	496.50 FL	*- FL
4	1		*REAR TAILGATE LOWER STOPPER RUBBER	Not Necessary	72.60 FL	*- FL
5	1		*REAR TAILGATE LOWER STOPPER BRACKET	Bent	106.50 FL	*106.50 FL
6	1		*REAR TAILLAMP-L/H	Not Necessary	329.65 FL	*- FL
7	1		*REAR TAILLAMP PANEL	Not Necessary	199.50 FL	*- FL
8	1		*SIDE GATE-L/H	Dented	1,465.50 FL	*1,465.50 FL
9	1		*SIDE GATE LOWER MEMBER	Repair	682.50 FL	*- FL
10	1		*REAR TAILGATE FLAMMABLE GAS STICKER	Not Necessary	40.00 FS	*- FS
11	1		*REAR TAILGATE 70KM/H STICKER	Not Necessary	25.00 FS	*- FS
12	1		*SET REAR TAILGATE COMPANY STICKER	Not Necessary	350.00 FS	*- FS
13	1		*SET REAR REVERSE SENSOR	Not Necessary	350.00 FS	*- FS
14	1		*SET SIDE GATE COMPANY STICKER	Necessary	400.00 FS	*280.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	5,928.35	1,852.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,190.84	393.00
Total Parts (\$\$)	4,737.51	1,459.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	180.00	40.00
3	TO APPLY UNDERCOATING	New	200.00	0.00
4	PANEL BEATING	New	1,600.00	250.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	400.00
Gross Labour Cost (\$\$)			3,560.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >