



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

Model : Mazda 2

Veh No: SLC960X

Front

Qty	List Items	Amount S\$
1	Bumper / Re	1200 933
2	Bumper side retainers @ 40	80 28
1 set	Bumper clips / MC	70 50
1	Tow cover X	40 X
1	Reinforcement bar X	500 X
1	Front grille chrome moulding	230 /
2	Fog lamp cover @ 60	120 53
1	Headlight L/H / SCR	1000 246
1	Fender L/H X Repaint	450 X
1	Fender inner shield L/H	250 86
1	Fender inner shield clips	70 30
2	Shock absorber L/H X	350 X

Sub Total 4360 2641

Parts Total 4360

Less 20% 872

3488

Labour charges

Check front electrical wiring	100 30
Check wheel alignment	100 X
Respray undercoating	180 X
Respray painting	1200 500
Panel beating, remove and replace above parts etc	1200 600
Sub Total	2780

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

6268

4 Days.

lamp sm repair

After repair. Photos.

Gau Qian - 8288 0282

27/12/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: