


ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

WDB1714452F209659

TP Budget Direct.

Denise.

Page No. 1

Vehicle No. SJP860G MERCEDES SLK200

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER <i>reld</i>		2094.30	1539.20
1	FRONT BUMPER FOGLAMP COVER LH <i>neu</i>		95.00	+
1	FRONT BUMPER SIDE RETAINER LH & RH @ \$151.00 <i>neu</i>		302.00	160
1	FRONT BUMPER LOGO <i>neu</i>		120.00	✓
1	FRONT BUMPER UPPER GARNISH <i>could</i>	2552.20	321.00	✓
1	FRONT GRILLE <i>could</i>	2256.58	785.00	✓ 412.
			3717.30	
		less 10%	371.73	10%
			3345.57	
	SPECIAL ITEMS			
4	PARKING SENSOR @ \$210.00 <i>neu</i>		840.00	+
1 SET	PARKING SENSOR WIRE HARNESS <i>neu</i>		175.00	+
1 SET	FRONT BUMPER CLIPS <i>neu</i>		100.00	30 90
1 SET	FRONT CAR PLATE WITH HOLDER <i>could</i>		100.00	60
	Total Parts		4460.57	

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SJP860G MERCEDES SLK200

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1000.00	250
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	800.00	250
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	+
5	To remove & replace parking sensor	120.00	60
6	To clear fault code with diagnostic computer and reset to Mercedes specification .	250.00	+
Labour Total :		2500.00	590
TOTAL (PARTS & LABOUR) :		6960.57	

Adrian Lj

L/S 028495.

total: 2876.88.

L/S: 2.3K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- **Parts** prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: