



ACE AUTOLUTIONPTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

TPAXA

Xiao Tony

Page No. 1

GK33414671

Vehicle No. SMN1844Y HONDA FIT

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR TAILGATE <i>Dented</i>		1252.00	✓ 900.40
1	REAR TAILGATE INNER LOCK <i>Dented</i>		210.00	✓
1	REAR TAILGATE CENTRE GARNISH <i>NEN</i>		255.00	✓
2	REAR TAILGATE NUMBER PLATE LAMP LH & RH @\$121.20 <i>NEN</i>		242.40	✓
1	REAR TAILGATE LOGO <i>NEN</i>		95.00	✓
1	REAR TAILGATE "FIT" EMBLEM <i>NEN</i>		80.00	45
1	REAR TAILGATE INNER TRIM BOARD <i>NEN</i>		285.00	✓
2	REAR TAILGATE UPPER REFLECTOR LH & RH @\$459.10 <i>LH cut</i>		918.20	280.50
2	REAR TAILLAMP LH & RH @\$555.00 <i>WT</i>		1110.00	761.60
2	REAR TAILLAMP PANEL LH & RH @\$284.30 <i>Regis</i>		568.60	✓
1	REAR WINDSCREEN MOULDING <i>NEN</i>		125.00	✓
1	REAR BUMPER <i>Dented</i>		813.50	495
2	REAR BUMPER SIDE RETAINER LH & RH @\$55.00 <i>NEN</i>		110.00	✓
2	REAR BUMPER SIDE BRACKET LH & RH @\$71.50 <i>NEN</i>		143.00	✓
1	REAR BUMPER SPONGE <i>NEN</i>		151.00	✓
1	REAR BUMPER LOWER <i>NEN</i>		281.00	✓
1	REAR BUMPER KEYLESS ANTENNA <i>could</i>		211.00	89
1	REAR END PANEL <i>Dented</i>		660.00	464
1	REAR END PANEL TOP GARNISH <i>Dented</i>	3786.10	217.80	✓
1	REAR SPARE TYRE TOP BOARD <i>NEN</i>	3028.88	315.10	✓
1	REAR SPARE TYRE SPONGE <i>NEN</i>		381.70	✓
1	REAR WIPER <i>NEN</i>		109.00	✓
1	REAR WIPER MOTOR <i>NEN</i>		229.00	✓
2	REAR FENDER GARNISH LH & RH @\$385.90 <i>NEN</i>		771.80	✓
	Rear End Panel Buzzer. <i>could</i> 87.80		9535.10	
		less 20%	1907.02	20%
			7628.08	
<u>SPECIAL NETT ITEMS</u>				
1 SET	REVERSE SENSOR <i>Dented</i>		280.00	200
1	REVERSE CAMERA <i>NEN</i>		350.00	✓
1	REAR END PANEL SEALANT <i>NEN</i>		100.00	60
1	REAR END PANEL TOP GARNISH CLIPS <i>NEN</i>	360	80.00	10
1 SET	REAR TAILGATE INNER TRIM CLIPS <i>NEN</i>		60.00	✓
1	REAR WINDSCREEN SEALANTS <i>NEN</i>		100.00	60
1 SET	REAR BUMPER CLIPS <i>NEN</i>		80.00	30
Total Parts			8678.08	



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SMN1844Y HONDA FIT

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1200.00	900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	900
3	To remove and refix wiring at damaged areas	200.00	300
4	To perform anti rust treatment on affected areas	150.00	800
5	To remove & refix / replace rear trims, garnish and fitting so as to facilitate repairs as rear compartment	150.00	800
6	To remove and replace reverse sensors and check for proper functions	120.00	500
7	To remove and refix rear tailgate windscreen	120.00	✓
8	To remove rear boot mechanism	120.00	800
Labour Total :		3060.00	
TOTAL (PARTS & LABOUR):		11738.08	

To remove rear camera. 1000.00

To remove rear video recorder 1000.00

2360

Total: 5748.88

h/s: 4.GK

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: