

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24274

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1520/2019/NS
Date : 27-Dec-19

Vehicle NOT IN workshop. Please arrange for survey

Your Insured Vehicle no : SGX 3007 C

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tan Xiuyun Jen
Address : 34 Upper Cross Street
#12-146
Singapore 050034
Telephone : HP +65 98734833
Type of Claim : Third Party Claim
Policy No. : 2100494510-03
Vehicle No : **SLJ 7016 P**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : 21/12/2016
Engine No : CHZ 138878
Chassis No : WAUZZZ8VXH1013682
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-19
Place of Accident : Bedok North Ave 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 7016 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 <i>500 x 1</i> ✓	<i>500</i>
3	To respray rear bumper. <i>550</i>	\$ 900.00 <i>500</i>	<i>550</i>
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,422.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 7016 P

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER / 	\$	1,793.00	1434.40
2	REAR BUMPER STICKY PAD /  X NN 4	\$	21.00	
3	REAR BUMPER FIXING PARTS X NN	\$	175.00	
4	REAR WHEEL HOUSING LINER ADAPTER - LH / RH X NN2	\$	68.00	
5	REAR BUMPER GUIDE SECTION - LH / RH ? X NN 2	\$	30.00	
6	REAR BUMPER LOCKING MECHANISM ? X NN 2	\$	53.00	
7	REAR BUMPER SPOILER - LH the / 	\$	216.00	172.80
8	REAR LIGHT REFLECTOR - RH X NN	\$	38.00	
9	REAR BUMPER SIDE REINFORCEMENT BEAM X NN	\$	522.00	
10	REAR BUMPER BRACKET - LH X ? X NN	\$	25.00	
11	REAR BUMPER BRACKET - RH ? X NN	\$	26.00	
12	REAR BUMPER GUIDE SECTION - LH / RH X NN 2	\$	120.00	
13	REAR PARKING AID SENSOR - LH / RH ? X NN 2	\$	462.00	
14	REAR PARKING AID SEAL RING /  X NN 4	\$	12.00	
15	SUNDRIES ? X NN	\$	200.00	
TOTAL SPARE PARTS		:	\$ 3,761.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 6,183.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

27/12/19, 1.00pm
Steve (LKK) WTL 1472

Surveyed Date

:

3 days

Authorised Date

:

P/P

Excess Cost

:

Liability

:

Ry BPL SKJ

Remarks

:

Please Note

:

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant