

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19022804/EGA3Q2

**Date:** 19/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100425864

**Claimant**  
**Vehicle No :** SLJ7016P **Insured Vehicle No :** SGX3007C

Date of Loss: 23/12/2019 Nature of Claim: TP Claim No: 2331994870SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ7016P	Engine No:	CHZ138878
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8VXH1013682
Reg. Date:	21/12/2016 (Man. Year: 2016)	Odometer:	58544 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,761.00	1,607.20	2,153.80	57.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,183.00</b>	<b>3,129.20</b>	<b>3,053.80</b>	<b>49.39</b>
<b>+ GST 7.00/7.00% (S\$)</b>	432.81	219.04	213.77	49.39
<b>Nett Amount (S\$)</b>	<b>6,615.81</b>	<b>3,348.24</b>	<b>3,267.57</b>	<b>49.39</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,500.24</b>		

### INSPECTION

Date of Assignment: 27/12/2019

Date Inspected: 27/12/2019 Inspected At: 281 ALEXANDRA RD  
Repairer: Premium Automobiles Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,793.00 FS	*1,434.40 FS
2	4		*REAR BUMPER STICKY PAD	Not Necessary	21.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	175.00 FS	*- FS
4	2		*REAR WHEEL HOUSING LINER ADPATER -LH/RH	Not Necessary	68.00 FS	*- FS
5	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	30.00 FS	*- FS
6	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	53.00 FS	*- FS
7	1		*REAR BUMPER SPOILER	Cut	216.00 FS	*172.80 FS
8	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	38.00 FS	*- FS
9	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	522.00 FS	*- FS
10	1		*REAR BUMPER BRACKET -LH	Not Necessary	25.00 FS	*- FS
11	1		*REAR BUMPER BRACKET-RH	Not Necessary	26.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	120.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR -LH/RH	Not Necessary	462.00 FS	*- FS
14	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
15	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
					<b>Total Parts (S\$)</b>	<b>3,761.00 1,607.20</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTAL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,422.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >