	1); <u>abnu wll</u>	of	TIL (conice)	Date/	Time: 27	112/19@ 3.07
Estimated Co	STTP RES / OD RES		Bill to:			
Γο Inspect V	ehicle No:	FBQ 566		Insured;	SHC	3934A
at Workshop	m/s	GLIN Suece	85	Tel:	9828	9277
of	1 Carlei	Buleit Are 6	# 02-03			
Policy No:_			Claim No:			
Sum Insured:			Excess:	ir.		
Viake of Veh Client's Recor	The state of the s			D.O.	A/	7/12/2019
CA / REV	/ REP. / REV 24 HR	S		11.0	D.D. Endorsemer	nt:
Date/Time:	317pm@ 27/12/16	Person Contacted:	Aht	1	DOUT	
	Action/Instruction	Islamoly (
Peto/Time	PBQ 5663R-	Y				

(08/11/13) wef ASS. REC. BY: March (REF:	111/	,		
100.1120.01.7 (01.2)		ASSIGNMEN	Т		
		1		2	/2
From:	Date:			Yr Regn: (
stimated Cost:				Lorry / Taxi / Prime Mo	over/
DITTO WS I TP RES I OD RES I	5-2		K / Trailer or		
o Inspect Vehicle No:	TBQSB1	Make:	- Monda W	W ((0) c.c	15-3
: Workshop m/s	10 Stees	Colour	culticolour	A/C: Insured /	Std / NI / NA
f		Sp.Reading	26778	T/Radio: Insured	Std / NI / NA
sured:		Eng/No:	MULLIT	2 10	
olicy No.		C/No:	MAMKE	12A8C50	03/6/
laims No.		Gen. Cond:	od / Fair / Poor / Bu	rnt	
um Insured:	Excess:	Steering: In	goer / Jammed / Leake	ed / Burnt or	
(Client's Record)		Brake: In	ofder Lammed / Leake	ed / Burnt or	
Take of Veh:		Modi: Ni	1 Stam / STD A/Rim	or	
		Tyre Size:	^	0-90-1	V
(Policy Condition)					/
temark: The veh had commenced	dits	N/S O/S RS / DUN /	EXNOVA / GY / FS / 1 17	A MIC OHTSU/PIR	SUMI
repair at the time of insp		TOYO / YO		3/100/PIK	John /
	4(00)			Deer	1
al. or Market Value:	, ,	Front R/Bal.	6	Rear R/Bal.	0
	Consistent? : Yes or N		mm	2011/2011	mm
(/.	Consistent? : Yes or N	ASSESSMENT.	2/12/10 mm	L/Bal.	1 . 1.0
st. Repairs: Adays			11/0/19	D.O.I. 2 7/	17/18
um Sum: 2 %	3 Val.: Yes or				•
CA / REV / REP. / 24 HRS		•	^ -	S N/S U/C Rooft	op or
Date: Person Con		nicle: IN / OUT	V .	als soly	
		The U/C	/ Chassis frame / Bo	ody Structure affected	due to collision
Action / Instruction 344 (1/20 1/5 & 2) (\$4,05	4.90 conf	34 Ped - 65%	neijie		
		RECEIVED	D 8 JAN 2020		
		ž			
ata/Tima Eila Bass ta?			. 44		
0401120	reli. Report	Days Of Re		1000 and F	
7/-1-	nal Report	Resurvey N	lo. of Trip:	Survey Fee:	290
Date/Time, File Return to?		A d d	l /¢	Transportation:	
			Insp (\$)S + RS,SI	- 1
			view (\$) Photos	
Report Format :	1	=	h. Invs (\$) Others	11
ump Sum / I.B.I: (\$ 2, 200	»/- 4s)	: We	ekend (\$)	
				TOTAL	261

Nivitha (LKK Auto)

From:

Motor Claim - III < motorclaim@iii.com.sg>

Sent:

Friday, 27 December 2019 3:07 PM

To:

'sur@lkkauto.com'; Nivitha (LKK Auto)

Cc:

Ruby Ong; feena@htapartners.com.sg; Gabriel Wee; Pooi Chin Han Daniel RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR FBQ 5663R [OUR REF.

Subject:

TCL.GCN.RO.50776.19.ESS1

3.17pm@ 27112 19 p. Ah huad Y:1N

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FBQ5663R and let us have your report urgently.

This claim will be handled by Mr. Daniel.

Aside to Feena,

Kindly assist to provide your client's SAS report for surveyor to handle.

*Kindly upload this survey request email to merimen.

*We have started using audatex since 1st Dec 2019. Please do adjustments through Audatex and upload the report onto Merimen.

Thank You.

Warmest regards,

Stanley fai

Motor & Work Injury Claims Department India International Insurance Pte Ltd

64 Cecil Street, IOB Building, Level 5 Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



From: Motor Claim - III

Sent: Friday, 27 December, 2019 3:01 PM

To: 'feena@htapartners.com.sg' <feena@htapartners.com.sg>

Cc: 'Ruby Ong' <ruby@htapartners.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR FBQ 5663R [OUR REF. TCL.GCN.RO.50776.19.ESS]

Dear Feena,

Per our earlier tele-conversation, please confirm your proposed appointment of LKK Auto Consultants as SJE.

Thank you.

Your ref:

SHC 3934A

WITHOUT PREJUDICE

Our ref :

·TCL.GCN.ro.50776.19.ess

23 December 2019

India International Insurance Pte Ltd

By Email Only

Motor Claims Department 64 Cecil Street #04-00 IOB Building Singapore 049711

VERY URGENT

Dear Sirs,

CLAIMANT: MEDUSA LEASING

ACCIDENT INVOLVING FBQ 5663R & SHC 3934A ALONG SERANGOON AVENUE 3 ON 17 DECEMBER 2019 @ 1245HRS

We are instructed by Medusa Leasing to notify you of a road traffic accident on 17 December 2019 at about 1245hrs along Serangoon Avenue 3 involving our client's vehicle registration number <u>FBQ 5663R</u> and vehicle registration number SHC 3934A driven by your insured/insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, our client proposes to appoint <u>LKK Auto Consultants Pte Ltd</u> as the single joint expert to carry out the prerepair survey for <u>FBQ 5663R</u>.

Please make the necessary arrangements with the contact person. The details are as follows:

Venue

Euro Success Services Pte Ltd

1 Kaki Bukit Avenue 6 #02-03 Autobay Singapore 417883

Contact Person:

Ah Huat (Tel. 9828 9277 / 6742 6231)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416

Tel: 6533 0212 ext 278 Fax: 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Warmest regards,

Stanley fai

Motor & Work Injury Claims Department India International Insurance Pte Ltd

64 Cecil Street, IOB Building, Level 5 Singapore 049711 Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



From: Motor Claim - III

Sent: Monday, 23 December, 2019 9:52 AM To: Ruby Ong <ruby@htapartners.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR FBQ 5663R [OUR REF. TCL.GCN.RO.50776.19.ESS]

Dear Sir / Mdm,

We acknowledge receipt of your email.

We proprose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1^{st} dec 2019. Please submit your estimate/quotation throught Audatex so that our surveyors can make the adjustments according.

Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711

Tel: 6347 6100, Ext - 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]

Sent: 23 December, 2019 8:58 AM

To: Motor Claim - III < motorclaim@iii.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR FBQ 5663R [OUR REF. TCL.GCN.RO.50776.19.ESS]

Importance: High

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ner ID Type:	Business
Owner ID:	829E
/ehicle Details	
Vehicle No.:	FBQ5663R
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	WW150
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	KF12E2015488
Chassis No.:	MLHKF12A8C5003168
Maximum Power Output:	
Open Market Value:	\$2,643.00
Original Registration Date:	22 Nov 2013
First Registration Date:	22 Nov 2013
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$397.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	*
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Nov 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,712.00
COE Rebate Amount:	\$666.00
Total Rebate Amount:	\$666.00

The information contained herein is correct as at 27 Dec 2019

ОК



(/listing/usedbike/honda-honda-cbr150r/15351/)

SGD\$7800

Reg: 30/10/2017 Type: Sport Bikes

150cc

Well Maintain Condition. Loan Available, Welcome Trade In. Come Visit Us At New Southern Motor. Block 1008 Bukit Merah Lane 3 #01-12 S(159762). Interested Buyers Are Welcome To Negotiate.

Posted on: 18/12/2019

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-CBR150R/15351/)

■ COMPARE

Honda CBR150R (/listing/usedbike/honda-honda-cbr150r/13838/)



(/listing/usedbike/honda-honda-cbr150r/13838/)

SGD\$4600

Reg: 05/09/2013

Type: Sport Bikes

150cc

77282km

Well Maintain Condition. Just Changed Engine Oil And New Battery. Viewing At At Blk 613 Bukit Panjang Ring Road Singapore 670613. Call R. Rama For Meet Up.

Posted on: 17/12/2019

★ PAID AD **★** DIRECT SELLER

DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-CBR150R/13838/)

■ COMPARE

Honda CBR150R (/listing/usedbike/honda-honda-cbr150r/15383/)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT	
Date Of Report	18/12/2019 11:31	
Date Of Accident	17/12/2019 12:45	
Exact Location Of Accident	SERANGOON AVENUE 03	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	2 4
Vehicle Registration Number	FBQ5663R	
Insured/Policyholder		
Name Of Registered Owner	MEDUSA LEASING	
Co Reg No	53393829E	
Email Address	NOEMAIL	
Mobile Phone No		
Alternative Phone No	OFFICE-97777282	

Vehicle Particulars

HONDA Manufacturer WW150 Model

Exact Purpose for which vehicle was being used at

time of accident

WORK-PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

MOTORCYCLE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

5108497799

Cover Note Number

Driver

Name of Driver SHAFIQ BIN SAID

NRIC No S9534269H Date Of Birth 15/09/1995 OUTDOOR Occupation Date Of Driving Pass 18/11/2013

Driving Experience 6 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97334936

Fax Number Contact Number

EMail Address NOEMAIL Address

BLK 237 HOUGANG STREET 21 #10-398

Postcode

530237

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

Police Station Name

POTONG PASIR NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 142 POTONG PASIR AVENUE 3, POSTCODE: 350142.

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2829999 - FAX NO: 62815964

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20191217/2133;

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC3934A

Vehicle Make/Model/Colour

HYUNDAI / I40 1.7L CRDI AT ABS AIRBAG 4DR

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

0 (0 /	
· · · · · · · · · · · · · · · · · · ·	DETAILS OF INJURED PERSON 1
Name	SHAFIQ BIN SAID
Approximate Age	24
Injuries Sustain	
Injured person in which vehicle?	FBQ5663R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	BLK 237 HOUGANG STREET 21 #10-398
Postcode	530237

SKETCH PLAN

IMPORTANT NOTICE



- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misregresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any latse reporting may be referred to the Police for investigation
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (POPA)

Lunderstand, acknowledge, agree and consent that

- (ii) My insurer, my workshop and the General Insurence Association of Singapore ("GiA") may/are permitted to collect, use disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers Insurers/lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all instiners and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


MEDUSA LEASING

70.10 hurtimuriji.neg me 60e Ave 5 800-46 569880

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416687 Fax: 67492305
Email: vackb@vlcom.com.sq

Reporting Centre Personnel's Signature Name: NRIC/FIN No.

DAME INSTITUTE VI



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



DECLARATION

I/We declare the foregoing particulars are true in every respect.

MEDUSA LEASING

of 1 Signature 508 49 549880

UEH: 55399829E

Date & Time:

(If driver is not the policyholder)

Date & Time:

GISHK DatoRytom 73

IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 #02-02 Singapore 415933 Tel: 67416697 Fax 67492305 Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature

Name

NEC/FIN No.:





Police Station Of Origin Potong Pasir NPP 142 Potong Pasir Avenue 3 #01-240 SINGAPORE 350142 Tel No. 1800-2829999 † of 4 Report No. T/20191217/2133

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/12/2019 16:29			Vide Report No.	Station Diary No. 22	
Informa	nt's Partic	ulars			
	Informant BIN SAID		Address APT BLK 237 HOUGA 530237	ING STREET 21 #10 398 SINGAPORE	
ID Type / ID No NRIC NO / S9534269H		Contact No. Home/Office	Mobile 97334936		
National SINGAP	lity PORE CITIZ	EN	Email		
Sex: Male	Age: 24	Date of Birth. 15/09/1995	Type of Informant: Rider		
Race Javanes	e		Language English	Institution / School Name	
Occupation Delivery Rider			Oriving Licence Information Class 2A 3 Date of Expiry		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident 17/12/2019 12:45	Type of Locatio T-Junction	
Outside entra	N AVENUE 3				
Weather: Raining		Road Surface: Wet		Road Speed Limit:	
Traffic Flow		Traffic Control Not Controlled		Traffic Volume No Traffic	
One Way					

Vehicle No	Type.	Make	Model	Color	Condition	No of Passenger
FBQ5663R	Motorcycle	HONDA	WW150		Seriously Damaged	0
SHC3934A	Car	HYUNDAI	I40 1.7L CRDI AT ABS AIRBAG 4DR			0





Police Station Of Origin Potong Pasir NPP 142 Potong Pasir Avenue 3 #01-240 SINGAPORE 350142 Tel No. 1800-2829999 2 of 4 Report No. 17201912117/2133

CONTINUATION OF REPORT

No. of Pedestrians Injured: NIL.			Use of Pedestrian Crossing: NA			sing: NA
Rider						
Name	SHAFIQ BIN SAID			ID No		S9534269H
Related Vehicle	FBQ5863R (Motorcycle)			Contact No.		97334936
Hospital/Clinic	Potong Pasir Medical Clinic			Class of Driving Licence & Expiry Date		Class 2A,3 Date of Expiry NIL
Date Treatment	NIL		Date Disc			
No. of Days gran	ted Medical Leave	03	Degree of			AUS
Driver		100			1900	A Secretary
Name	DAS			ID No		NIL
Related Vehicle	SHC3934A (Car)			Contact No.		90044269
Hospital/Clinic	NIE		Class of Driving Licence & Expiry Date		Class NIL Date of Expiry NIL	
Date Treatment			Date Disc			
No. of Days grant	ted Medical Leave	NIL	Degree of			

Brief Details.

On 17/12/2019 at about 1246hrs I was travelling on my bike(FBQ5663R) along Serangoon avenue 3. When I reached a T junction, I was going straight however a taxi(SHC3934A) wanted to turn right from the opposite side of the lane without checking for oncoming traffic. I was travelling at about 15km/h only as it was raining and slippery. I did not see the taxi and once I saw him turning right without giving way and not signaling turning right, I had no choice but to use my emergency brake. This resulted in me skidding and as he still did not stop, my bike skidded and hit onto the front of his taxi.

The driver of the taxi came out of his taxi and we exchanged particulars. He then proceeded to tell me that it was my fault as he said I was speeding. After a while he changed his story and said that he thought I was turning left which was why he turned right without giving way to me. The taxi driver then said that he wanted to go off and then I could claim any compensation direct from his company(Comfort). I would like to say that the driver did not seem to show any remorse for his actions and did not even bother to check on my injuries. He told me to go shead and call ambutance and police if I wanted to I then took some pictures of the accident and managed to get the drivers name and number.

My bike is badly damaged. The whole left side of the bike has deep scratches and dents. The headlights are damaged, the handle bar alignment is not centred anymore, and the body frame on the left side of the bike is torn off.

I then proceeded to a clinic and am suffering from a lot of abrasions, cuts and bruising on my left knee. I am also suspected to be suffering from fractured ribs and thus have an appointment for an X-ray. I also



T20191217/2133

Police Station Of Origin Potong Pasir NPP 142 Potong Pasir Avenue 3 #01-240 SINGAPORE 350142 Tel No. 1800-2829999 3 of 4 Report No. 1/20191217/2133

CONTINUATION OF REPORT

have huge abrasion and cut on my left elbow and cuts on both my paims. The doctor also informed me that I high blood pressure due to the pain I am feeling. I was given 3 days MC.

During the visit to the doctor I got a call from the driver's brother who asked if I wanted to settle the matter privately but I have informed him that I will settle it the way my insurance has advised me to do so I would like to mention that my bike has no CCTV recording. I am lodging this report for my own insurance and recording purposes.

EURO SUCCESS SERV PTE. LTD Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: FBQ 5663R

Model:PCX 150

			THE CONTRACTOR OF THE CONTRACT		the still live
	<u>YTY</u>		<u>List Items</u>	<u>P</u>	rice & Whe she Illie ing
	1		HEADLAMP LED	101	11 1018.00 X
	1		FRONT FORK		Su 982.00 V
	1		FRONT MUD GUARD FENDER		82 230.00 X
	1		RIM SUB		47 60.00 ×
	1		FRONT L/H COVER		cu7 320.00
	1		L/H STEP COVER 266.00		CU7 275.00 -
	1		L/H STEP LOWER COVER 295.00		Cu7 313.00
	1		SIDE STAND		N 80.00 X
	1	MH	REAR BRAKE LEVEL		SUN 63.00
	1		HANDLE BAR		Sul 143.00
	1		L/H MIRROR		CU7 80.00
	1		L/H BOX LOCK		1 270.00 X
	1		L/H BOX LOCK COVER		110.00 A
	1		MAIN STAND		R 88.00 €
	1		AIR FILTER COME		C47 380.00
1 SET			REAR bely cover		Cu7 350.00
	1		REAR L/H fostrest		(4) 48.00
	1		REAR MUDGUARD		17 75.00X
	1		FRONT WINDSHIELD		17 97.00 X
	1		FRONT L/H WINDSHIELD LOWER COVER		C97180.00 —
	1		REAR L/H SIDE COVER 415.00		Cu7 450.00
	1		L/H HANDLE BALANCER 34°		SUR 49.00
				TOTAL	\$5,661.00 2575
				LESS 10%	\$566.10
				2200 2070	\$5,094.90
					43,034.30
			Labour Charge		26
			Transportation charges		120.00 35
			To respray painting and ETC		260.00 250
			To check front and rear electrical wiring		11 50.00 ×
			To straighten, repair and realign chassis		1 380.00 ×
			frame member		2 (2)
			Panel beating,cut,weld remove and		350.00 LSV
			replace above parts		I would still to shoot manner

I Yn Joyly Consultants hence notify

ESTIMATE PARTS AND LABOUR GRAND TOTAL

Not Albert 1/5# 2200

\$6,254.90

\$1,160.00

...CLAIM SUBFOLDER...(Pending for Survey Report) Non-Reporting

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	1	Adj Submitted	Ins Auth'ed	Sta	itus			
Main	09 Jan 2020 14:44 Edit Reg	09 Jan 2020 27 Dec 2019 00:00 \$\$2,			Jan 2020 27 Dec 2019 5\$2,200.00 \$\$2,200.			5\$2,200.00 View Rpt		Re	nding for port ancel Case	
	Main	Refe	rence	Cla	im Details		Document	s	s	how All		
CLAIM SU	JBFOLDER DE	TAILS				[Created	by adjuster]					
Insured:	-, Co. Reg	. No.: -										
Main Claimant:	-											
Vehicle Re No.:	g. FBQ5663	FBQ5663R					17/12/2019 00:00 - :59 [72 Months and 25 Days From LTA Reg Date (Man Yr)]					
Claim Type	: TP				Policy/Cover Note No.:							
Vehicle Re No. (Insured):	SHC3934A	SHC3934A			Policy No. (Claimant):							
					Excess:							
Repairer:	Euro Succ	ess Services Pte L	td (HQ) 1 KAKI BU	KIT AVENU	E 6 #02-03	AUTOBAY, 41	7883 Kaki Bukit	- Tel:				
Handling Insurer:	- CANTAGE CALLES	rnational Insuran	5-3-3110-31-4-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-	CH-14 AVIOLATICS S	1030Y 1 5030M 103011	Participation (April 1997)	1,2000000000000000000000000000000000000					
Adjuster:	LKK Auto	Consultants Pte Lt	d (HQ) - Tel: 6256	5-3561 [Handled by	MARCUS CH	UA] [Final R	pt due 0	9/01/20	20]		
ASSOCIA	TED MAIL REG	CEIVED					Vi	ew All	Compose	Case Mail		
There are	no mail for this	case.										
ALL ASS	OCIATED TAS	ks⊡				View All	Search Tasks	Create New	Task	Complete		
Due Da		Type Task G	roup Subject	Handle	r Assig	ned By	Completed On	Crea	ated On	Done		

Claim Documents

*FBQ5663R [SHC3934A] TP

Dec 17 2019 12:00AM [-] Euro Success Services Pte Ltd

Pho	tos/Images		3 per page ✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	_
1	07/01/20 09:46	General View	1 Load JPG	V
2	07/01/20 09:46	General View	Load JPG	V
3	07/01/20 09:46	General View	6 Load JPG	V
4	07/01/20 09:46	General View	6 Load JPG	V
5	07/01/20 09:46	General View	■ Load JPG	V
5	07/01/20 09:46	General View	1 Load JPG	Z
7	07/01/20 09:46	General View	1 Load JPG	V
8	07/01/20 09:46	General View	■ Load JPG	V
9	07/01/20 09:46	General View	■ Load JPG	V
10	07/01/20 09:46	General View	■ Load JPG	V
11	07/01/20 09:46	General View	1 Load JPG	V
12	07/01/20 09:46	General View	■ Load JPG	1 =
13	07/01/20 09:46	General View	Load JPG	
14	07/01/20 09:46	General View	■ Load JPG	
15	07/01/20 09:46	General View	■ Load JPG	-
16	07/01/20 09:46	General View	Load JPG	V
17	07/01/20 09:46	General View	■ Load JPG	-
18	07/01/20 09:46	General View	 Load JPG 	
19	07/01/20 09:46	General View	Load JPG	-
20	07/01/20 09:46	General View	1 Load JPG	
21	07/01/20 09:46	General View	Load JPG	
22	07/01/20 09:46	General View	Load JPG	
23	07/01/20 09:46	General View	1 Load JPG	-
24	07/01/20 09:46	General View	1 Load JPG	
25	07/01/20 09:46	General View	■ Load JPG	-
26	07/01/20 09:46	General View	€ Load JPG	-
27	07/01/20 09:46	General View	Load JPG	
28	07/01/20 09:46	General View	Load JPG	-
29	07/01/20 09:46	General View	■ Load JPG	-
30	07/01/20 09:46	General View	Load JPG	-
31	07/01/20 09:46	General View	Load JPG	
32	07/01/20 09:46	General View	Load JPG	
33	07/01/20 09:46	General View	Load JPG	-
34	07/01/20 09:46	General View	■ Load JPG	
35	07/01/20 09:46	General View	1 Load JPG	
36	07/01/20 09:46	General View	1 Load JPG	
37	07/01/20 09:46	General View	1 Load JPG	1 -
38	07/01/20 09:46	General View	Load JPG	
39	07/01/20 09:46	General View	Load JPG	
40	07/01/20 09:46	General View	1 Load JPG	-
			1 Load JPG	
41	07/01/20 09:46	General View	1 Load JPG	1-
42	07/01/20 09:46	General View	1 Load JPG	<u>A</u>

Pho	tos/Images		3 per	page 🗸	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	1
44	07/01/20 09:46	General View	0	Load JPG	V
45	07/01/20 09:46	General View	0	Load JPG	V
46	07/01/20 09:46	General View	0	Load JPG	V
47	07/01/20 09:46	General View	0	Load JPG	V
48	07/01/20 09:46	General View	0	Load JPG	V
49	07/01/20 09:46	General View	0	Load JPG	₽
50	07/01/20 09:46	General View	0	Load JPG	₹
51	07/01/20 09:46	General View	0	Load JPG	2
52	07/01/20 09:46	General View	0	Load JPG	E
53	07/01/20 09:46	General View	0	Load JPG	2
54	07/01/20 09:46	General View	0	Load JPG	E
55	07/01/20 09:46	General View	0	Load JPG	E.
56	07/01/20 09:46	General View	0	Load JPG	V
57	07/01/20 09:46	General View	0	Load JPG	E
58	07/01/20 09:46	General View	0	Load JPG	6
59	07/01/20 09:46	General View	0	Load JPG	6
60	07/01/20 09:46	General View	0	Load JPG	6
51	07/01/20 09:46	General View	0	Load JPG	6
62	07/01/20 09:46	General View	6	Load JPG	6
63	07/01/20 09:46	General View	0	Load JPG	6
54	07/01/20 09:46	General View	0	Load JPG	6
55	07/01/20 09:46	General View	0	Load JPG	6
56	07/01/20 09:46	General View	0	Load JPG	6
57	07/01/20 09:46	General View	0	Load JPG	6
58	07/01/20 09:46	General View	0	Load JPG	2
69	Lancow Control Marine, Secretary States		0	// // // // // // // // // // // // //	5
	07/01/20 09:46	Reinspection Photo		Load JPG	5
70	07/01/20 09:46	Reinspection Photo	0	Load JPG	-
71	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
72	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
73	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
74	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
75	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
76	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
77	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
78	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
79	07/01/20 09:46	Reinspection Photo	0	Load JPG	2
30	07/01/20 09:46	Reinspection Photo	0	Load JPG	2
31	07/01/20 09:46	Reinspection Photo	0	Load JPG	2
32	07/01/20 09:46	Reinspection Photo	0	Load JPG	2
33	07/01/20 09:46	Reinspection Photo	0	Load JPG	5
34	07/01/20 09:46	Reinspection Photo	0	Load JPG	5
35	07/01/20 09:46	Reinspection Photo	0	Load JPG	5
36	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
37	07/01/20 09:46	Reinspection Photo	0	Load JPG	5
38	07/01/20 09:46	Reinspection Photo	0	Load JPG	5
39	07/01/20 09:46	Reinspection Photo	0	Load JPG	6
	-				_
Оос	umentation		1 per	page 🔻	5
lo	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Pri

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Merimen e-Claims Page 3 of 3

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
	,	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/III19022820/USD3E2

Date:

09/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

SHC3934A

Claimant Vehicle No: Date of Loss:

FBQ5663R 17/12/2019 Insured Vehicle No:

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBQ5663R

Make & Model:

HONDA WW150, 153cc

Engine No:

KF12E2015488

Reg. Date: Colour:

22/11/2013 (Man. Year: 2013)

Chassis No:

MLHKF12A8C5003168

Engine Capacity:

Multi-colour

Odometer:

26778 km

153 cc

Market Value/New Car

Sum Insured (S\$):

N/A

Price:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

90-90-14

Rear Tyre Size:

100-90-14

Front Tyre Size: Front Left Side:

Michelin 6 mm

Michelin 6 mm

Front Right Side:

0 mm

Rear Left Side: Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
5,094.90	2,317.50	2,777.40	54.51
0.00	0.00	0.00	
1,160.00	535.00	625.00	53.88
0.00	0.00	0.00	
0.00	0.00	0.00	
6,254.90	2,852.50	3,402.40	54.40
	2,200.00		
6,254.90	2,200.00	4,054.90	64.83
	5,094.90 0.00 1,160.00 0.00 0.00 6,254.90	5,094.90 2,317.50 0.00 0.00 1,160.00 535.00 0.00 0.00 0.00 0.00 6,254.90 2,852.50 2,200.00	5,094.90 2,317.50 2,777.40 0.00 0.00 0.00 1,160.00 535.00 625.00 0.00 0.00 0.00 0.00 0.00 0.00 6,254.90 2,852.50 3,402.40 2,200.00

INSPECTION

Date of Assignment:

27/12/2019

Date Inspected:

27/12/2019 Inspected At:

Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03

AUTOBAY

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen		(Last Synchronised: 09 Jan 2020)		
Parts:	N/A	HONDA WW150 153cc (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for FBQ5663R)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LED	Not Necessary	1,018.00 FL	*-FL
2	1		*FRONT FORK	Serviceable	982.00 FL	*-FL
3	1		*FRONT MUD GUARD FENDER	Serviceable	230.00 FL	*-FL
4	1		*RIM SUB	Not Necessary	60.00 FL	*-FL
5	1		*FRONT L/H COVER	Cut	320.00 FL	*320.00 FL
6	1		*L/H STEP COVER	Cut	275.00 FL	*266.00 FL
7	1		*L/H STEP LOWER COVER	Cut	313.00 FL	*295.00 FL
8	1		*SIDE STAND	Repair	80.00 FL	*- FL
9	1		*L/H LEVEL	Scratched	63.00 FL	*63.00 FL
10	1		*HANDLE BAR	Bent	143.00 FL	*143.00 FL
11	1		*L/H MIRROR	Cut	80.00 FL	*80.00 FL
12	1		*L/H BOX LOCK	Not Necessary	270.00 FL	*- FL
13	1		*L/H BOX LOCK COVER	Not Necessary	110.00 FL	*- FL
14	1		*MAIN STAND	Repair	88.00 FL	*- FL
15	1		*AIR FILTER COVER	Cut	380.00 FL	*380.00 FL
16	1		*SET REAR BELLY COVER	Cut	350.00 FL	*350.00 FL
17	1		*REAR L/H FOOTREST	Cut	48.00 FL	*48.00 FL
18	1		*REAR MUDGUARD	Not Necessary	75.00 FL	*- FL
19	1		*FRONT WINDSHIELD	Not Necessary	97.00 FL	*- FL
20	1		*FRONT L/H WINDSHIELD LOWER COVER	Cut	180.00 FL	*180.00 FL
21	1		*REAR L/H SIDE COVER	Cut	450.00 FL	*415.00 FL
22	1		*L/H HANDLE BALANCER	Scratched	49.00 FL	*35.00 FL
F=Fra	anchise	part. L=ListIt	emDisc.			
				Sub Total (S\$)	5,661.00	2,575.00
			- List Item Discount on L Item	s 10.00/10.00% (S\$)	566.10	257.50
				Total Parts (S\$)	5,094.90	2,317.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TRANSPORTATION CHARGES	New	120.00	35.00
2	TO RESPRAY PAINTING	New	260.00	250.00
3	TO CHECK FRONT AND REAR ELECTRICAL WIRING	New	50.00	0.00
4	TO STRAIGHTEN, REPAIR AND REALIGN CHASSIS FRAME MEMBER	New	380.00	0.00
5	PANEL BEATING, CUT, WELD REMOVE AND REPLACE ABOVE PARTS	New	350.00	250.00
	Gross Labor	ur Cost (S\$)	1,160.00	535.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >