

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ben Tang

Date: 13 Mar 2020

Preliminary Advice

Vehicle No	: SJP9938H	Accident Date	: 25/12/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: DMPCSN1619871903
Assignment Date	: 05/03/2020	Excess	: S\$0.00
Date of Inspection	: 30/12/2019	Est. Duration of Repair	: 20.00
Inspection At	: BLK 5 DEFU LANE 10 #01-410/412		
	REPAIRER : SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion. The chassis frame affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,000.00
Revised Amount	:S\$	13,000.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	23,617.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,383.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :