



Your Ref: SNM19D206130/SJP9938H/BEN

Date: 11th Mar 2020

Our Ref: CS/CTI19022829/Uvf3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Dear Sir / Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO: SJP 9938H
ACCIDENT ON 25.12.2019**

Instruction was received from Mr Ben Tang to inspect the vehicle Reg. No. SJP 9938H at the premises of M/s: Block 5 Defu Lane 10 #01-410/412, Repairer : Sng Ah Tee Motor & Panel Service Pte Ltd on 30.12.2019.

The following information were recorded: -

<i>Registration Number</i>	: SJP 9938H
<i>Make & Model</i>	: Toyota Corolla Altis 1.6 Auto
<i>Chassis Number</i>	: MR053ZEE106144112
<i>Year of Registration</i>	: 2009
<i>Engine Capacity</i>	: 1598 cc

The following are our observation / comments:-

The vehicle sustained damages at the front portion. The chassis frame affected due to collision.
(Details see photographs enclosed)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

The repaired M/s Sng Ah Tee Motor & Panel Service Pte Ltd had agreed to undertake the repair of vehicle SJP 9938H at Lump Sum \$13,000.00.

Enclosed please find damaged vehicle's photos and out invoices for your necessary action.

Yours faithfully



CHUA KANG SENG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.