

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24010

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1515/2019/NS
Date	:	26-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ah Yat Abalone Forum Restaurant Holdings Pte Ltd
Address	:	200 Turf Club Road #03-01 Singapore 287994
Telephone	:	+65 98772618
Type of Claim	:	Own Damage Claims
Policy No.	:	1900168047
Vehicle No	:	SDA 1389 U
Model Code	:	Audi Q5 2.0 TFSI QU
Model / Year	:	30-09-19
Engine No	:	DAX 057741
Chassis No	:	WAUZZZF0K2118021
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	23-Dec-19
Place of Accident	:	Dunearn road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDA 1389 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,600.00 500	
3	To respray front bumper, front bumper lower spoiler, lhs front fender and both front wheel arch trims.	\$ 3,500.00 192 5	
4	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 5,772.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 1389 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER ✓ CVT	\$	2,364.00
2	FRONT BUMPER FIXING PARTS X	\$	244.00
3	FRONT BUMPER SECURING STRIP - LH ✓ MC	\$	34.00
4	FRONT BUMPER CLOSING ELEMENT - LH X	\$	101.00
5	FRONT BUMPER SPOILER X R	\$	685.00
6	FRONT BUMPER UNDERRUN BAR X	\$	431.00
7	FRONT BUMPER CLOSING ELEMENT X	\$	156.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH X	\$	519.00
9	FRONT BUMPER END CAP - LH X	\$	83.00
10	FRONT BUMPER GUIDE SECTION - LH ?	\$	34.00
11	FRONT BUMPER FOAM FILLER PIECE X	\$	259.00
12	FRONT BUMPER CARRIER X	\$	831.00
13	HEADLIGHT MOUNTING - LH X	\$	107.00
14	LED HEADLIGHT - LH X	\$	7,227.00
15	LIFT CYLINDER - LH X	\$	128.00
16	FRONT WHEEL COVER - LH / RH ✓ MC	2 \$	1,154.00
17	SUNDRIES ?	\$	300.00

TOTAL SPARE PARTS : \$ 14,657.00

TOTAL LABOUR CHARGES : \$ 5,772.00

GRAND TOTAL : \$ 20,429.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

65 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

30/12/19, 10.15 am
: Steve (LKK) OD - Not Auth (Paul)
: 5 chg
: P/P
: My Bel SN
: Excess - ?

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant