

Surveyor

marcus

ASSIGNMENT (Office)

From (Person):

Irene Tay Hui Ping

of

CT1

Date/Time:

30.12.19 10.13A.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Inspect Vehicle No:

GBH 1508E

Insured:

at Workshop info:

Fastech Auto

Tel:

67465405

of

1 KAR BUKI AM 4701-46/48/50

Policy No:

DM CVSN30103219011

Claim No:

SNM 19D 206131001

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

26.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

30.12.19 10.40A.m

Person Contacted:

Shi Ying

Vehicle

(IN)

OUT

Date/Time

Action/Instruction

(✓) Estimate

GBH 1508E - MA / CT1 19022836/443 SV

RCA - 26/12/2019

30/12/19

Revert via merimen

31/12/19

Rece approved \$10,000 from Irene by merimen

31/12/19

Informed Shi Ying c/A on LS repair Not exceeding \$10,000 ex \$500 by email

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBH150SL

Yr Regn:

2 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

c.c.

2982

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

86069

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KD42318031730

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

155 R13

Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

26/12/19

D.O.I.

30/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 29490

8/1/20 4/5 @ 6500 confirmed with other CRad 12,73920, 6690

RECEIVED 08 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 8/1 - typist

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

Merimen

Lump Sum / I.B.I. (\$ 6500/2

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Dec 2019		30 Dec 2019 10:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: GENERAL WATERPROOFING & SERVICE PTE LTD	
Vehicle Reg. No.: GBH1508E	Date of Loss: 26/12/2019 15:00 - :59
Claim Type: OD / SNM19D206131C01	Policy/Cover Note No.: DMCVSN30103219011 (Comprehensive)
	Excess: S\$500.00
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405	
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/01/2020]	
Adj Asg. Remarks: PLEASE SURVEY AND REVERT	

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 31 December 2019 10:29 AM
To: SUR; shiying.ong@fastechauto.com.sg
Subject: GBH 1508E-DOA: 26/12/2019 (CHINA TAIPING OD)

Dear Shi Ying,

As instructed by our client , please proceed to repair the **insured vehicle GBH 1508E on Lump Sum Repair Not Exceeding S10,000 or whichever lower (Excess S500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***GBH1508E (SNM19D206131C01)**
OD
Dec 26 2019 3:00PM
[GENERAL WATERPROOFING & SERVICE PTE LTD]
Fastech Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **31/12/2019 10:11 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10000.00) - GBH1508E - Claim Handler: Irene Tay Hui Ping

Approved:10000.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tay Hui Ping	Date: 30 Dec 2019

Preliminary Advice

Vehicle No	: GBH1508E	Accident Date	: 26/12/2019
Make	: TOYOTA DYNA 1.5T	Policy No.	: DMCVSN30103219011
Assignment Date	: 30/12/2019	Excess	: S\$500.00
Date of Inspection	: 30/12/2019	Est. Duration of Repair	: 6
Inspection At	: KIM CHWEE AUTO PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,005.20
Revised Amount	:S\$	4,998.40
Check Items (Estimated)	:S\$	7,623.00
Total	:S\$	12,621.40

Lump Sum Repair (Estimated)	:S\$	10,000.00
-----------------------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	29,490.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,510.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2019 13:59
Date Of Accident	26/12/2019 15:20
Exact Location Of Accident	SELETAR WEST LINK TWDS YISHUN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH1508E
Insured/Policyholder	
Name Of Registered Owner	GENERAL WATERPROOFING & SERVICE PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-83598728

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORK

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3010321901
Cover Note Number	

Driver

Name of Driver	GOVINDASAMY MUTHUKRISHNAN
NRIC No	FXXXX552R
Date Of Birth	10/05/1977
Occupation	OUTDOOR
Date Of Driving Pass	01/07/2014
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83598728
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 1 YISHUN ST 23 #05-06
Postcode	768441
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6795J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJG7680K
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

Accident Sketch Plan

SKETCH PLAN



A: GBH 1508E

B: SHD 6795J

C: SJG 7680K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 26th Dec. Thursday as I was driving my Mitsubishi GBH 1508E on the 2nd lane from Belstar West link Towards Yisbun, there was a vehicle C (SJG 7680K) that did not stop in time and hit the 1st vehicle B. SHD 6795J. and impact was so hard the car (SJG 7680K) bounced back and hit my car even after I had slow down and came to a stop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	170M
Vehicle Details	
Vehicle No.:	GBH1508E
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 MANUAL
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2761298
Chassis No.:	KDY2318031730
Maximum Power Output:	-
Open Market Value:	\$32,984.00
Original Registration Date:	02 Feb 2018
First Registration Date:	02 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$1,650.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Feb 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$36,458.00
COE Rebate Amount:	\$29,490.00
Total Rebate Amount:	\$29,490.00

The information contained herein is correct as at 30 Dec 2019

OK

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Festive Dining

Now Till Year End

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2017 Feb Honda Vezel 1.5 Sensing Ideal For Family



Below Average Mileage And
Lowest Depreciation In The
Market! High Loan Available
StarAd



Browse by Category

Sort by Date Posted

20 results/page

13 vehicles

dyna

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	dyna		Any	Any	2018	Any	Any	Any	Available
	Toyota	Dyna 150 3.0M	\$55,800	\$6,600 /yr	11-Jun-2018	2,982 cc	31,130 km	Truck	Available
Fuel Type: Diesel Flexible Packages With 100% Loan Available! Almost Like New Unit That Equipped With 6 Ft Box To Cater For Maximum Storage Space.... Car (S) Pte Ltd Posted: 30-Dec-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$57,800	\$6,790 /yr	02-Jul-2018	2,982 cc	-	Truck	Available
Fuel Type: Diesel One Owner Only, Low Mileage, Owner Spare Vehicle, Sell Due To Unutilised, High Trade In, High Loan Available, Call Us Now. SG Motor Link Pte Ltd Posted: 30-Dec-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$56,800	\$6,640 /yr	19-Jul-2018	2,982 cc	31,888 km	Truck	Available
Fuel Type: Diesel Best Bargain! Owner Loss A Lot, Buyer Gains. High Specs Unit! View To Believe! New Paintwork.3 Months Warranty Will Be Given. Ready... Car (S) Pte Ltd Posted: 27-Dec-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$55,800	\$6,700 /yr	26-Apr-2018	2,982 cc	39,000 km	Truck	Available
Fuel Type: Diesel Confirm Cheapest In Market, No Hidden Costs. Tip Top Condition. New Improve Diesel Engine By Toyota Super Low Fuel Consumption,... Net Link Partners Pte Ltd Posted: 27-Dec-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Pushing the limits for better cars Not only is Gazoo Racing the face of Toyota's motorsports endeavours, it also helps to improve Toyota's lineup of cars. Here's what Gazoo Racing is all about. Read this article								
	Toyota	Dyna 150 3.0M	\$58,000	\$6,720 /yr	15-Aug-2018	2,982 cc	39,000 km	Truck	Available
Fuel Type: Diesel Not Used In Construction! Pristine Condition! Regularly Serviced And Well Maintained By Borneo Motors. Warranty Under Borneo Motors!... Posted: 26-Dec-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota	Dyna 150 3.0M	\$64,800	\$7,360 /yr	16-Oct-2018	2,982 cc	7,800 km	Truck	Available
Fuel Type: Diesel Still Got New Car Smell. Done 7800km Only. Flawless. Under Utilised Due To Business Model Change. Power Gate Worth \$3k. Huge Carg... Posted: 23-Dec-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									

Compare

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 21612

Date : 28.12.2019

Vehicle Num : GBH1508E

Make/Model : TOYOTA DYNA

Chassis/Engine no :

Accident Date : 26.12.2019

Claim No : 1219-21612

Reference :

Policy No :

Auto Consultants hence notify the owner of the following:

- 1. In the event of a total loss, the vehicle will be replaced by a similar vehicle of the same make and model.
- 2. The vehicle will be replaced on a "Without Prejudice" basis.
- 3. The vehicle will be replaced by a similar vehicle of the same make and model.
- 4. The vehicle will be replaced by a similar vehicle of the same make and model.
- 5. The vehicle will be replaced by a similar vehicle of the same make and model.
- 6. The vehicle will be replaced by a similar vehicle of the same make and model.
- 7. The vehicle will be replaced by a similar vehicle of the same make and model.
- 8. The vehicle will be replaced by a similar vehicle of the same make and model.
- 9. The vehicle will be replaced by a similar vehicle of the same make and model.
- 10. The vehicle will be replaced by a similar vehicle of the same make and model.

Acknowledged by Repairer

Signature:

Date:

Qty Particular

Amount S\$

List Item :

- 1 pc Front windscreen rubber
 2 pc Front wiper arm @ 80.00
 2 pc Front wiper nozzle @ 32.00
 1 pc Front wiper panel
 1 set Front wiper linkage
 1 pc Front wiper motor
 1 pc Front panel
 1 pc Front panel emblem "DYNA"
 2 pc Front corner panel @ 90.00
 1 pc Front grille assy
 1 pc Front grille logo
 1 pc Front bumper assy
 1 pc Front chassis crossmember
 2 pc Front bumper bracket @ 125.00
 2 pc Front fog lamp @ 125.00
 2 pc Front cabin mounting @ 275.00
 2 pc Front door @ 750.00
 2 pc Front step board housing @ 48.00
 2 pc Headlamp @ 481
 1 pc Dashboard
 1 pc Dashboard reinforcement
 1 pc Brake booster
 1 pc Brake booster master pump
 1 pc Aircon heater unit
 1 pc Aircon blower unit
 1 pc Steering box
 2 pc Aircon heater hose @ 49.00
 1 pc L/H aircon condenser with bracket assy

List Item Total :

Cost Plus 10 % :

Special Nett Item :

- 1 pc Front number plate LTA
 1 set Front door company name sticker

Special Nett Total :

Labour Charge :

- To check wiring
 Remove and refix aircon blower unit heater unit and refix gas
 Remove and refix meter dashboard and check wiring
 Remove and refix front windscreen glass
 Remove and refix cushion seat
 Labour for panel beateng
 To putty and spray painting
 Labour Charge Total :

\$ 111	115.00	✓
\$ 11	160.00	X
\$ 11	64.00	X
\$ 11	220.00	✓
\$ 11	160.00	X
\$ 11	320.00	✓
\$ 11	680.00	✓
\$ 11	32.00	✓
\$ 11	180.00	X
\$ 11	220.00	✓
\$ 11	55.00	✓
\$ 11	320.00	✓
\$ 11	380.00	X
\$ 11	250.00	✓
\$ 11	250.00	✓
\$ 11	550.00	X
\$ 11	1,500.00	X
\$ 11	96.00	X
\$ 11	962.00	✓
\$ 11	680.00	X
\$ 11	420.00	X
\$ 11	650.00	X
\$ 11	350.00	X
\$ 11	1,250.00	✓
\$ 11	550.00	✓
\$ 11	1,470.00	X
\$ 11	98.00	X
\$ 11	650.00	X
\$	12,632.00	
\$	13,895.20	
\$	26,527.20	

\$ 11	350.00	14
\$ 11	30.00	✓
\$	380.00	

\$	80.00	30
\$	250.00	100
\$	450.00	200
\$	150.00	60
\$ 11	200.00	X
\$	1,800.00	800
\$	1,800.00	900
\$	4,730.00	

E & O : E

Total Amount : \$ 31,637.20 19,005.00

5224

P-5484
 102
 6032.4
 2134.00
 8166.4
 6533

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Supplementary : 21612

Date : 06.01.2020

Vehicle Num : GBH 1508E

Make/Model : TOYOTA DYNA

Chassis/Engine no :

Accident Date : 26.12.2019

Claim No : 1219-21612

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc Clutch cable

ADD

\$ 260.00 ✓

List Item Total :

\$ 260.00

Discount 10 % :

\$ 26.00

\$ 234.00

286

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Dec 2019		30 Dec 2019 10:13 Edit Adj Rpt	S\$6,500.00 Edit Estimates	S\$6,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GENERAL WATERPROOFING & SERVICE PTE LTD , Co. Reg. No.: -		
Vehicle Reg. No.:	GBH1508E	Date of Loss:	26/12/2019 15:00 - :59 [22 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D206131C01	Policy/Cover Note No.:	DMCVSN30103219011 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/01/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- CHINA_TAIPING (31/12/2019): Alert - Adj Mandate Approved (S\$10000.00) - GBH1508E - Claim Handler: Irene Tay ...

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH1508E (SNM19D206131C01)

OD

Dec 26 2019 3:00PM

[GENERAL WATERPROOFING & SERVICE PTE LTD]

Fastech Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/12/19 13:59	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/12/19 14:51	Chassis Number	1 Load JPG	
2	30/12/19 14:52	Odometer Reading	1 Load JPG	
3	30/12/19 14:52	General View	1 Load JPG	
4	30/12/19 14:52	General View	1 Load JPG	
5	30/12/19 14:52	General View	1 Load JPG	
6	30/12/19 14:52	General View	1 Load JPG	
7	30/12/19 14:52	General View	1 Load JPG	
8	30/12/19 14:52	General View	1 Load JPG	
9	30/12/19 14:52	General View	1 Load JPG	
10	30/12/19 14:52	General View	1 Load JPG	
11	30/12/19 14:52	General View	1 Load JPG	
12	30/12/19 14:52	General View	1 Load JPG	
13	30/12/19 14:52	General View	1 Load JPG	
14	30/12/19 14:52	General View	1 Load JPG	
15	30/12/19 14:52	General View	1 Load JPG	
16	30/12/19 14:52	General View	1 Load JPG	
17	30/12/19 14:52	General View	1 Load JPG	
18	30/12/19 14:52	General View	1 Load JPG	
19	30/12/19 14:52	General View	1 Load JPG	
20	30/12/19 14:52	General View	1 Load JPG	
21	30/12/19 14:52	General View	1 Load JPG	
22	30/12/19 14:52	General View	1 Load JPG	
23	30/12/19 14:52	General View	1 Load JPG	
24	30/12/19 14:52	General View	1 Load JPG	
25	30/12/19 14:52	General View	1 Load JPG	
26	30/12/19 14:52	General View	1 Load JPG	
27	30/12/19 14:52	General View	1 Load JPG	
28	30/12/19 14:52	General View	1 Load JPG	
29	30/12/19 14:52	General View	1 Load JPG	
30	30/12/19 14:52	General View	1 Load JPG	
31	30/12/19 14:52	General View	1 Load JPG	
32	30/12/19 14:52	General View	1 Load JPG	
33	30/12/19 14:52	General View	1 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	30/12/19 14:52	General View	 Load JPG	☒
35	30/12/19 14:52	General View	 Load JPG	☒
36	30/12/19 14:52	General View	 Load JPG	☒
37	30/12/19 14:52	General View	 Load JPG	☒
38	30/12/19 14:52	General View	 Load JPG	☒
39	30/12/19 14:52	General View	 Load JPG	☒
40	30/12/19 14:52	General View	 Load JPG	☒
41	30/12/19 14:52	General View	 Load JPG	☒
42	30/12/19 14:52	General View	 Load JPG	☒
43	30/12/19 14:52	General View	 Load JPG	☒
44	30/12/19 14:52	General View	 Load JPG	☒
45	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
46	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
47	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
48	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
49	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
50	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
51	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
52	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
53	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
54	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
55	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
56	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
57	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
58	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
59	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
60	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
61	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
62	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
63	01/01/20 07:44	Reinspection Photo	 Load JPG	☒
64	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
65	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
66	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
67	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
68	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
69	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
70	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
71	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
72	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
73	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
74	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
75	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
76	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
77	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
78	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
79	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
80	01/01/20 07:45	Reinspection Photo	 Load JPG	☒
81	01/01/20 07:45	Reinspection Photo	Load JPG	☒

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=901176&extid=327098&corole=4&C... 3/3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19022836/UVF3S2

Date: 20/01/2020

REFERENCE

Insured/Claimant: GENERAL WATERPROOFING & SERVICE PTE LTD

Policy No: DMCVSN30103219011

Date of Loss: 26/12/2019

Nature of Claim:

OD

Claim No:

SNM19D206131C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH1508E

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A)

Reg. Date: 02/02/2018 (Man. Year: 2017)

Colour: White

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$50,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1KD2761298

Chassis No: KDY2318031730

Odometer: 86069 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Front Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size:

155 R13 (D)

Rear Left Side:

Yokohama 6/6 mm

Rear Right Side:

Yokohama 6/6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,561.20	6,076.40	8,484.80	58.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	2,090.00	2,640.00	55.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,291.20	8,166.40	11,124.80	57.67
Approved Total (Overridden) (S\$)		6,500.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	18,791.20	6,000.00	12,791.20	68.07
+ GST 7.00/7.00% (S\$)	1,315.38	420.00	895.38	68.07
Nett Amount (S\$)	20,106.58	6,420.00	13,686.58	68.07

INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 30/12/2019

Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jan 2020)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1508E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN RUBBER (WCP)	Necessary	115.00 F	*115.00 F
2	2		*FRONT WIPER ARM (WCP)	Not Necessary	160.00 F	*- F
3	2		*FRONT WIPER NOZZLE (WCP)	Not Necessary	64.00 F	*- F
4	1		*FRONT WIPER PANEL (WCP)	Dented	220.00 F	*220.00 F
5	1		*SET FRONT WIPER LINKAGE (WCP)	Not Necessary	160.00 F	*- F
6	1		*FRONT WIPER MOTOR (WCP)	Jammed	320.00 F	*320.00 F
7	1		*FRONT PANEL (WCP)	Dented	680.00 F	*680.00 F
8	1		*FRONT PANEL EMBLEM DYNA (WCP)	Necessary	32.00 F	*32.00 F
9	2		*FRONT CORNER PANEL (WCP)	Repair	180.00 F	*- F
10	1		*FRONT GRILLE ASSY (WCP)	Cracked	220.00 F	*220.00 F
11	1		*FRONT GRILLE LOGO (WCP)	Necessary	55.00 F	*55.00 F
12	1		*FRONT BUMPER ASSY (WCP)	Torn	320.00 F	*320.00 F
13	1		*FRONT CHASSIS CROSSMEMBER (WCP)	Repair	380.00 F	*- F
14	2		*FRONT BUMPER BRACKET (WCP)	Bent	250.00 F	*250.00 F
15	2		*FRONT FOG LAMP (WCP)	Cracked	250.00 F	*250.00 F
16	2		*FRONT CABIN MOUNTING (WCP)	Serviceable	550.00 F	*- F
17	2		*FRONT DOOR (WCP)	Repair	1,500.00 F	*- F
18	2		*FRONT STEP BOARD HOUSING (WCP)	Not Necessary	96.00 F	*- F
19	2		*HEADLAMP (WCP)	Broken	962.00 F	*962.00 F
20	1		*DASHBOARD (WCP)	Not Necessary	680.00 F	*- F
21	1		*DASHBOARD REINFORCEMENT (WCP)	Not Necessary	420.00 F	*- F
22	1		*BRAKE BOOSTER (WCP)	Not Necessary	650.00 F	*- F
23	1		*BRAKE BOOSTER MASTER PUMP (WCP)	Not Necessary	350.00 F	*- F
24	1		*AIRCON HEATER UNIT (WCP)	Cracked	1,250.00 F	*1,250.00 F
25	1		*AIRCON BLOWER UNIT (WCP)	Cracked	550.00 F	*550.00 F
26	1		*STEERING BOX (WCP)	Serviceable	1,470.00 F	*- F
27	2		*AIRCON HEATER HOSE (WCP)	Not Necessary	98.00 F	*- F
28	1		*L/H AIRCON CONDENSER WITH BRACKET ASSY (WCP)	Serviceable	650.00 F	*- F
29	1		*FRONT NUMBER PLATE	Bent	350.00 FS	*14.00 FS
30	1		*SET FRONT DOOR COMPANY LTA STICKER	Necessary	30.00 FS	*30.00 FS
31	1		*CLUTCH CABLE (WCP)	Damaged	260.00 F	*260.00 F

F=Franchise part, S=SpcNett.

Sub Total (\$\$)	13,272.00	5,528.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,289.20	548.40
Total Parts (\$\$)	14,561.20	6,076.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING.	New	80.00	30.00
2	REMOVE AND REFIX AIRCON BLOWER UNIT HEATER UNIT AND REFILL GAS.	New	250.00	100.00
3	REMOVE AND REFIX METER DASHBOARD AND CHECK WIRING.	New	450.00	200.00
4	REMOVE AND REFIX FRONT WINDSCREEN GLASS.	New	150.00	60.00
5	REMOVE AND REFIX CUSHION SEAT.	New	200.00	0.00
6	LABOUR FOR PANEL BEATING.	New	1,800.00	800.00
7	TO PUTTY AND SPRAY PAINTING.	New	1,800.00	900.00
Gross Labour Cost (\$\$)			4,730.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >