

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

GBG 1166M

Not Allowed
N/A
4/5 ~~3250~~
427.
30/12/18

1PC	TAILGATE	1399.70
1PC	TAILGATE ,NISSAN, EMBLEM	141.80
1PC	TAILGATE LOWER MEMBER	
2PCS	TAILGATE LOCK LATCHES @215.00	
2PCS	TAILGATE HINGES \$50.00	
2PCS	TAILGATE 'L' LOWER PANELS @145.00	
2PCS	TAILGATE 'L' LOWER PANEL STOPPERS @121.00	
2PCS	TAILLAMPS @208.00	
2PCS	TAILLAMP BRACKERS @165.00	
2PCS	DROP SIDEGATES @2998.00	
2PCS	DROP SIDEGATE LOWER PANELS @981.00	
1PC	REAR CARGO PANEL FRONT PANEL	
1PC	REAR SPARE TYRE & CHAIN	399.10
1PC	CHASSIS FRAME N/S	

m/Ref	\$2,668.00	→
m	\$175.00	→
n	\$688.00	X
n1	\$430.00	X
n1	\$100.00	X
n1	\$290.00	X
n1	\$242.00	X
one	\$416	✓
15	\$330.00	X
n	\$5,996.00	X
n	\$1,962.00	X
n1	\$1,455.00	X
m/y/m	\$799.00	→
n	\$3,800.00	X
	\$19,351.00	

S.NETT

1SET	70KM/H STICKER & 13 PAX
1SET	REAR REVERSE SENSOR

rec	\$25.00	20
one	\$280.00	200

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
	\$80.00	50
n1	\$880.00	X
	\$180.00	50
	\$1,800.00	680
	\$1,800.00	680
TOTAL	\$24,446.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2356.60
102
2120.94
3820.94