

22 Dec 2019

AIG Insurance Ltd

Singapore

Attn. : Motor Claim Department

Re : | Quotation

Vehicle no. SGD 3622G (Kia)

S/N	Description	
	Parts Replacement	
	Front bumper <i>Ry</i>	\$ 489.00
	Bumper lower grille <i>CM</i>	\$ 129.00
	Bumper Right protector <i>mir</i>	\$ 82.00
	Bumper spone	\$ 121.00
	Bumper right retainer <i>CM</i>	\$ 67.00
	Front right headlamp <i>my CM</i>	\$ 549.00
	Front right fender	\$ <i>Ry</i> 450.00
	Right fender cowling <i>CM</i>	\$ 178.00
	Right fender protector <i>mir</i>	\$ 54.00
	Front right knuckle	\$ 372.00
	Front right wheel bearing	\$ 287.00
	Front right bearing hup	\$ 281.00
	Front right shock absorber	\$ 328.00
	Road rim <i>rw</i>	\$ 260.00
	Washer tank	\$ 110.00
	Drive shaft	\$ <i>R</i> 876.00
		\$ 4,633.00
	less 10%	
		\$ 4,169.00
	Labour Charges	
	To remove and refix new parts ,panel beating inner panel.	\$ 700.00
	To putty and spray paint on panel and new parts.	\$ 700.00
	To remove and replace front undercarriage parts	\$ 200.00
	To do wheel alignment	\$ 50.00
		\$ 5,819.00
	Total:	

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

\$ 5,819.00

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: