

LOH HENG

Automotive Repair Services
Accident Insurance Claims

22 Dec 2019

AIG Insurance Ltd

Singapore

Attn : Motor Claim Department

Re : Quotation

Vehicle no. SGD 3622G (Kia)

S/N	Description		
Parts Replacement			
	Front bumper	R ₁	\$ 489.00
	Bumper lower grille	CM	\$ 129.00
	Bumper Right protector	RM	\$ 82.00
	Bumper spone	CM	\$ 121.00
	Bumper right retainer	CM	\$ 67.00
	Front right headlamp	RM CM	\$ 549.00
	Front right fender		\$ R ₁ 450.00
	Right fender cowl	CM	\$ 178.00
	Right fender protector	RM	\$ 54.00
	Front right knuckle	R ₁	\$ 372.00
	Front right wheel bearing	RM	\$ 287.00
	Front right bearing hup	R ₁	\$ 281.00
	Front right shock absorber	R ₁	\$ 328.00
	Road rim	RM	\$ 260.00
	Washer tank	CM	\$ 110.00
	Drive shaft		\$ R 876.00
			\$ 4,633.00
	less 10%		
			\$ 4,169.00
Labour Charges			
	To remove and refix new parts ,panel beating inner panel.		\$ 700.00
	To putty and spray paint on panel and new parts.		\$ 700.00
	To remove and replace front undercarriage parts		\$ 200.00
	To do wheel alignment		\$ 50.00
			\$ 5,819.00
	Total:		

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel 64532237 / 64530797
Fax 64556384

Not Authorized
L1 Sy @ 3400h
Recovery After Rain
5 days

3,300.00
less 10%
\$2,970.00

500

600

780

\$1,330.00

\$4,300.00

e H6

\$3,400.00

I, the undersigned, hereby notify the Repairer of the following:
• To remove before delivery
• To display damaged parts during recovery
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary items of modification surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: