From (Person);	Ren Tuna	ASSIGN	MENT (Office) -CTL	Dat	e/Time: 30/12/	ac 10an
Estimated Cost:			Bill to:			
	TP RES / OD RES	EVA/INV/MY	//-CS	Insured:	31p 993	844
To Inspect Vehi		SIW 5115E		Tel:	6844 24	
of	***	ubi Avenue	1 # 01-24			
Policy No:			Claim No:	SUMIADS	06130/SJP9	9384/BEI
Sum Insured:			Excess:			
Make of Veh: (Client's Record)				D.	0.A 25/12	1/2019
(Chem a recora)	REP. / REV 24 HI		ted: Dawn		H.O.D. Endorsement:	
	3pm@30/12/19	_ 1 Gloom Comes	Control of the second s			
			1			W
Date/Time: Date/Time	Action/Instruction	Tehnnyly (~)	Refinan	e ready l	e will am
Date/Time:		Ishmoti (~)	Refiner	e ready l	e will am

	* This vehicle have limit Repur	r,			11/3/20	20
	have not inform ws yet	DECE	WED 2.7	MAD 2020		
	Confirm with Shushun.	KLUL	IVLD	Likili none		
		lass (H/S)	(\$	29.788.2	s Red.	-62%2
Date/Time, File P.	Prell. Report	Days	Of Repair:	10		* 184
1) Typ.	1	Resi	rvey No. of T	rlp:	Survey Fee:	270
Date/Time, File F	eturn (o?	_	_		Transportation:	
2)	0:=200000	Add Fee:	: Site Insp	(\$	\$ + RS,\$J	
			: Interview	(\$) Pholos	
Peparen	mest:	Ē	: Tech. Invs	(\$ ·) Others	
Lynnp Sym	11.E.1:15 \$ 18.650/ L/SI		: Weel and	(\$	i	
	7	(anarri			TOTAL	220

Nivitha (LKK Auto)

From:

Ben Tang <Ben.Tang@sg.cntaiping.com>

Sent:

Monday, 30 December 2019 10:00 AM

To:

'assignments@lkkauto.com'

Subject:

FW: OUR REF: SNM19D206130/SJP9938H/BEN & YOUR REF: T1912-44 // -

ACCIDENT INVOLVING SJP9938H AND SJW5115E -TO CONDUCT PRS -SJW5515E

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SJW5115E.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer. This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Darren <kntcars@gmail.com>

Sent: Monday, December 30, 2019 9:51 AM To: Ben Tang <Ben.Tang@sg.cntaiping.com>

Ce: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D206130/SJP9938H/BEN & YOUR REF: T1912-44 // -ACCIDENT

INVOLVING SJP9938H AND SJW5115E -TO CONDUCT PRS -SJW5515E

WITHOUT PREJUDICE

Dear Ben Tang,

Please appoint LKK TAUFIKH

From: Ben Tang

Sent: Monday, 30 December 2019 9:50 AM

To: kntears a gmail.com Ce: Claims Dept of CTI

Subject: RE: OUR REF: SNM19D206130/SJP9938H/BEN & YOUR REF: T1912-44 // -ACCIDENT

INVOLVING SJP9938H AND SJW5115E -TO CONDUCT PRS -SJW5515E

WITHOUT PREJUDICE

Dear Sit.

We refer to your email dated 27 December 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING	
Kelvin Ang	
SEE CHEW SENG	
MOHD FADHILAH BIN	
OSMAN	
XING QUO QIANG	
KENNETH KONG	
SIMON HO	
CHUA WEIJIE	
MARCUS CHUA	
HENRY NO	

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID (65) 6389 6175 | F: (65) 6222 1033

W: www.sg_cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclarmer. This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Friday, December 27, 2019 8:09 PM

To: Ben Tang < Ben. Tang@sg.cntaiping.com >; kntcars@gmail.com

Subject: OUR REF: SNM19D206130/SJP9938H/BEN & YOUR REF: T1912-44 // - ACCIDENT

INVOLVING SJP9938H AND SJW5115E -TO CONDUCT PRS -SJW5515E

Dear BeN

Please conduct PRS- SJW5115E soonest possible.

File with officer in charge -Ben Tang -DID: 6389 6175.

Dear Shu Shan,

*** Landly quote our reference number when replying.

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6339 6116

Fax (65) 6224 7175 / 6224 7478

Email claimsdept@sg.cntaiping.com

Website:www.sq.cntaiping.com

Discipliner This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: K&T CARS [mailto:kntcars@gmail.com]

Sent: Friday, 27 December, 2019 5:48 PM

To: Claims Dept of CTI

Ce: K&T CARS

Subject: OUR REF: T1912-44 // YOUR REF: SJP9938H ACCIDENT INVOLVING SJP9938H AND

SJW5115E

WITHOUT PREJUDICE

OUR REF: T1912-44 YOUR REF: SJP9938H

Dear Sir / Madam,

PRE-REPAIR INSPECTION FOR SJW5115E

ACCIDENT INVOLVING SJP9938H AND SJW5115E ON 25.12.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regurds.

Shu Shan

K & 1 Cars Blk 53 Ubi Avenue 1 * #01-24

Paya Ubi Industrial Park Singapore 408934

Tel: 6844 2475 Fax:6844 2474

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	Waterway 1970 August W
Owner ID Type:	Singapore NRIC
Owner ID:	223J
/ehicle Details	Lucia sa pa
/ehicle No.:	SJW5115E
/ehicle to be Exported:	No
ntended Deregistration Date:	02 Jan 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA200 (R18)
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	27091030379538
Chassis No.:	WDD1173432N084908
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$29,920.00
Original Registration Date:	05 Jun 2014 / 4 yrs 5 mths / 53 mths
First Registration Date:	05 Jun 2014
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$23,888.00 / 11,944
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2024
PARF Rebate Amount:	\$16,721.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$72,290.00
COE Rebate Amount:	\$31,968.00
Total Rebate Amount:	\$48,689.00

The information contained herein is correct as at 02 Jan 2020

$$13,500/12 = 1,125$$
 OK
 $1,125 \times 53$ m+hs =
 $\frac{59,625}{11,944}$
MV = $71,569$
PV = $48,689$

NV: 22,880

SGCARMART.COM

Login Sign up

Used Cars Rental Cars Sell My Car Directory

New 5 Years Renewal COE Toyota View 1.5A

Products Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!



2.88% P.A. SO Down, 10 Admin, Monthly From \$430, 2 Ym Warranty Engine/Sesirbox. GV Credit Shared



Browse by Category

Post an Ad

Advertiser Login Ways of Selling

Mercedes Benz cla200

Sort by Date Posted Advanced Seinch 🔀

▼ 20 results/page ▼

7 vehicles

Model

Price Depreciation Reg Date Eng Cap Arvy

Arry:

2014

Any

Mileage

Veh Type Status Any:

Available

Search Selection

Mercedes Benz cla200

\$14,740 /yr

16-Jan-2014

55,000 km

Luxury

Available



Mercedes-Benz CLA-Class CLA200

\$70,800

1,595 cc

6 Months Warranty, Excellent Condition, Accident Free, Bank Loan/In House Loan Available, Trade In Welcome.

Posted: 28-Dec-2019 Tags: 2014 Mercedes-Benz CLA200, 2014 mercedes-benz da200, Mercedes-Benz CLA200, mercedes-benz da200, Mercedes-Benz, CLA200, da200, Used Mercedes-Benz



Mercedes-Benz CLA-Class CLA200

\$70,800

\$13,980 /vr

21-Mar-2014 1,595 cc 79,500 km

Available Luxury

METTER TOP

Graded B by STR

High Paper Value! C&C Unit. Meticulously Well Maintained By Previous Owner! Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Interest Rate And Competitive Trade In Price! Call Now To Find Out More! GST Included In Price!

Autolink Holdings Pte Ltd Posted: 26-Dec-2019
Tags: 2014 Mercedes-Benz CLA200, 2014 mercedes-benz cla200, Mercedes-Benz CLA200, mercedes-benz cla200, Mercedes-Benz CLA200, cla200, Used Mercedes-Benz CLA200, mercedes-benz cla200, Mercedes-Benz CLA200, cla200, Used Mercedes-Benz CLA200, merc

Mercedes-Benz CLA-Class

\$75,200 \$15,100 /yr 01-Apr-2014 1,595 cc 27,288 km

Luxury

Available

CLA200

High ARF, Pristine Condition Maintained By 1 Owner, Cycle Unit. Stylish And Eye Catching Model. Kindly Call/WhatsApp For A Test Drive

on, View To Believe, Trade In And Loan Welcome.

Posted: 25-Dec-2019 Tags: 2014 Nercedes-Benz CLA200, 2014 mercedes-benz cla200, Mercedes-Benz CLA200, mercedes-benz cla200, Mercedes-Benz CLA200, cla200, Used Mercedes-Benz

Mercedes-Benz CLA-Class

\$70,888

\$13.810 /yr 02-May-2014

1,595 oc

Luxury

Available

CLA200 Careful Owner, Selling Due To Upgrade, Call Now Don't Miss, Price Negotiate C&C Unit, 1.98% Interest, All The Service Records, Low Depreciation, All Credit Profile Welcome, 100% Loan Available, Free Warranty And Servicing. Hurry Call Now.

Posted: 30-Nov-2019 Tags: 2014 Mercedes-Benz CLA200, 2014 mercedes-benz cla200, Mercedes



Juzz Performance Pte Ltd - Specialist for Mercedes Car repair, servicing & maintenance

Juzz Performance, a modern car garage filled with motorheads of over 20 years of experience in maintenance, repair & tuning of European makes.

More info about this shop



Mercedes-Benz CLA-Class

\$70,800

\$13,630 /vr

21-May-2014

Available

C&C Unit, Original Full Leather! Immaculate Condition! New Road Tax! 6 Months Warranty. 100% Accident Free, Buy With Peace Of Mind! Trade In Available. STA Evaluation/Workshop Check Welcome, Bank Loan And In House Loan Available! Call Us Now Or Drop By Our Sh...

Posted: 30-Dec-2019 Tags: 2014 Mercedes-Benz CLA200, 2014 mercedes-benz cla200, Mercedes-Benz CLA200, mercedes-benz cla200, Mercedes-Benz CLA200, cla200, cla200, used Mercedes-Benz

Mercedes-Benz CLA-Class

\$73,800

\$14,260 /yr / 27-May-2014 / 1,595 cc

101,000 km

Available

Luxury

CLA200 AA Trust Certified Quality Pre-Owned Vehicle! Beautiful Pearl White Executive Sporty Sedan At An Affordable Price! Wear & Tear Almost \$10k With Receipts! From Steering Rack, Suspension, Lower Arm To New Tyres Barely 2 Weeks Old! Travel In Style And Comfort That S.

(CONSIGNMENT)

STATE OF THE PARTY OF

AA Trust Automotive

Posted: 18-Nov-2019 Tags: 2014 Mercodes-Benz CLA200, 2014 mercedes-benz cla200, Mercedes-Benz CLA200, cla200, Used Mercedes-Benz CLA200, mercedes-benz cla200, Mercedes-Benz CLA200, cla200, Used Mercedes-Benz CLA200, cla

Mercedes-Benz CLA-Class CLA200

\$73,800 \$13,880 /yr / 11-Jul-2014 / 1,595 cc

109,892 km

Available Luxury

C&C Unit, Upgraded Alpine 2 Way Component Speakers And Active Subwoofer, Original Full Leather! Immaculate Condition! New Road Tax! 6 Months Warranty, 100% Accident Free, Buy With Peace Of Mind! Trade-In Available, STA Evaluation/Workshop Check Welcome....

Posted: 01-Nov-2019 Tags: 2014 Mercedes-Benz CLA200, 2014 mercedes-benz da200, Mercedes-Benz CLA200, mercedes-benz da200, Mercedes-Benz, CLA200, da200, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

Model

Price Depreciation Rep Date Eng Cap Mileage Veh Type Shalls

1/2

Oi Sun Pin (LKK Auto)

From:

K&T CARS <kntcars@gmail.com>

Sent:

Friday, 20 March, 2020 10:38 AM

To:

Oi Sun Pin (LKK Auto)

Cc:

K&T CARS

Subject:

RE: SJW5115E MERCEDES CLA200

Follow Up Flag:

Follow up

Flag Status:

Flagged

Dear Sun Pin,

We confirm COR @\$18650 and DOR @ 10 days.

Thank you and have a nice day.

Regards,

Shu Shan

K & T Cars

Blk 53 Ubi Avenue 1

#01-24

Paya Ubi Industrial Park

Singapore 408934 Tel: 6844 2475 Fax:6844 2474

From: Oi Sun Pin (LKK Auto)

Sent: Friday, 13 March 2020 11:28 AM

To: Darren

Subject: RE: SJW5115E MERCEDES CLA200

'WITHOUT PREJUDICE'

Dear Darren,

Good day, regarding your request for L/SUMP repair cost need \$22,500, that have try summit to insurance after other party insurance management did not approve this amount.

at last other party insurance management offer to your repair cost L/SUMP amount COR \$ 18,650 and DOR 10 DAYS.

Kindly to take noted, will be base finalized amount COR \$18,650 and DOR 10 DAYS to close this case.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 27/12/2019 17:37

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

By the lodgement of this report to the insurers, you aforesaid.	a nereby consent to the archiving of any report of the control and to copies at the report of the
	ACCIDENT STATEMENT
Date Of Report	27/12/2019 16:00
Date Of Accident	25/12/2019 14:45
Exact Location Of Accident	YIO CHU KANG ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJW5115E
Insured/Policyholder	
Name Of Registered Owner	CHIANG PAUL
NRIC No	SXXXX223J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96931067
Alternative Phone No	OTHERS-96931067
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ

Manufacturer MERCEDES-BENZ

Model CLA 200-1.6 SHOOTING BRAKE (R18 BI) (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

2100475405-03

Cover Note Number

Driver

Name of Driver CHIANG TIEN CHEE

 NRIC No
 SXXXX464D

 Date Of Birth
 24/11/1950

 Occupation
 INDOOR

 Date Of Driving Pass
 22/06/1971

Driving Experience 48 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97579083

Fax Number Contact Number

EMail Address NOEMAIL

Address

BLK 148 SERANGOON NORTH AVE 1

#01-483

Postcode

550148

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

PARENT

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

3

NO

involved in the accident

YES

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: GRACE CHIANG PO YIN

GENDER:

: FEMALE

Passenger 2

NAME:

: SEETOH LYE CHENG

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

10 UBI AVENUE 3

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY KAREN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO WITH THE OWNER.

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJP9938H

Vehicle Make/Model/Colour

Details Of Properties Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHA9414E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHIANG TIEN CHEE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJW5115E

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

SEETOH LYE CHENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJW5115E

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

GRACE CHIANG PO YIN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJW5115E

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN		
KITCHELLIA.		
		7
	111111111111111111111111111111111111111	1 1
		A. SZWSUSE
	C Can A Can	(SHARUILE)
		8: ALTES (57P9938H)
	1/2 1/2	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REfer to Police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy holder's signature Date & time: Driver's signature (if driver is not policy holder) Date & time: reporting centre personnel's Signature NRIC/FIN No.:

Page 6

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of :
 - Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) Investigations the accident and/or my claims;
 - (III) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (IV) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelops/mail packages); and/or
 - (V) Complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (I) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
 - (II) For complying with requirements under my regulations, laws or court orders.

Policy holder's signature Date / time: Driver's signature (if driver is not policy holder) Date / time: reporting centre personnel's Signature
Date / time: \(\) \(\) \(\) \(\) \(\) \(\)

POLICE REPORT



REPORT OF A TRAFFIC ACCIDENT

T20191226/2024

Date of Expiry:

0191226/2024

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

SEMI RETIRED

1 of 3 Report No. T/20191226/2024

Date/Time Report Made:
26/12/2019 10:15

Vide Report No.:
F/20191225/0167

Informant's Particulars

Name of Informant:
CHIANG TIEN CHEE

ID Type / ID No.:

Vide Report No.:
F/20191225/0167

Station Diary No.:
Address:
Address:
APT BLK 148 SERANGOON NORTH AVENUE 1 #01-483
SINGAPORE 550148

Contact No.:

ID Type / ID No .: Mobile: 97579083 Home/Office: NRIC NO / S0184464D Email: Nationality: SINGAPORE CITIZEN Date of Birth: Type of Informant: Sex: Age: 24/11/1950 Driver 69 Male Institution / School Name: Language: Race: Chinese Driving Licence Information: Occupation:

Class: 3

General Information of the Accident Type of Location: Date/Time of Drink Injury Type of X-Junction Drive: Accident: Attended by Police Accident: 25/12/2019 14:30 No Location: Junction of Road 1 and Road 2 YIO CHU KANG ROAD ANG MO KIO AVENUE 3 TOWARDS HOUGANG Road Speed Limit: Road Surface: Weather: Dry Clear Traffic Volume: Traffic Control: Traffic Flow: Moderate Traffic Light - Working Two Way Anyone conveyed by Type of Collision: ambulance: Between Moving Vehicles - Head To Side Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
SJP9938H	Car	ТОУОТА	COROLLA ALTIS 1.6 AUTO	Beige		2
SJW5115E	Car	MERCEDES BENZ	MERCEDES BENZ	Red		2

Details of Person Involved	MARKET STATE OF THE STATE OF TH
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



T/20191226/2024

2 of 3

Police Station Of Origin: Traffic Police

Report No. T/20191226/2024

10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Driver				1	115-116	001011010
Name	CHIANG TIEN CHE	E		ID No		S0184464D
Related Vehicle	NIL			Conta	ct No.	97579083
Hospital/Clinic	NIL			Class Drivin Licent Expiry	9	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Dis		NIL	
	ted Medical Leave	NIL	Degree o	of Injury	NIL	

Brief Details.

ON THE MENTIONED DATE TIME AND LOCATION,

I WAS TURNING RIGHT TOWARDS SERANGOON GARDEN AND THE GREEN LIGHT WAS IN MY FAVOUR. THEN A CAR CAME IN FROM YIO CHU KANG RD TWDS SENGKANG AND HIT ON THE RIGHT OF MY VEHICLE PASSENGER SIDE. AFTER THAT MY CAR SWING AND THE AIRBAG BURST. AFTER THAT AMBULANCE CAME AND CONVEYED MY DAUGHTER. TRAFFIC POLICE WAS ALSO AT SCENE.

POLICE REPORT





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20191226/2024

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report. Signature Of Informant: NURSADIY ZULFIKAR BIN SHAWAL Date/Time: Signature Of Interpreter: 26/12/2019 10:15 Not applicable Classification Of Case SINGAPORE Officer In Charge Of Case: POLICE FORCE TP / GIT / Sr Staff Sqt NORAMEERA BINTE MOHAMED HUSSEIN Contact No.: 65476236 Authentication Stamp Signature: -NP168

K&T CARS

K&T Cars

53 Ubi Avenue 1 #01-23 Spore 408934

Tel: 6844 5938

E-mail: kntcars@gmail.com ROC number: 53208965X

CHINA TAIPING INSURANEPTE LTD 3 Anson Rd #16-00 .Springleaf Tower Singapore 079909

REPAIR PERFORMA INVOICE

Vehicle number	SJW5115E
Make / Model	MERCEDES / CLA200
Chassis number	WDD1173432N084908
Accident date	25 December 2019
Reference	T1912-44

Qty Particulars

Unit Price - SGD \$

Qty	Particulars	Unit Price - 300 3
	PARTS REPLACEMENT - LIST ITEMS	V
1	RH DOOR PILLAR 7 XR	× 717.60
1	IRH DILLAR LIPPER TRIM	/ 519.20
1	RH PILLAR BOTTOM TRIM 7 XSVC	× 519.20
1	FRONT RH DOOR PANEL	1,850 2002.15
2	FRONT RH DOOR HINGE	× 257.60
1	FRONT RH DOOR WEATHERSTRIP ?/cut	280 408.00
1	FRONT RH DOOR LOCK ASSY / Jamed.	/ 384.00
1	FRONT RH DOOR HANDLE XSVC.	× 184.80
1	FRONT RH DOOR CYCLINDER GUIDE XS VC	× 85.20
1	FRONT RH DOOR BEARING BRACKET 2 X 5 VC	× 211.20
1	FRONT RH DOOR INNER TRIM ? / SCR	1,050 1454.75
1	FRONT RH DOOR REGULATOR MOTRO X SVC.	× 819.60
1	FRONT RH DOOR OUTER MOULDING / STR	229.20
1	FRONT RH DOOR GLASS X 5 VC	×247.20
1	REAR RH DOOR PANEL / CRU.	/ 2280.00
2	REAR RH DOOR HINGE / CRY	200 280.80
1	REAR RH DOOR WEATHERSTRIP / CRM-	280 408.00
1	REAR RH DOOR LOCK ASSY / Jam	380 422.40
1	REAR RH DOOR BEARING ? XSVC	X 211.20
1	REAR RH DOOR HANDLE	/ 184.80
1	REAR RH DOOR INNER TRIM	1,690 1518.00
1	REAR RH DOOR REGULATOR 7 - BT	5W 800.40
1	REAR RH DOOR OUTER MOULDING / SCH	/ 237.60
1	REAR RH FENDER / PD	1,612 2030.90
1	REAR RH FENDER INNER SHIELD / CRM.	/ / 183.60
1	REAR RH FENDER INNER TIRM ? - Cut	274.80
1	REAR RH WHEEL CARRIER 7 XSVC	×1696.25
1	REAR RH WHEEL BEARING 7 13T	350 513.60
1	REAR RH SHOCK ABSORBER 7 - BT	/ 499.20
1	REAR RH CAMBER ARM 7 / BT	181.20
1	REAR RH RADIS ROD Z KK Auto Consultants hence notify the Repairer of the following:	×201.60

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

*	1	REAR RH TIE ROD 7 XSVC	×138.00	1
,	1	SIDE CRASH SENSOR Nec	246.00	
,	1	FRONT RH SEAT ASSY % XSVC	>2365.55	
	1	RH SIDE CURTAIN AIR BAG / BR	1144.80	
	1	ROOF LINING	1189.10	
	1	REAR BUMPER / CRU.	/ 1546.75	İ
		REAR BUMPER RETAINER / BR	1,650 1932.00	
	1	PDC SENSOR blad spot senson 7 X SVC	73.60	
	1	REAR EXHAUST ASSY 7 X R	× 351.90	
		EXHAUST MOUNTING ? XIVC	×1811.25 × 43.20	
- 1	1	RH SILL GARNISH / CRY.	280 1200.30	
		INT SILE GARRISTI	280 1200.30	18,615-85
			32006.50	10/612-0)
		Less 10%	3200.65	
		Subtotal	28805.85	
		Balance C/F	20003.03	
		PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	1 SET	REAR BUMPER CLIP / Nec	50.00 30/	
		FRONT RH DOOR INNER TRIM CLIP - N-PC	30.00	
		REAR RH DOOR INNER TRIM CLIP / N.CC.	30.00	
1	_	RIM - PC /SEN CUT	1500.00 700	7
5	1	TYRE - BR.CVT	450.00 270	
	1	JONT SEALANT NEC.	150.00 60	
		WINDSCREEN SEALANT /NEC	150.00	b
		, nec	130.00	1,180
		Subtotal	750.00 2360	,
		Balance C/F	29555.85	
-		LABOUR AND MISCELLANEOUS CHARGES	500000000000000000000000000000000000000	
		Balance B/F	29555.85	
	1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30	
	355	REMOVE, REFIT LINING, TRIM AND GARNISH	200.00 80	
		REMOVE AND RENEW REAR REVER SENSOR	120.00 30	
	66	REMOVE AND NEW REAR EXHAUST ASSY	120.00 ? 80	
1	82	DIAGNOIS CHECK AND CLEAR FAULT CODE	400.00 ?×	
-		REMOVE, RENEW AIRBAG ASSY AND DOWNLOAD ECU	500.00 ? 200	
-	255	REMOVE AND RENEW ROOF LINING	300.00 50	
	522 77	COMPUTERISED AND CHECK REASR WHEEL ALIGNMENT	150.00 60	
-	and Special	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	200.00 7 106	
-	- 1	TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO	200.00 € ○	
	10.68001	TRANSFR PARTS, ATTACHMENT FROM REAR OLD DOOR TO NEV	200.00 60	
1	255	PANEL BEATING ON AFFECTED AREAS	2000.00 1,200	1,400
	- 1	SPRAY PAINTING ON AFFECTED AREAS	1800.00 1,400	1,600
	14	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40	2 700
1		Repair day day Subtotal	6400.00	3,790
		Lump Sum Sun Pin (Lick) Grand total	35955.85	
		Afferspray photo- 31/12/2019 To without prejuder.	48 438.20	50048.20
		# ** C 20 ** C		

K&T CARS

K&T Cars

53 Ubi Avenue 1 #01-23 Spore 408934

Tel: 6844 5938

E-mail: kntcars@gmail.com ROC number: 53208965X

CHINA TAIPING INSURANEPTE LTD

3 Anson Rd

#16-00 .Springleaf Tower

Singapore 079909

REPAIR PERFORMA INVOICE

Vehicle number	SJW5115E
Make / Model	MERCEDES / CLA200
Chassis number	WDD1173432N084908
Accident date	25 December 2019
Reference	T1912-44

Otv Particulars

QLY	raiticulars		Unit Price - SGD \$	8
	PARTS REPLACEMENT - LIST ITEMS			1
1	LEVER SENSOR / Shurt		300 1501.60 A	
1	REAR RH CHASSIS MEMBER X R	1	2620.60 A	
1	REAR RH SEAT X R		3365.50 A	
1	REAR RH SEAT PULLING COVER / CRA		✓ 189.00 A	
1	TAILLAMP RH / SC R	- 1	755 1100.00 A	
1	TAILLAMP SIDE COVER RH X SVC		121.00 A	
1	BOOTLID HINGE COVER RH Y SVC		89.60 A	
1	FRONT AIRBAG CONTROL UNIT X 5 Vc		2835.60	
1	RH CENTRE PILLAR GLASS X 5VC		1201.02 A	
1	RH CENTRE PILLAR GLASS MOULDING / TRY		∠ 131.80 A	
1	RH CENTRE PILLAR GLASS GARNISH / SCR		∕ 158.00 A	1,533.8
	12		13313.72	17,333.0
		Less 10%	1331.37	
		Subtotal	11982.35	
		Balance C/F	11982.35	
	LABOUR AND MISCELLANEOUS CHARG	<u>ES</u>		
1	MOUNT VEHICLE ON BENCH FOR ALIGNMENT		500.00 200	
		Subtotal	500.00	
		Grand total	12482.35	

		ence notify
	ne follo	wing:
		ray painting
+ To	d part(s)	durino resurve

- First prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- he flegal modification(s) is allowed
- Supplementary (tem(s) must be resurveyed and is subject to final approval from insurance Company

10 days

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING						77	The review of	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed	Status	
Main	27 Dec 2019		02 Jan 2020 16:44 Edit Adj Rpt	S\$18,65 Edit Est	5555500 · * *	100000	8,650.00 ew Rpt		Pending Report Cancel C	for Survey
	Main	R	eference	CI	aim Deta	ails		Documen	ts	Show All
CLAIM SU	IBFOLDER DE	TAILS			-		[Created	by insurer]	Name of Street or other Designation of the Owner, where the Owner, which is the Owner, where the Owner, which is the Owner, where the Owner, which is	
Insured:	-, Co. Re	g. No.: -					4,5,0,000,000,000			
Main Claimant:	CHIANG F	CHIANG PAUL								
Vehicle Reg No.:	SJW511	SJW5115E			Date of L	oss:	25/12/2019 00:00 - :59 [66 Months and 20 Days From LTA Reg Date (Man Yr)]			te (Man Yr)]
Claim Type	re: TP / SNM19D206130/SJP9938H/BEN				Policy/Co Note No.		DMPCSN1619871903 (Comprehensive)			
Vehicle Reg No. (Insured):		SJP9938H			Policy No (Claiman					
					Excess:		S\$0.00			
Repairer:	K & T Can	(Ubi) 53 Ubi Av	e 1 #01-23 Paya Ut	oi Industrial	Park, 408	934 L	Ubi - Tel: 68	442475		
Handling Insurer:	China Tai	oing Insurance (Singapore) Pte. L	td. (HQ) - 1	el: 6389	6111	[Handled	by Ben Tang]		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	[Handled	by O	I SUN PIN]	[Final Rpt	due 13/01/2	020]
ASSOCIA	TED MAIL RE	CEIVED						Vi	ew All Comp	ose Case Mai
There are r	o mail for this	case.								
ALL ASSO	CIATED TAS	ks⊟				V	/iew All S	earch Tasks	Create New Task	Complete
Due Dat		Type Task	Group Subjec	t Handle	er As	sign	ed By	Completed On	Created	On Done

Claim Documents

Photos/Images		3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	l Prin
1	02/01/20 17:41	Chassis Number	1 Load JPG	✓
2	02/01/20 17:41	Odometer Reading	Load JPG	\checkmark
3	02/01/20 17:41	General View	1 Load JPG	☑
4	02/01/20 17:41	General View	6 Load JPG	☑
5	02/01/20 17:41	General View	■ Load JPG	V
6	02/01/20 17:41	General View	Load JPG	V
7	02/01/20 17:41	General View	1 Load JPG	✓
8	02/01/20 17:41	General View	1 Load JPG	V
9	02/01/20 17:41	General View	1 Load JPG	V
10	02/01/20 17:41	General View	Load JPG	V
11	02/01/20 17:41	General View	1 Load JPG	☑
12	02/01/20 17:41	General View	1 Load JPG	V
13	02/01/20 17:41	General View	Load JPG	V
14	02/01/20 17:41	General View	1 Load JPG	☑
15	02/01/20 17:41	General View	Load JPG	V
16	02/01/20 17:41	General View	1 Load JPG	V
17	02/01/20 17:41	General View	1 Load JPG	V
18	02/01/20 17:41	General View	■ Load JPG	V
19	02/01/20 17:41	General View	1 Load JPG	V
20	02/01/20 17:41	General View	Load JPG	V
21	02/01/20 17:41	General View	1 Load JPG	V
22	02/01/20 17:41	General View	1 Load JPG	V
23	02/01/20 17:41	General View	1 Load JPG	✓
24	02/01/20 17:41	General View	1 Load JPG	V
25	02/01/20 17:41	General View	■ Load JPG	V
26	02/01/20 17:41	General View	1 Load JPG	V
27	02/01/20 17:41	General View	1 Load JPG	V
28	02/01/20 17:41	General View	1 Load JPG	V
29	02/01/20 17:41	General View	■ Load JPG	V
30	02/01/20 17:41	General View	Load JPG	✓
31	02/01/20 17:41	General View	1 Load JPG	V
32	02/01/20 17:41	General View	1 Load JPG	✓
33	02/01/20 17:41	General View	1 Load JPG	V
34	23/03/20 18:07	Dismantled Parts	Load JPG	V
35	23/03/20 18:07	Dismantled Parts	1 Load JPG	☑
36	23/03/20 18:07	Dismantled Parts	Load JPG	V
37	23/03/20 18:07	Dismantled Parts	■ Load JPG	V

Pho	tos/Images		3 per page 💟	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	
38	23/03/20 18:07	Dismantled Parts	1 Load JPG	N.
39	23/03/20 18:07	Dismantled Parts	1 Load JPG	✓
10	23/03/20 18:07	Dismantled Parts	1 Load JPG	-
1	23/03/20 18:07	Dismantled Parts	€ Load JPG	V
12	23/03/20 18:07	Dismantled Parts	1 Load JPG	-
13	23/03/20 18:07	Dismantled Parts	1 Load JPG	-
14	23/03/20 18:07	Dismantled Parts	1 Load JPG	-
15	23/03/20 18:07	Dismantled Parts	Load JPG	-
16	23/03/20 18:07	Dismantled Parts	■ Load JPG	V
7	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
18	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
19	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
50	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
-	400000000000000000000000000000000000000	Dismantled Parts	1 Load JPG	V
51	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
52	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
54	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
55	23/03/20 18:07	Dismantled Parts	1 Load JPG	V
56	23/03/20 18:07	Dismantled Parts	1 Load JPG	
57	23/03/20 18:07	Dismantled Parts	Load JPG	
58	23/03/20 18:07	Dismantled Parts	Load JPG	. 5
59	23/03/20 18:07		Load JPG	
60	23/03/20 18:07	Dismantled Parts	€ Load JPG	-
61	23/03/20 18:07	Dismantled Parts	■ Load JPG	
62	23/03/20 18:07	Dismantled Parts	■ Load JPG	-
63	23/03/20 18:07	Dismantled Parts	1 Load JPC	-
64	23/03/20 18:07	Dismantled Parts	1 Load JPC	-
65	23/03/20 18:07	Dismantled Parts	1 Load JPC	
66	23/03/20 18:07	Dismantled Parts	10 Load JPC	-
67	23/03/20 18:07	Dismantled Parts	1 Load JPC	-
68	23/03/20 18:07	Dismantled Parts	1 Load JPC	
69	23/03/20 18:07	Dismantled Parts	1 Load JPC	-
70	23/03/20 18:07	Dismantled Parts	1 Load JPC	-
71	23/03/20 18:07	Dismantled Parts	1 Load JPC	P
72	23/03/20 18:07	Dismantled Parts		-
73	23/03/20 18:07	Dismantled Parts	1 Load JPC	1 6
74	23/03/20 18:07	Dismantled Parts		-
75	23/03/20 18:07	Dismantled Parts	1 Load JPC	
76	23/03/20 18:07	Dismantled Parts	1 Load JPC	
77	23/03/20 18:07	Dismantled Parts		
78	23/03/20 18:07	Dismantled Parts	1 Load JPC	
79	23/03/20 18:07	Dismantled Parts		
80	23/03/20 18:07	Dismantled Parts	1 Load JP	
81	23/03/20 18:07	Dismantled Parts	1 Load JP	-
82	23/03/20 18:07	Dismantled Parts	1 Load JPI	
83	23/03/20 18:07	Dismantled Parts	1 Load JP	
84	23/03/20 18:07	Dismantled Parts	1 Load JP	
85	23/03/20 18:07	Dismantled Parts	1 Load JP	
86	23/03/20 18:07	Dismantled Parts	1 Load JP	-
87	23/03/20 18:07	Dismantled Parts	1 Load JP	G E

Pho	Photos/Images		3 per page	~	☑ Deint
10	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thum Load	JPG	Print ✓
8	23/03/20 18:07	Dismantled Parts	O Load		₹.
9	23/03/20 18:07	Dismantled Parts	O Load		V
0	23/03/20 18:07	Dismantled Parts		JPG	∀
1	23/03/20 18:07	Dismantled Parts		JPG	V
2	23/03/20 18:07	Dismantled Parts		JPG	₹
3	23/03/20 18:07	Dismantled Parts		1 JPG	V
4	23/03/20 18:07	Dismantled Parts		0.000	V
5	23/03/20 18:07	Dismantled Parts		JPG	-
6	23/03/20 18:07	Dismantled Parts		d JPG	Z.
7	23/03/20 18:07	Dismantled Parts		d JPG	▼
98	23/03/20 18:07	Dismantled Parts		d JPG	V
99	23/03/20 18:07	Dismantled Parts		d JPG	₩.
100	23/03/20 18:07	Dismantled Parts		d JPG	<u>A</u>
101	23/03/20 18:07	Dismantled Parts		d JPG	V
102	23/03/20 18:07	Dismantled Parts		d JPG	V
103	23/03/20 18:07	Dismantled Parts		d JPG	V
104	23/03/20 18:07	Dismantled Parts		d JPG	V
105		Dismantled Parts		d JPG	V
106	5 23/03/20 18:07	Dismantled Parts		d JPG	V
107	23/03/20 18:07	Dismantled Parts		d JPG	Y
108	3 23/03/20 18:07	Dismantled Parts		d JPG	4
109	9 23/03/20 18:07	Dismantled Parts		d JPG	4
110	0 23/03/20 18:07	Dismantled Parts		d JPG	V
11	1 23/03/20 18:07	Dismantled Parts		d JPG	-
11	2 23/03/20 18:07	Dismantled Parts		d JPG	
11	3 23/03/20 18:07	Dismantled Parts		id JPG	
11	4 23/03/20 18:07	Dismantled Parts		ad JPG	-
11	5 23/03/20 18:07	Dismantled Parts		ad JPG	-
11	6 23/03/20 18:07	Dismantled Parts		ad JPG	-
11		Dismantled Parts		ed JPG	-
11	8 23/03/20 18:07	Dismantled Parts		ad JPG	_
	9 23/03/20 18:07	Dismantled Parts		ad JPG	-
12		Dismantled Parts	1 Los	ad JPG	
12		Dismantled Parts		ad JPG	-
12		Dismantled Parts		ad JPG	-
12	3 23/03/20 18:07	Dismantled Parts		ad JPG	-
-	4 23/03/20 18:07	Dismantled Parts		ad JPG	-
12		Dismantled Parts		ad JPG	
12	6 23/03/20 18:07	Dismantled Parts		ad JPG	-
12	7 23/03/20 18:07	Dismantled Parts		ad JPG	-
12		Dismantled Parts	1 Lo	ad JPG	
12		Dismantled Parts		ad JPG	_
13		Dismantled Parts		ad JPG	
-	31 23/03/20 18:07	Dismantled Parts		ad JPG	
	32 23/03/20 18:07	Dismantled Parts		ad JPG	-
	33 23/03/20 18:07	Dismantled Parts		ad JPG	
	34 23/03/20 18:07	Dismantled Parts	1 Lo	ad JPG	3 6
	35 23/03/20 18:07	Dismantled Parts	6 Lo	ad JPC	
	36 23/03/20 18:07	Dismantled Parts	⑥ Lo	ad JPC	
	37 23/03/20 18:07	Dismantled Parts	1 Lo	ad JPG	3 6

n	hotos/Images		3 per p	age 🔻	✓
				Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load JPG	V
138	23/03/20 18:07	Dismantled Parts	- contract	1 4 300	V
139	23/03/20 18:07	Dismantled Parts	0	Load JPG	
140	23/03/20 18:07	Dismantled Parts	0	Load JPG	✓
141	23/03/20 18:07	Dismantled Parts	0	Load JPG	✓
100		Control Contro	0	Load JPG	V
142	23/03/20 18:08	After Repair Photo	0	Load JPG	V
143	23/03/20 18:08	After Repair Photo			
144	23/03/20 18:08	After Repair Photo	0	Load JPG	V
145		After Repair Photo	0	Load JPG	✓
145			0	Load JPG	V
146	23/03/20 18:08	After Repair Photo		1 4 300	V
147	23/03/20 18:08	After Repair Photo	0	Load JPG	A
	200 2 00 4 00 4 00 10 10 10 10 10 10 10 10 10 10 10 10		1 per	page 🔻	V
Doc	umentation			Thumbnail	-
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load PDF	
1	30/03/20 09:21	Supplementary		2000	-

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19022876/QSD3E2

Date:

30/03/2020

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMPCSN1619871903

Claimant Vehicle

No:

SJW5115E

Insured Vehicle No:

SJP9938H

Date of Loss:

25/12/2019

Nature of Claim:

TP

Claim No:

SNM19D206130/SJP9938H/BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJW5115E

Make & Model:

MERCEDES-BENZ CLA200, 1.6 SB ORANGE-ART-

Engine No:

27091030379538

141744 km

ED (R18 BI) (A) 05/06/2014 (Man. Year: 2014)

Chassis No: Odometer:

WDD1173432N084908

Reg. Date: Colour:

Red

1595 cc Engine Capacity:

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side:

Pirelli 5 mm

Rear Left Side:

Pirelli 5 mm

Front Right Side:

Pirelli 5 mm

Rear Right Side:

Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF OLAIMS	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS	43.148.20	19,314.68	23,833.52	55.24
Parts	0.00	0.00	0.00	
Miscellaneous Items	6.900.00	3,990.00	2,910.00	42.17
Labour Deintwerk Labour	0.00	0.00	0.00	
Paintwork Labour Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,048.20	23,304.68	26,743.52	53.44
Approved Total (Overridden) (S\$)	10 CO CO * 10 CO	18,650.00		
Nett Amount (S\$)	50,048.20	18,650.00	31,398.20	62.74

INSPECTION

Date of Assignment:

02/01/2020

Date Inspected:

31/12/2019 Inspected At:

K & T Cars (Ubi)

53 Ubi Ave 1 #01-23 Paya Ubi Industrial

Park

Singapore 408934

Estimated Period of Repair:

10.0 days

Adjuster Report Page 2 of 5

Adjuster: OI SUN PIN Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 30 Mar 2020) Part Source: MRM-SG

MERCEDES-BENZ CLA200 1.6 SB ORANGE-ART-ED (R18 BI) (A) (Catalogue:Merimen 143 Parts:

Singapore 1.0)

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SJW5115E)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

	commend		Condition	Repairer's	Amount
No.	Qty Part No.		Repair	717.60 FL	*-FL
	1	*RH DOOR PILLAR	Crumpled	519.20 FL	*519.20 FL
2	1	*RH PILLAR UPPER TRIM	Serviceable	519.20 FL	*- FL
3	1	*RH PILLAR BOTTOM TRIM	Dented	2,002.15 FL	*1,850.00 FL
1	1	*FRONT RH DOOR PANEL	Serviceable	257.60 FL	*-FL
5	2	*FRONT RH DOOR HINGE	Cut	408.00 FL	*280.00 FL
3	1	*FRONT RH DOOR WEATHERSTRIP	Jammed	384.00 FL	*384.00 FL
7	1	*FRONT RH DOOR LOCK ASSY	Serviceable	184.80 FL	*-FL
В	1	*FRONT RH DOOR HANDLE	Serviceable	85.20 FL	*- FL
9	1	*FRONT RH DOOR CYCLINDER GUIDE	Serviceable	211.20 FL	*- FL
10	1	*FRONT RH DOOR BEARING BRACKET	Scratched	1,454.75 FL	*1,050.00 FL
11	1	*FRONT RH DOOR INNER TRIM	Serviceable	819.60 FL	*- FL
12	1	*FRONT RH DOOR REGULATOR MOTRO		229.20 FL	*229.20 FL
13	1	*FRONT RH DOOR OUTER MOULDING	Scratched	247.20 FL	*- FL
14	1	*FRONT RH DOOR GLASS	Serviceable	2,280.00 FL	*2,280.00 FL
15	1	*REAR RH DOOR PANEL	Crumpled	2,280.00 FL 280.80 FL	*200.00 FL
16	2	*REAR RH DOOR HINGE	Crumpled		*280.00 FL
17	1	*REAR RH DOOR WEATHERSTRIP	Crumpled	408.00 FL	*380.00 FL
18	1	*REAR RH DOOR LOCK ASSY	Jammed	422.40 FL	*- FL
19	1	*REAR RH DOOR BEARING	Serviceable	211.20 FL	*184.80 FL
20	1	*REAR RH DOOR HANDLE	Scratched	184.80 FL	
21	1	*REAR RH DOOR INNER TRIM	Crumpled	1,518.00 FL	*1,050.00 FL
22	1	*REAR RH DOOR REGULATOR	Bent	800.40 FL	*500.00 FL
23	i	*REAR RH DOOR OUTER MOULDING	Scratched	237.60 FL	*237.60 FL
24	1	*REAR RH FENDER	Dented	2,030.90 FL	*1,672.00 FL
25	1	*REAR RH FENDER INNER SHIELD	Crumpled	183.60 FL	*183.60 FL
26	1	*REAR RH FENDER INNER TRIM	Cut	274.80 FL	*274.80 FL
27	1	*REAR RH WHEEL CARRIER	Serviceable	1,696.25 FL	*- Fl
28	1	*REAR RH WHEEL BEARING	Bent	513.60 FL	*350.00 FI
	1	*REAR RH SHOCK ABSORBER	Bent	499.20 FL	*499.20 FI
29		*REAR RH CAMBER ARM	Bent	181.20 FL	*181.20 F
30	1	*REAR RH RADIS ROD	Serviceable	201.60 FL	*- F
31	1	*REAR RH TIE ROD	Serviceable	138.00 FL	*-F
32	1	*SIDE CRASH SENSOR	Necessary	246.00 FL	*246.00 F
33	1	*FRONT RH SEAT ASSY	Serviceable	2,365.55 FL	*-F
34	1	*RH SIDE CURTAIN AIR BAG	Broken	1,144.80 FL	*1,144.80 F
35		*AIR BAG CONTROL UNIT	Necessary	1,189.10 FL	*1,189.10 F
36			Crumpled	1,546.75 FL	*1,546.75 F
37		*ROOF LINING	Crumpled	1,932.00 FL	*1,550.00 F
38	1	*REAR BUMPER	Oranipire -	10.000	

Report was unsubmitted during this print-out.

lo.	Qty	Dort No	Destinutore	Condition		
9	774.4	Part No.	Particulars	Broken	73.60 FL	*73.60 FL
	2		*REAR BUMPER RETAINER	Serviceable	351.90 FL	*- FL
10	1		*PDC SENSOR	Repair	1,811.25 FL	*-FL
11	1		*REAR EXHAUST ASSY	Serviceable	43.20 FL	*-FL
12	2		*EXHAUST MOUNTING	Crumpled	1,200.30 FL	*280.00 FL
43	1		*RH SILL GARNISH	Necessary	50.00 FS	*30.00 FS
44	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
45	1		*SET FRONT RH DOOR INNER TRIM CLIP	Necessary	30.00 FS	*30.00 FS
46	1		*SET REAR RH DOOR INNER TRIM CLIP	Cut	1,500.00 FS	*700.00 FS
47	1		*RIM		150.00 FS	*60.00 FS
48	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
49	1		*WINDSCREEN SEALANT	Necessary	1,501.60 FL	*300.00 FL
50	1		*LEVER SENSOR	Shorted	2,620.60 FL	*-FL
51	1		*REAR RH CHASSIS MEMBER	Repair	3,365.50 FL	*- FL
52	1		*REAR RH SEAT	Repair	189.00 FL	*189.00 FL
53	1		*REAR RH SEAT PULLING COVER	Cracked	1,100.00 FL	*755.00 FL
54	1		*TAILLAMP RH	Scratched	121.00 FL	*- FL
55	1		*TAILLAMP SIDE COVER RH	Serviceable	89.60 FL	*- Fl
56	1		*BOOTLID HINGE COVER RH	Serviceable	2,835.60 FL	*- FL
57	1		*FRONT AIRBAG CONTROL UNIT	Serviceable	1,201.02 FL	*- FL
58	1		*RH CENTRE PILLAR GLASS	Serviceable	131.80 FL	*131.80 FL
59	1		*RH CENTRE PILLAR GLASS MOULDING	Crumpled	158.00 FL	*158.00 FI
60	1		*RH CENTRE PILLAR GLASS GARNISH	Scratched	450.00 FS	*270.00 F
61	1		*TYRE	Cut	450.0013	270.001
F=F	ranchis	se part. S=Sp	cNett. L=ListItemDisc.	Sub Total (S\$)	47,680.22	21,329.65
						2,014.97
			- List Item Discount on L Items	5 10.00/10.00% (34)	4,002.02	###.E00000
				Total Parts (S\$)	43,148.20	19,314.68

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CHECK WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE, REFIT LINING, TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR REVER SENSOR	New	120.00	30.00
4	REMOVE AND NEW REAR EXHAUST ASSY	New	120.00	80.00
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	400.00	0.00
6	REMOVE, RENEW AIRBAG ASSY AND DOWNLOAD ECU	New	500.00	200.00
7	REMOVE AND RENEW ROOF LINING	New	300.00	50.00
8	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	New	150.00	60.00
9	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	New	200.00	100.00
10	TRANSFER PARTS, ATTACHMENT FROM OLD FRONT DOOR TO	New	200.00	60.00
11	TRANSFER PARTS, ATTACHMENT FROM REAR OLD DOOR TO NEW	New	200.00	60.00
12	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	1,400.00
13	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
14	MOUNT VEHICLE ON BENCH FOR ALIGNMENT	New	500.00	200.00
15	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	1,600.00
	Gross Labor	Gross Labour Cost (S\$)		3,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >