

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24341

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/1524/2019/NS  
Date : 27-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tan Qiuxuan  
Address : 30 Jalan Chengkek  
Singapore 369253  
Telephone : (HP) +65 98450566  
Type of Claim : Own Damage Claims  
Policy No. : 1700070038-02  
Vehicle No : **SLT 6893 C**  
Model Code : Audi A3 SB 1.0 TF  
Model / Year : 7/11/2017  
Engine No : CHZ 571037  
Chassis No : WAUZZZ8V8JA040904  
Mileage : 45893  
Date In : 27-Dec-19  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 27-Dec-19  
Place of Accident : AYE Towards Tuas

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SLT 6893 C

| S/n                         | Nature of Jobs                                                                                                                                                                                              | Estimated Charges      | Surveyor's Recommendations                              |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|---------------------------------------------------------|
| 1                           | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.                                                                              | S/N \$ 360.00          | ✓                                                       |
| 2                           | To remove and renew aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.                                  | S/N \$ 1,200.00        | ? ✓                                                     |
| 3                           | To dismantle and renew front bumper, rhs front fender, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. | \$ <del>5,600.00</del> | 1250 (without Lock Carrier)<br>2500 (with Lock Carrier) |
| 4                           | To respray front bumper, rhs front fender, hinges and bonnet.                                                                                                                                               | \$ <del>3,500.00</del> | 1650                                                    |
| 5                           | To carry out diagnostic check.                                                                                                                                                                              | S/N \$ 192.00          | ✓                                                       |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                             | <b>: \$ 10,852.00</b>  |                                                         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLT 6893 C

| S/N                   | Parts Description                                      | Damaged Parts & Prices |                        |
|-----------------------|--------------------------------------------------------|------------------------|------------------------|
|                       |                                                        | S/Nett                 | Remarks                |
| 1                     | FRONT BUMPER <i>Distorted.</i>                         | \$ 1,698.00 ✓          | 1352.40                |
| 2                     | FRONT BUMPER FIXING PARTS <i>new</i>                   | \$ 170.00 +            |                        |
| 3                     | FRONT BUMPER GUIDE SECTION - RH <i>Scuffed.</i>        | \$ 35.00 ? ✓           | 27.52                  |
| 4                     | FRONT BUMPER GRILLE - CENTRE <i>new</i>                | \$ 146.00 +            |                        |
| 5                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i> | \$ 270.00 +            |                        |
| 6                     | FRONT BUMPER CLOSING ELEMENT - RH <i>Not nec</i>       | \$ 270.00 ? X          |                        |
| 7                     | RADIATOR GRILLE <i>could</i>                           | \$ 1,301.00 ✓          | 1040.80                |
| 8                     | RADIATOR GRILLE CLOSING ELEMENT <i>Scuffed.</i>        | \$ 174.00 ? ✓          | 138.80                 |
| 9                     | FRONT BUMPER AIR GUIDE GRILLE - RH <i>could</i>        | \$ 170.00 ✓            | 136.40                 |
| 10                    | FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Best</i>       | \$ 660.00 ? ✓          | 527.60                 |
| 11                    | FRONT BUMPER FOAM FILLER PIECE <i>could</i>            | \$ 172.00 ✓            | 137.60                 |
| 12                    | FOAM FILLER PIECE COVER <i>Not nec</i>                 | \$ 111.00 ? X          |                        |
| 13                    | AIRCON STICKER <i>3 new</i>                            | NEC \$ 7.00 ✓          | 5.12                   |
| 14                    | CAUTION SIGN STICKER                                   | NEC \$ 13.00 ✓         | 9.76                   |
| 15                    | SIGNAL HORN - RH LOW TONE <i>Not nec</i>               | \$ 182.00 ? X          |                        |
| 16                    | FRONT FENDER - RH <i>Repair</i>                        | \$ 778.00 +            |                        |
| 17                    | FRONT FENDER ATTACHMENT PARTS <i>new</i>               | \$ 65.00 +             |                        |
| 18                    | FRONT FENDER FRONT BRACKET - RH <i>2</i>               | \$ 25.00 +             |                        |
| 19                    | FRONT FENDER REAR BRACKET - RH <i>new</i>              | \$ 43.00 +             |                        |
| 20                    | FRONT FENDER BRACE                                     | \$ 88.00 +             |                        |
| SUB TOTAL SPARE PARTS |                                                        | : \$                   | <u><u>6,378.00</u></u> |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLT 6893 C

| S/N                   | Parts Description                                | Damaged Parts & Prices |               |
|-----------------------|--------------------------------------------------|------------------------|---------------|
|                       |                                                  | S/Nett                 | Remarks       |
| 21                    | FRONT FENDER CLOSING ELEMENT - RH                | \$ 56.00               | +             |
| 22                    | FRONT WHEEL HOUSING LINER - RH                   | \$ 158.00              | +             |
| 23                    | WHEEL HOUSING LINER ATTACHMENT PARTS             | \$ 52.00               | +             |
| 24                    | BONNET <i>Dented</i>                             | \$ 2,501.00            | 2000.80       |
| 25                    | BONNET ATTACHMENT PARTS <i>Not nec.</i>          | \$ 149.00              | ? X           |
| 26                    | BONNET LID HINGE - LH / RH <i>not nec</i>        | 2 \$ 112.00            | +             |
| 27                    | BONNET GAS FILLED STRUT <i>not nec</i>           | \$ 109.00              | +             |
| 28                    | BONNET EDGE PROTECTION - FRONT <i>not nec</i>    | \$ 25.00               | 1992          |
| 29                    | BONNET CATCH HOOK                                | \$ 81.00               | +             |
| 30                    | BONNET STRIKER - LH / RH                         | 2 \$ 200.00            | +             |
| 31                    | BONNET CATCH HOOK                                | \$ 58.00               | +             |
| 32                    | BONNET LID LOCK                                  | 2 \$ 367.00            | +             |
| 33                    | BONNET BOWDEN CABLE - CENTRE                     | \$ 53.00               | +             |
| 34                    | BONNET LID LOCK CABLE                            | \$ 67.00               | +             |
| 35                    | BONNET SOUND ABSORBER <i>not nec</i>             | \$ 201.00              | +             |
| 36                    | PLENUM CHAMBER COVER <i>not nec</i>              | \$ 164.00              | +             |
| 37                    | LED HEADLIGHT - LH / RH <i>not nec</i>           | 2 \$ 10,058.00         | 5029. 4023.70 |
| 38                    | MAINB LIGHT POWER MODULE <i>not nec</i>          | \$ 693.00              | ? X           |
| 39                    | LIGHT CONTROL SYSTEM CONTROL UNIT <i>not nec</i> | \$ 508.00              | ? X           |
| 40                    | LED WITH HEAT SINK - RH <i>not nec</i>           | \$ 666.00              | ? X           |
| SUB TOTAL SPARE PARTS |                                                  | : \$ 16,278.00         |               |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLT 6893 C

| S/N                   | Parts Description                               | Damaged Parts & Prices |                    |
|-----------------------|-------------------------------------------------|------------------------|--------------------|
|                       |                                                 | S/Nett                 | Remarks            |
| 41                    | HEADLIGHT HOSE - RH <i>new</i>                  | \$ 36.00 <sup>+</sup>  |                    |
| 42                    | LIFT CYLINDER <i>changed</i>                    | \$ 128.00              | ? ✓ 107.20         |
| 43                    | LIFT CYLINDER HOSE <i>new</i>                   | \$ 61.00               | +                  |
| 44                    | LOCK CARRIER <i>bracket</i>                     | \$ 663.00              | ? ✓ 530.40         |
| 45                    | AIRCON CONDENSER <i>new</i>                     | \$ 503.00              | +                  |
| 46                    | AIRCON CONDENSER BRACKET <i>new</i>             | \$ 25.00               | +                  |
| 47                    | DUAL CLIP <i>new</i>                            | \$ 28.00               | +                  |
| 48                    | REFRIGERANT LINE                                | \$ 601.00              | +                  |
| 49                    | REFRIGERANT LINE                                | \$ 461.00              | +                  |
| 50                    | REFRIGERANT LINE                                | \$ 461.00              | +                  |
| 51                    | EXTERNAL TEMPERATURE SENSOR                     | \$ 54.00               | +                  |
| 52                    | EXTERNAL TEMPERATURE SENSOR BRACKET             | \$ 17.00               | +                  |
| 53                    | READY MIX COOLANT <i>new</i>                    | 4 \$ 84.00             | ? ✓ 67.20          |
| 54                    | RADIATOR <i>new</i>                             | \$ 878.00              | +                  |
| 55                    | ADDITIONAL RADIATOR <i>new</i>                  | \$ 837.00              | +                  |
| 56                    | RADIATOR BRACKET <i>new</i>                     | 2 \$ 77.00             | +                  |
| 57                    | RADIATOR BUSH - LOWER <i>new</i>                | 2 \$ 18.00             | +                  |
| 58                    | RADIATOR AIR GUIDE - RH <i>del.</i>             | \$ 22.00               | ? ✓ 17.12          |
| 59                    | RADIATOR AIR GUIDE - UPPER CENTRE <i>34 new</i> | \$ 11.00               | ? X                |
| 60                    | AIR INTAKE DUCT AIR INLET <i>new</i>            | \$ 53.00               | ? X                |
| SUB TOTAL SPARE PARTS |                                                 | :                      | \$ <u>5,018.00</u> |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLT 6893 C

| S/N                         | Parts Description                                  | Damaged Parts & Prices |            |
|-----------------------------|----------------------------------------------------|------------------------|------------|
|                             |                                                    | S/Nett                 | Remarks    |
| 61                          | AIR INTAKE AIR DUCT AIR GUIDE <i>Not rec</i>       | \$ 62.00               | <i>X</i>   |
| 62                          | AIR INTAKE DUCT SEAL <i>Not rec</i>                | \$ 13.00               | <i>? X</i> |
| 63                          | AIR INTAKE DUCT WATER DRAINAGE HOSE <i>Not rec</i> | \$ 31.00               | <i>? X</i> |
| 64                          | AIR INTAKE DUCT AIR FILTER <i>Not rec</i>          | \$ 252.00              | <i>? X</i> |
| 65                          | AIR INTAKE DUCT INTAKE MANIFOLD <i>X4</i>          | \$ 129.00              | <i>X</i>   |
| 66                          | FRONT NO PLATE <i>rec</i>                          | S/N \$ 40.00           | <i>/</i>   |
| 67                          | SUNDRIES <i>Not rec</i>                            | \$ 400.00              | <i>? X</i> |
| <b>TOTAL SPARE PARTS</b>    |                                                    | <b>: \$ 28,601.00</b>  |            |
| <b>TOTAL LABOUR CHARGES</b> |                                                    | <b>: \$ 10,852.00</b>  |            |
| <b>GRAND TOTAL</b>          |                                                    | <b>: \$ 39,453.00</b>  |            |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name  
Surveyed Date  
Authorised Date  
Excess Cost  
Liability  
Remarks

: Adrian Lj  
: 30/12/19

: Not Authorised, 06 Days (without lock carrier)  
09 Days (with lock carrier)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant