

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 11 Mar 2020

Preliminary Advice

Insured Vehicle No : GBD9687P
TP Vehicle No : SLA591M
Make : HYUNDAI ELANTRA
Date of Inspection : 31/12/2019
Inspection At : CAS GARAGE PTE LTD (HQ)
NO.1, KAKI BUKIT AVE 6, #02-22 AUTOBAY
SINGAPORE 417883

Accident Date : 31/08/2019
Assignment Date : 30/12/2019
Est. Duration of Repair : 4.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,312.32
Revised Amount	:S\$	3,508.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,508.24
Lump Sum Repair	:S\$	2,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.