Frem (Person		of	MENT (Office) , MSIG	Date/Time: 30/2/190 4:020
Estimated Co	Activities to the second secon		Bill to:	
To Inspect Ve	chicle No:		1000	ured: SLP 64 244
at Workshop		EM solut		Tel: 6455 0226.
of Policy No:	7911475		ive # 03-18/	615760
Sum Insured:	The state of the s	0	Claim No:	P13160
OTHER TRISHLED			37	
Make of Veh: (Client's Record			Excess:	D.O.A. 22/12/2019
Make of Veh: (Client's Record CA / REV	n / REP. / REV 241	HRS Cup	(POLE	D.O.A. 22/12/2019 H.O.D. Endorsement: Vehicle_IN/OUT
Make of Veh: (Client's Record CA / REV	n REP. REV 24 I 4 SOpm @30 :	Person Contacted	(POLE	H.O.D. Fndorsement:
Make of Veh: (Client's Record CA / REV Date/Time:	n / REP. / REV 241	Person Contacted 1 Shrviol V	(POLE	H.O.D. Fndorsement:
Make of Veh: (Client's Record CA / REV Date/Time: Date/Time	Action/Instruction SLP 6+240 SLU 83669	In Person Contacted In Person Contacted Yohrwork X	(POLE	H.O.D. Endorsement: Vehicle_IN / OUT

 \mathbf{x}

MSG

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Chhia Nyuk Pui

Date:

07 Jan 2020

Preliminary Advice

Insured Vehicle No : SLP6424U

: SLQ8766P

Accident Date

: 22/12/2019

TP Vehicle No Make

: VOLKSWAGEN SPORTSVAN

Assignment Date

: 31/12/2019

Date of Inspection : 06/01/2020

Est. Duration of Repair

: 4.00

Inspection At

: E M SOLUTION PTE LTD (HQ) 160 SIN MING DRIVE,, #03-18, SIN MING AUTOCITY

SINGAPORE 575722

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,977.10
Revised Amount	:S\$	4,460.23
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,460.23
Lumn Sum Renair	:S\$	3,550.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

1	1	The vehicle is	economical/not	economical	for	repair.
		The vehicle is	s economicalmo	COCHOHINGE.		

(X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From:

Crystal Lee <crystal_lee@sg.msig-asia.com>

Sent:

Monday, 30 December 2019 4:02 PM Admin-D (LKKAuto); assignments

To: Cc:

Ong Zi Hui

Subject:

Survey Request - Manual Assigned

OUR REF.: E21-112510.19 (SLQ8766P @ 22.12.2019) // MSIG REF NO : SLP6424U (GRAB)

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg







A Member of MS&AD INSURANCE GROUP

The same of the sa

From: Winnie Chua

Sent: Monday, 30 December, 2019 2:29 PM
To: Sally Chong <sallychong@visionlawllc.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi

Hui <zihui ong@sg.msig-asia.com>

Subject: RE: OUR REF.: E21-112510.19 (SLQ8766P @ 22.12.2019) // MSIG REF NO: SLP6424U

(GRAB)

Hi.

Thank you for your selection.

We will proceed to appoint/assign KENNETH KONG- LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)
Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

6 6 6

A Member of MS&AD INSURANCE GROUP

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Monday, 30 December 2019 2:25 PM

To: Winnie Chua chua@sg.msig-asia.com; Claims <claims@sg.msig-asia.com</pre>; Jasmine Lok

Kheng Kwei <jasmine_lok@sg.msig-asia.com>
Cc: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: OUR REF.: E21-112510.19 (SLQ8766P @ 22.12.2019) // MSIG REF NO : SLP6424U (GRAB)

Importance: High

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

URGENT

Dear Winnie,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: WU FAN

ACCIDENT INVOLVING SLQ 8766P & SLP 6424U ON 22 DEC 2019 ALONG CAIRNHILL CIRCLE TOWARDS ORCHARD AT ABOUT 11:30 HRS

We refer to your email of even date below and your list of surveyors therein.

Our client now confirms the appointment of <u>KENNETH KONG- LKK Auto Consultants Pte Ltd</u> as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,

Singapore 575722

Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX: 6535-6802

From: Winnie Chua [mailto:pingping_chua@sg.msig-asia.com]

Sent: Monday, 30 December, 2019 10:56 AM

To: judysoh@visionlawllc.com

Cc: Helene Phua

Subject: FW: OUR REF.: E21-MISC.19 (SLQ8766P @ 22.12.2019) MSIG REF NO: SLP6424U (GRAB)

Importance: High

Hi,

We refer to your email/faxed dated 27/12/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- Appraisal VP Pte Ltd
- AutoProbe Consultants
- MSIG In-House Surveyors

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong	
2) Kenneth Kong	7) Siew Meng Hui	
3) Marcus Chua	8) Daniel Chan	
4) Ng You Han	9) Victor Png	
5) Gary Soon	10) Samuel Phun	

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) *Fast lane settlement is not applicable for cases that liability is in dispute*
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

^{*}This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor*

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey) Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MS&AD INSURANCE GROUP

From: Judy Soh [mailto:judysoh@visionlawllc.com]

Sent: Friday, 27 December 2019 5:41 PM

To: Pauline Tham
pauline tham@sg.msig-asia.com>; Motor Survey <motorsurvey@sg.msig-asia.com>;
</code>

Elaine Ngu <elaine ngu@sg.msig-asia.com>; Claims <claims@sg.msig-asia.com>

Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; sallychong@visionlawllc.com;

derekkeh@singnet.com.sg; Tanvin13@vahoo.com.sg

Subject: OUR REF.: E21-MISC.19 (SLQ 8766P @ 22.12.2019) MSIG REF NO : SLP 6424U

Importance: High

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: WU FAN

ACCIDENT INVOLVING SLQ 8766P & SLP 6424U ON 22 DEC 2019 ALONG CAIRNHILL CIRCLE

TOWARDS ORCHARD AT ABOUT 11:30 HRS

We are instructed by WU FAN to notify you of a road traffic accident ON 22 DEC 2019 ALONG CAIRNHILL CIRCLE TOWARDS ORCHARD AT ABOUT 11:30 HRS involving our client's vehicle registration number SLQ 8766P and vehicle registration number SLP 6424U driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Judy Soh

VISION LAW LLC 133 NEW BRIDGE ROAD. #18-01/02, CHINATOWN POINT,

SINGAPORE 059413 TEL.: 6534-2811 (ext 147)

FAX: 6535-6802

C.c.:

VEHICLE OWNER OF SLP 6424U

GRAB RENTALS PTE LTD

6 Shenton Way #38-01 OUE Downtown Singapore 068809

VISION LAW LLC

Advocates & Solicitors (Incorporated with limited liability) Unique Entity No. 200721148H

Address: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	o: NDIC
Owner ID Type:	Singapore NRIC
Owner ID:	695D
/ehicle Details	01 007//P
/ehicle No.:	SLQ8766P
/ehicle to be Exported:	No
ntended Deregistration Date:	07 Jan 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SPORTSVAN 1.4 HIGHLINE AM14HZ
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CZC122861
Chassis No.:	WVWZZZAUZGW557591
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$27,558.00
Original Registration Date:	28 Jun 2017
First Registration Date:	28 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$25,582.00
OPC Cash Rebate Details	No
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	•
OPC Cash Rebate Amount: Intended PARF Rebate Details	3 - 0
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2027
PARF Rebate Amount:	\$19,186.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp
COE Period(Years):	10
QP Paid:	\$25,801.00
COE Rebate Amount:	\$19,279.00
Total Rebate Amount:	\$38,465.00

The information contained herein is correct as at 07 Jan 2020

E M SOLUTION PTE LTD.

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226 Fax: 64584500

Registration No: 201016308K

Wu Fan

Not Nothaire 02.01.2020

Not Nothaire 02.01.2020

CIPUT & 3550h

REKNY Afre Paint

N SPORTVAN - SLQ 8766 P

REPAIR ESTIMATE FOR VOLKSWAGEN SPORTVAN - SLQ 8766 P

1421711	0	0
1 pc	front bumper 11 52 -82	Bre/ Ru 1,380.00
1 pc	front bumper fog lamp	∕∽ 280.00 X
1 pc	front bumper LH side retainer	011 58.00 W
4 pcs	front bumper parking sensors	254.00 1,016.00 X
1 pc	LH headlamp assy 1955-35	2,380.00
1 pc	LH front fender 545-20	₹ 760.00 <u></u>
1 pc	LH front fender inner shield	<u>√</u> 195.00 X
		6,069.00
	Less 1	
		5,462.10
1 pc	front number plate	12 70.00 SN 4552
1 set	front bumper clips	Me 45.00 SN -
1 pc	LH front sport rim	550.00 SN X
1)	Check electrical wiring.	60.00 201
2)	Repair damages and renew above parts.	780.00 4001
3)	Renew front parking sensors	80.00 501
4)	Spray paint on affected portions.	750.00 45d
5)	Dismantle & reseal front weekend number p	late 120.00 %
6)	Rust proofing on affected portions.	60.00 301
5553. #	5 CONTRACTOR - CON	\$ 7,977.10
		the state of the s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from loss range Consequents

Acknowledged by Repairer

Signature

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19022887/KQD3N2

Date:

13/01/2020

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29114756

Claimant Vehicle

SLQ8766P

Insured Vehicle No:

SLP6424U

No:

Date of Loss:

22/12/2019

Nature of Claim:

TP

615760 Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLQ8766P

Make & Model:

VOLKSWAGEN SPORTSVAN, 1.4 (A)

Engine No:

CZC122861

14668 km

Reg. Date:

28/06/2017 (Man. Year: 2015) Metallic Black

Chassis No: Odometer:

WVWZZZAUZGW557591

Colour: Engine Capacity:

1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side:

Bridgestone 6 mm

Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,127.10	3,430.23	2,696.87	44.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,030.00	820.00	44.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,977.10	4,460.23	3,516.87	44.09
Approved Total (Overridden) (S\$)		3,550.00		
(\$\$)	7,977.10	3,550.00	4,427.10	55.50
+ GST 7.00/7.00% (S\$)	558.40	248.50	309.90	55.50
Nett Amount (S\$)	8,535.50	3,798.50	4,737.00	55.50
10 10 10 10 10 10 10 10 10 10 10 10 10 1		- EUO/WOOD		

INSPECTION

Date of Assignment:

31/12/2019

E M Solution Pte Ltd (HQ)

Date Inspected:

06/01/2020 Inspected At:

160 Sin Ming Drive,, #03-18, Sin Ming Autocity

Singapore 575722

Estimated Period of Repair:

4.0 days

KENNETH KONG Adjuster:

Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

(Last Synchronised: 13 Jan 2020)

Part Source: Parts:

VOLKSWAGEN SPORTSVAN 1.4 (A) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ8766P)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended	Parts
-------------	-------

0.7070	Qty Part No.	Particulars	Condition	Repairer's	Amount
_		*FRONT BUMPER	Buckled/Dented	1,380.00 FL	*1,152.82 FL
1		*FRONT BUMPER FOG LAMP	Serviceable	280.00 FL	*-FL
2	1	*FRONT BUMPER LH SIDE RETAINER	Distorted	58.00 FL	*58.00 FL
3	1	*FRONT BUMPER PARKING SENSORS	Serviceable	1,016.00 FL	*- FL
1	4	*LH HEADLAMP ASSY	Cut	2,380.00 FL	*1,955.35 FL
5	1	*LH FRONT FENDER	Bent	760.00 FL	*545.20 FL
5	-	*LH FRONT FENDER INNER SHIELD	Serviceable	195.00 FL	*-FL
8	1	*FRONT NUMBER PLATE	Necessary	70.00 FS	*45.00 FS
ī—	1	*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
9 10	1	*LH FRONT SPORT RIM	Serviceable	550.00 FS	*- FS
	anchise part. S=Spcl	Nett, L=ListItemDisc.		0.704.00	2 004 27
			Sub Total (S\$)	6,734.00	3,801.37
		- List Item Discount on	L Items 10.00/10.00% (S\$)	606.90	371.14
			Total Parts (S\$)	6,127.10	3,430.23

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended Labour			
No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items		2004	20.00
1	CHECK ELECTRICAL WIRING	New	60.00	20.00
2	REPAIR DAMAGES AND RENEW ABOVE PARTS	New	780.00	400.00
3	RENEW FRONT PARKING SENSORS	New	80.00	50.00
4	SPRAY PAINT ON AFFECTED PORTIONS	New	750.00	450.00
5	DISMANTLE & RESEAL FRONT WEEKEND NUMBER PLA	TE New	120.00	80.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	60.00	30.00
		Gross Labour Cost (S\$)	1,850.00	1,030.00
_	Report was unsubmitte	ed during this print-out.		

< END OF ESTIMATES >