

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER S.048623

Supplementary Estimate : ES311219

Attention : Motor Claim Department
Contact : 64616555 Fax No. : 62213302

Date : 31/12/2019
Vehicle Num. : SLZ 1725 G
Make/Model : HONDA FIT
Chassis/Eng# : GK31309310
Accident Date : 24/12/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	REAR TAILGATE <i>/ Buc</i>	803.2	1,150.00
2.	1 PC	REAR WINDSCREEN SEALANT <i>- 4 pc.</i>	35	120.00
3.	1 PC	REAR WINDSCREEN MOULDING	68.5	125.00
4.	1 PC	REAR TAILGATE EMBLEM <i>- Mc.</i>	42.5	80.00
5.	6PCS	REAR BUMPER CLIPS <i>- Mc.</i>	5.00	30.00
6.	LH	REAR TAIL LAMP <i>- 2 pc.</i>	305	480.00
7.	1 PC	REAR END PANEL <i>- 2 pc.</i> ☒ Buc	320.4	550.00
8.	1 PC	REAR END PANEL TOP GARNISH ☒ NN	x	180.00
9.	LH	SIDE RETAINER <i>- 2 pc.</i>	18	40.00
10.	RH	SIDE RETAINER <i>- 2 pc.</i>	x	40.00
11.	1 PC	TAILGATE LOCK <i>- 2 pc.</i>	x	280.00
12.	1 PC	REAR BUMPER <i>- 2 pc.</i>	545.3	750.00
13.	REPAIR	REAR FENDER (LH) ☒ NN		
14.	1 PC	REAR TAILGATE RUBBER ☒ NN		
List TotalS\$:			2167.9	x 160.00
			20%: 1734.32	3,985.00
SPECIAL NETT ITEMS :				
1.	1 SET	REVERSE SENSOR <i>- 1 pc.</i> ☒ NW	☒	200.00
Special Nett Total S\$:				200.00
LABOUR :				
RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS			NN	☒ 100.00
TO CHECK&TEST LIGHTING FUNCTIONS & REVERSE SENSOR WIRING				☒ 40.00
TO REMOVE & REFIT REAR WINDSCREEN				
LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR &				

CONTINUE / ...

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE #05-01/06

SINGAPORE LAND TOWER S.048623

Attention : Motor Claim Department

Contact : 64616555 Fax No. : 62213302

Supplementary Estimate : ES311219

Date : 31/12/2019

Vehicle Num. : SLZ 1725 G

Make/Model : HONDA FIT

Chassis/Eng# : GK31309310

Accident Date : 24/12/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
	600	RE-ALIGN DAMAGE PARTS	1400	800.00
	600	PUTTY & SPRAY PAINT REAR BOOTLID, REAR BUMPER & OTHER AFFECTED AREAS	1400	1,000.00
		TO REMOVE & REFIT REAR WINDSCREEN TO ASSIST REPAIRS	✓	100.00
	1340	Labour Total S\$:		2,040.00

3274.32

SingDollars : Six Thousand Two Hundred Twenty-Five Only

E. & O.E.

Total S\$: 6,225.00

=====


 for BODYFIX

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: