

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 30.12.19

TO : **AXA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMF5335R**
MODEL : **TOYOTA ESTIMA**
DATE OF ACCIDENT : 28.12.19
TIME OF ACCIDENT : 18:15HRS

Xiao Tony,

ACR50014851

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	CENTRE GRILLE <i>Cracked</i>	1	\$ 435.00	\$ 435.00
2	CENTRE GRILLE (CHROME) <i>Not a</i>	2	\$ 175.00	\$ 350.00
3	CENTRE GRILLE LOGO <i>new</i>	1	\$ 75.00	\$ 75.00
4	FRONT GRILLE TOP RUBBER <i>3 new</i>	1	\$ 57.00	\$ 57.00
5	FRONT FENDER INNER COWLING	2	\$ 270.00	\$ 540.00
6	FRONT BUMPER <i>Deformed</i>	1	\$ 1,750.00	\$ 1,750.00
7	FRONT BUMPER FOGLAMP <i>Not a</i>	2	\$ 295.00	\$ 590.00
8	FRONT BUMPER FOGLAMP HOUSING <i>new</i>	2	\$ 125.00	\$ 250.00
9	FRONT BRACE PANEL <i>new</i>	1	\$ 106.00	\$ 106.00
10	FRONT BUMPER LOWER GRILLE <i>Cracked</i>	1	\$ 150.00	\$ 150.00
11	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 90.00	\$ 180.00
12	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 475.00	\$ 475.00
13	FRONT BUMPER SPONGE <i>Del'd</i>	1	\$ 185.00	\$ 185.00
14	FRONT BUMPER UNDER COVER <i>new</i>	1	\$ 170.00	\$ 170.00
15	HEADLAMP (HID) <i>LH cracked</i>	2	\$ 1,930.00	\$ 3,860.00
16	FRONT SUPPORT PANEL TOP COVER <i>new</i>	1	\$ 250.00	\$ 250.00
17	HORN <i>LH cracked</i>	2	\$ 116.00	\$ 232.00
18	RADIATOR SIDE SUPPORT GARNISH <i>2 new</i>	2	\$ 165.00	\$ 330.00
19	AIRCON CONDENSOR <i>Dented</i>	1	\$ 1,480.00	\$ 1,480.00
20	REAR BUMPER <i>Del'd</i>	1	\$ 1,350.00	\$ 1,350.00
21	REAR BUMPER TOW HOOK COVER <i>2 new</i>	2	\$ 30.00	\$ 60.00
22	REAR TOWING HOOK LH	1	\$ 420.00	\$ 420.00
23	REAR BUMPER SIDE RETAINER (FRONT) <i>2 new</i>	2	\$ 78.10	\$ 156.20
24	REAR BUMPER SIDE RETAINER (REAR) <i>new</i>	2	\$ 80.00	\$ 160.00
25	REAR BUMPER SIDE SPONGE <i>RA cracked</i>	2	\$ 110.00	\$ 220.00
26	REAR FENDER RH <i>Repair</i>	1	\$ 850.00	\$ 850.00
27	REAR FENDER INNER TRIM RH <i>Not new</i>	2	\$ 680.00	\$ 1,360.00

✓

+

✓

+

+

756.

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

347.90

1980

116.

1345

782

110

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SMF5335R
 MODEL : TOYOTA ESTIMA
 DATE OF ACCIDENT : 28.12.19
 TIME OF ACCIDENT : 18:15HRS

28	REAR FENDER COWLING <i>new</i>	1	\$ 95.00	\$ 95.00	+
29	REAR FENDER AIR VENT COVER RH <i>Missing</i>	1	\$ 125.00	\$ 125.00	✓
30	REAR FENDER GLASS C/W MOULDING RH <i>new</i>	1	\$ 910.00	\$ 910.00	+
31	REAR FENDER AIR CON BLOWER C/W MOTOR <i>new</i>	1	\$ 2,865.00	\$ 2,865.00	+
32	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 360.00	\$ 360.00	+

6536.90
 4902.67

TOTAL PRICE \$ 20,396.20
 LESS 25% \$ 5,099.05
SUB TOTAL PRICE \$ 15,297.15

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE (SPECIAL TYPE) <i>could</i>	1	\$ 180.00	\$ 180.00	60
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	CENTRE GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
4	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	COOLANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
6	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
7	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
8	REAR FENDER SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	+
9	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
10	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
11	REAR FENDER GLASS SEALANT RH <i>new</i>	1	\$ 120.00	\$ 120.00	+
12	REAR FENDER GLASS INNER SHIELD RH <i>new</i>	1	\$ 80.00	\$ 80.00	+
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
14	REAR END PANEL LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
15	REVERSE SENSOR (SET) <i>new</i>	1	\$ 220.00	\$ 220.00	+

140

TOTAL \$ 1,390.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	250
3	WIRING CHECK	\$ 180.00	30
4	REFOCUS HEADLAMP BEAM	\$ 60.00	+
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	*60

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMF5335R**
 MODEL : **TOYOTA ESTIMA**
 DATE OF ACCIDENT : 28.12.19
 TIME OF ACCIDENT : 18:15HRS

6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	X
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	400
3	TUFF COAT	\$ 250.00	50
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
7	REMOVE AND REFIX REAR FENDER GLASS	\$ 100.00	X
8	REMOVE AND REFIX REAR FENDER AIR CON BLOWER AND REFILL AIRCON GAS	\$ 180.00	X

TOTAL

\$ 7,280.00

1600

Adrian L

2/2 31/12/19.

07 Days.

TOTAL PARTS COST : \$ 16,687.15
 TOTAL LABOUR COST : \$ 7,280.00
 TOTAL REPAIR COST : \$ 23,967.15

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

total: 6642.67.
 2/2 : 5.31c