

ASS. REC. BY:

REF: CS/AAP19022905/Dtd352

Special Instructions:

Surveyor: Bryen

ASSIGNMENT (Office)

From (Person): Bundonchua

or

Arada AdjustersDate/Time: 26/12/19 3:58 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKM 50G

Insured:

public liability

at Workshop in/s

Complete VMS

Tel:

9029 6572

of

Sin Ming2

Policy No:

19948871BL

Claim No:

G1908895

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

upSurvey @ Manymount

H.O.D. Endorsement:

Date/Time:

2:01pm 27/12/19

Person Contacted:

Randy

Vehicle

IN/OUT

Date/Time	Action/Instruction	Estimate
	SKM 50G - X	✓
	public liability.	
	NO GIA.	
	Submit preli advise vehicle not sent in for repair	

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: P/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKM 50G

Yr Regn:

2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X5 M50D c.c. 2993

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

81488

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAK3820200G67411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/40 R20

R:

315/35 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 04/11/2019

D.O.I. 27/12/2019

Survey held at 9 Marymont Terrace

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front bonnet dent

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/12 Tokio Marine Public Liability
Charge additional \$80 for survey after 6pm. Surveyor direct incentive \$300.

RECEIVED 09 JAN 2020

Date/Time, File Pass to?

11/8/1 Typist

Date/Time, File Return to?

2)

Rep. Form:

Lump Sum / LEI: 0

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 1

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

320

80 After 6p

400

Nivitha (LKK Auto)

From: brandonchua@areda.com.sg
Sent: Thursday, 26 December 2019 3:58 PM
To: assignments@lkkauto.com
Subject: New assignment: Vehicle SKM 50G
Attachments: Quotation.pdf

TM's ref: G1908895
Our ref: 1994887/BC

9 Mountbatten Terrace

Dear Sirs,

As spoken, on behalf of Tokio Marine Insurance Singapore Ltd, we would like to appoint your office, LKK Auto Consultants Pte Ltd, to carry out an inspection on a third party's vehicle. The details are as follows:

Third Party : Mr Randy Lim
Contact no : 9029 6572
Vehicle : SKM 50G, BMW X5

*15 Kaki Bukit Road 4 #
01-39 Bentley Biz
Integrated*

Enclosed is a copy of the quotation submitted by the third party's solicitor.

We would appreciate your acknowledgement and please contact the third party urgently to make an arrangement.

Meanwhile, if you have any query, please do not hesitate to contact the undersigned.

Thank you.

Brandon Chua
Areda Adjusters Pte Ltd
229 Mountbatten Road
#01-10 Mountbatten Square
Singapore 398007
Tel: 6557 0258 Fax: 6557 0256

AREDA

SERVICE REQUEST FORM (SRF)

Pls. return by FAX / EMAIL

M/s LKK AUTO CONSULTANTS PTE LTD

51 Ubi Avenue 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Tel: 6256 3561 Fax: 6256 4315

Dear Sir/Madam,

Vehicle No(s). : SKM 50G

Accident Date : 04 November 2019

We refer to the above matter.

We/I confirmed to appoint your company to carry out inspection on third party vehicle as details mentioned above and agreed to pay the professional fees S\$428.00 (Inclusive of GST) within 30 days upon received of the stated report.

Company Name : Areda Adjusters Pte Ltd

**Company Stamp &
Authorized Signature**





Date : 27 December 2019

.....
Witness: (for LKK Auto Consultants Pte Ltd)

Name: _____

Signature: _____



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LIM HAN BENG
9 MARYMOUNT TERRACE #11-10
SINGAPORE 573964

Quotation : QT000519

Date Printed : 03/01/2020
Vehicle Num. : SKM50G
Make/Model : BMW X5 M50D
Mileage(Km) :
P.O./R.O No. :
Ref./Remark :

Contact : 90296572

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	FRONT BONNET Dental	2,795.00	2,795.00 ✓
2.	10	BONNET RUBBER CLIP Svc	8.50	85.00 X
3.	1	BMW LOGO Hec	169.00	169.00 ✓
4.	3	CLIO EMBLEM Hec	5.30	15.90 X
5.	2	FRONT BONNET RUBBER Svc	125.00	250.00 X
SPRAY PAINT DAMAGED AREA AFFECTED				580.00 300/-
REMOVE & INSTALL FRONT BONNET				260.00 200/-
GST 7%				288.04
LOSS OF USE \$200 X 4 DAYS				800.00

5% disc.

27/12/2019 @ 1900hrs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SingDollars : Five Thousand Two Hundred Two & Cents Ninety-Four Only

1 Dryer Part by Part
LKK Auto 1 day

Total S\$: 5,202.94

Terms : Cash

4114.90

COMPLETE VMS PTE LTD



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LIM HAN BENG
9 MARYMOUNT TERRACE #11-10
SINGAPORE 573964

Attention : THE OWNER
Contact : 90296572


Estimate : ES006838

Date : 08/11/2019
Vehicle Num. : SKM50G
Make/Model : BMW X5 M50D-2015
Chassis/Eng# : WBAKS820200G67411/90271153N57I
Accident Date : 04/11/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS :		
2.	10	FRONT BONNET		2,795.00
3.	1	BONNET RUBBER CLIP	8.50	85.00
4.	1	BMW LOGO		169.00
4.	3	CLIO EMBLEM	5.30	15.90
		Nett Total S\$:		3,064.90
		5.00% Discount S\$:		153.25
				2,911.65
1.	2	SPECIAL NETT ITEMS :		
		FRONT BONNET RUBBER	125.00	250.00
		Special Nett Total S\$:		250.00
		LABOUR :		
		SPRAY PAINT DAMAGED AREA AFFECTED		550.00
		REMOVE AND INSTALL FRONT BONNET		250.00
		Labour Total S\$:		800.00

SingDollars : Three Thousand Nine Hundred Sixty-One & Cents Sixty-Five Only

Total S\$: 3,961.65
=====


COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LIM HAN BENG
9 MARYMOUNT TERRACE #11-10
SINGAPORE 573964

Quotation : QT000519

Contact : 90296572

Date Printed : 03/01/2020
Vehicle Num. : SKM50G
Make/Model : BMW X5 M50D
Mileage(Km) :
P.O./R.O No. :
Ref./Remark :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	FRONT BONNET	2,795.00	2,795.00
2.	10	BONNET RUBBER CLIP	8.50	85.00
3.	1	BMW LOGO	169.00	169.00
4.	3	CLIO EMBLEM	5.30	15.90
5.	2	FRONT BONNET RUBBER	125.00	250.00
		SPRAY PAINT DAMAGED AREA AFFECTED		550.00
		REMOVE & INSTALL FRONT BONNET		250.00
		GST 7%		288.04
		LOSS OF USE \$200 X 4 DAYS		800.00

SingDollars : Five Thousand Two Hundred Two & Cents Ninety-Four Only

Total S\$: 5,202.94

=====

Terms : Cash


COMPLETE VMS PTE LTD

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CS/AAP19022905/Dtd3s2

C/O : AREDA ADJUSTERS PTE LTD
229 MOUNTBATTEN ROAD #01-10 MOUNTBATTEN
SQUARE
SINGAPORE 398007

Date : 09-01-2020



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKM 50G
Policy No.	1994887/BC	Coverage (\$)	0.00
Claim No.	G1908895	Excess (\$)	0.00
Assign From	BRANDON CHUA	Assign Date	26/12/2019

2. Vehicle Particulars & Condition

Make & Model	BMW X5 M50D	c.c	2993
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBAKS820200G67411	Colour	BLACK
Odometer	81488	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/40 R20	CONTINENTAL	6 mm
L/H Front Tyre	275/40 R20	CONTINENTAL	6 mm
R/H Rear Tyre	315/35 R20	CONTINENTAL	6 mm
L/H Rear Tyre	315/35 R20	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT BONNET DENTED. DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/11/2019	Inspection Date	27/12/2019
Survey held at	9 MARYMOUNT TERRACE		
Repairer	COMPLETE VMS PTE LTD		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 50G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	DENTED	2,795.00	2,795.00
10	BONNET RUBBER CLIP @ \$8.50	SERVICEABLE	85.00	-
1	BMW LOGO	NECESSARY	169.00	169.00
3	CLIO EMLEM @ \$5.30	NOT NECESSARY	15.90	-
2	FRONT BONNET RUBBER @ \$125.00	SERVICEABLE	250.00	-
	LESS 5% DISCOUNT		-	-148.20
			3,314.90	2,815.80
	LABOUR			
	SPRAY PAINT DAMAGED AREA AFFECTED.		550.00	300.00
	REMOVE & INSTALL FRONT BONNET.		250.00	200.00
			800.00	500.00
	GRAND TOTAL		4,114.90	3,315.80
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			3,315.80

Report Ref No. CS/AAP19022905/Dtd3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.