

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD Ref: CS/AAP19022905/Dtd3s2				
C/ O : AREDA ADJUSTERS PTE LTD 229 MOUNTBATTEN ROAD #01-10 MOUNTBATTEN SQUARE SINGAPORE 398007			Date: 09-01-2020	
			Code: TMI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKM 50G
	Policy No.	G1908895	Coverage (\$)	0.00
	Claim No.	1994887/BC	Excess (\$)	0.00
	Assign From	BRANDON CHUA	Assign Date	26/12/2019
2. Vehicle Particulars & Condition				
	Make & Model	BMW X5 M50D	c.c	2993
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WBAKS820200G67411	Colour	BLACK
	Odometer	81488	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/40 R20	CONTINENTAL	6 mm
	L/H Front Tyre	275/40 R20	CONTINENTAL	6 mm
	R/H Rear Tyre	315/35 R20	CONTINENTAL	6 mm
	L/H Rear Tyre	315/35 R20	CONTINENTAL	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT BONNET DENTED.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	04/11/2019	Inspection Date	27/12/2019
	Survey held at	9 MARYMOUNT TERRACE		
	Repairer	COMPLETE VMS PTE LTD		
5a.	Remarks			
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Estimate Days of Repair

1 Working Days