

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1912167

03rd January 2020

The Manager
Motor Claim Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

3/3

Date of Accident : 26th December 2019
Location : 31 Changi South St. 1
Third Party Claim Vehicle No : YP 9557 x
Repair Cost For Vehicle No : SLL 4169 R Subaru Forester

Supplementary Supply of Parts

No.	Particulars		Qty	Price	Amounts
1	Tail Lamp Clip	@4.50	4	18.00	\$ 18.00
					\$ 18.00

GST will be reflected in the final bills.

Parts: $4300 + 18.00 = 4318.00$
less 20% $= 863.80$
 3454.40
s/nett $= 900$
 4354.40
labour $= 1970.00$
 6324.40