

SECTION

ASS. REC. BY:

Surveyor: Kenneth

REF:

CS/INC19022927/Kvd3⁷²

Special Instruction:

ASSIGNMENT (Office)

From (Person): Theresa Yimala of INC

Date/Time: 31/12/2019 @ 9.47am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Impact Vehicle No: SIR 808Z Insured: 3JP 7805X

at Workshop w/a BH Auto Service Tel: 9621 2084

of Blk 1 # 01-115 Sin Ming Ind. est. sec C

Policy No: _____ Claim No: MT/1077171-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/12/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9.53am @ 31/12/19 Person Contacted: Wen Zheng Vehicle: IN/OUT

Date/Time	Action/Instruction
	<u>Estimate ✓</u>
	<u>SIR 808Z - X</u>
<u>6/1/2020</u>	<u>@ 2.00pm Wen Zheng said vehicle has not send in for repair pending liability.</u>
<u>17/1</u>	<u>61 Lm 8800 Confirm (Ref 9162.56, 9275)</u>

ASS. REC. BY:

REF: INC1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. _____

7

mm

L/Bal. _____

7

mm

D.O.A. _____

24/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to

RECEIVED 17 JAN 2020

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 17/1 - typist

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

800 f

Days Of Repair: _____

2

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Fuel

Others

TOTAL

250

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 31 December 2019 1:50 PM
To: 'assignments'
Cc: Theresa Vimala D/O Balagangadharan
Subject: FW: TP CASES FARMED OUT TO LKK ON 31/12/2019

List of OIC, details, thanks

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Hi LKK

Please assist to survey these vehicles. Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
----	-----	-----------	-------------	---------	---------------	------------------	------------------	-------------	--------	-----	--------------------

1	Alice Low	MT/1077171-002	31/12/2019	SJR808Z	BH AUTO SERVICES PTE LTD	BLK 1 #01-115 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575636	Wen Zheng / 6559 / 8945 / 9621 2084	10:00-13:00	SIP7805X	24/12/2019	
2	Chryllis Quah	MT/1077895-001	31/12/2019	SJM1898I	COMFORTDELGRO ENGINEERING PTE LTD	205 BRADDELL ROAD EAST WING 3RD FLR SINGAPORE 579701	Ngo Toh Wee / 6383 8115 / 6383 7362 / 6383 7656	09:30-10:30	YP400Z	30/12/2019	This vehicle belong to our MD of ComfortDelGro (REQUESTED- 9am to 10am)
3	Rajeswary	MT/1077719-001	31/12/2019	SLX253T	CP MOTORS PTE LTD	BLK 160 SIN MING DRIVE SIN MING AUTO CITY #05-05	Thomas Tan / 8201 8103	10:00-12:00	SIV6239E	27/12/2019	
4	Azhari	MT/1077789-001	31/12/2019	SLU7303C	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	CARMEN / 8799 0066 / 6566 2112		SKP2361Y	29/12/2019	
5	Chryllis Quah	MT/1077726-001	31/12/2019	5ML358B	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	10:00-12:00	SIV9565T	29/12/2019	
6	Serene Lim	MT/1077814-001	31/12/2019	5MJ3775X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	10:00-12:00	SMF7565	28/12/2019	
7	Huey Huey	MT/1077878-001	31/12/2019	5MK9435	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999		SIZ620Z	30/12/2019	agreeable with the appointment of Mr Lim - LKK

8	Helena	MT/1077820-001	31/12/2019	SLV5356H	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999		SGK1569D	28/12/2019	agreeable with the appointment of Mr Lim - LKK
9	Airwan	MT/1077830-001	31/12/2019	SLV2518C	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	Raymond Teo / 64532121		FU7961Z	29/12/2019	
10	David	MT/1076933-002	31/12/2019	SU3638U	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	Raymond Teo / 64532121		SLL1656X	21/12/2019	

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attitudes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Here is a car loan that's got
our green light!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

New 5 Years Renewal COE Toyota Wish 2.0A



2.88% P.A. 90 Admin, Monthly
From \$588, 2 Years Warranty,
Engine And Gearbox,
StarAd



ABWIN

ONE-STOP



Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

1 vehicles

Search Subaru Legacy

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Subaru Legacy

Any

Any

2016

Any

Any

Any

Available



Subaru Legacy 2.5i-S

\$64,000

\$8,880 /yr

23-Jan-2016

2,498 cc

89,000 km

Luxury

Available

High Loan And Trade In Available, Warranty Included, Free In Car Cam And Grooming!

Posted: 17-Dec-2019

Tags: 2016 Subaru Legacy, 2016 subaru legacy, subaru legacy, subaru legacy, subaru legacy, subaru legacy, legacy, Used Subaru

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & QPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, car parts sales & car insurance. Find buy used Subaru Legacy, Subaru Legacy Singapore, used Subaru Legacy Singapore, used Subaru Legacy, used vehicles Singapore or even buy used Subaru Legacy Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, movies, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Download on the
App StoreGET IT ON
Google play
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

SHORTLISTED



RECENT



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	069H
Vehicle No.:	SJR808Z
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2019
Vehicle Make:	SUBARU
Vehicle Model:	LEGACY 2.5I-S CVT AWD SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	FB25Y254745
Chassis No.:	JF1BN9KC2GG011203
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$21,591.00
Original Registration Date:	21 Nov 2016
First Registration Date:	21 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$22,228.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2026
PARF Rebate Amount:	\$16,671.00
COE Expiry Date:	20 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,206.00
COE Rebate Amount:	\$38,780.00
Total Rebate Amount:	\$55,451.00

The information contained herein is correct as at 27 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/12/2019 02:48
Date Of Accident	24/12/2019 12:35
Exact Location Of Accident	CTE TOWARDS AYE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR808Z
Insured/Policyholder	
Name Of Registered Owner	TAN SOON CHEONG
NRIC No	SXXXX069H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98003299
Alternative Phone No	OFFICE-98003299

Vehicle Particulars

Manufacturer	SUBARU
Model	LEGACY 2.5I-S CVT AWD SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AVPPSB0550591902
Cover Note Number	

Driver

Name of Driver	GAN LAY PENG
NRIC No	SXXXX399I
Date Of Birth	10/06/1971
Occupation	INDOOR
Date Of Driving Pass	12/09/1991
Driving Experience	28 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98003299
Fax Number	
Contact Number	
Email Address	STEPHANIE@BHH.COM.SG

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : RYAN TAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving slowly on the most right lane as the traffic on the expressway was heavy. As I was driving, Suddenly I felt an impact from my rear vehicle. I step my brakes and I felt another impact. I stop and realized that I am involved in a chain collision of 3 vehicles. Mine being the first vehicle. We exchange particulars. My neck and shoulder are hurting. I will be going to see my Family GP. No injury involved.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP7805X
Vehicle Make/Model/Colour	KIA / CERATO FORTE 2.0L SX A/T SR ABS D/AB 2WD / GOLD
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	CHANDRAN S/O P VELLASAMY
NRIC/Passport Number	SXXXX773E
Contact Number	94759574
Address	
Postcode	
Insurance Company Name	

SKETCH PLAN

CTE / AYE



C - SME 710D.

REFER TO ATTACHED STATEMENT.

Refined/Other: _____

Date & Time: _____

Date & Time: 24/12/19.

ACCIDENT STATEMENT (2000 characters)

I was driving slowly on the most right lane as the traffic on the expressway was heavy. As I was driving, Suddenly I felt an impact from my rear vehicle. I step my brakes and I felt another impact.

I stop and realised that I am involved in a chain collision of 3 vehicles. Mine being the first vehicle.

We exchange particulars.

My neck and shoulder are hurting. I will be going to see my Family GP.

No injury involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD AZALY BIN ABDULLAH

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

24 December 2019 at 6:49 PM

Date/Time:

24 December 2019 at 6:49 PM

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

NTUC Income Insurance Co-operative Ltd

1 Maritime Square

#10-01 HarbourFront Centre

Singapore 099253

Attn: Motor Claim Department

Tel: 6338 1504 Fax: 63396277

*Not Notion
C/Ping & God
Renny After Paint*

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJR808Z

MODEL : SUBARU LEGACY 2.5

POLICY NO : AVPPSB0550591902

YEAR : 2016

DATE/TIME OF ACCIDENT: 24/12/2019 1235HRS at CTE Towards AYE.

THIRD PARTY VEHICLE NO: SJP7805X

Date: 28/12/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price S\$	Condition	Amount S\$
1 Bootlid	1	612.00	Dented	612.00 X
2 Bootlid emblem	1	78.00	Necessary	78.00 X
3 Bootlid hinge LH	1	108.00	Bented	108.00 X
4 Bootlid hinge RH	1	108.00	Bented	108.00 X
5 Bootlid lock	1	245.90	Bented	245.90 X
6 Bootlid lettering "SUBARU AWD"	1	72.00	Necessary	72.00 X
7 Bootlid lettering "LEGACY"	1	50.40	Necessary	50.40 X
8 Bootlid lamp LH	1	150.00	To check	150.00 X
9 Bootlid lamp RH	1	150.00	To check	150.00 X
10 Rear tail lamp LH	1	360.00	Scratches	360.00 X
11 Rear tail lamp RH	1	360.00	Scratches	360.00 X
12 Rear tail lamp clip	4	4.50	Necessary	18.00 X
13 Rear bumper	1	594.40	Torn	594.40 ✓
14 Rear bumper side retainer LH	1	36.00	Necessary	36.00 X
15 Rear bumper side retainer RH	1	36.00	Necessary	36.00 X
16 Rear bumper clip	12	3.50	Necessary	42.00 ✓
17 Rear bumper radar sensor LH	1	1,008.00	Malfunction	1,008.00 X
18 Rear bumper radar sensor RH	1	1,008.00	Malfunction	1,008.00 X
19 Rear bumper tow cover	1	9.00	Scratches	9.00 X
20 Rear bumper reinforcement	1	396.00	Dented	396.00 X
21 Rear end panel	1	250.00	Bented	250.00 X
22 Rear end panel top garnish	1	136.00	Kinked	136.00 X
23 Rear exhaust silencer assy	1	540.00	Bented	540.00 X
24 Rear exhaust tail pipe finisher chrome	1	108.00	Scratches	108.00 X

Sub-Total: 6,475.70

Less: 20% discount - 1,295.14

Total Parts after 20% discount: 5,180.56

Special Nett Items

1 Anti-rust coating	2	80.00	160.00 X
2 Rear bumper sensor	1	250.00	250.00 X

3	Rear end panel garnish clip	10	4.20	~	42.00	X
4	Reverse camera	1	300.00	~	300.00	X
6	Rear number plate with casing	1	100.00	~	100.00	X
7	Rear end panel seal	1	100.00	~	100.00	X
					952.00	

Total Parts: 6,132.56

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	2001	1,500.00	
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,000.00	2201	
3	Provide skill labour to diagnosis and reprogramming radar sensor	~	400.00	X
4	Provide skill labour to disconnect and check electrical wiring	~	80.00	X
5	Provide skill to remove and refit bumper sensor		80.00	501
6	Provide skill labour to remove and replace reverse camera with wiring installation	~	120.00	X
7	Labour to remove and refit rear end panel lining and garnish to facilitate repair	~	100.00	X
8	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair	~	100.00	X
9	Provide skill labour to mount vehicle onto chassis alignment bench	~	350.00	X
10	Dismantle and transfer bootlid fitting and mechanism to new/facilitate repair	~	100.00	X

Total Labour:

3,830.00

Total Parts & Labour:

9,962.56

GST 7%

697.38

Grand Total:

10,659.94

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SJR808Z

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : Kennerly
 Company : LKIC
 Date : 31/12/19
 Time : _____
 Contact No : 98910663
 Email : _____

LKIC Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC19022927/Kvd3n2

Date: 20-01-2020



ATTN: ALICE LOW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 7805X	Veh. Inspected	SJR 808Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1077171-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	31/12/2019

2. Vehicle Particulars & Condition

Make & Model	SUBARU LEGACY (A)	c.c	2498
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1BN9KC2GG011203	Colour	METALLIC PEARL WHITE
Odometer	57381 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	MICHELIN	7 mm
L/H Front Tyre	225/50 R18	MICHELIN	7 mm
R/H Rear Tyre	225/50 R18	MICHELIN	7 mm
L/H Rear Tyre	225/50 R18	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/12/2019	Inspect Date / Time	31/12/2019 (12:21 PM)
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 808Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	TO REPAIR SEE LABOUR	612.00	-
1	BOOTLID EMBLEM	NOT NECESSARY	78.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	108.00	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	108.00	-
1	BOOTLID LOCK	TO REPAIR SEE LABOUR	245.90	-
1	BOOTLID LETTERING "SUBARU AWD"	NOT NECESSARY	72.00	-
1	BOOTLID LETTERING "LEGACY"	NOT NECESSARY	50.40	-
1	BOOTLID LAMP LH	SERVICEABLE	150.00	-
1	BOOTLID LAMP RH	SERVICEABLE	150.00	-
1	REAR TAIL LAMP LH	SERVICEABLE	360.00	-
1	REAR TAIL LAMP RH	SERVICEABLE	360.00	-
4	REAR TAIL LAMP CLIP	NOT NECESSARY	18.00	-
1	REAR BUMPER	BUCKLED	594.40	594.40
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	36.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	36.00	-
12	REAR BUMPER CLIP	NECESSARY	42.00	42.00
1	REAR BUMPER RADAR SENSOR LH	SERVICEABLE	1,008.00	-
1	REAR BUMPER RADAR SENSOR RH	SERVICEABLE	1,008.00	-
1	REAR BUMPER TOW COVER	SERVICEABLE	9.00	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	396.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	136.00	-
1	REAR EXHAUST SILENCER ASSY	TO REPAIR SEE LABOUR	540.00	-
1	REAR EXHAUST TAIL PIPE FINISHER CHROME	SERVICEABLE	108.00	-
	LESS 20% DISCOUNT		-1,295.14	-127.28
			5,180.56	509.12

Report Ref No. CS/INC19022927/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
1	REAR BUMPER SENSOR (SN)	SERVICEABLE	250.00	-
10	REAR END PANEL GARNISH CLIP (SN)	NOT NECESSARY	42.00	-
1	REVERSE CAMERA (SN)	SERVICEABLE	300.00	-
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	100.00	-
1	REAR END PANEL SEAL (SN)	SERVICEABLE	100.00	-
			792.00	-
LABOUR				
	ANTI-RUST COATING.	NOT NECESSARY	160.00	-
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID,BOOTLID HINGE LH,BOOTLID HINGE RH,BOOTLID LOCK,REAR BUMPER REINFORCEMENT,REAR END PANEL AND REAR EXHAUST SILENCER ASSY.		1,500.00	200.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		1,000.00	220.00
	PROVIDE SKILL LABOUR TO DIAGNOSIS AND REPROGRAMMING RADAR SENSOR.	NOT NECESSARY	400.00	-
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.	NOT NECESSARY	80.00	-
	PROVIDE SKILL TO REMOVE AND REFIT BUMPER SENSOR.		80.00	50.00
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE REVERSE CAMERA WITH WIRING INSTALLATION.	NOT NECESSARY	120.00	-
	LABOUR TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR.	NOT NECESSARY	100.00	-
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE EXHAUST PIPE/SYSTEM TO FACILITATE REPAIR.	NOT NECESSARY	100.00	-
	PROVIDE SKILL LABOUR TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH.	NOT NECESSARY	350.00	-
	DISMANTLE AND TRANSFER BOOTLID FITTING AND MECHANISM TO NEW/FACILITATE REPAIR.	NOT NECESSARY	100.00	-
			3,990.00	470.00
GRAND TOTAL			9,962.56	979.12

Report Ref No. CS/INC19022927/Kvd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			800.00
--	--	--	--------

Report Ref No. CS/INC19022927/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.