

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22286

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1457/2019/NS
Date : 10-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no. : **GBA 6516 K**

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Lee Junxian
Address : Blk 105 Aljunied Crescent
#12-227
Singapore 380105
Telephone : (HP) +65 96655489
Type of Claim : Third Party Claims
Policy No. : MT/00682035
Vehicle No : **SMD 8183 C**
Model Code : Audi A5 Sportsback 2.0 TFSI
Model / Year : Sep-18
Engine No : CVK 068125
Chassis No : WAUZZZF58JA132050
Mileage : 20284
Date In : 30-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Dec-19
Place of Accident : Traffic Light Junction Along Stamford Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMD 8183 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	✓
2	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. Renew if necessary.	S/N \$ 480.00	✓
3	To remove and transfer, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✗ NN
4	To carry out first measurement on car-o-liner.	S/N \$ 800.00	✗ NN
5	To remove and reinstall engine assy with gearbox assy to facilitate car-o-liner repairs.	S/N \$ 2,800.00	✗ NN
SUB TOTAL LABOUR CHARGES		: \$ 5,560.00	760

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMD 8183 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall front suspension assy with subframe to facilitate car-o-liner repairs. Inspect for damages and renew if necessary.	S/N \$ 2,400.00	X NN
7	To set up and place vehicle on car-o-liner	S/N \$ 2,400.00	X NN
8	To dismantle front bumper, bonnet and rhs front fender. Cut out and weld rhs fender top support. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	800 \$ 9,200.00	2800
9	To respray front bumper, rhs front fender, bonnet and rhs fender top support. To carry out joint sealer works.	\$ 3,800.00	2500
10	To renew rhs front rim and tyre. Carry out wheel alignment.	S/N \$ 280.00	/
11	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 23,832.00	6532

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 8183 C

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Be</i>	\$	2,073.00	✓
2	FRONT BUMPER FIXING PARTS <i>X NN</i>	\$	368.00	X
3	FRONT BUMPER AIR GUIDE - RH <i>Spec.</i>	\$	56.00	55.5
4	FRONT BUMPER SECURING STRIP <i>2</i>	\$	64.00	63.6
5	FRONT BUMPER GUIDE SECTION - RH <i>X NN</i>	\$	33.00	X
6	RADIATOR GRILLE <i>X NN</i>	\$	2,131.00	X
7	ULTRASOUND SENSOR SUPPORT - LH / RH <i>X NN</i>	2 \$	96.00	X
8	RADIATOR GRILLE COVER - UPPER <i>X NN</i>	\$	174.00	X
9	FRONT BUMPER COVER <i>✓</i> DE	\$	116.00	115.5
10	CAUTION SIGN STICKER <i>✓</i> NEC	NEC \$	13.00	12.2
11	AIRCON STICKER <i>✓</i> NEC	NEC \$	7.00	6.4
12	FRONT FENDER - RH <i>Blue</i>	\$	968.00	✓
13	FRONT FENDER ATTACHMENT PARTS <i>X NN</i>	\$	48.00	X
14	FRONT FENDER CLOSING ELEMENT - RH <i>AC.</i>	\$	68.00	67.2
15	FRONT FENDER BRACKET - RH	\$	53.00	52.1
16	FRONT FENDER BRACKET <i>2</i>	\$	63.00	✓
17	FRONT FENDER BRACE - RH	\$	107.00	✓
18	FRONT FENDER BRACKET - RH	\$	32.00	31.5
19	FRONT FENDER CLOSING ELEMENT - RH	\$	30.00	✓
20	FRONT WHEEL HOUSING LINER - RH <i>X NN</i>	\$	256.00	X
SUB TOTAL SPARE PARTS		:	\$ 6,756.00	3645

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 8183 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	WHEEL SPOILER ✓ CRA	TBC	68.8
22	WHEEL HOUSING LINER ATTACHMENT PARTS ✗ NN	\$ 82.00	✗
23	FENDER LEDGE COVER - RH FRONT / mbc	\$ 14.00	13.8
24	FENDER LEDGE COVER - RH REAR /	\$ 32.00	31.8
25	FRONT FENDER TRIM - RH ✓ CRA	\$ 145.00	144.5
26	BONNET / Bue	\$ 2,602.00	✓
27	BONNET ATTACHMENT PARTS ✗ NN	\$ 111.00	✗
28	BONNET IMPACT PROTECTION - CENTRE / LH / RH 31 / mbc	\$ 75.00	74.3
29	BONNET LID HINGE - LH / RH / BT	2 \$ 762.00	✓
30	BONNET STRIKER - LH / RH ✓ BT	2 \$ 92.00	90.6
31	BONNET LID LOCK ✗ NN	2 \$ 391.00	✗
32	BONNET BOWDEN CABLE - CENTRE ✗ NN	\$ 53.00	✗
33	BONNET BOWDEN CABLE - CENTRE ✗ NN	\$ 53.00	✗
34	BONNET LID LOCK CABLE ✗	\$ 67.00	✗
35	LED HEADLIGHT - RH / CRA	\$ 7,204.00	✓
36	MAIN LIGHT POWER MODULE ✗ ✓ DM	\$ 693.00	692.5
37	LIGHT CONTROL SYSTEM CONTROL UNIT ✗ ✓ DM	\$ 685.00	✓
38	LED WITH HEAT SINK - RH ✓ CRA	\$ 1,053.00	1052
39	HEADLIGHT HOSE ✗ NN	\$ 32.00	✗
40	HEADLAMP ASSEMBLY SPACER ✗ NN	\$ 39.00	✗
SUB TOTAL SPARE PARTS		: \$ 14,185.00	13421.3

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SMD 8183 C

		Damage Parts & Prices			
S/N	Parts Description	S/Nett	Remarks		
41	HEADLAMP ASSEMBLY SPACER X NN	\$ 36.00	X		
42	HEADLAMP ASSEMBLY SPACER X NN	\$ 36.00	X		
43	LIFT CYLINDER BRACKET - RH X NN	\$ 13.00	X		
44	LIFT CYLINDER - RH X NN	\$ 181.00	X		
45	HEADLIGHT CORRUGATED PIPE X NN	\$ 78.00	X		
46	WASH WATER RESERVOIR X NN	\$ 130.00	X		
47	HEADLIGHT SEAL X NN	\$ 55.00	X		
48	LOCK CARRIER X NN	\$ 928.00	X		
49	CONNECTING PLATE - RH X NN	\$ 197.00	X		
50	REINFORCED APRON - RH X NN	\$ 228.00	X		
51	NOISE INSULATION PLATE - RH X NN	\$ 23.00	X		
52	READY MIX COOLANT X NN	4 \$ 84.00	X		
53	FRONT ALUMINIUM RIM - RH X 60 ✓ CUT	\$ 943.00	✓		
54	FRONT TYRE - RH X NN	\$ 1,067.00	X		
55	ASSEMBLY CARRIER X NN	TBC	X		
56	FRONT WISHBONE LINK - RH X NN	\$ 491.00	X		
57	FRONT SUSPENSION GUIDE - RH X NN	\$ 861.00	X		
58	GUIDE - RH X NN	\$ 466.00	X		
59	REAR GUIDE - RH UPPER X NN	\$ 466.00	X		
60	WHEEL BEARING HOUSING - RH X NN	\$ 884.00	X		
SUB TOTAL SPARE PARTS		\$ 7,167.00	943		

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 8183 C

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
61	SWIVEL JOINT X NN	\$	175.00	X
62	WHEEL HUB X NN	\$	657.00	X
63	COUPLING ROD X NN	2 \$	245.00	X
64	GAS SHOCK ABSORBER X NN	\$	268.00	X
65	STEERING GEAR X NN	\$	5,939.00	X
66	TIE ROD END - RH X NN	\$	180.00	X
67	BONNET SOUND ABSORBER / acc	\$	311.00	✓
68	FRONT NO PLATE X NN	S/N \$	40.00	X
69	ACRYLIC SEALANT / acc.	S/N \$	180.00	✓
70	CAVITY WAX / acc.	S/N \$	140.00	✓
71	SUNDRIES X NN	\$	800.00	66.1

TOTAL SPARE PARTS	:	\$ 37,043.00	19774.4
TOTAL LABOUR CHARGES	:	\$ 23,832.00	
GRAND TOTAL	:	\$ 60,875.00	26306.4

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

61,943.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

[Handwritten signature]
31/2020

7 Days.

Gmo Qian - 82880282

before paint photos.

02/1/2020

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534
Attn: Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Estimate No. PA/TP/1457/2019/NS
Date 11-Jan-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SMD 8183 C
Model No Audi A5 Sportsback 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT ALUMINIUM RIM -LH <i>✓ Cut</i>	\$ 943.00	
1	Bracket for lock carrier <i>✓ BR</i>	\$ 125	
TOTAL		\$ 943.00 1068	

For Premium Automobiles Pte Ltd

Gino Qiao

LKK

Authorised Signature

LKK Auto Compensation notice
Bike Repairs: 01-11-2019
• To be used for the purpose of painting
• To be used for the purpose of survey
• Parts prices are subject to confirmation
• Third party liability need a "Without Prejudice" basis
• All claims must be submitted to the Insurance Company
• Supplementary claims must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature:
Date: