

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24627

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1539/2019/NS
Date : 02-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Chan Kheng Hui
Address : 17 Cairnhill Circle
#16-05
Singapore 229816
Telephone : HP +65 97351331
Type of Claim : Own Damagr. Claims
Policy No. : 1900169775
Vehicle No : **SMQ 328 L**
Model Code : Audi Q5 SPORT 2.0 TFSI qu
Model / Year : 30/9/22019
Engine No : DAX 059818
Chassis No : WAUZZZF7K2139013
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Dec-19
Place of Accident : Tanglin Rd Near China Embassy

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMQ 328 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	X ✓
2	To remove and transfer both lhs front and rear door's multi-lock system and power window devices.	S/N \$ 720.00	/ ✓
3	To dismantle front bumper, lhs front fender, lhs front and rear doors. Inspect lhs B-pillar and lhs rear fender for damages. Renew front bumper, lhs front fender, lhs front and rear doors and lhs rear wheel arch trim. Reinstall all parts removed.	\$ 4,000.00	2500 ✓
4	To respray front bumper, lhs front fender, lhs front and rear doors, door covers and wheel arch trims.	\$ 5,300.00	2200 3200
5	To renew lhs rear rim. Carry out wheel alignment.	S/N \$ 280.00	X
6	To carry out diagnostic check.	S/N \$ 192.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 10,972.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 328 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>repair</i>	\$ 2,364.00	
2	FRONT BUMPER GUIDE SECTION - LH <i>X</i> nn	\$ 34.00	
3	FRONT FENDER - LH <i>repair</i> <i>✓</i> bt	\$ 1,301.00	1040.80
4	FRONT FENDER BRACKET - LH <i>X</i> SVC	\$ 16.00	
5	FRONT FENDER BRACE - LH <i>X</i> SVC	\$ 206.00	
6	FRONT WHEEL HOUSING LINER - LH <i>X</i> SVC	\$ 246.00	
7	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i> nn	\$ 35.00	
8	WHEEL SPOILER - LH <i>X</i> SVC		TBC
9	FRONT WHEEL COVER - LH <i>sc</i> RH <i>X</i> <i>✓</i> nec	<i>1pc 2</i> \$ 1,154.00	922.40
10	S-LINE INSCRIPTION <i>X</i> nn	\$ 113.00	
11	DOOR - LH <i>bt</i> <i>✓</i>		TBC 2377.60
12	OUTER DOOR SEAL - LH / RH <i>sc</i> <i>✓</i>	NEC \$ 370.00	147.60
13	BONDING AGENT <i>sc</i> <i>✓</i>	NEC \$ 45.00	35.92
14	CLEANING SOLUTION <i>sc</i> <i>✓</i> <i>X</i> nn	NEC \$ 65.00	
15	DOOR ATTACHMENT PARTS <i>?</i> <i>X</i> nn	\$ 239.00	
16	DOOR CATCH <i>X</i> <i>✓</i> bt	\$ 132.00	109.60
17	WINDOW REGULATOR - LH <i>?</i> <i>X</i> SVC	\$ 270.00	
18	FRONT DOOR COVER - LH <i>?</i> <i>✓</i> nec	\$ 661.00	528.80
19	DOOR - RH <i>bt</i> <i>✓</i>		TBC 2377.60
20	OUTER DOOR SEAL - RH <i>sc</i> <i>✓</i>	NEC \$ 190.00	154.40
SUB TOTAL SPARE PARTS		: \$	<u><u>7,441.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 328 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	BONDING AGENT <i>nn /</i> X nn	NEC \$	45.00
22	CLEANING SOLUTION <i>nn /</i> X nn	NEC \$	65.00
23	SEALING STRIP ? X nn	\$	15.00
24	DOOR CATCH X SVC	\$	132.00
25	DOOR HINGE HALF UPPER PART - LH UPPER X SVC	\$	42.00
26	DOOR HINGE HALF LOWER PART - LH UPPER X SVC	\$	42.00
27	DOOR HINGE HALF UPPER PART - LH LOWER ? X SVC	\$	42.00
28	DOOR HINGE HALF LOWER PART - LH LOWER ? X SVC	\$	42.00
29	REAR DOOR SEAL BRACKET - LH ? X SVC	\$	39.00
30	REAR DOOR COVER - LH ? ✓ nec	\$	577.00 461.20
31	REAR WHEEL COVER - LH <i>sc</i>	\$	487.00 389.60
32	REAR ALUMINIUM RIM - LH X SVC	\$	923.00
33	SUNDRIES ? ✓ nec	\$	400.00 22.72

TOTAL SPARE PARTS	:	\$ 10,292.00
TOTAL LABOUR CHARGES	:	\$ 10,972.00
GRAND TOTAL	:	\$ 21,264.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Rasul - Hp 96010068
Surveyed Date : 31/12/19 @ 1120
Authorised Date : 10 days
Excess Cost :
Liability : EXCESS. TBA
Remarks :
Revert
Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant