

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMQ 328 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. (stripped for respray front bumper)	S/N \$ 480.00 X	✓
2	To remove and transfer both lhs front and rear door's multi-lock system and power window devices.	S/N \$ 720.00 /	✓
3	To dismantle front bumper, lhs front fender, lhs front and rear doors. Inspect lhs B-pillar and lhs rear fender for damages. Renew front bumper, lhs front fender, lhs front and rear doors and lhs rear wheel arch trim. Reinstall all parts removed.	\$ 4,000.00 2500	✓
4	To respray front bumper, lhs front fender, lhs front and rear doors, door covers and wheel arch trims. (2x door covers and 3x wheel arch trims added \$1000)	\$ 5,300.00 2200	3200
5	To renew lhs rear rim. Carry out wheel alignment.	S/N \$ 280.00 X	nn
6	To carry out diagnostic check.	S/N \$ 192.00 /	✓
TOTAL LABOUR CHARGES		: \$ 10,972.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 328 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER repair	\$ 2,364.00	
2	FRONT BUMPER GUIDE SECTION - LH X nn	\$ 34.00	
3	FRONT FENDER - LH repair ✓ bt	\$ 1,301.00	1040.80
4	FRONT FENDER BRACKET - LH X SVC	\$ 16.00	
5	FRONT FENDER BRACE - LH X SVC	\$ 206.00	
6	FRONT WHEEL HOUSING LINER - LH X SVC	\$ 246.00	
7	WHEEL HOUSING LINER ATTACHMENT PARTS X nn	\$ 35.00	
8	WHEEL SPOILER - LH X SVC	TBC	
9	FRONT WHEEL COVER - (LH/RH) X nec ✓	1pc X \$ 1,154.00	922.40
10	S-LINE INSCRIPTION X nn	\$ 113.00	
11	DOOR - LH bt	TBC	
12	OUTER DOOR SEAL - LH / RH nec	NEC \$ 370.00	2377.60
13	BONDING AGENT nec	NEC \$ 45.00	147.60
14	CLEANING SOLUTION nec X nn	NEC \$ 65.00	35.92
15	DOOR ATTACHMENT PARTS ? X nn	\$ 239.00	
16	DOOR CATCH X ✓ bt	\$ 132.00	109.60
17	WINDOW REGULATOR - LH ? X SVC	\$ 270.00	
18	FRONT DOOR COVER - LH ? nec ✓	\$ 661.00	528.80
19	DOOR - RH bt	TBC	2377.60
20	OUTER DOOR SEAL - RH nec	NEC \$ 190.00	154.40
SUB TOTAL SPARE PARTS		:	\$ 7,441.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 328 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	BONDING AGENT NE ✓ X NH	NEC \$	45.00
22	CLEANING SOLUTION NE ✓ X NH	NEC \$	65.00
23	SEALING STRIP ? X NH	\$	15.00
24	DOOR CATCH X SVC	\$	132.00
25	DOOR HINGE HALF UPPER PART - LH UPPER X	\$	42.00
26	DOOR HINGE HALF LOWER PART - LH UPPER X	\$	42.00
27	DOOR HINGE HALF UPPER PART - LH LOWER ? X SVC	\$	42.00
28	DOOR HINGE HALF LOWER PART - LH LOWER ? X	\$	42.00
29	REAR DOOR SEAL BRACKET - LH ? X SVC	\$	39.00
30	REAR DOOR COVER - LH ? ✓ NEC	\$	577.00 461.20
31	REAR WHEEL COVER - LH SVC	\$	487.00 389.60
32	REAR ALUMINIUM RIM - LH X SVC	\$	923.00
33	SUNDRIES ? ✓ NEC	\$	400.00 22.72
TOTAL SPARE PARTS		:	\$ 10,292.00
TOTAL LABOUR CHARGES		:	\$ 10,972.00
GRAND TOTAL		:	\$ 21,264.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.