

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

27/12/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR - SEK43Y

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1pc	front bonnet	972.55
2pcs	front bonnet hinge @\$141.45	
1pc	front bonnet cardboard	
8pcs	front bonnet cardboard clip @\$5.00	
1pc	front bonnet inner lock	
1pc	front bonnet inner lock cable	
1pc	front centre grille base	434.80
1pc	* front centre grille garnish	
1pc	front centre grille "TOYOTA" logo	
1pc	front centre grille top garnish	
1pc	front centre grille top rubber	
1pc	* front centre grille inner PCS sensor	
1pc	* front centre grille beam	281.50
2pcs	front headlamp @\$2821.40	c/s m/j com
2pcs	front headlamp lower beam @\$271.75	
1pc	front LH fender	691.00
1pc	front LH fender "HYBRID" emblem	
2pcs	front fender protector @\$374.20	C210
1pc	front fender LH inner shield	272.60
1pc	front bumper	946.50
2pcs	front bumper side retainer @\$133.35	
1pc	front bumper grille	154.70
1pc	front bumper lower lid	410
2pcs	front bumper side garnish @\$374.45	C255
1pc	front bumper towing cover	
1pc	front bumper number plate garnish	122.80
1pc	front bumper LH parking sensor	
1pc	* front bumper hardness	408.50
1pc	front bumper centre LH sensor cover	
1pc	* front bumper LH fog lamp	354.
1pc	* front bumper LH fog lamp bracket	
1pc	* front bumper reinforcement	461.60
2pcs	front bumper reinforcement side bracket @\$132.10	
1pc	front bumper sponge	95.20
1pc	* front bumper lower reinforcement	173.10
2pcs	front bumper lower reinforcement bracket @\$141.45	

Bu	\$	972.55	✓
Dis	\$	282.90	✓
Pa	\$	371.75	X
ra	\$	40.00	✓
R	\$	274.10	✓
Lu	\$	181.60	✓
CM	\$	591.45	✓
nd	\$	371.50	✓
Sen	\$	691.45	✓
Pa	\$	381.90	X
Pa	\$	174.45	X
nd/m/j com	\$	1,850.50	✓
R	\$	358.20	✓
n/s CM	\$	5,642.80	✓
n/s Dis	\$	543.50	✓ + 271.75
Bu	\$	781.90	✓
ra	\$	68.25	✓
Bu	\$	748.20	✓
Dis	\$	381.90	✓
R	\$	974.45	✓
Dis	\$	266.70	✓
CM	\$	274.45	✓
nd/CM	\$	680.00	✓
n/s Dis	\$	748.90	✓ + 374.45
Dis	\$	43.75	✓
nd	\$	271.85	✓
n/s	\$	281.55	✓
Ta	\$	681.50	✓
Sen	\$	85.00	✓
m/j com	\$	381.50	✓
Dis	\$	121.50	✓
R	\$	581.10	✓
R	\$	264.20	X
CM	\$	181.90	✓
R	\$	561.90	✓
R	\$	282.90	X

balance c/f

\$ 21,392.05



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

27/12/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR - SFK43Y

balance b/f

1pc	* front bumper lower sponge	89.50
1pc	* front bumper lower cover	
1pc	front support top panel	381.85
2pcs	front support side panel @ \$281.85	
1pc	front support lower panel	
2pcs	LH * front support panel side garnish @ \$177.75	
1pc	* front support panel top garnish	245.60
1pc	* front support panel lower garnish	135.20
1pc	* front air-con condenser	1218.50
1pc	front air-con cowling motor	
1pc	front air-con cowling fan	
1pc	front radiator	
1pc	front radiator top hose	
1pc	front radiator lower hose	
1pc	* front radiator cowling	291.38
1pc	front radiator cowling motor	
1pc	front radiator cowling fan	
1pc	front radiator inverter wash tank	
1pc	front radiator inverter wash tank top hose	
1pc	front radiator inverter wash tank lower hose	
1pc	front air duct	
1pc	front air duct hose	
1pc	front air duct hose inner pipe	
1pc	front air intake box	
1pc	front air intake box cover	
1pc	front LH fluse box cover	
1pc	front gear box oil cooler	
1pc	front gear box oil cooler hose 1	
1pc	front gear box oil cooler hose 2	
1pc	front windscreen glass	1712.50
1pc	front windscreen moulding	
1pc	front dashboard	1218
1pc	front dashboard air bag	
1pc	front steering air bag	
1pc	front steering clock spring	

balance c/f

\$ 21,392.05

CM	\$ 174.45	✓
CM	\$ 182.50	✓
Bu	\$ 381.85	✓
N/S Bu	\$ 563.70	✓ 281.85
R	\$ 225.25	✓
N/S CM	\$ 355.50	✓ 177.75
CM	\$ 374.45	✓
N/S	\$ 289.90	✓
Ru	\$ 1,218.50	✓
Su	\$ 561.60	✓
Su	\$ 274.45	✓
Su	\$ 1,718.80	✓
Su	\$ 61.10	X
Su	\$ 121.35	✓
CM	\$ 374.80	✓
Su	\$ 561.60	✓
Su	\$ 280.85	✓
Su	\$ 177.10	✓
Su	\$ 132.25	✓
Su	\$ 141.45	✓
Su	\$ 174.45	X
Su	\$ 181.90	X
Su	\$ 274.45	X
Su	\$ 371.80	✓
Su	\$ 174.40	✓
N/S	\$ 182.55	✓
Su	\$ 591.25	✓
Su	\$ 131.30	✓
Su	\$ 141.45	✓
CM	\$ 1,712.50	✓
Ru	\$ 181.90	✓
Tu	\$ 1,318.10	✓
Bu	\$ 2,580.50	✓
Su	\$ 2,550.25	✓
Ru	\$ 685.50	✓

\$ 40,815.80



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE BIK 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) Fax: 64514658
GST Reg No. 201629438M

27/12/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR - SFK43Y

	balance b/f		\$ 40,815.80
2pcs	front seat belt @\$785.70		
1pc	front air bag control unit 781.90	Tm	\$ 1,571.40 —
2pcs	front air bag impact sensor @\$261.60	Mr	\$ 781.90 —
1pc	front engine lower cover	Mr	\$ 523.20 —
1pc	front engine lower cover LH side garnish	Sm	\$ 930.00 2x
1pc	front engine lower cover front garnish	Sm	\$ 277.00 2x
2pcs	rear seat belt @\$772.70	Sm	\$ 580.00 2x
2pcs	rear fender inner trim @\$880.30 e 608.80	Tm	\$ 1,545.40 —
2pcs	roof top air bag @\$2881.55 e 2870.	CM	\$ 1,760.60 —
1PC	roof top trim 1680	Mr	\$ 5,763.10 —
		Deform	\$ 2,550.85 —
			\$ 57,099.25
	less 25%		\$ 14,274.81
			\$ 42,824.44

1pc	towing	
1pc	IU bracket	
1set	private hire car decal	
1pc	front number plate & casing	
	battery	
	remove & refix air bag system	
	remove & refix front dashboard	
	remove & refix front windscreen glass	
	reset & reprogram air bag unit	
	reset ECU	
	sealant	
	tuffkote	
	wiring	
	spray painting	
	labour charges	
	Total	

(Bill)	s.nett	\$ 100.00	✓
Mr	s.nett	\$ 80.00	265m
Mr	s.nett	\$ 20.00	✓
Mr	s.nett	\$ 50.00	45m
Mr	s.nett	\$ 200.00	508m
		\$ 350.00	2501
		\$ 320.00	2501
		\$ 120.00	✓
		\$ 280.00	2201
		\$ 380.00	2501
		\$ 80.00	401
		\$ 180.00	901
		\$ 180.00	401
		\$ 1,600.00	10001
		\$ 1,800.00	801
		\$ 48,564.44	



49,133.13

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

27/12/2019

Owner: HYMS CAR LEASING PTE LTD

SUPPLEMENTARY TO REPAIR TOYOTA C-HR - SFK43Y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

1pc front LH headlamp HID control unit 680

Net \$ 758.25 ✓

less 25%

\$	758.25
\$	189.56
\$	568.69

13/01/20
enrol Kenneth
Supplementary ?
adv upon photos

20/01/20
Resend.

10/02/20
Resend

17/02/20
Resend

04/03/20
Resend.

18/03/20
Resend.

20/04/20
Resend

sup
$$\begin{array}{r} 45'981.75 \\ 758.25 \\ \hline 46'740 \end{array}$$

25% less
$$\begin{array}{r} 11'685 \\ 35'055 \\ 241 \end{array}$$

SN 1cbar
$$\begin{array}{r} 3060 \\ 38'356 \end{array}$$

2520%
$$\begin{array}{r} 7'671.20 \\ 25 \\ \hline 30'650 \end{array}$$