

TRIPLE-T AUTOMOBILE

BLK 5 DEPU LANE 10 #01-574 SINGAPORE 539186

TEL: 6385 1171

Vehicle No: YP3768T
Model No: Mitsubishi Fuso
Chassis no: FM65PM2RDEB

Accident Date: 26/12/2019
Owner: Global Consolidators Pte Ltd
Date of Estimate: 04/2/2020

Estimate for Accident Vehicle No. YP3768T

List Items:	Qty	Unit Price	Total Amount
1 Front bumper ✓ BT	1	\$1,158.90	\$1,158.90 1056.20 ✓
2 Front bumper fog lamp rh ✓ CRA	1	\$358.70	\$358.70 275.36 ✓
3 Headlamp rh X (SVC)	1	\$854.20	\$854.20
4 Front corner panel rh ✓ LRA	1	\$912.50	\$912.50 383.60 ✓
5 Front corner panel bracket rh X (NAM)	1	\$75.00	\$75.00
6 Front corner lamp rh X (SVC)	1	\$421.00	\$421.00
7 Front door rh ✓ BT	1	\$3,658.90	\$3,658.90 2500.70 ✓
8 Front door reflector rh X (SVC)	1	\$77.00	\$77.00
9 Front door hinges ✓ LRM	2	\$96.70	\$193.40 193.40 ✓
10 Front door window glass rubber X (SVC)	1	\$195.00	\$195.00
11 Front door weatherstripping rh ✓ new	1	\$298.70	\$298.70 210.70 ✓
12 Front side mirror assy rh ✓ CRA	1	\$275.50	\$275.50 ✓
13 Front side mirror latch bracket rh ✓ LRM	1	\$150.00	\$150.00 78.80 ✓
14 Front door upper step garnish rh ✓ SVC	1	\$376.00	\$376.00 376 ✓
15 Front door lower step garnish rh X (LR)	1	\$412.00	\$412.00
16 Front windscreen pillar "A" X (LR)	1	\$654.50	\$654.50
17 Front door inner board rh X (SVC)		Sub-Total Amount =	\$10,071.30
18 Front door inner board rh		Less: parts discount = 25%	\$1,510.70
		Sub-Total =	\$8,560.61

Special New Items	Qty	Unit Price	Total Amount
1 Front door company sticker rh ✓ new	1	\$320.00	\$320.00 250 ✓
2 Front windscreen sealant X (SVC)	1	\$60.00	\$60.00
		Sub-Total =	\$380.00
		Total cost for parts =	\$8,940.61

Labour charges

1 Panel beating for replace and repair affected parts ✓	\$1,000.00	700 ✓
2 Spray painting ✓	\$1,050.00	700 ✓
3 Apply putty and anti-corrosion to affected parts ✓	\$80.00	50 ✓
4 Wiring / bulb checking ✓	\$50.00	30 ✓

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6385 1171

Vehicle No: YP3768T
Model No: Mitsubishi Fuso
Chassis no: PM05PM2RDEB

Accident Date: 26/12/2019
Owner: Global Consolidators Pte Ltd
Date of Estimate: 04/2/2020

Estimate for Accident Vehicle No. YP3768T

- 5 R&R front windscreen glass to facilitate pillar "A" repair X
6 Transfer front door mechanism th ✓

\$180.00

\$100.00

\$3,060.00

Total parts = \$8,940.61

Total labour = \$3,060.00

Total Amount = \$12,000.61

*Reserve refer part
without payment
Hock Bee
PS311179
Hock Bee 6 days
2.30pm 5/2/20
14/2/20
Reserve refer part
without payment
Hock Bee
PS311179
Hock Bee 6 days
2.30pm 5/2/20
14/2/20*

Parts 5350.20

parts less 25%

4012.65

Spe nett 250

labour 1540

5802.65

L/s less 20%

4642.12

total L/s Amt \$4650.4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: