

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 24558**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/1534/2019/NS  
**Date** : 31-Dec-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle no : SKS 1584 U**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms Chung Lye Peng  
**Address** : 20 Toh Tuck Crescent  
Singapore 596934  
**Telephone** : (HP)+65 97860896  
**Type of Claim** : Third Party Claim  
**Policy No.** : 1700016379-02  
**Vehicle No** : **SLP 6864 H**  
**Model Code** : Q2 1.0 TFSI S TRONIC  
**Model / Year** : 14/6/2017  
**Engine No** : CHZ 345025  
**Chassis No** : WAUZZZGA3HA040768  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 27-Dec-19  
**Place of Accident** : Ramp After Toh Tuck Ave Towards PIE Tuas

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLP 6864 H

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	
2	To dismantle and renew front bumper assy. Re-organise front crash management components. Reinstall all parts removed.		\$ 1,200.00	
3	To respray front bumper.		\$ 1,000.00	
4	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	
<b>SUB TOTAL LABOUR CHARGES</b>		<b>:</b>	<b><u>\$ 2,840.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLP 6864 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00	
6	To respray rear bumper.	\$ 1,000.00	
7	To carry out diagnostic check.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 5,232.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLP 6864 H

S/N	Parts Description	<u>Damaged Parts &amp; Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,706.00	
2	FRONT BUMPER FIXING PARTS	\$ 314.00	
3	FRONT BUMPER GRILLE - CENTRE	\$ 179.00	
4	FRONT BUMPER SPOILER	\$ 273.00	
5	FRONT BUMPER CARRIER	\$ 625.00	
6	FRONT BUMPER FOAM FILLER PIECE	\$ 71.00	
7	RADIATOR GRILLE	\$ 1,301.00	
8	RADIATOR GRILLE STRIKER	\$ 114.00	
9	FRONT WHEEL COVER - LH / RH	2 \$ 588.00	
10	FRONT NO PLATE	S/N \$ 40.00	
11	REAR BUMPER	\$ 1,074.00	
12	REAR BUMPER SPOILER - LH	\$ 259.00	
13	REAR BUMPER CARRIER	\$ 501.00	
14	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 24.00	
15	REAR WHEEL COVER - LH / RH	2 \$ 312.00	
16	SUNDRIES	\$ 400.00	

<b>TOTAL SPARE PARTS</b>	<b>:</b>	<b>\$ 7,781.00</b>
<b>TOTAL LABOUR CHARGES</b>	<b>:</b>	<b>\$ 5,232.00</b>
<b>GRAND TOTAL</b>	<b>:</b>	<b>\$ 13,013.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant