



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662872

Chew Tow

27-5-17/11:41

27-5-17/15:41

24-5-17/15:41

### SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5360Y

Ref. No : TAX/05/17/2180

Reg. Date : 28/07/2010

Vehicle Type : TAXI

Make : CHRYSLER

Model : C300

Name of Driver : HENRY CHEW PONG HWEE  
( HENRY ZHOU PENGHU

Type of Accident : HEAD-ON

Date / Time of Accident : 24/05/2017 06:40:00 AM

Accident Reported Date / Time : 24/05/2017 12:00:00 AM

Surveyor is Required? : Yes

Survey by : Kalvin

Vehicle is Towed Back? : Yes

Towed Back Date/Time : 24/05/2017

Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024089790


Special Instruction to ARC, if any : 4S

Towed \$100 / SLA9262D / AXA

AFTER REPAIR PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR KALVIN (LKK) /  
Email: kalvinang@lkkauto.com

LUMPSUM REPAIR  
TYRE = 70%

Prepared Date : 24/05/2017 09:25:21 AM



1415 5/6/17 PASS

Recording Camera:

Radio Antenna

1<sup>st</sup> witness

Date

24-5-17

2<sup>nd</sup> witness

Date

5/6/17

Vehicle to Waga Auto by: 25/5 Towing: peng

Waga Job No: 13186/05

Vehicle sent to SMRT Date by: 16/6 Towing: [Signature]

Est: 1340

E (R) 1/2 F

KM 1058610

10121  
24/5/17  
K. S. S. S.

B - To be Completed by Service Advisor, Accident Repair Centre

Job No : 1C3C96CM3AY108625

Mileage : 0

Workshop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	400.00
Total Spray Painting Charges	: 1,486.00	400.00
Total Material Charges	: 9,028.96	8,056.96
Other Charges	: 1,340.00	440.00
<b>TOTAL</b>	<b>: 12,868.96</b>	<b>9,296.96</b>
Lum Sum Total	: 12,850.00	9,300.00
No. of Repair Days	: 6.00	5.00
Prepared / Adjusted By		KALVIN (LKK)
Arc / Surveyor Sign Off Date	: 24/05/2017 10:54:37 AM	24/05/2017 03:29:09 PM

*[Handwritten signature]*

*[Handwritten signature]*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 24/05/2017 10:53:43 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

*QN-1706-0159*

Invoice No :

Quotation Date :

*5/6*

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/24/2017 10:55:42 AM

Part 1 - Details of Repair Estimates  
Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	1,014.00	400.00
<b>Total Labour</b>	<b>1,014.00</b>	<b>400.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	473.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY FRONT FENDER RH	473.00	200.00
TO RESPRAY RIM	180.00	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,486.00</b>	<b>400.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	140.00	100.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00
TO TEST AND REFIX FRONT SENSOR SYSTEM	120.00	20.00
TO REMOVE AND REFIX UNDERCARRIAGE	250.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	0.00
TO REMOVE AND REFIX CROSSMEMBER	250.00	150.00
<b>Total Other Costs</b>	<b>1,340.00</b>	<b>440.00</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey by relatter spray painting
- To display damaged part(s) during resurvey
- Parts prices subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Spare Parts / Material Usage

Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
4806287 AD	FRONT		FRONT BUMPER ASSY <i>Deat</i>	1	1,830.00	10.00	1,647.00	Replace	Replace	No ✓
	COMMON		FRT BUMPER CLIP <i>see</i>	6	10.00	10.00	54.00	Replace	Replace	No ✓
	COMMON		FRT BUMPER RIVET <i>see</i>	6	20.00	10.00	108.00	Replace	Replace	No ✓
4806454 AA	FRONT		ENERGY ABSORBER, FRONT BUMPER <i>see</i>	0	408.00	10.00	0.00	Replace	Not given	No ✓
4805872 AB	FRONT		FRONT BUMPER RAIL <i>see</i>	0	1,246.00	10.00	0.00	Replace	Not given	No ✓
4805859 AB	FRONT		FOG LAMP ASSY - FRONT RH <i>see</i>	0	89.00	10.00	0.00	Replace	Not given	No ✓
	FRONT		MOULDING FRT BUMPER RH <i>see</i>	1	650.00	10.00	585.00	Replace	Replace	No ✓
	FRONT		NOZZLE FRT BUMPER RH <i>see</i>	0	320.00	10.00	0.00	Replace	Not given	No ✓
	COMMON		FRONT BUMPER INDICATOR LAMP RH <i>see</i>	1	77.00	10.00	69.30	Replace	Replace	No ✓
	FRONT		SENSOR FRT BUMPER <i>see</i>	3	320.00	10.00	864.00	Replace	Check	No ✓
4806166 AG	FRONT		HEADLAMP ASSY, FRONT RH <i>see</i>	0	2,100.00	10.00	0.00	Replace	Not given	No ✓
5135906 AI	RIGHT		FRONT FENDER ASSY, RH <i>Deat</i>	1	1,020.00	10.00	918.00	Replace	Replace	No ✓
	COMMON		FENDER PROTECTOR-FRONT RH <i>see</i>	0	130.00	10.00	0.00	Replace	Not given	No ✓
4806224 AE	COMMON		FRT FENDER LAMP <i>see</i>	0	60.00	10.00	0.00	Replace	Not given	No ✓
	COMMON		TYRE <i>Deat</i>	1	395.00	30.00	276.50	Replace	Replace	No ✓
IDV22PA KAB	COMMON		TYRE RIM <i>see</i>	1	958.00	10.00	862.20	Replace	Replace	No ✓
			TIE ROD RH <i>Deat</i>	1	200.00	10.00	180.00	Replace	Replace	No ✓
2013468 AB	COMMON		TIE-ROD ENDS RH <i>Deat</i>	1	144.00	10.00	129.60	Replace	Replace	No ✓
4782561 AE	COMMON		ARM ASSY - FRONT LOWER RH <i>Deat</i>	1	580.00	10.00	522.00	Replace	Replace	No ✓
4782666 AB	COMMON		ARM ASSY - FRONT UPPER RH <i>Deat</i>	1	640.00	10.00	576.00	Replace	Replace	No ✓
4782740 AC	COMMON		KNUCKLE - FRONT AXLE RH (ARM) <i>Deat</i>	1	1,580.00	10.00	1,422.00	Replace	Replace	No ✓
4782732 AE	COMMON		RH FRT, SHOCK ABSORBER <i>see</i>	0	310.00	10.00	0.00	Replace	Not given	No ✓
4779199 AA	COMMON		BEARING - FRONT WHEEL HUB RH <i>Deat</i>	1	492.00	10.00	442.80	Replace	Replace	No ✓
4782731 AD	COMMON		STRUT ASSY - FRONT AXLE RH <i>Deat</i>	1	302.00	10.00	271.80	Replace	Replace	No ✓
4895482 AA	COMMON		LINK SWAY, RH <i>Deat</i>	1	380.00	10.00	342.00	Replace	Replace	No ✓
	COMMON		FRONT STABILIZER BAR <i>see</i>	1	390.00	10.00	351.00	Replace	Check	No ✓
4782684 AA			ANTI-ROLL BAR BUSHING -SET <i>see</i>	0	19.40	10.00	0.00	Replace	Not given	No ✓
4854567 AA	COMMON		STEERING RACK ASSY <i>see</i>	0	1,424.00	10.00	0.00	Replace	Not given	No ✓
	COMMON		GARNISH ROCKER PANEL <i>see</i>	0	1,150.00	10.00	0.00	Replace	Not given	No ✓

10121 24/5/17

Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Recommended	Approved	Attached
COMMO N		CROSSMEMBER ASSY FRONT <i>part</i>	1	1,850.00	10.00	1,665.00	Replace	Replace <i>5</i>	No <input checked="" type="checkbox"/>
<b>TOTAL MATERIALS</b>							11,286.20	10,071.20	
<b>TOTAL MATERIALS(Discounted)</b>							9,028.96	8,056.96	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

$$\begin{array}{r}
 10071.20 \\
 - 20\% \\
 \hline
 8056.96 \\
 + 400 \\
 + 840 \\
 \hline
 9296.96
 \end{array}$$

45- \$9300 *contd*  
 13/6/17