

h

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095

Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

Not Admit
note
31/12/19
4 Lg.
the Mr. Henry.
1/5 3500

M/S : AIG INSURANCE

Estimate No: EST0001081

Date: 28 Dec 2019

Veh Reg No: SLK4391U

Make/Model: MAZDA 3

Chassis No: JM6BN22A8H0135776

Engine No: P520421104

Reg. Date: 17/01/2017

ATTN: Motor Claim Department
Your Ref No: SLK4391U MAZDA3
Claim Type: Third Party
Accident Date: 27.12.19

Estimate Repair Cost to Vehicle No :SLK4391U

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Front Fender - RH	3uc	756.20	1 PC	756.20 ✓
2 Front Fender Dust Cover - RH	17	124.40	1 PC	124.40 X
3 Front Fender Dust Cover Clipse -RH	121	5.50	6 PC	33.00 ✓
4 Front Head Lamp o/s	S.2	773.30	1 PC	773.30 ✓
5 Front Bumper	D.5	925.20	1 PC	925.20 ✓
6 Front Bumper Side Retainer o/s	bet	39.70	1 PC	39.70 ✓
7 Front Washer Tank	de	80.40	1 PC	80.40 ✓
8 Front Rim - RH	bet	290.20	1 PC	290.20 ✓
9 Front Rim Cap - RH	C.17	90.40	1 PC	90.40 ✓
10 Front Shock Absorber - RH o/s	17	492.40	1 PC	492.40 X
11 Front Shock Absorber Top Mounting o/s	17	167.20	1 PC	167.20 X
12 Front Knuckle Arm o/s	bet	564.20	1 PC	564.20 ✓
13 Front Hub Bearing o/s	re	245.40	1 PC	245.40 ✓
14 Front Lower Arm o/s	bet	482.00	1 PC	482.00 ✓
15 Front Steering Ball Joint o/s	17	93.20	1 PC	93.20 X
			5,157.20	
			Less 20%	1,031.44 4,125.76
Special Net				
16 Front Tyre - RH	6u	280.00	1 PC	280.00 X
			280.00	280.00

4280
3424

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : AIG INSURANCE

ATTN: Motor Claim Department
Your Ref No: SLK4391U MAZDA3
Claim Type: Third Party
Accident Date: 27.12.19

Estimate No: EST0001081

Date: 28 Dec 2019

Veh Reg No: SLK4391U

Make/Model: MAZDA 3

Chassis No: JM6BN22A8H0135776

Engine No: P520421104

Reg. Date: 17/01/2017

Estimate Repair Cost to Vehicle No :SLK4391U

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
17 Panel Beating	850.00	1 PC	850.00	400
18 Check Wiring	60.00	1 PC	60.00	20
19 Rust Proofing	60.00	1 PC	60.00	30
20 Alignment Adjustment	50.00	1 PC	50.00	✓
21 To Remove & Replace Front Under Carriage	280.00	1 PC	280.00	120
22 To Spray Painting	800.00	1 PC	800.00	400
			2,100.00	2,100.00
			Total	S\$ 6,505.76

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED AND FIVE AND CENTS SEVENTY SIX ONLY

For FOCUS AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE