

Reopen Car

INS. CASE OWNER: Lyntwin CC ASM AXA1901 4557, A 657 LKE IDAC: 20/8/19

Surveyor: Adrian DOI: 20/8/19 Date / Type: 20/8/19

Pre-assign / CCU / FTE: PC 4126 P 25/10/19

Insured Vehicle No: PC 4126 P Claim No: SM02XFE (172225)

Name of Insured: REN QUAN TRANH Policy No: P165685

Insured Tel No: 41570 HP: 15/8/19 Make / Model: GOLDEN DEARWIN

Excess Sec II SS: 41570 D.O.A: 15/8/19 Place of Accident: X-7000

Is driver the owner? (YES / NO) Nature of Accident: TP

If NO, Driver Name / Age: LOH KIM DUY OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Driver Tel No: 41570 (V/L: YES / NO) Insured Liability: % Final ? Yes / No

SUC 73270

INSRS: WSP: Lyntwin INSRS: WSP: CarSmith INSRS: WSP: CarSmith INSRS: WSP: CarSmith INSRS: WSP: CarSmith

Tel: 41570 Tel: 41570 Tel: 41570 Tel: 41570 Tel: 41570

Liability: CarSmith Liability: CarSmith Liability: CarSmith Liability: CarSmith Liability: CarSmith

RMKS: CarSmith RMKS: CarSmith RMKS: CarSmith RMKS: CarSmith RMKS: CarSmith

Date/Time	STAGE	DATE/PIC
	Non-Reporting to (1st)	
	Non-Reporting to (2nd)	
	Non-Reporting to (Final)	
	Notification to (if non-pickup)	
	Call CR	
	After call to CR	
	Documentation Check List: (Initial) Type	
	Notification to (if non-pickup)	
	After call to CR	
	Authorization To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	ITA / CGA	
	Medical Bill	
	PDR	
	Mend/Reject Instruction	
	LOR	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	

PRELIMINARY ADVICE Date/Time: 24/4/19 Sent By: CarSmith

FINALIZATION Date/Time: 24/4/19 Confirm with: Wilson Confirm by: CarSmith

Repair Cost: \$5 5500.00 days) Reduction: % 15 Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 24/4/19 Confirm with: Wilson Email ☒ Call ☐

Final Liability: % 15 (Agreed / Agreed) BOLA S/N No: 15

Repair Cost: \$5 5500.00 (7 days) x 15 (20.00)

Loss of Rental (LOR): \$5 840.00 (5 - x days)

Loss of Use (LOU): \$5 840.00 (5 - x days)

Loss of Income (LOI): \$5 840.00 (5 - x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GLA/TA Search: \$5 840.00

Medical: \$5 840.00

Disbursement: \$5 840.00 (e.g. Tow/Independent)

Legal Cost: \$5 840.00

Total: \$5 6220.00 Global Sum \$5: 6220.00

FINAL PAYMENT Date/Time: 24/4/19 Confirm with: CarSmith Email ☒ Call ☐

Payee 1: \$5 6220.00 Name 1: CarSmith Pte Ltd

Payee 2: (Strike if N.A.) \$5 6220.00 Name 2: CarSmith Pte Ltd

Payee 3: (Strike if N.A.) \$5 6220.00 Name 3: CarSmith Pte Ltd

COPY SENT 24/4/2020

No amendment done in final doc. doc. re (from AXA)

CARSMITH PTE LTD

Bartley Biz Centre, 13 Kallitukit Road A, #01-20 Singapore 417807
TEL : 6281 0087 FAX : 6281 0187 Email : sales@mia.com.sg

97910000
Hex

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower. S066811

Estimate No :
Date :

Email : motor.survey@axa.com.sg

Tel : 6880 4741 (Hotline)

Fax : 6880 4740 / 6880 4838

ATTN : Motor Claim Department

Your Ref No : SLC7327D

Claim Type : Third Party

Accident Date : 15.08.2019

TP Veh Reg No : PC4126P

Policy No :

Veh Reg No :

Make/Model :

Chassis No :

Engine No :

Reg Date :

SLC7327D

Audi A4 Sedan 2.0

WAUZZZF40IA232991

Estimate Repair Cost to Vehicle No : SLC7327D

Description	Quantity	Amount
SLC7327D Audi A4 Sedan 2.0 TFSI 8W		
List Price		
1 Rim, RH <i>cat</i>	1 pc	\$ 800.00 ✓
2 Rear Bumper <i>Rebuilt</i>	1 pc	\$ 3,320.00 2015
3 Rear Fender, RH <i>Distorted</i>	1 pc	\$ 2,870.00 2443
4 Rear Fender Splash Shield, RH <i>total</i>	1 pc	\$ 135.80 ✓
5 Liner Rear Wheelhouse, RH <i>new</i>	1 pc	\$ 380.00 ✓
6 Panel Quarter Wheelhouse Outer, RH <i>Repair</i>	1 pc	\$ 1,360.00 ✓
7 Panel Quarter Wheelhouse Inner, RH <i>Repair</i>	1 pc	\$ 1,880.00 ✓
8 Retainer Quarter Panel, RH <i>Repair</i>	1 pc	\$ 98.00 ✓
9 Rear Fender Inner Trim Clip <i>new</i>	1 set	\$ 45.00 30
10 Fender Liner Retainer Clip <i>new</i>	1 set	\$ 50.00 30
11 Lower Control Arms	1 pc	\$ 1,260.00 ✓
12 Upper Control Arms	1 pc	\$ 1,880.00 5354.11
13 Ball Joint	1 pc	\$ 200.00 ✓
14 Sway Bar Link	1 pc	\$ 467.00 8 N-60
15 Steering Knuckle Spindle <i>new</i>	1 pc	\$ 900.60 ✓
16 Bushing	1 pc	\$ 350.60 ✓
17 Disk Brake, RH	1 pc	\$ 627.60 ✓
18 Rear Windscreen <i>Rebuilding. new</i>	180	\$ 16,624.60
19 Rear Windscreen <i>Rebuilt.</i>	180 <i>60(24)</i>	\$ 831.23 Less 5%
		\$ 15,793.37
Labour		
18 To spray painting on affected area.		\$ 1,800.00 500
19 To spray anti-rust coating on new and affected panels.		\$ 180.00 60
20 To remove and reinstall rear fender & windscreen.		\$ 200.00 120
21 To remove and reinstall rim, RH.		\$ 150.00 50
22 To check and replace rear sensor.		\$ 120.00 60
23 To conduct wheel alignment.		\$ 300.00 20
24 <i>OK To check electrical wiring system.</i>		\$ 160.00 20
25 <i>To remove and reinstall undercarriage parts.</i>		\$ 350.00 ✓
26 <i>To provide labour charges, workmanship to dismantle above damaged parts, repair</i>		\$ 1800.00 600
- To including cut and weld; re-align body structure and damaged consistent to the accident. - Parts price are subject to confirmation. - Third party survey is on a "Without Prejudice" basis. - No illegal modification(s) is allowed. - Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company.		
Total : SINGAPORE DOLLAR TWENTY THOUSAND EIGHT HUNDRED FIFTY THREE AND CENTS THIRTY-SEVEN ONLY.		\$ 20,853.37
Acknowledged by Repairer		
Signature:		
Date:		

Total

5.5K

Total 6972.11

L/S 5.5K

06 Days



WHEEL ALIGNMENT SYSTEM

Customer: Reg. N.: SLC7117D
Description: AUDI A4 Repair order no.
Reference Diameter: 18" Mileage: km
Working Notes: *
Date: 23/09/2019 Time: 14.51.31
Operator:

	Databank				Previous Values		Final Values	
	Data		- Tolerance	+ Tolerance	LH	RH	LH	RH
FRONT AXLE	LH	RH						
Total toe	+00.33"		-00.07"	+00.07"	+00.88"		+00.31"	
Half-toe	+00.17"	+00.17"	-00.04"	+00.04"	+00.71"	+00.17"	+00.15"	+00.16"
Max Dif.								
Camber	-00.33"	-00.33"	-00.42"	+00.42"	-00.39"	-01.15"	-00.32"	-01.19"
Max Dif.	00.00"		-00.50"	+00.50"	+00.76"		+00.87"	
Caster					+03.64"	+04.05"	+03.61"	+04.09"
Max Dif.								
King-pin angle					+01.97"	+02.38"	+01.97"	+02.38"
Max Dif.								
Included angle					+01.57"	+01.23"	+01.65"	+01.20"
Steering angle diff. at 20°								
Max Int. Steering Angle								
Max Ext. Steering Angle								
Set Back					-00.11"		-00.23"	
REAR AXLE	LH	RH			LH	RH	LH	RH
Total toe	+00.33"		-00.17"	+00.25"	+00.67"		+00.39"	
Half-toe	+00.17"	+00.17"	-00.09"	+00.12"	+00.31"	+00.36"	+00.21"	+00.19"
Max Dif.								
Camber	-00.83"	-00.83"	-00.33"	+00.33"	-00.53"	-01.03"	-00.97"	-00.99"
Max Dif.	00.00"		-00.50"	+00.50"	+00.50"		+00.02"	
Set Back					-00.40"		-00.32"	
Thrust angle	00.00"		-00.25"	+00.25"	-00.02"		+00.01"	
Track difference					-00.51"		-00.53"	

Publicity Messg 1
Publicity Messg 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0980/2019/NS
Date : 19-Aug-19

Vehicle not in workshop. Kindly arrange for survey.

Your Insured veh no. : PC 4126 P

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : MR CHUA SWEE HEE
Address : BLK 642 PASIR RIS DRIVE 10
 #07-36
 Singapore 510642
Telephone : 96868474
Type of Claim : Third Party Claims
Policy No. : 1800126073
Vehicle No : SLC 7327 D
Model Code : Audi A4 SEDAN 2.0 TFSI 8W
Model / Year : Oct-18
Engine No : CVK 069074
Chassis No : WAUZZZF40JA232991
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Aug-19
Place of Accident : CECIL ROAD NEAR LAMP POST 24/1 JUNCTION

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 7327 D

S/n	Nature of Jobs		Estimated Charges	SURVEYOR'S RECOMMENDATION
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function	S/N	\$ 360.00	✓
2	To renew windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N	\$ 600.00	✓
3	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	X
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical audio equipment.	S/N	\$ 1,400.00	✓
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	✓
SUB TOTAL LABOUR CHARGES		:	\$ 4,040.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 7327 D

S/n	Nature of Jobs	Estimated Charges	SURVEYOR'S RECOMMENDATION
6	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. Renew rhs rear door and rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	S 6,300.00	4200
7	To respray rear bumper, rhs rear fender, rhs rear door, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	S 5,500.00	700 x 4 = 2800
8	To renew rhs rear rim and carry out wheel alignment.	S/N S 280.00	✓
9	To carry out diagnostic checks.	S/N S 192.00	✓
TOTAL LABOUR CHARGES		S 16,312.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 7327 D

S/N	Parts Description	Damaged Parts & Prices		REMARKS
			S/Nett	
1	REAR BUMPER <i>Replaced</i>	\$	2,015.00	✓
2	BUMPER FIXING PARTS <i>new</i>	\$	66.00	✓
3	REAR BUMPER SECURING STRIP <i>?</i>	NEC \$	203.00	?
4	REAR BUMPER SPOILER <i>new</i>	\$	227.00	✓
5	REAR LIGHT REFLECTOR - RH <i>new</i>	\$	38.00	✓
6	REAR BUMPER GUIDE SECTION - RH <i>?</i>	\$	41.00	?
7	REAR BUMPER GUIDE SECTION - RH <i>?</i>	\$	20.00	?
8	REAR FENDER SIDE PANEL <i>Replaced</i>	\$	2,443.00	✓
9	RIVETTED CAP NUT <i>?</i>	NEC \$	2.00	✓
10	GROMMET <i>new</i>	NEC \$	2.00	✓
11	BLIND RIVET STUD <i>new</i>	NEC \$	9.00	✓
12	REAR WINDOW <i>new</i>	\$	1,049.00	✓
13	SIDE WINDOW - RH <i>new</i>	\$	561.00	✓
14	PRIMER <i>new</i>	\$	25.00	✓
15	WHEEL HOUSING LINER - RH <i>new</i>	\$	223.00	✓
16	ALUMINIUM RIM - LH <i>cut</i>	\$	651.00	✓
17	RUBBER VALVE <i>new</i>	\$	13.00	✓
18	DOOR - RH <i>new</i>	\$	2,152.00	✓
19	OUTER DOOR SEAL - RH <i>new</i>	NEC \$	185.00	✓
20	BONDING AGENT - RH <i>new</i>	NEC \$	45.00	✓
SUB TOTAL SPARE PARTS CHARGES		\$	9,970.00	

Premium Automobiles

55, Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 7327 D

S/N	Parts Description	Damaged Parts & Prices		REMARKS
		S/Nett		
21	CLEANING SOLUTION	NEC	\$ 65.00	+
22	SEALING STRIP		\$ 15.00	X
23	DOOR CATCH		\$ 109.00	X
24	DOOR ATTACHMENT PARTS		\$ 515.00	X
25	ACRYLIC SEALANT	S/N	\$ 180.00	✓
26	CAVITY WAX	S/N	\$ 140.00	✓
27	STONE CHIP	NS/N	\$ 180.00	✓
28	METAL FILLER POWDER	S/N	\$ 280.00	✓
29	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	✓
30	1/4 GLASS SEALANT	S/N	\$ 100.00	✓
31	SUNDRIES	S/N	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 12,254.00	
TOTAL LABOUR CHARGES			\$ 16,312.00	
GRAND TOTAL			\$ 28,566.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183



Telefax

Name : Adrian L
Surveyed Date : 20/08/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 12 days.

Please Note : This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	902G
Vehicle No:	SLC7327D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No:	CVK069074
Chassis No:	WAUZZZF40JA232991
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,432.00
Original Registration Date:	22 Oct 2018
First Registration Date:	22 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$38,805.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Oct 2028
PARF Rebate Amount:	\$29,103.00
COE Expiry Date:	21 Oct 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,302.00
COE Rebate Amount:	\$25,041.00
Total Rebate Amount:	\$54,144.00

The information contained herein is correct as at 20 Aug 2019

OK

<<

<TP - Mandate IA> - S9M01XAE [ACCIDENT INVOLVING PC 4129P(OI) & SLC 7327D(TP) ON 15/08/2019]

Type

🔗 Question

Message

Liability: 100%. Insured driver changed lane and collided with third party. Inform OI about third party claim, will let AXA to handle and aware NCD issue. We seek your mandate at \$6,509.00(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 2-Jan-20

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 02/01/2020

Survey Details:

Date of loss	15.08.2019
Date of appointment	20.08.2019
Date of survey	20.08.2019
Location of survey	CARSMITH PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLC 7327D
Make and Model	AUDI A4
Date of registration	22/10/2018
Excess	
Market Value	\$138,000
Part Rebate	\$54,144
Nett Loss	\$83,856

Repair details:

Initial Estimate	\$ 20,853.37
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,412.11
Check items (estimate)	NIL
Labour	\$ 1,500.00
Total	\$ 6,912.11
Lump Sum(if applicable)	\$ 5,500.00
Number of days for repair	06



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID changed lane and collided with third party.

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$	5,500.00
Loss of use		NIL no. of days
Loss of rental	\$	980.00 (7days x \$140.00)
Loss of income		NIL no. of days
LTA search fees	\$	29.00 (subject to receipt)
Others		NIL
Proposed Total	\$	6,509.00



Re:<TP - Mandate IA> - S9M01XAE [ACCIDENT INVOLVING PC 4129P(OI) & SLC 7327D(TP) ON 15/08/2019]

Type
❗ Question

Message
Approve

Reply

Hsiao Tong (LKKAUTO)

From: CARSMITH PRIVATE LIMITED <carsmithpl@gmail.com>
Sent: Monday, 17 February 2020 1:35 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A; Carsmith Pte Ltd
Subject: Re: Your Ref: SLC7327D *LKK Ref: CC4/ASM19014557/Apb3q2-1 [ACCIDENT INVOLVING PC 4126P(AXA) AND SLC 7327D ON 15/08/2019]

Hi Ms Chew

we will accept the settlement as of Jan 13 2020.

Kindly forward the DV.

thanks

Wilson
Carsmith Pte Ltd
Bartley Biz Centre,
13 Kaki Bukit Road 4
#01-20
Singapore 417807

On Mon, Jan 13, 2020 at 10:52 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Your Ref: **SLC7327D** **Without Prejudice**

LKK Ref: CC4/ASM19014557/Apb3q2-1

Dear Sirs/Mdm,

ACCIDENT INVOLVING PC 4126P(AXA) AND SLC 7327D ON 15/08/2019

We refer to the above matter.

We propose settlement at a global sum of **\$6,220.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

"Wishing you a Happy and Prosperous New Year"



Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

CARSMITH PTE LTD

25 TEBAN GARDEN ROAD #10-181 SINGAPORE 600025
Telephone no: +65 9091 0000

60170415

To: AXA INSURANCE PTE LTD

3019002022---

Address:

8 Shenton way, #24-01, AXA Tower, s068811
customer centre, #B1-01

(Your Insured motor vehicle no: PC 4126P)

Dear Sirs

Claimant name: CHUA SWEE HEE (S1639902G)

Address: BLK 642 PASIR RIS DRIVE 10 #07-36

(Claimant motor vehicle no: SLC7327D)



We are representing the above mention claimant to claim damages against you in connection with an accident on (DOA-15-08-2019) along (Location: CECIL ROAD NEAR LAMP POST 24/1 JUNCTION) involving vehicle registration numbers (SLC7327D & PC4126P) driven by your client at the material time of the accident.

Letter of demand

- 1) Pre-repair inspection day - \$ 320.00
- 2) Rental / Loss of used - \$ 1120.00
- 3) Final repair cost - \$ 5500.00
- 4) GIA Search Fees - \$ 29.00

In compliance with the protocol, we have engaged your panel of surveyor for the damages claim to the said amount. Do refer to attachment and we hope to have an amicable settlement reply soon.

With Regards,

Alex Beh



CARSMITH PRIVATE LIMITED
BARTLEY BIZ CENTRE
13 KAKI BUKIT ROAD 4 #01-20
Singapore 417807
+65 90910000
carsmithpl@gmail.com

INVOICE

INVOICE TO
SLC73270

INVOICE NO. 1075
DATE 09/10/2019
DUE DATE 09/10/2019
TERMS Due on receipt

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
09/10/2019	LUMP SUM REPAIR AS RECOMMENDED & AGREED WITH SURVEYOR		0	5,500.00	5,500.00

BALANCE DUE

S\$5,500.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014557/Apb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 25-10-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 4126P	Veh. Inspected	SLC 7327B
Policy No.	P1656875	Coverage (\$)	0.00
Claim No.	S9M01XAE	Excess (\$)	0.00
Assign From		Assign Date	20/08/2019

2. Vehicle Particulars & Condition

Make & Model	AUDI A4 SEDAN	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WAUZZZF40JA232891	Colour	RED
Odometer	18966	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/08/2019	Inspection Date	20/08/2019
Survey held at	55 UBI ROAD 1 . SINGAPORE 408699		
Repairer	CARSMITH PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7327D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RIM ,RH (CONSISTENT)	CUT✓	800.00✓	800.00✓
1	REAR BUMPER (CONSISTENT)	DEFORMED	3,320.00✓	2,015.00✓
1	REAR FENDER ,RH (CONSISTENT)	DISTORTED✓	2,870.00✓	2,443.00✓
1	REAR FENDER SPLASH SHIELD ,RH (CONSISTENT)	TORN ✓	135.80✓	135.80✓
1	LINER REAR WINDSCREEN ,RH (CONSISTENT)	NOT NECESSARY	380.00✓	-
1	PANEL QUARTER WHEELHOUSE OUTER ,RH (CONSISTENT)	TO REPAIR SEE LABOUR ✓	1,360.00✓	-
1	PANEL QUARTER WHEELHOUSE INNER ,RH (CONSISTENT)	TO REPAIR SEE LABOUR ✓	1,880.00✓	-
1	RETAINER QUARTER PANEL ,RH (CONSISTENT)	TO REPAIR SEE LABOUR ✓	98.00✓	-
1	SET REAR FENDER INNER TRIM CLIP (CONSISTENT)	NECESSARY✓	45.00✓	30.00✓
1	SET FENDER LINER RETAINER CLIP (CONSISTENT)	NECESSARY✓	50.00✓	30.00✓
1	LOWER CONTROL ARMS (CONSISTENT)	NOT NECESSARY	1,260.00✓	-
1	UPPER CONTROL ARMS (CONSISTENT)	NOT NECESSARY	1,880.00✓	-
1	BALL JOINT (CONSISTENT)	NOT NECESSARY	200.00✓	-
1	SWAY BAR LINK (CONSISTENT)	NOT NECESSARY	467.00✓	-
1	STEERING KNUCKLE SPINDLE (CONSISTENT)	NOT NECESSARY	900.60✓	-
1	BUSHING (CONSISTENT)	NOT NECESSARY	350.60✓	-
1	DISK BRAKE ,RH (CONSISTENT)	NOT NECESSARY	627.60✓	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY ✓	180.00✓	180.00✓
	LESS 5% DISCOUNT		-840.23✓	-281.69✓
			15,964.37✓	5,352.11✓
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY✓	100.00✓	60.00✓
			100.00✓	60.00✓
	<u>LABOUR</u>			
	TO SPRAY PAINTING ON AFFECTED AREA.		1,800.00✓	500.00✓
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		180.00✓	60.00✓
	TO REMOVE AND REINSTALL REAR WINDSCREEN.		200.00✓	120.00✓

Report Ref No. CC4/ASM19014557/Apb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL RIM ,RH .		150.00	50.00
	TO CHECK AND REPLACE REAR SENSOR .		120.00	60.00
	TO CONDUCT WHEEL ALIGNMENT.		300.00	80.00
	TO CHECK ELECTRICAL WIRING SYSTEM.		160.00	30.00
	TO REMOVE AND REINSTALL UNDERCARRIAGE PARTS.	NOT NECESSARY	350.00	-
	TO PROVIDE LABOUR CHARGES, WORMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD,RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF PANEL QUARTER WHEELHOUSE OUTER ,RH,PANEL QUARTER WHEELHOUSE INNER ,RH AND RETAINER QUARTER PANEL ,RH .		1,800.00	600.00
			5,060.00	1,500.00
	GRAND TOTAL		21,124.37	6,912.11
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00

Report Ref No. CC4/ASM19014557/Apb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9MD1XAE
Reference	CC4/ASM19014557/Apb3a2-1
Loss Date	15 August 2019
Report Date	16 Aug 2019 3:52:00 PM
Request Date	20 August 2019

Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next StepWait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SLC7327D
Make	TPVD AUDI
Model	A4 SEDAN 2.0
Service Address	

Primary Contact/Insured	
REN QUAN TRANSPORT BLK 356 YISHUN RING ROAD, #08-182B, 760356, Singapore 96659336 INSURANCE@SCAUTO.COM.SG	

Claim Handler	
LOH Cynthia 6568804843 cynthia.loh@axa.com.sg	

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document TypeDocument SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Accident Statement	Reports & Statement	Measures
--------------------	---------------------	----------

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 TP-MANDATE IA DO 020120.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	2 January 2020
 LETTER TO CL_.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	2 January 2020
 TO LKK.tif	Letters and Correspondence	Investigator / Adjustor	LOH Cynthia	30 October 2019
 LKKInvoice1 (4).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 LKK PHOTO-2.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 LKK PHOTO-3.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
 EMAIL.mng	Letters and Correspondence	Others	VISHNU BATHAM Shekhar	18 October 2019
 TP LOD.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	18 October 2019
 TP ESTIMATE_MARKED-Carnesh Pte Ltd.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	8 October 2019
 EMAIL FROM WORKSHOP.mng	Letters and Correspondence	Others	NIKAM Santosh Pandurang	16 September 2019
 Co claimant.mng	Letters and Correspondence	Workshop	DHANAJ Raghav	13 September 2019
 TP-IA 7327.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 August 2019
 EMAIL FOIRM WORKSHOP.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	20 August 2019
 reply from workshop.mng	Letters and Correspondence	Others	NIKAM Santosh Pandurang	20 August 2019
 TP mar Video - Accident.MP4	Evidence	Videos	LOH Cynthia	19 August 2019
 TP front Vidno - Accident.MP4	Evidence	Videos	LOH Cynthia	19 August 2019
 P1656875_CL_00048_0008_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NIKAM Santosh Pandurang	16 August 2019
 P1656875_EN_00043_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NIKAM Santosh Pandurang	16 August 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 EMAIL FROM WORKSHOP FOR TP REG.mig	Letters and Correspondence	Others	NIKAM Santosh Pandurang	16 August 2019
 PC4126P INSD GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	16 August 2019